

Chapter 7 – Page 7-39

(This step has been corrected in Version 2011).



Step 8:

- Click Hole-Wizard.

- Select/Enter the following:

- * Standard: **Ansi Inch**
- * Type: **Flat Head Screw (100)**.
- * Size: **1/4"**
- * Fit: **Normal**
- * End Condition: **Blind**
- * Depth: **1.250"**

(Do not click OK just yet).




- Click the **Position** tab (arrow).

- Click the **3D Sketch** button (Arrow).


*This step activates the **Point** command, which will be used to create the center of the hole.*


- With the Point command selected, click approximately as indicated to place the center of the 1st hole

- This is a 3D sketch hole it should be created on a surface and later, snapped to the midpoint of a line to fully define it.



- Add a Midpoint relation between the Centerpoint of the hole and the horizontal line as noted.





- The C'sink should be fully defined at this point.

- Click **OK** to close out of the Hole-Wizard mode.

Step 9:

- Click **Curve Driven Pattern** under the Linear Pattern drop down list.


- For Pattern-Direction, select the **Curve2** from the Feature tree.

- Enter **30** for Number of Instances.

- Enable the **Equal Spacing** check box.

- Enable: **Transform Curve** and **Tangent to Curve**

- In the Features to Pattern dialog, select the **C'sink hole** from the Feature tree.



- Click **OK**.