# Autodesk **Inventor** 2024 A Tutorial Introduction Includes video instruction



L. Scott Hansen, Ph.D.





## Visit the following websites to learn more about this book:





Googlebooks






# Learning to Create a Detail Drawing


# **Objectives:**

- 1. Create a simple sketch using the Sketch Panel
- 2. Extrude a sketch into a solid using the 3D Model Panel
- 3. Create an Orthographic view using the Place Views/Drawing Views Panel
- 4. Extrude a sketch in the 3D Model Panel
- 5. Edit the appearance of a Solid Model using the Edit Views command



Chapter 3 includes instruction on how to design the parts shown.

- 1. Start Autodesk Inventor 2024 by referring to "Chapter 1 Getting Started."
- **2.** After Autodesk Inventor 2024 is running, begin a new sketch.
- 3. Complete the drawing on the XY Plane shown in Figure 1.



**4.** Move the cursor to the right portion of the screen and left click on the 3D Model tab. Left click on the **Chamfer** icon as shown in Figure 2.

													Left Cl	ick Here	
Conference of the Conference o	7 🛃 <≒ + ↔	・ 合 売 Annotate		Generic Tools Man		Default	👻 🖗 🙌		Iaborate G	Help & Con	nmands Q	Sign In	• 🕞 🤇	D• -	- 🗆
		Sweep	Emboss Derive	🛃 Decal	Hole Fillet	Chamfe	1	Shape Generator	Plane 2	Tell a	Box P		Stress Analysis	Convert to Sheet Metal	• •
Sketch		Crea	ate			Modify -		Explore	Work Features		Create Freeform	Surface	Simulation	Convert	

5. After selecting **Chamfer**, the Chamfer dialog box will appear. Left click on the **Edge** icon. Left click on the "Two Distance Chamfer" icon as shown in Figure 3.


hamfer	×
namfer Partial	
	Distance 1
The Edge	0.125 in >
TT TT	Distance2
<u>`</u>	0.125 in >
Edge Chain	Setback
	*
Preserve All Features	

Figure 3

- Line Turned Red Chamfer X Ш× Chamfer Partial Distance 1 z. Edge 0.125 in > Ŷ +± Distance2 0,\$,4°,4.10° 0.125 in > Edge Chain Setback 00 \* \* Preserve All Features ? OK Cancel Apply
- 6. Move the cursor to the front upper corner. A red line will appear as shown in Figure 4.



7. Inventor will provide a preview of the anticipated chamfer as shown in Figure 5.





**8.** Move the cursor to Distance 1 in the dialog box and highlight the text. Enter **.25** in the dialog box. Inventor will provide a preview of the chamfer as shown in Figure 6.






Figure 6

**9.** Move the cursor to Distance 2 in the dialog box and highlight the text. Enter **.1875** in the dialog box. Inventor will provide a preview of the chamfer. To flip the direction of the chamfer simply left click on the Flip icon as shown in Figure 7.





**10.** Left click on **OK**. Your screen should look similar to Figure 8.



#### Figure 8

**11.** Save the part file for easy retrieval to be used in the following section. Do not close the part file.

#### Create an Orthographic view using the Drawing Views Panel

12. After the part file has been saved, move the cursor to the upper left portion of the screen and left click on the drop-down arrow to the right of the "New" icon. A drop-down menu will appear. Left click on Drawing as shown in Figure 9. Once the Drawing Views Panel appears, skip to step 14. If the Drawing Views Panel does not appear, move to step 13.

Left Click Here

	Pr Ch	• 🔊 • 🖓	🛞 Generic	- 😡 🖬	Default	<del>7 (1</del> . 1)	Part1	<b>ب</b> ا	earch H	elp & Con	nmands 👤	Sign In	- 17 (	D• -	_ □
Assembly	etch Annotate	Inspect	Tools Man	age View	Environments	Get Sta	arted Col	laborate	٠	•					
-	volve	Emboss	10.77 S	Hole Fillet	Chamfer		Shape Generator	Plane	<ul> <li>↓</li> <li>↓</li> <li>↓</li> </ul>		Box		Stress Analysis	Convert to Sheet Metal	•
Part Part	Cre	ate			Modify 🕶		Explore	Work Fe	atures	Pattern	Create Freeform	Surface	Simulation	Convert	
Presentation	QE														


Figure 9

 The Create New File dialog box is shown below. Left click on the drop-down arrow next to en-US. Left click on the English folder. Left click on the ANSI (in).idw. Left click on Create as shown in Figure 10.

I Create New File	sk\ <u>Unvector 2020</u> \Templates\	
<ul> <li>Templates</li> <li>en-US</li> <li>English</li> <li>Metric</li> <li>Mold Design</li> <li>OldTemplates</li> </ul>	<ul> <li>Part - Create 2D and 3D objects</li> <li>Sheet Standard Metal (in).ipt (in).ipt</li> <li>Assembly - Assemble 2D and 3D components</li> <li>Mold Standard Weldment Design (in).iam (ANSI).ian (in).iam</li> <li>Drawing - Create an annotated document</li> <li>Drawing - Create an annotated document</li> <li>Drawing - Create an annotated document</li> <li>ANSI (in).dwg</li> <li>Presentation - Create an exploded projection of ar</li> <li>Standard (in).ipn</li> </ul>	g



14. Your screen should look similar to Figure 11.





- **15.** Inventor is now in the Drawing Views Panel. Notice the commands at the top of the screen are now different.
- **16.** Move the cursor to the upper left portion of the screen and left click on **Base** as shown in Figure 12.

						<ul> <li>Left Click Here</li> </ul>	
I D·D·B·A·A·G·····························	÷		Drawing1			<ul> <li>Search Help &amp; Commands</li> </ul>	Q Sign In
File Place Views Annotate Sketch Tools Manage V	View	Environments	Collaborate	•			
Nailboard	野		₿.₽				
Base Projected Auxiliary Section Detail Overlay	Draft	Break Break Ou	t Slice Crop	Horizontal	Start Sketch	New Sheet	
Create			Modify		Sketch	Sheets	
Figure 12							

**17.** The drawing of the wedge block should appear attached to the cursor. If the part does not appear attached to the cursor, use the "Explore" icon to locate the part file as shown in Figure 13.

			/ Left Click Here if Pa	rt is Not Attached to Cur	sor
	・わた詞・キャ	Chapter Graphic1	▶ Search Help & Commands	<u>Q</u> Sign In 🔹 🔓 🕐 •	_ 🗆 X
File Place Views Annotate Sketch	Tools Manage View Environn	nents Get Started Collaborate	•		
Base Projected Auxiliary Section Detail Ov	Nailboard Connector Draft Break B	reak Out Slice Crop Horizontal	Start New Sheet		
Create		Modify	Sketch Sheets		
Model $\times$ + Q $\equiv$	Drawing View	×		a	) E ×
Drawing3     * Drawing8 Resources     * AnSI - Large	Component Madel State Deplay Option File  SyscottiPublished Inventor 2018/Chap1 Representation  IS- Master  Component  C	er 3 Graphics(Chapt ) () Style () Raster View Label () Scale () OK Cancel () () () () () () () () () ()	1 		
Ready					0 3
Figure 13					
				Part Attached to Curso	or

18. Different views can be selected for the front, top, and side views. Select the desired view from the view orientation cube as shown in Figure 14. To understand how the view orientation cube works, left click on the arrows that signify **Top**, **Left or Right** to have the top view, left view or right view as the front (base) view. Select the **Front** view for the base view as shown in Figure 14.






Figure 14

 Left click on the Scale drop-down box and set the drawing scale to 4:1 (if it is not already set to 4:1). The size of the wedge block will become larger as shown in Figure 15. Left click on OK.



**20.** Place the part just above the title block that is in the lower right corner of the screen and left click once. This will place the part as shown in Figure 16.



- **21.** If the part was inadvertently placed too low or too high, move the cursor over the dots that surround the part, left click (holding the mouse button down), and drag the part to the desired location.
- **22.** Move the cursor to the upper left portion of the screen and left click on **Projected** as shown in Figure 17.




Figure 17

**23.** The part will be attached to the cursor. Move the cursor upward and left click as shown in Figure 18.






Figure 18

**24.** Notice the black lines around the top view as shown in Figure 19. This indicates that the view has been placed.




**25.** Move the cursor over to the upper right corner of the page and left click once as shown in Figure 20.






**26.** Move the cursor down to where the side view will be located and left click once as shown in Figure 21.




27. Right click on the last view created (side view). A pop-up menu will appear. Left click on **Create** as shown in Figure 22.





**28.** Your screen should look similar to Figure 23.



#### Create a Solid Model using the Edit Views command

**29.** Move the cursor over the isometric view in the upper right corner of the drawing. Red dots will appear as shown in Figure 24.





Figure 24

**30.** After the red dots appear, right click once. A pop-up menu will appear. Left click on **Edit View** as shown in Figure 25.






**31.** The Drawing View dialog box will appear. Left click on the "blue sphere." Left click on **OK** as shown in Figure 26.

Prawing View	N			
Component	Model State	Display Options	Recovery	Options
File				
J:\Scott\Pu	blished Invent	or 2015\Chapter	3 Graphics \(	Chapte / 🖸
Represent	tation		Style [	
Î <b>⊒</b> ª Mast	er	~	89 89	0
			Raster	liew
			Label VIEW3	0
			Scale	
			4:1	~
? 🗆 🕈	n d		ок	Cancel

Figure 26

32. The isometric view will become a miniature solid model as shown in Figure 27.



**33.** Your screen should look similar to Figure 28.






Figure 28

### **Chapter Problems**




Create 3 view/multi view drawings of the following parts.


Problem 3-2








Problem 3-4 Hint: Use the 2 directional Extrude-Cut command to create the 1.625 Diameter Hole





Problem 3-6

