
CATIA V5 Tutorials

Mechanism Design & Animation

Release 19



Nader G. Zamani

University of Windsor

Jonathan M. Weaver

University of Detroit Mercy



Schroff Development Corporation www.schroff.com

Better Textbooks. Lower Prices.

Chapter 4

Slider Crank Mechanism


Introduction

In this tutorial you create a slider crank mechanism using a combination of revolute and cylindrical joints. You will also experiment with additional plotting utilities in CATIA.

1 Problem Statement

A slider crank mechanism, sometimes referred to as a three-bar-linkage, can be thought of as a four bar linkage where one of the links is made infinite in length. The piston based internal combustion is based off of this mechanism. The analytical solution to the kinematics of a slider crank can be found in elementary dynamics textbooks.

In this tutorial, we aim to simulate the slider crank mechanism shown below for constant crank rotation and to generate plots of some of the results, including position, velocity, and acceleration of the slider. The mechanism is constructed by assembling four parts as described later in the tutorial. In CATIA, the number and type of mechanism joints will be determined by the nature of the assembly constraints applied. There are several valid combinations of joints which would produce a kinematically correct simulation of the slider crank mechanism. The most intuitive combination would be three revolute joints and a prismatic joint. From a degrees of freedom standpoint, using three revolute joints and a prismatic joint redundantly constrains the system, although the redundancy does not create a problem unless it is geometrically infeasible, in this tutorial we will choose an alternate combination of joints both to illustrate cylindrical joints and to illustrate that any set of joint which removes the appropriate degrees of freedom while providing the capability to drive the desired motions can be applied. In the approach suggested by this tutorial, the assembly constraints will be applied in such a way that two revolute joints and two cylindrical joints are created reducing the degrees of freedom are reduced to one. This remaining degree of freedom is then removed by declaring the crank joint (one of the cylindrical joints in our approach) as being angle driven. An exercise left to the reader is to create the same mechanism using three revolute joints and one prismatic joint or some other suitable combination of joints. We will use the Multiplot feature available in CATIA is used to create plots of the simulation results where the abscissa is not necessarily the time variable.



2 Overview of this Tutorial


In this tutorial you will:

- 1. Model the four CATIA parts required.
- 2. Create an assembly (CATIA Product) containing the parts.
- 3. Constrain the assembly in such a way that only one degree of freedom is unconstrained. This remaining degree of freedom can be thought of as rotation of the crank.
- 4. Enter the **Digital Mockup** workbench and convert the assembly constraints into two revolute and two cylindrical joints.
- 5. Simulate the relative motion of the arm base without consideration to time (in other words, without implementing the time based angular velocity given in the problem statement).
- 6. Add a formula to implement the time based kinematics associated with constant angular velocity of the crank.
- 7. Simulate the desired constant angular velocity motion and generate plots of the kinematic results.

3 Creation of the Assembly in Mechanical Design Solutions

Although the dimensions of the components are irrelevant to the process (but not to the kinematic results), the tutorial details provide some specific dimensions making it easier for the reader to model the appropriate parts and to obtain results similar to those herein. Where specific dimensions are given, it is recommended that you use the indicated values (in inches). Some dimensions of lesser importance are not given; simply estimate those dimensions from the drawing.

In CATIA, model four parts named base, crank, conrod, and block as shown below.



Enter the **Assembly Design** workbench which can be achieved by different means depending on your CATIA customization. For example, from the standard




In order to change the default name, move the curser to **Product.1** in the tree, right click and select **Properties** from the menu list.

From the **Properties** box, select the **Product** tab and in **Part Number** type slider crank.

This will be the new product name throughout the chapter. The tree on the top left corner of your computer screen should look as displayed below.






The next step is to insert the existing parts in the assembly just created. From the standard Windows toolbar, select **Insert > Existing Component**.

From the **File Selection** pop up box choose all four parts. Remember that in CATIA multiple selections are made with the **Ctrl** key. The tree is modified to indicate that the

parts have been inserted.






Note that the part names and their instance names were purposely made the same. This practice makes the identification of the assembly constraints a lot easier down the road. Depending on how your parts were created earlier, on the computer screen you have the four parts all clustered around the origin. You may have to use the **Manipulation** icon Move




in the **Move** toolbar

to rearrange them as desired.



The best way of saving your work is to save the entire assembly. Double click on the top branch of the tree. This is to ensure that you are in the **Assembly Design** workbench.


Select the **Save** icon . The **Save As** pop up box allows you to rename if desired. The default name is the **slider_crank**.



Your next task is to impose assembly constraints.

Pick the **Anchor** icon from the **Constraints** toolbar and select the **base** from the tree or from the screen. This removes all six degrees of freedom for the base.





Next, we will create a coincident edge constraint between the base and the block. This removes all dof except for translation along the edge of coincidence and rotation about the edge of coincidence. The two remaining dof are consistent with our desire to create a cylindrical joint between the block and the base. To make the constraint, pick the


Coincidence icon from the **Constraints** toolbar



Select the two edges of the **base** and the

block as shown below.


This constraint is reflected in the appropriate branch of the tree.



Use **Update** icon to partially position the two parts as shown.


Note that the **Update** icon no longer appears on the constraints branches.

Depending on how your parts were constructed the block may end up in a position quite different from what is shown below. You can always use the **Manipulation** icon position it where desired followed by **Update** if necessary.




You will now impose assembly constraints between the conrod and the block. Recall that we ultimately wish to create a revolute joint between these two parts, so our assembly constraints need to remove all the dof except for rotation about the axis.

Pick the **Coincidence** icon from **Constraints** toolbar. Select the axes of the two cylindrical surfaces as shown below. Keep in mind that the easy way to locate the axis is to point the cursor to the curved surfaces.




The coincidence constraint just created removes all but two dof between the conrod and the base. The two remaining dof are rotation about the axis (a desired dof) and translation along the axis (a dof we wish to remove in order to produce the desired revolute joint). To remove the translation, pick the **Coincidence** icon from the **Constraints** toolbar and select the surfaces shown on the next page. If your parts are

originally oriented similar to what is shown, you will need to choose **Same** for the **Orientation** in the **Constraints Definition** box so that the conrod will flip to the desired orientation upon an update. The tree is modified to reflect this constraint.




Use **Update** icon to partially position the two parts as shown below. Note that upon updating, the conrod may end up in a location which is not convenient for

the rest of the assembly. In this situation the **Manipulation** icon can be used to conveniently rearrange the conrod orientation.




So far, we have created assembly constraints which leave degrees of freedom consistent with a cylindrical joint between the block and the base and a revolute joint between the block and the conrod. Next we will apply assembly constraints consistent with a revolute joint between the conrod and the crank. This will be done with a coincidence constraint between the centerlines of the protrusion on the conrod and the upper hole of the base and a surface contact constraint to position the parts along the axis of the coincidence

constraint. To begin this process, pick the **Coincidence** icon from **Constraints** toolbar. Select the axis of the cylindrical surface and the hole as shown below.




The coincidence constraint just applied removes all dof between the conrod and the crank except for rotation along the axis of coincidence and translation along that axis. To remove the unwanted translational dof, we will use a surface contact constraint (a coincidence constraint could also be applied, but we have chosen to illustrate a contact


constraint here). To create the constraint, Pick the **Contact** icon from **Constraints** toolbar and select the surfaces shown in the next page. The tree is modified to reflect this constraint.




Use **Update** icon to partially position the two parts as shown.



We need to apply one final constraint to locate the lower end of the crank onto the cylindrical protrusion on the base. Pick the **Coincidence** icon from **Constraints** toolbar. Select the axis of the cylindrical surface and the hole as shown below.




Use **Update** icon to get the final position of all parts as shown. Note that since we have chosen to create a cylindrical joint between the base and the crank, we do not need to specify a constraint to remove the translation along the axis of coincidence; that translation is effectively removed by the remainder of the assembly constraints.



The assembly is complete and we can proceed to the **Digital Mockup** workbench. As you proceed in the tutorial, keep in mind that we have created the assembly constraints with attention to the relative degrees of freedom between the parts in a manner consistent with having a cylindrical joint between the base and the crank, a revolute joint between the crank and the lower end of the conrod, a revolute joint between the upper end of the conrod and the block, and a cylindrical joint between the block and the base.

4 Creating Joints in the Digital Mockup Workbench

The **Digital Mockup** workbench is quite extensive but we will only deal with the **DMU Kinematics module**. To get there you can use the standard Windows toolbar as shown below: **Start > Digital Mockup > DMU Kinematics**.



Select the **Assembly Constraints Conversion** icon from the

DMU Kinematics toolbar . This icon allows you to create most common joints automatically from the existing assembly constraints. The pop up box below appears.



Select the **New Mechanism** button

This leads to another pop up box which allows you to name your mechanism. The default name is **Mechanism.1**. Accept the default name by pressing **OK**.

Note that the box indicates Unresolved pairs: 4/4






Select the **Auto Create** button Auto Create. Then if the **Unresolved pairs** becomes **0/4**, things are moving in the right direction.



Note that the tree becomes longer by having an **Application** Branch. The expanded tree is displayed below.



The **DOF** is 1 (if you have dof other than 1, revisit your assembly constraints to make sure they are consistent with those herein, delete your mechanism, then begin this chapter again). This remaining dof can be thought of as the position of the block along the base, or the rotation of the crank about the base. Since we want to drive the crank at constant angular speed, the latter interpretation is appropriate.

Note that because we were careful in creating our assembly constraints consistent with the desired kinematic joints, the desired joints were created based on the assembly

constraints created earlier and the **Assembly Constraints Conversion** icon




All of these joints could also be created directly using the icons in the **Kinematics Joints** toolbar




In order to animate the mechanism, you need to remove the one degree of freedom present. This will be achieved by turning **Cylindrical.2** (the joint between the base and the crank) into an **Angle driven** joint.

Note that naming the instances of parts to be the same as the part name makes it easy to identify the joint between any two parts.


Double click on **Cylindrical.2** in the tree. The pop up box below appears.



Check the **Angle driven** box. This allows you to change the limits.



Change the value of **2nd Lower Limit** to be 0.




Upon closing the above box and assuming that everything else was done correctly, the following message appears on the screen.

This indeed is good news.



According to CATIA V5 terminology, specifying **Cylindrical.2** as an **Angle driven** joint is synonymous to defining a command. This is observed by the creation of **Command.1** line in the tree.




We will now simulate the motion without regard to time based angular velocity. Select


the Simulation icon from the DMU Generic Animation toolbar


This enables you to choose the mechanism to be animated if there are several present. In this case, select **Mechanism.1** and close the window.

As soon as the window is closed, a Simulation branch is added to the tree.


DMU Generic Animation







As you scroll the bar in this toolbar from left to right, the crank begins to turn and makes a full 360 degree revolution. Notice that the zero position is simply the initial position of the assembly when the joint was created. Thus, if a particular zero position had been desired, a temporary assembly constraint could have been created earlier to locate the



mechanism to the desired zero position. This temporary constraint would need to be deleted before conversion to mechanism joints.

When the scroll bar in the **Kinematics Simulation** pop up box reaches the right extreme end, select the **Insert** button in the **Edit Simulation** pop up box shown above. This activates the video player buttons shown



Return the block to its original position by picking the **Jump to Start** button

Note that the **Change Loop Mode** button is also active now.

Upon selecting the **Play Forward** button , the crank makes fast jump completing its revolution.


In order to slow down the motion of the crank, select a different **interpolation step**, such as 0.04.

Upon changing the interpolation step to 0 0.04, return the crank to its original position by picking

the **Jump to Start** button Apply **Play**

Forward button and observe the slow and smooth rotation of the crank. It is likely that your slider will proceed beyond the end of the block; the entities involved in the joints are treated as infinite. If you wish, you may alter your block dimensions so the slider remains on the block.


DMUGeneric... 🗵




Select the Compile Simulation icon from the Generic Animation toolbar

and activate the option **Generate an animation file**. Now, pressing the **File name** button allows you to set the location and name of the animation file to be generated as displayed below.

Select a suitable path and file name and change the **Time step** to be 0.04 to produce a slow moving rotation in an AVI file.





The completed pop up box is displayed for your reference.


As the file is being generated, the crank slowly rotates. The resulting AVI file can be viewed with the Windows Media Player.



In the event that an AVI file is not needed, but one wishes to play the animation, repeatedly, a **Replay** need be generated.


Therefore, in the **Compile Simulation** box, check the **Generate a replay** button.

Note that in this case most of the previously available options are dimmed out.






A **Replay.1** branch has also been added to the tree.



Select the **Replay** icon from the **Generic Animation** toolbar Double clock on **Replay.1** in the tree and the **Replay** pop up box appears.

Experiment with the different choices of the **Change**

The **skip ratio** (which is chosen to be x1 in the right box) controls the speed of the **Replay**.



DMUGeneric

DMUPla..

Once a **Replay** is generated such as **Replay.1** in the tree above, it can also be played with a different icon.

Select the **Simulation Player** icon from the **DMUPlayer** toolbar



The outcome is the pop up box above. Use the cursor to pick **Replay.1** from the tree.




The player keys are no longer dimmed out. Use the **Play Forward (Right)** button to begin the replay.

5 Creating Laws in the Motion

You will now introduce some time based physics into the problem by specifying the crank angular velocity. The objective is to specify the angular position versus time function as a constant 1 revolution/sec (360 degrees/sec).

Click on **Simulation with Laws** icon in the **Simulation** toolbar You will get the following pop up box indication that you need to add at least a relation between a command and the time parameter.




To create the required relation, select the Formula icon from the Knowledge




The pop up box below appears on the screen.


imulati....×




Point the cursor to the **Mechanism.1, DOF=0** branch in the tree and click. The consequence is that only parameters associated with the mechanism are displayed in the **Formulas** box.

The long list is now reduced to two parameters as indicated in the box.






Select the entry **Mechanism.1\Commands\Command.1\Angle** and press the **Add Formula** button Add Formula Editor box.




Pick the **Time** entry from the middle column (i.e.. **Members of Parameters**) then double click on **Mechanism.1\KINTime** in the **Members of Time** column.




Since angle can be computed as the product of angular velocity (360deg)/(1s) in our case and time, edit the box containing the right hand side of the equality such that the formula becomes:

 $Mechanism.1 \setminus Commands \setminus Command.1 \setminus Angle = (360 \deg)/(1s)*(Mechnism.1 \setminus KINTime)$


The completed **Formula Editor** box should look as shown below.




Upon accepting **OK**, the formula is recorded in the **Formulas** pop up box as shown below.



Careful attention must be given to the units when writing formulas involving the kinematic parameters. In the event that the formula has different units at the different sides of the equality you will get **Warning** messages such as the one shown below.



We are spared the warning message because the formula has been properly inputted. Note that the introduced law has appeared in **Law** branch of the tree.




Keep in mind that our interest is to plot the position, velocity and accelerations generated by this motion. To set this up, select the **Speed and Acceleration** icon from the


DMU Kinematics


DMU Kinematics toolbar appears on the Screen.

The pop up box below




For the **Reference product**, select the **base** from the screen or the tree. For the **Point selection**, pick the vertex of the **block** as shown in the sketch below. This will set up the sensor to record the movement of the chosen point relative to the base (which is fixed).





For Reference product, pick the base

Note that the **Speed and Acceleration.1** has appeared in the tree.





Having entered the required kinematic relation and designated the vertex on the block as the point to collect data on, we will simulate the mechanism. Click on **Simulation with**

Laws icon in the Simulation toolbar.

This results in the **Kinematics Simulation** pop up box shown below.

Note that the default time duration is 10 seconds.







The scroll bar now moves up to 1s.

Check the **Activate sensors** box, at the bottom left corner. (Note: CATIA V5R15 users will also see a **Plot vectors** box in this window).

You will next have to make certain selections from the accompanying **Sensors** box.







Observing that the coordinate direction of interest is X, click on the following items to record position, velocity, and acceleration of the block:

Mechanism.1\Joints\Cylindrical.1\Length Speed-Acceleration.1\X_LinearSpeed Speed-Acceleration.1\X_LinearAcceleration


As you make selections in this window, the last column in the **Sensors** box, changes to **Yes** for the corresponding items. This is shown on the next page. Do not close the **Sensors** box after you have made your selection (leave it open to generate results).




Also, change the **Number of steps to 80**. The larger this number, the smoother the velocity and acceleration plots will be.



Note: If you haven't already done so, change the default units on position, velocity and acceleration to in, in/s and in/s², respectively. This is done in the **Tools**, **Options**, **Parameters and Measures** menu shown on the next page.





Finally, drag the scroll bar in the **Kinematics Simulation** box. As you do this, the crank rotates and the block travels along the base. Once the bar reaches its right extreme point, the crank has made one full revolution. This corresponds to 1s.




Outputs


Once the crank reaches the end, click on the **Graphics** button **Graphics**... **Options** in the **Sensor** box. The result is the plot of the position, velocity and acceleration all on the same axis (but with the vertical axis units corresponding to whichever one of the three outputs is highlighted in the right side of the window). Click on each of the three outputs to see the corresponding axis units for each output. The three plots for position (corresponding to cylindrical joint Length), velocity (X_LinearSpeed), and acceleration (X Linear Acceleration) are shown below.








It is not uncommon that you may develop a variety of simulation results before determining exactly how to achieve the desired results. In this case, prior results stored need to be erased. To do this, click on the **History** tab History of the **Sensors** box.




Use the **Clear** key to erase the values generated.




Next, we will create a plot which is not simply versus time. As an illustrative example, we will place a point somewhere along the conrod. For this point, we will plot its linear speed and linear acceleration versus crank angle. It is important to note that DMU computes positive scalars for linear speeds and linear accelerations since it simply computes the magnitude based on the three rectangular components.

First, return to **Part Design** and create a reference point on the conrod at the approximate location as shown below. Return to **DMU**.



The plan is to generate two plots. The first plot is the speed of the created point against the angular position of the crank. The second plot is the acceleration of the created point against the angular position of the crank.

In order to generate the speed and acceleration data, you need to use the **Speed and**





Click on


the icon and in the resulting pop up box make the following selections.

For **Reference product**, pick the base from the screen. For **Reference point**, pick the point that was created earlier on the conrod.

| Speed and Acce | eleration ?× |
|--------------------|-----------------------|
| Mechanism: | Mechanism.1 ▼ |
| Name: | Speed-Acceleration. 2 |
| Reference product: | base.1 |
| Point selection: | Point.1 |
| Main axis | O Other axis: |
| | OK Cancel |



The tree indicates that **Speed-Acceleration.2** is being generated which holds the data for the point on the conrod.





simulati....X

Click on **Simulation with Laws** icon in the **Simulation** toolbar This results in the **Kinematics Simulation** pop up box shown below.

Check the **Activate sensors** box, at the bottom left corner.

You will have to make the following selections from the accompanying **Sensors** box.





If you scroll down the list, you will notice that the data from **Speed-Acceleration.1** and **Speed-Acceleration.2** are both available.

Click on the **History** tab History of the **Sensors** box and make sure that no data is present. Of course the data can be cleared using the Clear button.

In the **Sensors** box, click on the following line items; be careful as many entries look alike with minor differences.

Mechanism.1\Joints\Cylindrical.2\LengthAngle Speed-Acceleration.2\LinearSpeed Speed-Acceleration.2\Linear Acceleration

Note: Depending upon your installation, you may see **Angle** instead of **LengthAngle**.

As you make these selections, the last column in the **Sensors** box, changes to **Yes** for the corresponding items. Be sure you have picked Cylindrical.2 for the angle since this is the cylindrical joint at the crank connection to the base.


Pick the **Options** button options in the Sensors box. The pop up box shown below appears. Check the **Customized** radio button.







Pick the **Add** button Add. The **Curve Creation** pop up box appears.

Use the pull down menu to make the following selections.



For Abscissa, select Mechanism.1\Joints\Cylindrical.2\LengthAngle For Ordinate, select Speed-Acceleration.2\LinearSpeed.






Press **OK** to close the box. Note that **Curve.1** is now setup.


Pick the **Add** button once again. The **Curve Creation** pop up box appears.


Use the pull down menu to make the following selections.



For Abscissa, select Mechanism.1\Joints\Cylindrical.2\LengthAngle For Ordinate, select Speed-Acceleration.2\Linear Acceleration

Press **OK** to close the box. Note that **Curve.2** is now setup.





Close the **Graphical Representation** box.

Drag the scroll bar in the Kinematics Simulation box all the way to the right or simply click on



Outputs

Once the crank reaches the end, click on **Graphics** button **Graphics** ... **Options** in the **Sensor** box. The **Multiplot** window appears and allows you to pick either **Curve.1**, or **Curve.2**.

The plots for **Curve.1** and **Curve.2** are shown on the next page.

