Table of Contents

Preface	
Acknow	ledgments

Chapter 1		
Introduction	- Getting	Started

Introduction	1-2
Development of Computer Geometric Modeling	1-2
Feature-Based Parametric Modeling	1-6
Getting Started with NX	1-7
The NX Main Window	1-8
NX Screen Layout	1-10
Quick Access Toolbar	1-11
Ribbon Bar	1-11
Style Toolbar	1-11
Additional Tools	1-11
Selection Toolbar	1-12
Message and Status Bar	1-12
Part Navigator	1-12
Resource Bars	1-12
Mouse Buttons	1-13
[Esc] - Canceling commands	1-14
On-Line Help	1-14
Leaving NX	1-14
Creating a CAD files folder	1-15

Chapter 2 **Parametric Modeling Fundamentals**

Introduction	2-2
The Adjuster design	2-3
Step 1: Starting NX and Units setup	2-3
NX Application Screen Layout	2-5
Step 2: Determine/Set Up the First Solid Feature	2-6
Work Plane – It is an XY CRT, but an XYZ World	2-7
Creating Rough Sketches	2-9
Sketch Settings	2-10
Step 3: Creating a Rough 2D Sketch	2-11
Geometric Constraint Symbols	2-12
Step 4: Apply/Modify Constraints and Dimensions	2-13
Quick View Functions	2-18
Dynamic Viewing Functions	2-18

Step 5: Completing the Base Solid Feature Display Orientations Dynamic Viewing – Icons, Mouse buttons and Quick keys Display Modes Step 6-1: Adding an Extruded Feature Step 6-2: Adding a Cut Feature Step 6-3: Adding another Cut Feature Save the Model and Exit NX Review Questions Exercises	2-19 2-20 2-21 2-23 2-24 2-28 2-31 2-35 2-36 2-37
Chapter 3 Constructive Solid Geometry Concepts	
Introduction Binary Tree The Locator Design Modeling Strategy - CSG Binary Tree Starting NX Base Feature Sketch Settings Use the Rectangle Command Completing the Base Solid Feature Creating the Next Solid Feature Creating a CUT Feature Creating a PLACED FEATURE Creating a Rectangular Cut Feature Review Questions Exercises	3-2 3-3 3-4 3-5 3-6 3-7 3-9 3-10 3-11 3-12 3-15 3-18 3-21 3-24 3-25
Chapter 4 Model History Tree	
The BORN Technique Model History Tree The Saddle Bracket Design Starting NX Modeling Strategy Apply the BORN Technique The NX Part Navigator Create the Second Solid Feature Use More Meaningful Feature Names Adjust the Width of the Base Feature Add a Placed Feature Create a Rectangular Cut Feature	4-2 4-3 4-4 4-4 4-5 4-7 4-12 4-13 4-16 4-17 4-20 4-22

	Parametric Modeling with NX
History-based Part Modifications A Design Change Assign and calculate the associated Physical Properties Review Questions Exercises	4-26 4-27 4-29 4-33 4-34
Chapter 5 Parametric Constraints Fundamentals	
CONSTRAINTS and RELATIONS Starting NX Display Existing Constraints Apply Geometric Constraints Implicitly Apply Geometric Constraints Explicitly Add Dimensional Constraints A Fully Constrained Sketch Over-Constraining 2D Sketches Delete Existing Constraints and Dimensions 2D Sketches with Multiple Loops Inferred Constraint Settings Parametric Relations Dimensional Values and Dimensional Variables Review Questions Exercises	5-2 5-3 5-6 5-8 5-9 5-11 5-13 5-15 5-17 5-20 5-22 5-23 5-24 5-27 5-28
Chapter 6 Geometric Construction Tools	
Introduction The Gasket Design Modeling Strategy Starting NX Create the Sketch of the Base Feature Edit the Sketch by Dragging the Entities Add Additional Constraints First Construction Method – Trim/Extend Create Fillets and Completing the Sketch Complete the Extrusion Feature Second Construction Method – Haystack Geometry Use the NX Selection Intent Option Create an Associative OFFSET Cut Feature Review Questions	6-2 6-2 6-3 6-4 6-5 6-7 6-9 6-10 6-13 6-14 6-15 6-20 6-22
Exercises	6-26

iii

Chapter 7 Parent/Child Relationships

Introduction	7-2
The U-Bracket Design	7-3
Create the Base Feature	7-4
Complete the Base Feature	7-6
The Implied Parent/Child Relationships	7-7
Create the Second Solid Feature	7-8
Fully Constraining the Sketch	7-10
Complete the Extrude Feature	7-12
Creating a Subtract Feature	7-13
Another Subtract Feature	7-14
Examine the Parent/Child Relationships	7-15
A Design Change	7-16
Feature Suppression	7-17
A Different Approach to the CENTER DRILL Feature	7-19
Examine the Parent/Child Relationships	7-20
Suppress the Rect Cut Feature	7-21
Create a Hole Feature	7-22
A Flexible Design Approach	7-24
Review Questions	7-25
Exercises	7-26
Chapter 8	
Part Drawings and Associative Functionality	
Drawings from Parts and Associative Functionality	8-2
Starting NX	8-3
Drawing Mode - 2D Paper Space	8-3
NX Drafting Mode	8-4
Add a Base View	8-5
Drawing Display Option	8-7
Change the Size of the Drawing Sheet	8-7
Turn Off the Datum Coordinate System	8-9
Text Orientation Setup	8-10
Display Feature Dimensions	8-11
Adjust the Display of Tangency Edges	8-15
Hide Feature Dimensions	8-16
Unhide the Hidden Dimensions	8-17
Delete Feature Dimensions	8-18
Add Center Marks	8-19
Add Additional Dimensions – Reference Dimensions	8-19
Change the Dimension Appearance	8-21
Associative Functionality – Modifying Feature Dimensions	8-22

	Parametric Modeling with NX
Review Questions	8-25
Exercises	8-26
Chapter 9	
Datum Features and Auxiliary Views	
Datum Features	9-2
Auxiliary Views in 2D Drawings	9-2
The Rod-Guide Design	9-2
Modeling Strategy	9-3
Start NX	9-4
Create the Base feature	9-5
Create an Angled Datum Plane	9-8
Create an Extruded Feature Using the Datum Plane	9-10
Apply Proper Constraints	9-11
Create an Offset Datum Plane	9-14
Create a Hole Feature Using the New Datum Plane	9-15
Create a Title Block Template	9-17
Use the Export File Command	9-21
Reopen the Rod Guide Design	9-22
Import the Title Block	9-23
Add a Base View	9-24
Create an Auxiliary View	9-25
Turn Off the Datum Planes and Reference Labels	9-27
Turn Off the Display Borders Option	9-28
Add another Base View	9-29
Drawing Display Option	9-30
Display Feature Dimensions	9-31
Delete and Add Dimensions	9-33
Review Questions	9-35
Exercises	9-36
Chapter 10	
Symmetrical Features in Designs	
Introduction	10-2
A Revolved Design: PULLEY	10-2
Modeling Strategy - A Revolved Design	10-3
Start NX	10-4
Create the Base Feature	10-5
Completing the Sketch and Creating the Feature	10-6
Mirroring Features	10-8
Join the Two Solid Features	10-10
Create a Pattern Leader	10-11

Circular Array Create a New Drawing in the Drafting Mode Import the Title Block Create 2D Views Add a Section View Turn Off the Datum Features Add Dimensions Adjust the Display of the Views Turn Off the Display Borders option Associative Functionality – A Design Change Review Questions Exercises	10-13 10-15 10-16 10-17 10-18 10-20 10-21 10-23 10-26 10-27 10-30 10-31
Chapter 11 Advanced 3D Construction Tools	
Introduction A Thin-Walled Design: Dryer Housing Modeling Strategy Start NX Create the Base Feature Create a Revolved Feature Create the Dryer Handle Create another Extruded Feature Create 3D Rounds and Fillets Create a Shell Feature Create a Pattern Leader Creating a Rectangular Array Create a Swept Cut Feature Define the Sweep Section Create the Swept Feature Review Questions Exercises	11-2 11-3 11-4 11-5 11-8 11-9 11-11 11-15 11-17 11-18 11-22 11-24 11-24 11-26 11-28 11-29
Chapter 12 Basic Sheet Metal Designs	
Sheet Metal Processes Sheet Metal Modeling K-Factor (Neutral Factor) The Actuator Bracket Design Start NX Sheet Metal Preferences Create the Base Feature of the Design	12-2 12-4 12-5 12-6 12-7 12-8 12-9

Create a Cut Feature with the Extrude Command	12-11
Create a Flange Feature	12-14
Confirm the Flange Location and Relief Dimensions	12-16
Modify the 2D Sketch of the Flange Feature	12-17
Create a Bend Feature	12-19
Create Mirrored Features	12-22
Create a 2D Sheet Metal Drawing	12-24
Import the Title Block	12-25
Creating 2D Views	12-26
Create the Associated Flat Pattern	12-27
Confirm the Flattened Length	12-30
Add an Isometric View	12-31
Setup Dimensions Preferences	12-33
Review Questions	12-35
Exercises	12-36
Chapter 13	
Assembly Modeling - Putting It All Together	
Introduction	13-2
The Shaft Support Assembly	13-2
Assembly Modeling Methodology	13-3
Additional Parts	13-4
(1) Collar	13-4
(2) Bearing	13-4
(3) Base-Plate	13-5
(4) Cap-Screw	13-5
Start NX	13-6
Loading and Placing the First Component	13-7
Placing the Second Component	13-8
Degrees of Freedom and Assembly Constraints	13-9
Apply the First Assembly Constraint	13-13
Apply another Align Constraint	13-14
Constrained Move	13-15
Apply another Assembly Constraint	13-17
Placing the Third Component	13-19
Quick Editing of Applied Constraints	13-22
Assemble the First Cap-Screw	13-23
Placing the Second Cap-Screw Part	13-26
Exploded View of the Assembly	13-27
Switch between the Exploded/Unexploded Views	13-30
Edit the Components	13-31
Setup a Drawing of the Assembly Model	13-34
Importing the Title Block	13-34
Create a Parts List	13-36

Parametric Modeling with NX

Complete the Assembly Drawing	13-36
Conclusion	13-38
Summary of Modeling Considerations	13-38
Review Questions	13-39
Exercises	13-40

Appendix A

Index

viii