CSMP TICILION Marerial

# SolidWorks 2015 Part II - Advanced Techniques

Parts, Surfaces, Sheet Metal, SimulationXpress, Top-Down Assemblies, Core and Cavity Molds



Paul Tran CSWE, CSWI

## Visit the following websites to learn more about this book:



# Table of Contents

Copyrights Notices Disclaimer Trademarks

Introduction: S	SolidWorks 2015 User Interface	XXV
	The 3 references planes	XXVI
4.1 4 - 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	The toolbars	XXVI
	The system feedback symbols	XXVIII
The state of the s	The status bar	XXVIII
	2D sketch examples	XXIX
	3D feature examples	XXX
1		

### **Advanced Modeling Topics**

Chapter 1: Int	roduction to 3D Sketch	1-1
	Tools Needed	1-2
	Adding 3D lines	1-3
	Using the reference axis indicator	1-3
	Using the tab key	1-4
	Completing the profile	1-4
	Adding dimensions	1-5
	Adding the sketch fillets	1-6
	Sketching the Sweep profile	1-7
	Creating the swept feature	1-8
	Questions for Review	1-9
	Exercise: Sweep with 3D Sketch	1-10
	Exercise: 3D Sketch & Planes	1-11
	Exercise: 3D Sketch & Composite Curve	1-18
Chapter 2: Pla	ne Creation	2-1
-	Tools Needed	2-2
	Sketching the base profile	2-3
	Creating a tangent plane	2-4

		Creating a flat surface Extruding with flip side to cut Creating an at-angle plane Showing the sketches Creating a coincident plane Creating a parallel plane Creating the recess Creating an offset-distance plane Creating the bore holes Creating a perpendicular plane Creating the side-grips Creating a circular pattern Creating a Mid-Plane Adding fillets to all edges Questions for Review Viewing the sections Exercise: Create new work planes	2-5 2-6 2-7 2-8 2-9 2-10 2-11 2-12 2-13 2-14 2-15 2-17 2-19 2-20 2-21 2-22
C	Chapter 3: Adv	vanced Modeling – 5/8" Spanner	3-1
		Tools needed	3-2
		Opening the part document	3-3
		Using min / max arc conditions	3-3
		Creating the transition sketch	3-4
		Creating a new work plane	3-6
		Creating the closed-end sketch	3-7
	No. Co.	Extruding the closed-end feature	3-7
		Adding a 12-sided polygon hole	3-8
	0	Creating the recess profile	3-9
		Mirroring the recessed feature	3-10
		Adding fillets	3-11
		Adding text	3-13
		Extruding the text	3-14
		Questions for Review	3-17
		Exercise: Circular text wraps	3-19
_	Nh and a di C		4 4
C	napter 4: Sw	eep with Composite Curves – Helical Ext. Spring	4-1
		Tools needed	4-2
		Creating the sweep path	4-3
		Defining the helix	4-3
		Creating a plane at angle	4-4
		Adding other hook features	4-5
		Creating a parallel plane	4-6

and the second	Combining sketches using Composite Curve	4-8
	Sketching the Sweep profile	4-9
	Creating the base sweep	4-9
	Other spring examples	4-10
	Questions for Review	4-14
	Exercise: Circular Spring – Expanded	4-15
	Using Variable Pitch	4-18
	Tools Needed	4-19
	Creating the base sketch	4-20
	Creating a helix using variable pitch	4-20
9	Sketching the sweep profile	4-21
: \	Adding a pierce relation	4-21
	Sweeping the profile along the path	4-22
	Creating the flat ends	4-23
	Extruding a cut	4-23
	Questions for Review	4-24
	Exercise: Projected Curve & Composite Curve	4-25
Chapter 5: Ac	Ivanced Modeling with Sweep & Loft	5-1
	Tools Needed	5-2
	Understanding the draft options	5-3
	Opening the base	5-4
	Sketching the upper inlet port - revolve	5-5
	Adding constant fillets	5-6
. 0	Creating offset-distance planes	5-7
	Creating the outlet port - loft	5-10
	Creating the mounting bosses	5-11
	Sketching the rear inlet port	5-12
	Revolving the rear inlet port	5-12
	Adding face Fillets	5-13
	Mirroring features	5-15
	Shelling the part	5-16
	Adding the ribs	5-17
	Mirroring the ribs	5-18
	Removing the sharp edges	5-19
Chapter 6: Lo	ft vs. Sweep – Water Meter Housing	6-1
	Tools Needed	6-2
	Constructing the body	6-3
9	Creating an offset distance plane	6-5
	Constructing loft profiles / features	6-5

	Constructing the Inlet / outlet profiles	6-6
	Using split entities	6-6
	Constructing the centerline parameter	6-10
	Creating the solid loft feature	6-11
	Using the shell command	6-13
	Adding the left / right brackets	6-14
	Adding a seal-ring	6-15
	Adding fillets / chamfers	6-17
	Questions for Review	6-19
	Exercise: Loft	6-20
Chapter 7: Lo	ft with Guide Curves – Waved Washer	7-1
•	Tools Needed	7-2
	Adding the construction geometries	7-3
	Creating an offset distance plane	7-4
L	Creating a derived sketch	7-5
	Creating a curve through reference points	7-5
	Constructing the loft sections	7-7
	Creating the derived sketches	7-7
	Creating the loft feature	7-10
$\sim \sim \sim \sim \sim$	Showing / hiding sketches	7-11
	Questions for Review	7-12
	Exercise: V-Shape – 3 revolutions	7-13
MO O O	Advanced Sweep - Wire Form	7-21
	Tools Needed	7-22
	Creating a helix	7-23
0000111600	Creating the sweep profile	7-24
	Creating a solid sweep	7-25
	Creating a circular Sketch pattern	7-27
13322775531	Creating a derived sketch	7-29
AHIH HELD	Creating a 3D sketch	7-30
00011999	Creating the wire form sweep	7-35
	Exercise: Using Curve Through Reference Points	7-37
Chapter 8: Us	ing Surfaces – Advanced Modeling	8-1
0ap.10. 0. 00	Tools Needed	8-2
	Creating offset distance plane	8-3
	Constructing the loft profiles	8-3
	Creating a surface-loft	8-6
	Setting the start/end constraints	8-6
	Splitting the surface	8-7
	~P	0 /

	Deleting surfaces	8-8
	Thickening the surface	8-9
	Calculating the angle between the faces	8-10
	Adding a full round fillet	8-12
	Sketching / extruding the slot contours	8-14
	Questions for Review	8-17
	Lofted Surface - Remote Control Casing	8-19
	Creating offset distance planes	8-19
	Sketching the loft sections	8-20
	Twisting the loft profiles	8-21
	Creating the loft surface	8-22
	Adding revolved surface	8-23
	Copying / moving surfaces	8-24
	Trimming surfaces	8-25
	Hiding surfaces	8-25
	Filling surfaces	8-26
	Knitting surfaces	8-30
4	Adding fillets	8-31
0	Thickening surfaces	8-32
	Removing the upper half	8-33
	Creating the lower half	8-34
	Questions for Review	8-37
	Exercise: Loft & Delete Face	8-38
Chapter 9: Adv	anced Surfaces-Offset Surface & Ruled Surface	9-1
	Tools Needed	9-2
	Using offset surface and ruled surface	9-3
	Creating the base loft	9-4
	Using the splitting lines	9-5
	Using offset surfaces	9-6
	Using ruled surface	9-7
	Using knit surfaces	9-8
	Creating a cut with surface	9-10
	Exercise: Advanced Surfaces	9-13
	Exercise: Advanced Surfacing Techniques	9-15
	Using the Deform Feature	9-25
- C	Creating a curve-to-curve deform	9-25
9/1	Setting the anchor faces	9-26
	Setting the stiffness	9-26
	Setting the stiffness Deforming a surface	9-26 9-27

9-27 9-28 9-28
10-1 10-2 10-3 10-4 10-4 10-6 10-7 10-7
10-11 10-14 10-16 10-18 10-19
10-21 10-22 10-23 10-24 10-24 10-25 10-27 10-27
11-1 11-2 11-3 11-4 11-4 11-5 11-6 11-7 11-7

	Creating the Cut-out slot with draft Creating a sweep cut Adding fillets Exercise: Advanced Loft – Turbine Blades Exercise: Advanced Sweep – Candle Holder	11-11 11-13 11-13 11-15 11-16
	Using PhotoView 360 Activating the Add-Ins Setting the appearance Setting the scene Setting the floor distance Setting the illumination Adjusting the render quality Setting the image file type Saving the final image Level 3: Final Exam	11-23 11-24 11-25 11-26 11-26 11-27 11-27 11-28 11-29
Chapter 12: S	imulationXpress – 5/8" Spanner  Tools Needed Starting SimulationXpress Setting up the units Adding a fixture Applying a force Selecting material Analyzing the model Viewing the Results Stress distribution Displacement distribution Factor of Safety (FOS) HTML report Viewing the report eDrawings Questions for Review Exercise: SimulationXpress: Force	12-1 12-2 12-3 12-4 12-5 12-7 12-8 12-9 12-10 12-11 12-11 12-11 12-12 12-13 12-17 12-20 12-21
	Exercise: SimulationXpress: Pressure  Sheet Metal Topics	12-22
Chapter 13: S	Tools Needed Creating the Base Sketch Extruding the Base Flange	13-1 13-2 13-3 13-3

	Creating an Edge Flange Editing the Edge Flange	13-4 13-5
	Setting the Auto-Relief	13-6
	Creating a Sketch Bend	13-7
	Adding Holes in Sheet Metal Parts	13-11
	Making the Flat Pattern	13-12
	Using the Sheet Metal Costing application	13-13
	Inputting the Costing information	13-14
	Setting the Baseline	13-15
	Questions for Review	13-17
	Sheet Metal Parts - Vents	13-18
1	Tools Needed	13-19
< · · / ·	Creating the Base Sketch	13-21
	Extruding the Base-Flange	13-21
	Creating the Miter-Flange	13-22
	Flattening the Part	13-24
	Creating a Forming Tool	13-25
	The Rectangle Options	13-25
	Revolve the Form Body	13-28
	The Position Sketch	13-31
	Saving the Forming Tool	13-33
	Applying the Forming Tools onto Sheet Metal Part	13-34
	Position the Form Tool	13-35
	Adding other Sheet Metal Features	13-36
	Creating a Linear Pattern of the Forming Tools	13-37
	Creating an Axis	13-38
	Creating a Circular Pattern	13-39
	Questions for Review	13-40
Chapter 14: Sh	neet Metal Forming Tools – Button with Slots	14-1
	Tools Needed	14-2
	Sketching the Base	14-3
	Revolving the Body	14-4
	Adding Slots	14-5
	Creating the Split Lines	14-7
	Defining the Stopping & Removing Faces	14-9
	Saving in the Design Library Questions for Review	14-10 14-12
	Designing Sheet Metal Parts – Mounting Tray	14-13
	Tools Needed	14-14

	Creating the Base Flange	14-15
	Creating an Edge Flange	14-16
	Adding Sheet Metal Cuts	14-17
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Unfolding a Sheet Metal Part	14-18
	Folding the Sheet Metal Part	14-20
	Accessing the Design Library	14-23
	Adding the Bridge Lance	14-24
	Creating a Linear Pattern	14-26
	Mirroring the Body	14-27
22 - 3	Sheet Metal Chamfers	14-30
S -17	Switching to the Flat Pattern	14-31
5	Questions for Review	14-32
Chapter 15: S	heet Metal Conversions	15-1
•	Tools Needed	15-2
	Opening an IGES Document	15-3
	Using the Rip Command	15-4
A	Inserting the Sheet Metal Parameters	15-5
	Adding Fillets	15-6
	Creating a Flat Pattern	15-7
Control of the Contro	Questions for Review	15-8
	Sheet Metal Gussets	15-9
	Opening a sheet metal document	15-9
	Creating a new gusset	15-10
	Applying the parameters	15-11
	Mirroring the gusset	15-12
	Flat Pattern Stent	15-13
1	Tools Needed	15-14
2	Revolving the Main Body	15-15
	Converting to Sheet Metal	15-16
•	Unfolding the Sheet Metal Part	15-16
	Sketching the 2D Pattern	15-17
	Creating the 2D Linear Pattern	15-18
	Folding the Sheet Metal Part	15-19
	Creating a Configuration	15-20
XXXXXX	Adding Fillets	15-20
	Switching to Flatten Mode	15-21
	Stent Sample - Sheet Metal Approach	15-23

	Shelling the Solid Body	15-24
	Creating an Offset Plane	15-25
	Creating a Rib Feature	15-25
	Patterning the Rib Feature	15-26
	Creating a Second Rib	15-27
	Patterning the Second Rib	15-27
	Using Combine Common	15-28
	Making an assembly from the part	15-28
	Creating a Circular Component pattern	15-29
Chapter 16: W	orking with Sheet Metal STEP Files	16-1
	Tools Needed	16-2
	Opening an Assembly Step File	16-3
	Mating the components	16-4
1	Adding the Sheet Metal tool tab	16-7
	Inserting Sheet Metal parameters	16-8
	Viewing the Flat Pattern	16-9
0	Converting other components	16-9
	Using the Hole Series	16-11
	Using the Hole Wizard	16-13
	Adding the Smart Fasteners	16-15
	Creating an Exploded View	16-17
	Adding Parts to the Toolbox Library	16-18
	Starting the Toolbox Settings Utility	16-18
	Setting the Standards	16-20
	Adding a new part	16-20
	Activating Toolbox	16-21
	Using the Taskpane	16-21
•	Locating the new part	16-22
	Viewing the new part	16-22
	Adding a Part Number and Description	16-23
	Weldments - Structural Members	16-24
	Opening a Weldments Frame Document	16-24
	Enabling the Weldment Toolbar	16-24
	Adding Structural Members	16-25
	Setting the Corner Treatments	16-25
	Adding Structural Members to Contiguous Groups	16-26
	Adding Structural Members to the Parallel Groups	16-27
	Trimming the Structural Members	16-29
	Adding the foot pads	16-36

16-37

16-39

16-41

Adding the Gussets

Adding the Fillet Beads

Viewing the Weldment Cut List

	Updating the Cut List	16-42
	Creating a drawing	16-43
	Inserting the cut list	16-43
	Inserting the balloons	16-43
	<b>Top-Down Assembly Topics</b>	
Chapter 17:	Core & Cavity – Linear Parting Lines	17-1
	Tools Needed	17-2
	Opening an existing Parasolid document	17-3
	Creating the Parting Lines	17-4
THE STATE OF THE PARTY OF THE P	Adding the Shut-Off Surfaces	17-5
	Creating Parting Surfaces	17-6
	Sketching the profile of the mold block	17-7
	Using Tooling Split	17-8
o Mille Str	Saving the Parts	17-10
	Separating the 2 blocks	17-11
	Questions for Review	17-13
	<b>Mold-Tooling Non Linear Parting Lines</b>	17-14
	Tools Needed	17-15
	Opening an existing Parasolid document	17-16
	Creating the Non-Planar Parting Lines	17-17
	Adding the Shut-Off Surfaces	17-18
	Adding the Parting Surfaces	17-19
	Creating the Ruled Surfaces	17-20
	Adding the surfaces patches	17-22
	Knitting all surfaces	17-26
	Trimming surfaces	17-28 17-29
	Creating the rolling Split	17-29
	Separating the solid bodies  Making the transparent bodies	17-31
	Making the transparent bodies	17-32
Chapter 18:	Top-Down Assembly: Miniature Vise	18-1
	Tools Needed	18-2
	Creating the Base part	18-3
	Adding side flanges	18-5
	Creating an offsetting distance plane	18-7

	Creating Loft Profiles and Guide Curves	18-8
	Creating a Loft with Guide Curves	18-11
	Creating a new part in an assembly	18-14
	Understanding the Inplace mates	18-15
	Offsetting existing geometry	18-15
	Creating a Loft with Guide Curve	18-20
	Using loft with guide curve in an assembly	18-22
	Extruding with Up-to-Surface option	18-24
	Creating Internal threads	18-26
	Creating a Section View	18-29
	Adding the sub-components	18-30
	Questions for Review	18-32
Chapter 19: To	op-Down Assembly – Water Control Valve	19-1
	Tools Needed	19-2
	Starting a New Assembly Template	19-3
	Changing the Units to IPS	19-3
	Creating the 1st Component	19-4
	Revolving the Base	19-5
	Adding a Flange	19-5
	Adding Mounting Holes	19-6
	Adding Chamfers and Fillets	19-8
	Saving as Virtual Component	19-10
	Creating the 2nd Component	19-10
	Extruding the Boss	19-12
	Adding the Transition Body	19-12
	Adding a Flange	19-13
	Adding other Features	19-14
	Exiting the Edit Part Mode	19-20
	Applying dimension changes	19-20
	Viewing the External References	19-22
	Inserting other components	19-23
	Mating the components	19-24
	Creating an assembly exploded view	19-24
	Questions for Review	19-25
	Exercise: Top Down Assembly: Using Lip & Groove	19-27
	Exercise: Top Down Assembly: Using Mounting Boss	19-31
Chapter 20: E	xternal References & Repair Errors	20-1
	External Reference Symbols	20-2
	Removing External References	20-3
	Understanding External Reference Symbols	20-4

	Repairing Sketch level	20-5
(0)	Repairing / replacing relations and dimensions	20-6
	Questions for Review	20-8
	Exercise: Repair Errors and External References	20-9
	What's wrong dialog box	20-10
	Using Display / Delete Relation	20-11
	Adding new dimensions	20-13
	Repair Errors and External References	20-17
	Level 4: Final Exam	20-25
Chapter 21: Using Appearances		
onapter 21. o.	Modeling diamond knurls	<b>21-1</b> 21-1
	Applying the knurl appearance	21-5
	Applying the wire mesh appearance	21-8
	Flatten surfaces	21-11
CSWP Core Pre	eparation Practice	
	Preparation Materials for the CSWP-Core Examination	22-1
	Part Modeling & Modifications	22-2
	Part Configurations & Design Tables	22-22
Mal.	Part Modifications	22-28
	Bottom Up assembly	22-37

#### Glossary

#### Index

#### **SolidWorks 2015 Quick-Guides:**

Quick Reference Guide to SolidWorks 2015 Command Icons and Toolbars.

