
Parametric Modeling with NX 12



Visit the following websites to learn more about this book:



amazon.com





Table of Contents

Preface	
Acknowle	dgments

Chapter 1 **Introduction - Getting Started**

Introduction	1-2
Development of Computer Geometric Modeling	1-2
Feature-Based Parametric Modeling	1-6
Getting Started with NX	1-7
The NX Main Window	1-8
NX Screen Layout	1-10
Quick Access Toolbar	1-11
Ribbon Bar	1-11
Zoom Toolbar	1-11
Additional Tools	1-11
Selection Toolbar	1-12
Message and Status Bar	1-12
Part Navigator	1-12
Resource Bars	1-12
Mouse Buttons	1-13
[Esc] - Canceling commands	1-14
On-Line Help	1-14
Leaving NX	1-14
Creating a CAD files folder	1-15

Chapter 2 Parametric Modeling Fundamentals

Introduction	2-2
The Adjuster design	2-3
Step 1: Starting NX and Units setup	2-3
NX Application Screen Layout	2-5
Step 2: Determine/Set Up the First Solid Feature	2-6
Work Plane – It is an XY CRT, but an XYZ World	2-7
Creating Rough Sketches	2-9
Sketch Settings	2-10
Step 3: Creating a Rough 2D Sketch	2-11
Geometric Constraint Symbols	2-12
Step 4: Apply/Modify Constraints and Dimensions	2-13
Quick View Functions	2-18
Dynamic Viewing Functions	2-18

Step 5: Completing the Base Solid Feature Display Orientations Dynamic Viewing – Icons, Mouse buttons and Quick keys Display Modes Step 6-1: Adding an Extruded Feature Step 6-2: Adding a Cut Feature Step 6-3: Adding another Cut Feature Save the Model and Exit NX Review Questions Exercises	2-19 2-20 2-21 2-23 2-24 2-28 2-31 2-35 2-36 2-37
Chapter 3 Constructive Solid Geometry Concepts	
Introduction Binary Tree The Locator Design Modeling Strategy - CSG Binary Tree Starting NX Base Feature Sketch Settings Use the Rectangle Command Completing the Base Solid Feature Creating the Next Solid Feature Creating a CUT Feature Creating a PLACED FEATURE Creating a Rectangular Cut Feature Review Questions Exercises	3-2 3-3 3-4 3-5 3-6 3-7 3-9 3-10 3-11 3-12 3-15 3-18 3-21 3-24 3-25
Chapter 4 Model History Tree	
The BORN Technique Model History Tree The Saddle Bracket Design Starting NX Modeling Strategy Apply the BORN Technique The NX Part Navigator Create the Second Solid Feature Use More Meaningful Feature Names Adjust the Width of the Base Feature Add a Placed Feature Create a Rectangular Cut Feature	4-2 4-3 4-4 4-4 4-5 4-7 4-12 4-13 4-16 4-17 4-20 4-22

	Parametric Modeling with NX
History-based Part Modifications	4-26
A Design Change	4-27
Assign and calculate the associated Physical Properties	4-29
Review Questions	4-33
Exercises	4-34
Chapter 5	
Parametric Constraints Fundamentals	
CONSTRAINTS and RELATIONS	5-2
Starting NX	5-3
Display Existing Constraints	5-6
Apply Geometric Constraints Implicitly	5-8
Apply Geometric Constraints Explicitly	5-9
Add Dimensional Constraints	5-11
A Fully Constrained Sketch	5-13
Over-Constraining 2D Sketches	5-15
Delete Existing Constraints and Dimensions	5-17
2D Sketches with Multiple Loops	5-20
Inferred Constraint Settings	5-22
Parametric Relations	5-23
Dimensional Values and Dimensional Variables	5-24
Review Questions	5-27
Exercises	5-28
Chantan C	
Chapter 6 Geometric Construction Tools	
	6.2
Introduction The Cocket Design	6-2 6-2
The Gasket Design	6-2 6-3
Modeling Strategy Starting NX	6-4
Create the Sketch of the Base Feature	6-5
Edit the Sketch by Dragging the Entities	6-7
Add Additional Constraints	6-9
First Construction Method – Trim/Extend	6-10
Create Fillets and Completing the Sketch	6-13
Complete the Extrusion Feature	6-14
Second Construction Method – Haystack Geometry	6-15
Use the NX Selection Intent Option	6-20
Create an Associative OFFSET Cut Feature	6-22
Review Questions	6-25
Exercises	6-26

Chapter 7 Parent/Child Relationships

Introduction	7-2
The U-Bracket Design	7-3
Create the Base Feature	7-4
Complete the Base Feature	7-6
The Implied Parent/Child Relationships	7-7
Create the Second Solid Feature	7-8
Fully Constraining the Sketch	7-10
Complete the Extrude Feature	7-12
Creating a Subtract Feature	7-13
Another Subtract Feature	7-14
Examine the Parent/Child Relationships	7-15
A Design Change	7-16
Feature Suppression	7-17
A Different Approach to the CENTER_DRILL Feature	7-19
Examine the Parent/Child Relationships	7-20
Suppress the Rect_Cut Feature	7-21
Create a Hole Feature	7-22
A Flexible Design Approach	7-24
Review Questions	7-25
Exercises	7-26
Chapter 8	
Part Drawings and Associative Functionality	
Drawings from Parts and Associative Functionality	8-2
Starting NX	8-3
Drawing Mode - 2D Paper Space	8-3
NX Drafting Mode	8-4
Add a Base View	8-5
Drawing Display Option	8-7
Change the Size of the Drawing Sheet	8-7
Turn Off the Datum Coordinate System	8-9
Text Orientation Setup	8-10
Display Feature Dimensions	8-11
Adjust the Display of Tangency Edges	8-16
Hide Feature Dimensions	8-17
Unhide the Hidden Dimensions	8-18
Delete Feature Dimensions	8-19
Add Center Marks	8-20
Add Additional Dimensions – Reference Dimensions	~ _ ~
rad raditional Dimensions Reference Dimensions	8-21
Change the Dimension Appearance	

	Parametric Modeling with NX	v
	0.26	
Review Questions	8-26 8-27	
Exercises	8-27	
Chapter 9		
Datum Features and Auxiliary Views		
Datum Features	9-2	
Auxiliary Views in 2D Drawings	9-2	
The Rod-Guide Design	9-2	
Modeling Strategy	9-3	
Start NX	9-4	
Create the Base feature	9-5	
Create an Angled Datum Plane	9-8	
Create an Extruded Feature Using the Datum Plane	9-10	
Apply Proper Constraints	9-11	
Create an Offset Datum Plane	9-14	
Create a Hole Feature Using the New Datum Plane	9-15	
Create a Title Block Template	9-17	
Use the Export File Command	9-21	
Reopen the Rod Guide Design	9-22	
Import the Title Block	9-23	
Add a Base View	9-24	
Create an Auxiliary View	9-25	
Turn Off the Datum Planes and Reference Labels	9-27	
Turn Off the Display Borders Option	9-28	
Add another Base View	9-29	
Drawing Display Option	9-30	
Display Feature Dimensions	9-31	
Delete and Add Dimensions	9-33	
Review Questions	9-35	
Exercises	9-36	
Chapter 10		
Introduction to 3D Printing		
What is 3D Printing	10-2	
Development of 3D Printing Technologies	10-3	
Primary types of 3D Printing processes	10-6	
Stereolithography	10-6	
Fused Deposition Modeling & Fused Filament Fab		
Laser Sintering / Laser Melting	10-8	
Primary 3D Printing Materials for FDM and FFF	10-9	
From 3D model to 3D printed Part	10-11	
Start NX	10-12	
Export the Design as an STL file	10-13	

Using the 3D Printing software to create the 3D Print Questions	10-14 10-23
Chapter 11 Symmetrical Features in Designs	
Introduction A Revolved Design: PULLEY Modeling Strategy - A Revolved Design Start NX Create the Base Feature Completing the Sketch and Creating the Feature Mirroring Features Join the Two Solid Features Create a Pattern Leader Circular Array Create a New Drawing in the Drafting Mode Import the Title Block Create 2D Views Add a Section View Turn Off the Datum Features Add Dimensions Adjust the Display of the Views Turn Off the Display Borders option Associative Functionality – A Design Change Review Questions Exercises	11-2 11-3 11-4 11-5 11-6 11-8 11-10 11-11 11-13 11-15 11-16 11-17 11-18 11-20 11-21 11-23 11-26 11-27 11-30 11-31
Chapter 12 Advanced 3D Construction Tools	
Introduction A Thin-Walled Design: Dryer Housing Modeling Strategy Start NX Create the Base Feature Create a Revolved Feature Create the Dryer Handle Create another Extruded Feature Create 3D Rounds and Fillets Create a Shell Feature Create a Pattern Leader Creating a Rectangular Array Create a Swept Cut Feature	12-2 12-2 12-3 12-4 12-5 12-8 12-9 12-11 12-15 12-17 12-18 12-22 12-24

	Parametric Modeling with NX
Define the Sweep Section Create the Swept Feature Review Questions Exercises	12-24 12-26 12-28 12-29
Chapter 13 Basic Sheet Metal Designs	
Sheet Metal Modeling K-Factor (Neutral Factor) The Actuator Bracket Design Start NX Sheet Metal Preferences Create the Base Feature of the Design Create a Cut Feature with the Extrude Command Create a Flange Feature Confirm the Flange Location Add another Extruded Feature Create a Bend Feature Create Mirrored Features Create a 2D Sheet Metal Drawing Import the Pre-Defined Title Block Create 2D Views Create the Associated Flat Pattern Add an Isometric View Confirm the Flattened Length Set up Dimensions Preferences Review Questions Exercises	13-2 13-4 13-5 13-6 13-7 13-8 13-9 13-11 13-14 13-16 13-17 13-19 13-22 13-24 13-25 13-26 13-27 13-30 13-31 13-33 13-35 13-36
Chapter 14 Assembly Modeling - Putting It All Togethe	er
Introduction The Shaft Support Assembly Assembly Modeling Methodology Additional <i>Parts</i> (1) Collar (2) Bearing (3) Base-Plate (4) Cap-Screw Start NX Loading and Placing the First Component	14-2 14-2 14-3 14-4 14-4 14-5 14-5 14-6 14-7

vii

Placing the Second Component	14-8
Degrees of Freedom and Assembly Constraints	14-10
Apply the First Assembly Constraint	14-14
Apply another Align Constraint	14-15
Constrained Move	14-16
Apply another Assembly Constraint	14-19
Placing the Third Component	14-21
Quick Editing of Applied Constraints	14-24
Assemble the First Cap-Screw	14-25
Placing the Second Cap-Screw Part	14-28
Exploded View of the Assembly	14-29
Switch between the Exploded/Unexploded Views	14-32
Edit the Components	14-33
Set up a Drawing of the Assembly Model	14-36
Importing the Title Block	14-36
Create a Parts List	14-38
Complete the Assembly Drawing	14-38
Conclusion	14-40
Summary of Modeling Considerations	14-40
Review Questions	14-41
Exercises	14-42

Appendix A

Index