# SOLIDWORKS<sup>®</sup> 2020 Advanced Techniques

Mastering Parts, Surfaces, Sheet Metal, SimulationXpress, Top Down Assemblies, Core & Cavity Molds



Paul Tran CSWE, CSWI



Better Textbooks. Lower Prices. www.SDCpublications.com

#### Visit the following websites to learn more about this book:





Googlebooks



## **Table of Contents**

Introductio	on SOLIDWORKS 2020 User Interface	XXIII
	The 3 references planes	XXIV
LVB KEMI-5 T (##1.7 ** 21 *) * KKO1,0+0+1#007 /4#	The toolbars	XXIV
	The system feedback symbols	XXVI
Tana Igrita	The status bar	XXVI
	2D sketch examples	XXVII
	3D feature examples	XXVIII

## **Advanced Modeling Topics**

Chapter 1	Introduction to 3D Sketch	1-1
-	Tools Needed	1-2
	Creating a 3D Sketch	1-3
	Completing the profile	1-4
	Adding dimensions	1-5
	Adding the sketch fillets	1-6
	Creating the swept feature	1-7
	Questions for review	1-8
	Exercise: Sweep with 3D Sketch	1-9
	Exercise: 3D Sketch & Planes	1-10
	Exercise: 3D Sketch & Composite Curve	1-17
Chapter 2	Plane Creation	2-1
-	Advanced Topics	2-1
	Tools Needed	2-2
	Revolving the base profile	2-3



Advanced Topics	2-1
Tools Needed	2-2
Revolving the base profile	2-3
Creating a tangent plane	2-4
Creating a flat surface	2-5
Extruding a cut	2-6
Creating an at-angle plane	2-7
Showing the sketches	2-8
Creating a coincident plane	2-9
Creating a parallel plane	2-10
Creating the recess	2-11
Creating an offset-distance plane	2-12
Creating the bore holes	2-12
Creating a perpendicular plane	2-13

	Creating the side-grips	2-14
	Creating a circular pattern of the grips	2-15
	Creating a Mid-Plane	2-17
	Adding fillets to all edges	2-19
	Questions for Review	2-20
	Exercise: Create New Planes	2-22
Chapter 3	Advanced Modeling	3-1
•	5/8" Spanner	3-1
	Tools needed	3-2
	Opening the spanner sketch document	3-3
	Creating the transition sketch	3-4
	Creating a new work plane	3-6
S	Creating the closed-end sketch	3-7
48	Extruding the closed-end feature	3-7
ABILITY SOL	Adding a 12-sided polygon hole	3-8
20 00 00 00 00 00 00 00 00 00 00 00 00 0	Creating the recess profile	3-9
	Mirroring the recessed feature	3-10
	Adding fillets	3-11
	Adding text	3-13
	Extruding the text	3-14
	Questions for Review	3-17
	Exercise: Circular text wraps	3-19
Chapter 4	Sweep with Composite Curves	4-1
	Helical Extension Spring	4-2
	Tools needed	4-2
1	Converting the circle into a helix	4-3
	Creating a 2-degree plane	4-4
	Sketching the large loop	4-5
	Sketching the large hook	4-5
	Creating a parallel plane	4-6
	Creating a Composite Curve	4-8
	Sweeping the profile along the path	4-11
	Other spring examples	4-12
	Questions for review	4-13
	Exercise: Circular Spring – 180 deg.	4-14
Omm	Using Variable Pitch	4-17
The second second	Multi-Pitch Spring with Closed Ends	4-18
	Tools Needed	4-18





Creating the base sketch	4-19
Creating a helix using variable pitch	4-19
Sweeping the profile along the path	4-21
Creating a trimmed sketch	4-22
Creating the flat ends	4-22
Extruding a cut	4-22
Questions for Review	4-23
Exercise: Projected Curve & Composite Curve	4-24

Chapter 5 Advanced Modeling with Sweep	<b>&amp; Loft</b> 5-1
Water Pump Housing	5-2
Tools Needed	5-2
Understanding the draft options	5-3
Extruding the base with draft	5-4
Sketching the upper inlet port	5-5
Revolving the upper inlet port	5-5
Adding fillets	5-6
Creating offset-distance planes	5-7
Creating a loft feature	5-10
Creating the mounting bosses	5-11
Sketching the rear inlet port	5-12
Revolving the rear inlet port	5-12
Adding face Fillets	5-13
Mirroring the rear inlet port	5-15
Shelling the part	5-16
Adding a rib	5-17
Mirroring the rib	5-18
Adding fillets	5-19


Chapter 6 Loft vs. Sweep	6-1
Water Meter Housing	6-2
Tools Needed	6-2
Sketching the loft profile	6-3
Constructing loft profiles / features	6-5
Creating the inlet feature	6-6
Constructing the Inlet / outlet profiles	6-6
Constructing the centerline parameter	6-10
Creating the outlet loft feature	6-11
Shelling the part	6-13
Extruding the left / right brackets	6-14
Constructing the upper ring	6-15



Adding fillets	6-17
Adding chamfers	6-18
Questions for Review	6-19
Exercise: Loft	6-20

Chapter 7







Loft with Guide Curves	7-1
Waved Washer	7-2
Tools Needed	7-2
Creating the construction profile	7-3
Creating an offset distance plane	7-4
Positioning the derived sketch	7-5
Creating a curve through reference points	7-5
Sketching the loft sections	7-7
Creating the loft section using derived sketch	7-7
Creating a loft with guide curve	7-10
Hiding the construction sketches	7-11
Questions for review	7-12
Exercise: Using Curve Driven Pattern	7-13
Advanced Sweep	7-19
Wire Form	7-20
Tools Needed	7-20
Creating the sweep path	7-21
Creating the sweep profile	7-22
Creating a sweep feature	7-23
Creating a circular Sketch pattern	7-25
Converting to construction geometry	7-26
Creating a derived sketch	7-27
Creating a 3D sketch	7-28
Creating the sweep feature	7-32
Exercise: Using Curve Through Reference Points	7-33

#### Chapter 8



Using Surfaces	8-1
Advanced Modeling	8-2
Tools Needed	8-2
Constructing a new work plane	8-3
Sketching the loft profiles	8-3
Creating a surface-loft	8-6
Splitting the surface	8-7
Deleting surfaces	8-8








Thickening the surface	8-9
Calculating the angle between the faces	8-10
Adding a full round fillet	8-12
Sketching the slot contours	8-13
Extruding cut the contour	8-15
Questions for Review	8-17
Lofted Surface	8-19
Creating new offset planes	8-19
Sketching the first profile	8-20
Selecting the loft profiles	8-21
Lofting between the profiles	8-22
Creating a revolved sketch	8-23
Copying the revolved surface	8-24
Trimming the base part	8-25
Hiding the surfaces	8-25
Filling the openings with surface-fill	8-26
Creating a Surface-Knit	8-29
Adding fillets	8-30
Creating a solid from the surface model	8-31
Removing the upper half	8-32
Questions for Review	8-36
Exercise: Loft & Delete Face	8-37







9-1

Chapter 10	Advanced Surfaces	10-1
	Computer Mouse	10-2
	Tools Needed	10-2



	Sketching the profiles Extruding a surface Trimming the surfaces Mirroring the surfaces Creating filled surfaces Creating a planar surface Creating a Knit surface Creating fillets	10-3 10-4 10-5 10-6 10-7 10-9 10-10 10-11
	Using Filled Surfaces Patch with Curvature Controls Tools Needed Enabling the surfaces toolbar Creating a planar surface Creating a surface fill with tangent control Creating a surface fill with curvature control Knitting all surfaces Creating a solid body Patch Types Questions for Review	<b>10-13</b> 10-13 10-14 10-15 10-16 10-16 10-18 10-19 10-19 10-20 10-22
	<b>Boundary and Freeform Surfaces</b> Creating the 1st boundary surface Creating the 2nd boundary surface Creating the Freeform feature	<b>10-23</b> 10-23 10-26 10-28
Chapter 11	Surfaces vs. Solid Modeling Safety Helmet Tools Needed Constructing the body of Helmet Creating a new work plane Sketching the sweep-profile Creating the sweep path Adding a planar surface Knitting the three surfaces bodies into one Creating a section view Adding an extruded cut feature Adding a revolve cut feature	<b>11-1</b> 11-2 11-2 11-3 11-4 11-4 11-5 11-6 11-6 11-7 11-7 11-7 11-9
	Adding the side cut features Creating the Cut-out slot Creating the sweep cut Adding fillets	11-10 11-11 11-13 11-13





XIV

	Exercise: Advanced Loft – Turbine Blades	11-15
	Exercise: Advanced Sweep – Candle Holder	11-16
	Advanced: Final Exam	11-23
Chapter 12	SimulationXpress	12-1
	Using the Analysis Wizard	12-2
P	Tools Needed	12-2
	Starting SimulationXpress	12-3
	Setting up the units	12-4
- 1800 1800 1800 1800	Adding a fixture	12-5
	Applying a force	12-7
-	Selecting the material	12-8
	Analyzing the model	12-9
	Viewing the Results	12-10
	Creating the report	12-12
7 State 00 6 Channel 6 State 00 5	Viewing the report	12-12
4 (1960) 21 (2000) 21 (2000) 21 (2000) 21 (2000) 21 (2000) 21 (2000)	Generating the eDrawings file	12-16
4 CBARH 1 Miler 10 Alfred 10 Alfred	Questions for Review	12-19
	Exercise 1: SimulationXpress: Force	12-20
	Exercise 2: SimulationXpress: Pressure	12-21

## **Sheet Metal Topics**

Chapter 13	Sheet Metal Parts	13-1
-	Post Cap	13-2
	Tools Needed	13-2
	Starting with the Base Profile	13-3
	Extruding the Base Flange	13-3
	Creating an Edge Flange	13-4
	Editing the Edge Flange Profile	13-5
· ·	Viewing the Flat Pattern	13-6
•	Changing the Fixed Face	13-6
	Creating a Sketch Bend	13-7
	Adding the Side Holes	13-11
	Making the Flat Pattern	13-12
	Using Sheet Metal Costing	13-13
	Inputting the information	13-14
	Setting the Baseline	13-15
	Questions for Review	13-17







Vents	13-18
Tools Needed	13-19
Sketching the first profile	13-20
Extruding the Base-Flange	13-21
Creating the Miter-Flanges	13-22
Flattening the Part	13-24
Creating a new Forming Tool	13-25
Other Rectangle Options	13-26
Extruding the Base	13-27
Building the louver body	13-27
Creating the Positioning Sketch	13-31
Saving the Form Tool	13-33
Applying the Form Tool	13-34
Positioning the Form Tool	13-35
Adding a mounting hole	13-36
Creating a Linear Pattern	13-37
Creating an Axis	13-38
Creating a Circular Pattern	13-39
Questions for Review	13-40







<b>Designing Sheet Metal Parts – Mounting Tray</b>	14-13
Tools Needed	14-14
Starting with the Base Sketch	14-15
Creating an Edge Flange	14-16
Adding Cut features	14-17
Extruding a cut	14-17
Using the Unfold Command	14-18
Using the Fold Command	14-20
Inserting a Sheet Metal Forming Tool	14-23
Locating the Bridge Lance	14-25

	1.
5-	11

	Creating the Linear Pattern of the Bridge Lance Mirroring the Body Adding Chamfers Switching to the Flat Pattern Questions for Review	14-26 14-27 14-30 14-31 14-32
Chapter 15	Sheet Metal Conversions From IGES to SOLIDWORKS Tools Needed Opening an IGES Document Creating the Rips Inserting the Sheet Metal Parameters Adding Fillets Switching to a Flat Pattern Questions for Review	<b>15-1</b> 15-2 15-3 15-4 15-5 15-6 15-7 15-8
	Sheet Metal Gussets Opening a sheet metal document Creating a gusset Viewing the resulted gusset Mirroring the gusset	<b>15-9</b> 15-9 15-11 15-12
	Flat Pattern Stent Tools Needed Converting to Sheet Metal Unfolding the Part Adding the Sketch Pattern Folding the Part Creating a new Configuration Adding Fillets Switching to Flatten Mode Questions for Review Exercise: Stent Sample - Sheet Metal Approach	<b>15-13</b> 15-14 15-16 15-16 15-17 15-19 15-20 15-20 15-21 15-22 15-23
Chapter 16	Working with Sheet Metal STEP Files Tools Needed Opening an Assembly Step File Mating the components Adding the Sheet Metal tool tab Inserting Sheet Metal parameters Viewing the Flat Pattern Converting other components Using the Hole Series	<b>16-1</b> 16-2 16-3 16-4 16-7 16-8 16-9 16-9 16-9 16-11



	Using the Hole Wizard	16-13
	Adding the Smart Fasteners	16-15
	Creating an Exploded View	16-17
	Adding Parts to the Toolbox Library	16-18
	Starting the Toolbox Settings Utility	16-18
	Activating Toolbox	16-21
	Locating the new part	16-22
	Viewing the new part	16-22
	Adding a Part Number and Description	16-23
Chapter 17	Advanced Weldments	17-1
-	Weldments Platform	17-2
A	Tools Needed	17-2
	Adding the weldments toolbar	17-3
	Adding the structural members	17-4
	Viewing the overlapped areas	17-8
$\mathcal{N}^{*}$	Trimming the overlapped areas	17-9
	Updating the cut list	17-12
	Using Weldments – Structural Members	17-14
	Enabling the Weldment Toolbar	17-14
	Adding Structural Members	17-15
	Setting the Corner Treatments	17-15
	Adding Structural Members to Contiguous Groups	17-16
	Adding Structural Members to the Parallel Groups	17-17
	Trimming the Structural Members	17-19
	Adding the foot pads	17-26
	Adding the Gussets	17-27
Y	Adding the Gussets Adding the Fillet Beads	17-27 17-29
Ŷ	Adding the Fillet Beads	
Y	•	17-29


## **Mold Tools Design Topics**

Chapter 18	Creating a Core and Cavity	18-1
	Linear Parting Lines	18-2
111 121	Tools Needed	18-2
	Opening an existing Parasolid document	18-3
	Creating the Parting Lines	18-4
a training	Creating the Shut-Off Surfaces	18-5



XVIII

	Creating the Parting Surfaces Sketching the profile of the mold blocks Creating the Tooling Split Saving the bodies as part files Separating the 2 blocks Exercise: Linear Parting Lines Questions for Review	18-6 18-7 18-8 18-10 18-11 18-13 18-19
Chapter 19	Non-Planar Parting Lines	19-1
-	Mold-Tooling Design	19-2
	Tools Needed	19-2
	Enabling the Mold Tools toolbar	19-3
	Creating the Parting Lines	19-4
	Creating the Shut-Off Surfaces	19-5
	Creating the Parting Surfaces	19-6
	Creating a Ruled Surface	19-7
	Creating the patches	19-9
	Knitting the surfaces	19-13
	Trimming the bottom of the ruled surface	19-15
	Creating the Tooling Split sketch	19-16
	Separating the solid bodies	19-18
	Making the body transparent	19-19
	<b>Creating Slides and Cores</b>	19-21
	Tools Needed	19-22
	Opening a part document	19-23
and the second s	Analyzing the undercuts	19-23
	Analysis parameters explained	19-24
	Scaling the part	19-25
	Creating the parting lines	19-26
	Creating the parting surfaces	19-27
	Creating a new sketch	19-28
	Creating the tooling split	19-29
	Finalizing the block sizes	19-29
	Renaming the bodies and assigning materials	19-32
	Creating the front slide core	19-32
	Creating the back slide core	19-34
	Creating an exploded view	19-35
Chapter 20	Top-Down Assembly – Part 1	20-1
•	Miniature Vise	20-2
	Tools Needed	20-2
	Creating the Base part	20-3




Adding the side flanges	20-5
Creating an offset distance plane	20-7
Creating the 3D Guide Curves	20-9
Creating the fixed jaw clamp	20-11
Creating a new component: The slide jaw	20-14
Using the offset entities command	20-15
Creating the Guide Curve to connect the two sketches	20-20
Creating the clamp block	20-22
Extruding the clamp block	20-23
Creating the Internal threads	20-26
Creating a Section View	20-29
Questions for Review	20-32





Top-Down Assembly – Part 2	21-1
Water Control Valve	21-2
Tools Needed	21-2
Starting a New Assembly Template	21-3
Creating the 1st Component	21-4
Adding the Inlet Flange	21-5
Adding the Mounting Holes	21-6
Adding Chamfers and Fillets	21-8
Saving as Virtual Component	21-10
Creating the 2nd Component	21-10
Creating the Transition Body	21-12
Adding another mounting Flange	21-13
Adding an Offset-Distance plane	21-14
Exiting the Edit Component Mode	21-20
Applying dimension changes	21-20
Viewing the External Reference Symbols	21-22
Inserting other components	21-23
Questions for Review	21-25

# Chapter 22



External References & Repair Errors	22-1
External Reference Symbols	22-2
Understanding & Removing External References	22-3
Removing External References	22-3
Understanding the External Symbols	22-4
Repairing the Sketches	22-5
Rebuilding the model	22-7
Questions for Review	22-8
Understanding and Repairing Part Errors	22-9
Repair Errors & External References	22-16

	Level 4: Final Exam	22-24
Chapter 23	Using Appearances	23-1
	Modeling diamond knurls	23-1
	Applying the knurl appearance	23-5
	Applying the wire mesh appearance	23-8
	Flatten surfaces	23-11
	Exercise: Flattening a shoe sole	23-15
Certification	Practice for the CSWP Mechanical Design Exam Challenge I: Part Modeling & Modifications Challenge II: Part Modifications & Configurations Challenge III: Bottom Up Assembly & Mates	<b>n 24-1</b> 24-2 24-27 24-48

**Glossary**, **Index, and SOLIDWORKS 2020 Quick-Guide** Quick Reference Guide to SOLIDWORKS 2020 Command Icons and Toolbars.