

The Complete Guide to **Mold Making with SOLIDWORKS® 2021**

Basic through Advanced Techniques



Paul Tran CSWE, CSWI

Visit the following websites to learn more about this book:




[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

Table of Contents

Chapter 1: Plastic Part Design		1-1
Remote Control		1-1
	Starting a new part document	1-1
	Creating the parent sketch	1-1
	Extruding the main body	1-2
	Making the upper curved cut	1-2
	Adding fillets	1-3
	Shelling the part	1-4
	Making the recess sketch	1-5
	Making the recess cut	1-6
	Copying a sketch	1-7
	Creating the mounting bosses	1-8
	Adding the support ribs	1-9
	Adding the mounting holes	1-10
	Adding the rib fillets	1-11
	Assigning material	1-12
	Changing the part color	1-13
	Calculating the mass	1-14
		Creating the core and cavity molds
Applying the scale factor		1-15
Creating the parting lines		1-15
Creating the shut-off surfaces		1-16
Creating the parting surfaces		1-17
Adding a reference plane		1-18
Inserting a tooling split		1-19
Separating the mold blocks		1-20
Hiding the references		1-21
Assigning material to the mold blocks		1-22
	Exercise – Plastic Part Design 2	1-23
	Opening a part document	1-23
	Extruding the fins	1-23
	Adding chamfers	1-24
	Adding fillets	1-24
	Applying scale	1-25
	Creating the parting line	1-25
	Adding the parting surfaces	1-26
	Sketching the mold profile	1-26
	Creating a tooling split	1-27



Trimming the mold blocks	1-27
Moving the front mold block	1-28
Moving the rear mold block	1-29
Hiding the reference surfaces	1-29
Saving your work	1-30

Chapter 2: Surface Repair 2-1





Mouse	2-1
Opening a parasolid document	2-1
Running Import Diagnostics	2-1
Examining the small surfaces	2-2
Deleting surfaces	2-3
Deleting hole	2-3
Patching the openings	2-4
Adding drafts	2-5
Creating a split line feature	2-6
Creating a face fillet	2-7
Adding thickness	2-8
Creating a recess cut	2-9

Chapter 3: Core and Cavity Creation 3-1




Plastic Tray	3-1
Opening a part document	3-1
Applying the scale factor	3-1
Creating the parting lines	3-2
Creating a parting surface	3-3
Making the mold block sketch	3-4
Creating a tooling split feature	3-5
Hiding the references	3-6
Assigning materials	3-7
Changing the transparency	3-7
Separating the mold blocks	3-8



Exercise – Creating a Core and Cavity	3-11
Plastic Knob	3-11
Opening a part document	3-11
Applying the scale	3-11
Creating the parting lines	3-12
Creating the shut-off surfaces	3-13
Creating the parting surfaces	3-14
Adding a new plane	3-15
Making the sketch of the mold block	3-15


Inserting a tooling split feature	3-16
Separating the mold blocks	3-17

Chapter 4: Planar Parting Lines 4-1




Drone's Canopy	4-1
Opening a part document	4-1
Scaling the part	4-1
Creating the parting lines	4-2
Creating the parting surfaces	4-3
Making the mold block sketch	4-4
Adding the move/copy command	4-5
Separating the mold blocks	4-6
Hiding the references	4-7
Renaming the mold blocks	4-8
Assigning the materials	4-8
Changing to transparency	4-9

Exercise - Planar Parting Lines 4-11



Drone Cover Housing	4-11
Opening a part document	4-11
Scaling the part	4-11
Creating the parting lines	4-12
Creating the parting surfaces	4-13
Adding a new plane	4-14
Making the mold block sketch	4-15
Inserting a tooling split	4-15
Changing materials	4-16




Chapter 5: Interlock Surface 5-1




Stabilizer	5-1
Opening a part document	5-1
Applying the scale factor	5-1
Creating the parting lines	5-2
Creating the parting surfaces	5-3
Making the mold block sketch	5-4
Hiding the references	5-5
Separating the mold blocks	5-6
Changing the transparency	5-7

Interlock Surface 2 5-9


Plastic Cap	5-9
Opening a part document	5-9

	Applying the scale factor	5-9
	Creating the parting lines	5-10
	Adding the shut-off surfaces	5-11
	Creating the parting surface	5-12
	Adding a new plane	5-13
	Making the mold block sketch	5-13
	Creating a tooling split feature	5-14
	Separating the mold blocks	5-15
	Hiding the references	5-16
	Renaming the solid bodies	5-17
	Assigning materials	5-17
Changing the transparency	5-18	
	Exercise - Interlock Surface 3	5-19
	Round Knob	5-19
	Opening a part document	5-19
	Applying the scale factor	5-19
	Creating the parting lines	5-20
	Creating the parting surfaces	5-21
	Adding a new plane	5-22
	Making the sketch of the mold block	5-22
	Inserting a tooling split feature	5-23
	Assigning materials	5-24
	Chapter 6: Non-Planar Parting Lines	
	Fan Cover	6-1
	Opening a part document	6-1
	Applying the scale factor	6-1
	Creating the parting lines	6-2
	Creating the shut-off surfaces	6-3
	Creating the parting surfaces	6-4
	Adding a new plane	6-4
	Making the mold block sketch	6-5
	Splitting the mold blocks	6-5
	Hiding the references	6-6
	Separating the mold blocks	6-7
Changing the transparency	6-8	
Changing the materials	6-9	
Exercise - Non-Planar Parting Lines		6-11
Meter Reader Upper Housing		6-11
Opening a part document		6-11



Applying scale	6-11
Creating the parting lines	6-12
Creating the parting surfaces	6-13
Adding the ruled surfaces	6-14
Closing off the left end	6-15
Extending the lofted surface	6-15
Trimming the left end	6-16
Closing off the right end	6-17
Extending the lofted and ruled surfaces	6-18
Trimming the right end	6-19
Knitting all surfaces	6-20
Creating the shut off surfaces	6-21
Adding a new plane	6-21
Inserting a tooling split feature	6-22
Separating the mold blocks	6-23
Changing materials	6-24


Chapter 7: Manual Parting Lines 7-1



Heat Shield	7-1
Opening a part document	7-1
Applying the scale factor	7-1
Creating the parting lines	7-2
Creating the shut-off surfaces	7-3
Creating the parting surfaces	7-4
Deleting the surfaces	7-5
Creating the ruled surfaces	7-6
Trimming with a sketch	7-7
Making a 3D sketch	7-8
Creating the first corner patch	7-9
Patching other corners	7-10
Knitting the surfaces	7-11
Creating a reference plane	7-12
Creating a tooling split	7-13
Separating the mold blocks	7-14
Hiding the references	7-15
Changing the transparency	7-16


Chapter 8: Undercuts and Slide Cores 8-1

Stress Gauge Upper Housing	8-1
Opening a part document	8-1
Applying the scale factor	8-1
Creating the parting lines	8-2



Creating the shut-off surfaces	8-3
Creating the parting surfaces	8-4
Making the mold block sketch	8-5
Analyzing the undercuts	8-6
Sketching the slide core profile	8-7
Extruding the slide core block	8-8
Separating the mold blocks	8-9
Moving the slide core block	8-10
Hiding the references	8-11
Changing the transparency	8-12

Chapter 9: Alternative Methods 9-1



Using Combine Subtract – Rocker Arm	9-1
Opening a part document	9-1
Applying the scale factor	9-1
Making the mold block sketch	9-2
Extruding the mold block	9-2
Creating a combine subtract feature	9-3
Splitting a solid body	9-4
Rotating a solid body	9-5




Using Cut with Surfaces – Rocker Arm	9-6
Opening a part document	9-6
Isolating the surface body	9-6
Making the mold block sketch	9-7
Converting to planar surface	9-8
Trimming the surfaces	9-9
Knitting the surfaces	9-10
Making the mold block sketch	9-11
Cutting with a surface	9-12
Moving a solid body	9-13



Using the Cavity Feature in Assembly – Rocker Arm	9-14
Opening an assembly document	9-14
Inserting the engineered part	9-14
Editing a component	9-15
Creating an exploded view	9-16

Chapter 10: Thickness Analysis 10-1

Medication Upper Case	10-1
Opening a part document	10-1



Setting the parameters	10-1
Analyzing the thickness	10-2
Creating a section view	10-3
Re-arranging the shell feature	10-4
Scaling the part	10-5
Creating the parting lines	10-5
Creating a parting surface	10-6
Adding a new plane	10-7
Making the mold block sketch	10-7
Extruding the mold blocks	10-8
Hiding the references	10-9
Separating the mold blocks	10-10
Changing the transparency	10-11

Chapter 11: Using the Plastics Wizard 11-1



Fill Tray	11-1
Opening a part document	11-1
Enabling SOLIDWORKS Plastics	11-1
Starting the wizard	11-2
Selecting material	11-4
Adding injection location	11-4
Running a flow analysis	11-5
Viewing the flow results	11-6
Completing the analysis	11-9

Chapter 12: Plastics Flow Analysis 12-1



Flow Simulation Analysis	12-1
Opening a part document	12-1
Enabling Plastics	12-1
Setting up the mesh	12-2
Viewing the PlasticsManager tree	12-3
Selecting a polymer	12-4
Adding an injection location	12-5
Running the flow analysis	12-6
Viewing the fill-time plot	12-7
Animating the results	12-8
Displaying the weld line	12-9
Viewing the results	12-10

Glossary

Index

SOLIDWORKS 2021 Quick-Guides:

Quick Reference Guide to SOLIDWORKS 2021 Command Icons and Toolbars.

