Parametric Modeling with SIEMENS® NX® 2212 Series





Better Textbooks. Lower Prices. www.SDCpublications.com

Visit the following websites to learn more about this book:





Googlebooks



Table of Contents

Preface Acknowledgments

Chapter 1 Introduction - Getting Started

Introduction	1-2
Development of Computer Geometric Modeling	1-2
Feature-Based Parametric Modeling	1-6
Getting Started with Siemens NX	1-7
The Siemens NX Main Window	1-8
Siemens NX Screen Layout	1-10
Quick Access Toolbar	1-11
Ribbon Bar	1-11
Zoom Toolbar	1-11
Additional Tools	1-11
Message and Status Bar	1-12
Part Navigator	1-12
Resource Bars	1-12
Mouse Buttons	1-13
[Esc] - Canceling commands	1-14
Online Help	1-14
Leaving Siemens NX	1-14
Creating a CAD Files Folder	1-15

Chapter 2 Parametric Modeling Fundamentals

Introduction	2-2
The Adjuster design	2-3
Step 1: Starting Siemens NX and Units setup	2-3
Siemens NX Application Screen Layout	2-5
Step 2: Define/Set Up the First Solid Feature	2-6
Work Plane – It is an XY CRT, but an XYZ World	2-7
Creating Rough Sketches	2-9
Step 3: Creating a Rough 2D Sketch	2-10
Geometric Constraint Symbols	2-11
Step 4: Apply/Modify Constraints and Dimensions	2-12
View Functions	2-17
Dynamic Viewing Functions	2-17
Step 5: Completing the Base Solid Feature	2-18
Display Orientations	2-19
Dynamic Viewing – Icons, Mouse buttons and Quick keys	2-20

Display Modes	2-22
Step 6-1: Adding an Extruded Feature	2-23
Step 6-2: Adding a Cut Feature	2-27
Step 6-3: Adding another Cut Feature	2-30
Save the Model and Exit Siemens NX	2-34
Review Questions	2-35
Exercises	2-36

Chapter 3 Constructive Solid Geometry Concepts

Introduction	3-2
Binary Tree	3-3
The Locator Design	3-4
Modeling Strategy - CSG Binary Tree	3-5
Starting Siemens NX	3-6
Base Feature	3-7
Use the Rectangle Command	3-9
Completing the Base Solid Feature	3-10
Creating the Next Solid Feature	3-11
Creating a Cut Feature	3-14
Creating a Placed Feature	3-17
Creating a Rectangular Cut Feature	3-19
Review Questions	3-23
Exercises	3-24

Chapter 4 Model History Tree

The BORN Technique	4-2
Model History Tree	4-3
The Saddle Bracket Design	4-4
Starting Siemens NX	4-4
Modeling Strategy	4-5
Apply the BORN Technique	4-7
The NX Part Navigator	4-12
Create the Second Solid Feature	4-13
Use More Meaningful Feature Names	4-16
Adjust the Width of the Base Feature	4-17
Add a Placed Feature	4-19
Create a Rectangular Cut Feature	4-21
History-based Part Modifications	4-25
A Design Change	4-26
Assign and Calculate the Associated Physical Properties	4-28
Review Questions	4-33

Exercises

4-34

Chapter 5 Parametric Constraints Fundamentals

Constraints and Relations	5-2
Starting Siemens NX	5-3
Display Existing Constraints	5-6
Apply Geometric Constraints Implicitly	5-7
Apply a Geometric Constraint Explicitly	5-8
Add Dimensional Constraints	5-9
A Fully Constrained Sketch – Fixed Curve	5-11
A Fully Constrained Sketch – Alignment to Sketch Origin	5-12
A Fully Constrained Sketch – Add location dimensions	5-13
Delete Existing Dimensions and Constraints	5-14
2D Sketches with Multiple Loops	5-17
Parametric Relations	5-20
Dimensional Values and Dimensional Variables	5-21
Review Questions	5-26
Exercises	5-27

Chapter 6 Geometric Construction Tools

Introduction	6-2
The Gasket Design	6-2
Modeling Strategy	6-3
Starting NX	6-4
Create the Sketch of the Base Feature	6-5
Edit the Sketch by Dragging the Entities	6-7
Add Additional Constraints	6-9
First Construction Method – Trim/Extend	6-10
Create Fillets and Completing the Sketch	6-13
Complete the Extrusion Feature	6-14
Second Construction Method – Haystacking Geometry	6-15
Use the NX Selection Intent Option	6-20
Create an Associative OFFSET Cut Feature	6-22
Review Questions	6-26
Exercises	6-27

Chapter 7 Parent/Child Relationships

Introduction	7-2
The U-Bracket Design	7-3

Create the Base Feature	7-4
Complete the Base Feature	7-6
The Implied Parent/Child Relationships	7-7
Create the Second Solid Feature	7-8
Fully Constrained 2D Sketch	7-10
Complete the Extrude Feature	7-11
Creating a Subtract Feature	7-12
Another Subtract Feature	7-13
Examine the Parent/Child Relationships	7-15
A Design Change	7-16
Feature Suppression	7-17
A Different Approach to the CENTER DRILL Feature	7-19
Examine the Parent/Child Relationships	7-20
Suppress the Rect_Cut Feature	7-21
Create a Circular Cut Feature	7-22
A Flexible Design Approach	7-23
Review Questions	7-24
Exercises	7-25

Chapter 8 Part Drawings and Associative Functionality

Drawings from Parts and Associative Functionality	8-2
Start NX	8-3
Drawing Mode - 2D Paper Space	8-3
NX Drafting Mode	8-4
Add a Base View	8-5
Drawing Display Option	8-7
Change the Size of the Drawing Sheet	8-7
Turn Off the Datum Coordinate System	8-9
Text Orientation Setup	8-10
Display Feature Dimensions	8-11
Adjust the Display of Tangency Edges	8-15
Edit the Display of Arrows on Diameter Dimensions	8-16
Hide Feature Dimensions	8-17
Unhide the Hidden Dimensions	8-18
Delete Feature Dimensions	8-19
Add Center Marks	8-20
Add Additional Dimensions – Reference Dimensions	8-21
Change the Dimension Appearance	8-22
Associative Functionality – Modifying Feature Dimensions	8-23
Review Questions	8-26
Exercises	8-27

Chapter 9 Datum Features and Auxiliary Views

Datum Features	9-2
Auxiliary Views in 2D Drawings	9-2
The Rod-Guide Design	9-2
Modeling Strategy	9-3
Start NX	9-4
Create the Base feature	9-4
Create an Angled Datum Plane	9-8
Create an Extruded Feature Using the Datum Plane	9-10
Apply Proper Constraints	9-11
Create an Offset Datum Plane	9-14
Create a Hole Feature Using the New Datum Plane	9-15
Create a Title Block Template	9-18
Use the Export File Command	9-22
Reopen the Rod Guide Design	9-23
Import the Title Block	9-24
Add a Base View	9-25
Create an Auxiliary View	9-26
Turn Off the Datum Planes and Reference Labels	9-28
Turn Off the Display Borders Option	9-29
Add another Base View	9-30
Loading the ASME Drafting Standard	9-31
Display Feature Dimensions	9-32
Delete and Add Dimensions	9-34
Review Questions	9-36
Exercises	9-37

Chapter 10 Introduction to 3D Printing

What is 3D Printing?	10-2
Development of 3D Printing Technologies	10-3
Primary types of 3D Printing processes	10-6
Stereolithography	10-6
Fused Deposition Modeling & Fused Filament Fabrication	10-7
Laser Sintering / Laser Melting	10-8
Primary 3D Printing Materials for FDM and FFF	10-9
From 3D model to 3D printed Part	10-11
Start NX	10-12
Export the Design as an STL file	10-13
Using the 3D Printing software to create the 3D Print	10-14
Questions	10-21

Chapter 11 Symmetrical Features in Designs

Introduction	11-2
A Revolved Design: PULLEY	11-2
Modeling Strategy - A Revolved Design	11-3
Start NX	11-4
Create the Base Feature	11-4
Completing the Sketch and Creating the Feature	11-6
Mirroring Features	11-8
Join the Two Solid Features	11-10
Create a Pattern Leader	11-11
Circular Array	11-13
Create a New Drawing in the Drafting Mode	11-15
Import the Predefined Title Block	11-16
Create 2D Views	11-17
Add a Section View	11-18
Turn Off the Datum Features	11-20
Add Dimensions	11-21
Adjust the Display of the Views	11-23
Turn Off the Display Borders Option	11-26
Associative Functionality – A Design Change	11-27
Additional Title Blocks	11-30
Review Questions	11-32
Exercises	11-33

Chapter 12 Advanced 3D Construction Tools

12-2
12-2
12-3
12-4
12-4
12-7
12-8
12-10
12-13
12-15
12-16
12-19
12-22
12-22
12-24
12-26
12-27

Chapter 13 Basic Sheet Metal Designs

Sheet Metal Processes	13-2
Sheet Metal Modeling	13-4
K-Factor (Neutral Factor)	13-5
The Actuator Bracket Design	13-6
Start NX	13-7
Sheet Metal Preferences	13-8
Create the Base Feature of the Design	13-9
Create a Cut Feature with the Extrude Command	13-11
Create a Flange Feature	13-14
Confirm the Flange Location	13-16
Add another Extruded Feature	13-17
Create a Bend Feature	13-19
Create Mirrored Features	13-22
Create a 2D Sheet Metal Drawing	13-24
Import the Saved Title Block	13-25
Create 2D Views	13-26
Create the Associated Flat Pattern View	13-27
Confirm the Flattened Length	13-31
Set up Dimensions Preferences	13-33
Review Questions	13-35
Exercises	13-36

Chapter 14 Assembly Modeling - Putting It All Together

Introduction	14-2
The Shaft Support Assembly	14-2
Assembly Modeling Methodology	14-3
Additional Parts	14-4
(1) Collar	14-4
(2) Bearing	14-4
(3) Base-Plate	14-5
(4) Cap-Screw	14-5
Start NX	14-6
Loading and Placing the First Component	14-7
Place the Second Component	14-9
Degrees of Freedom	14-10
Assembly Constraints	14-12
Apply the First Assembly Constraint	14-15
Apply another Align Constraint	14-16
Constrained Move	14-17
Show Degrees of Freedom	14-19
Apply another Assembly Constraint	14-20

Placing the Third Component	14-22
Apply Assembly Constraints on Datum Planes	14-25
Assemble the First Cap-Screw	14-26
Placing the Second Cap-Screw Part	14-29
Exploded View of the Assembly	14-30
Edit the Components	14-34
Set up a Drawing of the Assembly Model	14-37
Importing the Title Block	14-37
Create a Parts List	14-39
Complete the Assembly Drawing	14-39
Summary of Modeling Considerations	14-41
Review Questions	14-42
Exercises	14-43

Chapter 15 Advanced Assembly Modeling and Animation

Introduction	15-2
NX Motion Simulation	15-2
Motion Bodies	15-3
Joint Connections	15-3
The Crank-Slider Assembly	15-6
Creating the Required Parts	15-6
(1) End Cap	15-6
(2) Connecting Rod	15-7
(3) Base Block	15-8
(4) Crank Shaft	15-9
(5) Piston	15-10
Create the Crank Slider Assembly Model	15-11
Loading and Placing the First Component	15-12
Assembling the Crank Shaft	15-14
Assembling the Connecting Rod	15-16
Complete the Assembly	15-17
Start the NX Motion Simulation Module	15-19
Defining a New Simulation	15-20
Define the Motion Bodies	15-21
Define the Joint Connections	15-23
Set up a Motion Driver for the Animation	15-30
Set up an Animation Analysis	15-31
View the Animation	15-32
Output the Animation as a Video file	15-33
Conclusion	15-34
Review Questions	15-35
Exercises	15-36

Appendix A

Index