Beginner's Guide to SolidWorks 2013 - Level II

Sheet Metal, Top Down Design, Weldments, Surfacing and Molds

Alejandro Reyes MSME, CSWP, CSWI

Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents

List of commands introduced in each chapter. Note that many commands are used extensively in following chapters after they have been learned.

Multi Body Parts
Multi Body
Local Operations
Hide/Show Body
Merge
Feature Scope
Delete Body
Body Pattern
Combine Bodies
  Add
  Subtract
  Common
Bodies to keep
Offset from Surface
Sketch Picture

Contour Selection
Regions available
Contour Selection
Shared Sketch
Start From: Condition

Part Editing
What's Wrong
Parent/Child relations
Sketch Editing
Dangling Relations
Delete Absorbed
  Features
Sketch Relations
Over Defined Sketch
Not Solved Sketch
SketchXpert
View Sketch Relations

Equations
Rename Dimensions
Pattern Seed Only
Add Equations
Edit Equations
Delete Equations
Link Values

Top Down Design
New Part
Edit In Context
Assembly Transparency
Internal Part
Externalize Part
Edit Assembly
External References
  In Context
  Out of Context
  Locked
  Broken
List External References

Sheet Metal and Top Down Design
Base Flange
Sheet Metal Thickness
Bend Radius
Bend Allowance
Bend Deduction
K-Factor
Auto-Relief
  Rectangular
  Obround
  Tear
Flat Pattern
Forming Tools
Modify Sketch
Link to Thickness
Normal Cut
3D Content Central
Vent feature
Miter Flange
Unfold/Fold Bend
Edge Flange
Build Library Features
Library Parts
Mate Reference
Break Corners
Jog bend
Flat Pattern Drawing
Bend Notes

Convert to Sheet Metal
Closed Corners
Selection Filters
Sketch Pattern
Feature Driven Pattern
Hem Feature
Creating Forming Tools
Component Pattern
Collision Detection
Flexible Sub Assemblies
Assembly Features

3D Sketch
3D Sketch
3D Sketch Relations
Derived Sketch
Projected Curve

Weldments
3D Sketch review
Cut list
Weldment feature
Structural Member
Corner Treatment
  End Miter
  End Butt
Locate Profile
Rotate Profile
Trim/Extend
Gusset
End Cap
Weld Beads
Weldment Cut List
Weldment Drawings
Cut List Table
Weld Table
Weld Symbols
Save Bodies to
  Assembly
Structural Member
  Libraries

Surfacing	Mold Tools
Revolved Surface	Draft Analysis
Lofted Surface	Direction of Pull
Extruded Surface	Positive Draft
Direction of Extrusion	Negative Draft
Extrude with Draft	Draft
Trim Surface	Neutral Plane
Mutual Trim	Rollback/Roll Forward
Planar Surface	Scale
Filled Surface	Parting Line
Knit Surface	Parting Surface
Constant Width Fillet	Tooling Split
Thicken	Shut Off Surfaces
Body Split	Move/Copy body
Face Fillet	Delete Face
Extend Surface	Face Classification
Extrude From	Manual Parting Line
Mirror Bodies	Selection
Swept Surface	Select Open Loop
Twist Along Path	Rib
Sweep Cut	Side Core