Mastering Surface Modeling with SOLIDWORKS® 2020

Basic through Advanced Techniques



Lani Tran, CSWE

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

TABLE OF CONTENTS

Chapter 1: Introduction to Surfaces 1-1
Solids vs. surfaces 1-1
Patching with continuity 1-2
Contact, tangent, and curvature continuous 1-2
When to use surfaces 1-3
When not to use surfaces 1-3
The spline handles 1-4
Check your surface model frequently 1-5
The best approach 1-6

Chapter 2: Surfacing Basics 2-1
Extruded surface 2-1
Creating a curve through reference points 2-2
Creating the planar surfaces 2-3
Knitting the surfaces 2-4
Saving your work 2-4

Revolved surface 2-5
Creating a section view 2-6
Adding fillets 2-6

Swept surface 2-8
Sketching the sweep path 2-8
Creating a swept surface 2-9

Lofted surface 2-10
Sketching the 3rd profile 2-10
Creating a lofted surface 2-11

Boundary surface 2-13
Sketching the 3D splines 2-13
Creating a boundary surface 2-16

Chapter 3: Using Boundary and Lofted Surface 3-1
Starting a new part document 3-1
Creating the 1st reference plane 3-3
Sketching the 1st boundary profile 3-3
Sketching the 2nd boundary profile 3-4
Comparing methods 3-5
Creating a boundary surface 3-6

Creating the 2nd reference plane 3-7
Constructing the 1st trim sketch 3-8
Trimming the bottom 3-9
Constructing a split sketch 3-10
Creating a spilt line feature 3-11
Deleting faces 3-12
Thickening the surface model 3-13
Adding fillets 3-14
RealView graphics 3-15
Ambient occlusion 3-16

Advanced Surfaces – Surface Trim & Loft 3-17
Creating a revolved surface 3-17
Trimming with a sketch 3-18
Making a surface offset 3-18
Trimming with another sketch 3-19
Creating a lofted surface 3-20
Knitting all surfaces 3-21

Chapter 4: Surface Creation 4-1
Creating the 1st sketch 4-1
Creating the 2nd sketch 4-2
Trimming the surfaces 4-3
Mirroring a surface body 4-4
Making the loft profiles 4-5
Creating a lofted surface 4-6
Making the fill profiles 4-7
Creating two filled surfaces 4-8
Creating a planar surface 4-9
Knitting the surfaces 4-9
Adding fillets 4-10
Creating a split line feature 4-11
Creating a face fillet with hold line 4-12
Creating more fillets 4-13

Advanced Surfaces – Phone Case 4-15
Opening a part document 4-15
Creating a boundary surface 4-15
Creating the 1st lofted surface 4-16
Creating the 2nd lofted surface 4-17
Creating the 3rd lofted surface 4-18
Hiding the sketches 4-19
Knitting the surface 4-20

Chapter 5: Using Filled, Knit & Boundary Surface 5-1
Opening a part document 5-1
Creating a boundary surface 5-2
Creating a revolved surface 5-3
Creating a filled surface 5-4
Knitting the surfaces 5-5
Creating a split line feature 5-6
Changing the face color 5-7
Shelling the model 5-8
Enabling RealView graphics 5-8

Advanced Surfaces – Using Deform 5-9
Creating a lofted surface 5-9
Creating a deform feature 5-10
Trimming to the final size 5-11
Patching the bottom surface 5-12
Knitting the surfaces 5-12
Adding fillets 5-13

Chapter 6: Using Trim, Thicken & Configurations 6-1
Opening a part document 6-1
Trimming the surfaces 6-1
Mirroring a surface body 6-2
Creating a lofted surface 6-3
Patching the ends 6-4
Creating the led holes 6-5
Making the power cord opening 6-6
Knitting the surfaces 6-7
Adding fillets 6-7
Adding thickness 6-8
Creating a recess cut 6-9
Making the cover plate 6-10
Creating a cut using offset from surface 6-13
Using Configurations 6-15
Adding a new configuration 6-15
Modifying dimensions 6-16
Adding other configurations 6-17
Toggling between the configurations 6-18

Chapter 7: Curved Driven Pattern & Flex Bending 7-1
Opening a part document 7-1
Creating a 3D sweep path 7-1
Creating a swept surface 7-2
Creating a curve driven pattern 7-3

Stent designs – Exercise 1 7-5
Creating a planar surface 7-5
Creating a rolled pattern 7-6
Thickening a surface model 7-7
Stent designs – Exercise 2 7-8
Creating a split sketch 7-9
Creating a split line feature 7-10
Deleting faces 7-10
Adding thickness 7-11
Creating an axis 7-12
Creating a circular pattern 7-13
Combining the solid bodies 7-14
Stent designs – Exercise 3 7-15
Creating the base sketch 7-15
Creating a planar surface 7-16
Trimming with a sketch 7-16
Thickening the surface 7-17
Creating a flex bending feature 7-18

Chapter 8: Surfaces & Solids– Hybrid Modeling 8-1
Opening a part document 8-1
Creating the extruded surfaces 8-1
Trimming the surfaces 8-4
Adding fillets 8-5
Thickening the surface model 8-7
Adding the inner support feature 8-8
Creating an extruded cut 8-9
Adding the support ribs 8-10
Adding the mounting bosses 8-11
Adding fillets 8-12
Saving the housing right-half 8-13
Mirroring the part 8-13
Creating an extruded cut feature 8-15
Saving the left half 8-16
Adding the alignment pins 8-17
Adding chamfers 8-18
Saving the right half 8-18
Inserting a part document 8-19
Creating an exploded view 8-20

Chapter 9: Mold Tools, Intersect & Display States 9-1
Opening a part document 9-1
Sketch the base profile 9-1
Creating a revolve surface 9-2

Making the sweep path 9-2
Adding a new plane 9-3
Making the sweep profile 9-4
Creating the 1st rib 9-4
Patterning the rib 9-4
Trimming the overlaps 9-5
Adding thickness 9-6
Adding fillets 9-7
Making a mold 9-8
Assigning material 9-8
Scaling the model 9-8
Creating a parting line 9-9
Creating the shut off surfaces 9-10
Creating the parting surfaces 9-11
Creating a tooling split 9-12
Making an exploded view 9-13
Renaming the bodies 9-14
Using Intersect 9-15
Opening a part document 9-15
Inserting a part 9-15
Moving a solid body 9-16
Using the intersect options 9-17
Using Display States 9-19
Creating the 1st display state 9-19
Changing appearances 9-20
Adding other display states 9-21
Toggling between the display states 9-23
Copying & Pasting the exploded view 9-24
Making an assembly feature cut 9-24

Chapter 10: Surface Repairs and Patches 10-1
Opening a part document 10-1
Creating the lofted surfaces 10-2
Patching the raised feature 10-3
Patching the corner of the keyway 10-5
Using the filled surface command 10-6
Using the lofted surface command 10-7
Using the boundary surface command 10-8
Creating the additional curves 10-9
Creating a loft with guide curves 10-10
Removing features 10-11
Deleting holes 10-12
Removing features 10-13
Knitting the surfaces 10-14

Assigning material 10-15
Calculating the mass 10-15

Glossary

Index



Designed using SOLIDWORKS 2020, SP0