SOLIDWORKS® 2021 Advanced Techniques

Mastering Parts, Surfaces, Sheet Metal, SimulationXpress, Top Down Assemblies, Core & Cavity Molds

Paul Tran CSWE, CSWI

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents



Introduction SOLIDWORKS 2021 User Interface **XXIII**
The 3 references planes XXIV
The toolbars XXIV
The system feedback symbols XXVI
The status bar XXVI
2D sketch examples XXVII
3D feature examples XXVIII

Advanced Modeling Topics



Chapter 1 Introduction to 3D Sketch **1-1**
Tools Needed 1-2
Creating a 3D Sketch 1-3
Completing the profile 1-4
Adding dimensions 1-5
Adding the sketch fillets 1-6
Creating the swept feature 1-7
Questions for review 1-8
Exercise: Sweep with 3D Sketch 1-9
Exercise: 3D Sketch & Planes 1-10
Exercise: 3D Sketch & Composite Curve 1-17

Chapter 2 Plane Creation **2-1**
Advanced Topics 2-1
Tools Needed 2-2
Revolving the base 2-3
Creating a tangent plane 2-4
Creating a flat surface 2-5
Extruding a cut 2-6
Creating an at-angle plane 2-7
Showing the sketches 2-8
Creating a coincident plane 2-9
Creating a parallel plane 2-10
Creating the recess 2-11
Creating an offset-distance plane 2-12
Creating the bore holes 2-12
Creating a perpendicular plane 2-13

Creating the side-grips 2-14
Creating a circular pattern of the grips 2-15
Creating a Mid-Plane 2-17
Adding fillets to all edges 2-19
Questions for Review 2-20
Exercise: Create New Planes 2-22

Chapter 3 Advanced Modeling 3-1
5/8" Spanner 3-1
Tools needed 3-2
Opening the spanner sketch document 3-3
Creating the transition sketch 3-4
Creating a new work plane 3-6
Creating the closed-end sketch 3-7
Extruding the closed-end feature 3-7
Adding a 12-sided polygon hole 3-8
Creating the recess profile 3-9
Mirroring the recessed feature 3-10
Adding fillets 3-11
Adding text 3-13
Extruding the text 3-14
Questions for Review 3-17
Exercise: Circular text wraps 3-19

Chapter 4 Sweep with Composite Curves 4-1
Helical Extension Spring 4-2
Tools needed 4-2
Converting the circle into a helix 4-3
Creating a 2-degree plane 4-4
Sketching the large loop 4-5
Sketching the large hook 4-5
Creating a parallel plane 4-6
Creating a Composite Curve 4-8
Sweeping the profile along the path 4-11
Other spring examples 4-12
Questions for review 4-13
Exercise: Circular Spring – 180 deg. 4-14

Using Variable Pitch **4-17**
Multi-Pitch Spring with Closed Ends 4-18
Tools Needed 4-18

	Creating the base sketch	4-19
	Creating a helix using variable pitch	4-19
	Sweeping the profile along the path	4-21
	Creating a trimmed sketch	4-22
	Extruding a cut	4-22
	Questions for Review	4-23
	Exercise: Projected Curve & Composite Curve	4-24
Chapter 5	**Advanced Modeling with Sweep & Loft**	**5-1**
	Water Pump Housing	5-2
	Tools Needed	5-2
	Understanding the draft options	5-3
	Extruding the base with draft	5-4
	Sketching the upper inlet port	5-5
	Revolving the upper inlet port	5-5
	Adding fillets	5-6
	Creating offset-distance planes	5-7
	Creating a loft feature	5-10
	Creating the mounting bosses	5-11
	Sketching the rear inlet port	5-12
	Revolving the rear inlet port	5-12
	Adding face Fillets	5-13
	Mirroring the rear inlet port	5-15
	Shelling the part	5-16
	Adding a rib	5-17
	Mirroring the rib	5-18
	Adding fillets	5-19
Chapter 6	**Loft vs. Sweep**	**6-1**
	Water Meter Housing	6-2
	Tools Needed	6-2
	Sketching the loft profile	6-3
	Constructing loft profiles / features	6-5
	Creating the inlet feature	6-6
	Constructing the centerline parameter	6-10
	Creating the outlet loft feature	6-11
	Shelling the part	6-13
	Extruding the left / right brackets	6-14
	Constructing the upper ring	6-15
	Adding fillets	6-17
	Adding chamfers	6-18



Questions for Review 6-19
Exercise: Loft 6-20

Chapter 7 Loft with Guide Curves 7-1



Waved Washer 7-2
Tools Needed 7-2
Creating the construction profile 7-3
Creating an offset distance plane 7-4
Positioning the derived sketch 7-5
Creating a curve through reference points 7-5
Sketching the loft sections 7-7
Creating the loft section using derived sketch 7-7
Creating a loft with guide curve 7-10
Hiding the construction sketches 7-11
Questions for review 7-12
Exercise: Using Curve Driven Pattern 7-13



Advanced Sweep **7-19**
3D Sketch Path 7-20
Tools Needed 7-20
Creating the sweep path 7-21
Creating the sweep profile 7-22
Creating a sweep feature 7-23
Creating a circular Sketch pattern 7-25
Converting to construction geometry 7-26
Creating a derived sketch 7-27
Creating a 3D sketch 7-28
Creating the sweep feature 7-32
Exercise: Using Curve Through Reference Points 7-33



Chapter 8 Using Surfaces 8-1



Advanced Modeling 8-2
Tools Needed 8-2
Constructing a new work plane 8-3
Sketching the loft profiles 8-3
Creating a surface-loft 8-6
Splitting the surface 8-7
Deleting surfaces 8-8
Thickening the surface 8-9
Calculating the angle between the faces 8-10

Adding a full round fillet 8-12
Sketching the slot contours 8-13
Extruding cut the contour 8-15
Questions for Review 8-17



Lofted Surface **8-19**
Creating new offset planes 8-19
Sketch the first profile 8-20
Selecting the loft profiles 8-21
Lofting between the profiles 8-22
Creating a revolved sketch 8-23
Copying the revolved surface 8-24
Trimming the base part 8-25
Hiding the surfaces 8-25
Filling the openings with surface-fill 8-26
Creating a Surface-Knit 8-29
Adding fillets 8-30
Creating a solid from the surface model 8-31
Removing the upper half 8-32
Questions for Review 8-36
Exercise: Loft & Delete Face 8-37





Chapter 9 Offset Surface & Ruled Surface **9-1**
Tools Needed 9-2
Using offset & ruled surface options 9-3
Creating the base loft 9-4
Creating split lines 9-5
Creating offset surfaces 9-6
Creating a ruled surface 9-7
Knitting the 2 surfaces 9-8
Showing the solid body 9-10
Creating the surface cut 9-10
Exercise: Advanced Surfaces 9-13
Exercise: Advanced Surfacing Techniques 9-15

Chapter 10 Advanced Surfaces **10-1**
Computer Mouse 10-2
Tools Needed 10-2
Sketching the profiles 10-3
Extruding a surface 10-4

Trimming the surfaces 10-5
Mirroring the surfaces 10-6
Creating filled surfaces 10-7
Creating a new plane 10-9
Making a 3-Point Arc 10-9
Creating a planar surface 10-12
Creating a knit surface 10-13

Using Filled Surfaces 10-15
Patch with Curvature Controls 10-15
Tools Needed 10-16
Enabling the surfaces toolbar 10-17
Creating a planar surface 10-18
Creating a surface fill with tangent control 10-18
Creating a surface fill with curvature control 10-20
Knitting all surfaces 10-21
Patch Types 10-22
Questions for Review 10-24

Boundary and Freeform Surfaces 10-25
Creating the 1st boundary surface 10-25
Creating the 2nd boundary surface 10-28
Creating the Freeform feature 10-30

Chapter 11 Surfaces vs. Solid Modeling 11-1
Safety Helmet 11-2
Tools Needed 11-2
Constructing the body of Helmet 11-3
Creating a new work plane 11-4
Sketching the sweep-profile 11-4
Creating the sweep path 11-5
Adding a planar surface 11-6
Knitting the three surfaces bodies into one 11-6
Creating a section view 11-7
Adding an extruded cut feature 11-7
Adding a revolve cut feature 11-9
Adding the side cut features 11-10
Creating the Cutout slot 11-11
Creating the sweep cut 11-13
Adding fillets 11-13
Exercise: Advanced Loft – Turbine Blades 11-15
Exercise: Advanced Sweep – Candle Holder 11-16

Advanced: Final Exam 11-23

Chapter 12 SimulationXpress 12-1

Using the Analysis Wizard 12-2
Tools Needed 12-2
Starting SimulationXpress 12-3
Setting up the units 12-4
Adding a fixture 12-5
Applying a force 12-7
Selecting the material 12-8
Analyzing the model 12-9
Viewing the Results 12-10
Creating the report 12-12
Generating the eDrawings file 12-16
Questions for Review 12-19
Exercise 1: SimulationXpress: Force 12-20
Exercise 2: SimulationXpress: Pressure 12-21

Sheet Metal Topics

Chapter 13 Sheet Metal Parts 13-1



Post Cap 13-2
Tools Needed 13-2
Starting with the Base Profile 13-3
Extruding the Base Flange 13-3
Creating an Edge Flange 13-4
Editing the Edge Flange Profile 13-5
Viewing the Flat Pattern 13-6
Changing the Fixed Face 13-6
Creating a Sketch Bend 13-7
Adding Holes 13-9
Making the Flat Pattern 13-12
Using Sheet Metal Costing 13-13
Inputting the information 13-14
Setting the Baseline 13-15
Questions for Review 13-17



Vents 13-18
Tools Needed 13-19
Sketching the first profile 13-20





Extruding the Base-Flange 13-21
Creating the Miter-Flanges 13-22
Flattening the Part 13-24
Creating a new Forming Tool 13-25
Other Rectangle Options 13-26
Extruding the Base 13-27
Building the louver body 13-27
Creating the Positioning Sketch 13-31
Saving the Form Tool 13-33
Applying the Form Tool 13-34
Positioning the Form Tool 13-35
Adding a mounting hole 13-36
Creating a Linear Pattern 13-37
Creating an Axis 13-38
Creating a Circular Pattern 13-39
Questions for Review 13-40

Chapter 14 Sheet Metal Forming Tools 14-1
Button with Slots 14-2
Tools Needed 14-2
Creating the Base Block 14-3
Revolving the Body 14-4
Sketching Slot Profiles 14-5
Creating the Split Lines 14-7
Adding more fillets 14-9
Inserting the forming tool feature 14-9
Saving the forming tool 14-10
Questions for Review 14-12



Designing Sheet Metal Parts – Mounting Tray 14-13
Tools Needed 14-14
Starting with the Base Sketch 14-15
Creating an Edge Flange 14-16
Adding Cut features 14-17
Extruding a cut 14-17
Using the Unfold Command 14-18
Using the Fold Command 14-20
Inserting a Sheet Metal Forming Tool 14-23
Locating the Bridge Lance 14-25
Creating the Linear Pattern of the Bridge Lance 14-26
Mirroring the Body 14-27
Adding Chamfers 14-30





Switching to the Flat Pattern 14-31
Questions for Review 14-32

Chapter 15 Sheet Metal Conversions 15-1
From IGES to SOLIDWORKS 15-2

Tools Needed 15-2
Opening an IGES Document 15-3
Creating the Rips 15-4
Inserting the Sheet Metal Parameters 15-5
Adding Fillets 15-6
Switching to a Flat Pattern 15-7
Questions for Review 15-8

Sheet Metal Gussets 15-9

Opening a sheet metal document 15-9
Creating a gusset 15-9
Viewing the resulted gusset 15-11
Mirroring the gusset 15-12

Flat Pattern Stent 15-13

Tools Needed 15-14
Converting to Sheet Metal 15-16
Unfolding the Part 15-16
Adding the Sketch Pattern 15-17
Folding the Part 15-19
Creating a new Configuration 15-20
Adding Fillets 15-20
Switching to Flatten Mode 15-21
Questions for Review 15-22
Exercise: Stent Sample - Sheet Metal Approach 15-23

Chapter 16 Working with Sheet Metal STEP Files 16-1
Tools Needed 16-2

Opening an Assembly Step File 16-3
Mating the components 16-4
Adding the Sheet Metal tool tab 16-7
Inserting Sheet Metal parameters 16-8
Viewing the Flat Pattern 16-9
Converting other components 16-9
Using the Hole Series 16-11
Using the Hole Wizard 16-13
Adding the Smart Fasteners 16-15
Creating an Exploded View 16-17

Adding Parts to the Toolbox Library **16-18**
Starting the Toolbox Settings Utility 16-18
Activating Toolbox 16-21
Locating the new part 16-22
Viewing the new part 16-22
Adding a Part Number and Description 16-23

Chapter 17 Advanced Weldments **17-1**



Weldments Platform 17-2
Tools Needed 17-2
Adding the weldments toolbar 17-3
Adding the structural members 17-4
Viewing the overlapped areas 17-8
Trimming the overlapped areas 17-9
Updating the cut list 17-12



Using Weldments – Structural Members **17-14**
Enabling the Weldment Toolbar 17-14
Adding Structural Members 17-15
Setting the Corner Treatments 17-15
Adding Structural Members to Contiguous Groups 17-16
Adding Structural Members to the Parallel Groups 17-17
Trimming the Structural Members 17-19
Adding the foot pads 17-26
Adding the Gussets 17-27
Adding the Fillet Beads 17-29
Viewing the Weldment Cut List 17-31
Updating the Cut List 17-32
Creating a drawing 17-33

Mold Tools Design Topics

Chapter 18 Creating a Core and Cavity **18-1**

Linear Parting Lines 18-2
Tools Needed 18-2
Opening an existing Parasolid document 18-3
Creating the Parting Lines 18-4
Creating the Shut-Off Surfaces 18-5
Creating the Parting Surfaces 18-6
Sketching the profile of the mold blocks 18-7
Creating the Tooling Split 18-8

Saving the bodies as part files 18-10
Separating the 2 blocks 18-11
Exercise: Linear Parting Lines 18-13
Questions for Review 18-19

Chapter 19 Non-Planar Parting Lines 19-1
Mold-Tooling Design 19-2
Tools Needed 19-2
Enabling the Mold Tools toolbar 19-3
Creating the Parting Lines 19-4
Creating the Shut-Off Surfaces 19-5
Creating the Parting Surfaces 19-6
Creating a Ruled Surface 19-7
Creating the patches 19-9
Knitting the surfaces 19-13
Trimming the bottom of the ruled surface 19-15
Creating the Tooling Split sketch 19-16
Separating the solid bodies 19-18
Making the body transparent 19-19

Creating Slides and Cores 19-21
Tools Needed 19-22
Opening a part document 19-23
Analyzing the undercuts 19-23
Analysis parameters explained 19-24
Scaling the part 19-25
Creating the parting lines 19-26
Creating the parting surfaces 19-27
Creating a new sketch 19-28
Creating the tooling split 19-29
Finalizing the block sizes 19-29
Renaming the bodies and assigning materials 19-32
Creating the front slide core 19-32
Creating the back slide core 19-34
Creating an exploded view 19-35

Chapter 20 Top Down Assembly – Part 1 20-1
Miniature Vise 20-2
Tools Needed 20-2
Creating the Base part 20-3
Adding the side flanges 20-5
Creating an offset distance plane 20-7
Creating the 3D Guide Curves 20-9







	Creating the fixed jaw clamp	20-11
	Creating a new component: The slide jaw	20-14
	Using the offset entities command	20-15
	Sketching the Guide Curve	20-20
	Creating the clamp block	20-22
	Extruding the clamp block	20-23
	Creating the Internal threads	20-26
	Creating a Section View	20-29
	Questions for Review	20-32
Chapter 21	**Top-Down Assembly – Part 2**	**21-1**
	Water Control Valve	21-2
	Tools Needed	21-2
	Starting a New Assembly Template	21-3
	Creating the 1st Component	21-4
	Adding the Inlet Flange	21-5
	Adding the Mounting Holes	21-6
	Adding Chamfers and Fillets	21-8
	Saving as Virtual Component	21-10
	Creating the 2nd Component	21-10
	Creating the Transition Body	21-12
	Adding another mounting Flange	21-13
	Adding an Offset-Distance plane	21-14
	Exiting the Edit Component Mode	21-20
	Applying dimension changes	21-20
	Viewing the External Reference Symbols	21-22
	Inserting other components	21-23
	Questions for Review	21-25
Chapter 22	**External References & Repair Errors**	**22-1**
	External Reference Symbols	22-2
	Understanding & Removing External References	22-3
	Removing External References	22-3
	Understanding the External Symbols	22-4
	Repairing the Sketches	22-5
	Rebuilding the model	22-7
	Questions for Review	22-8
	Understanding and Repairing Part Errors	22-9
	Repair Errors & External References	22-16
	Level 4: Final Exam	**22-24**





Chapter 23 Using Appearances **23-1**
Modeling diamond knurls 23-1
Applying the knurl appearance 23-5
Applying wire mesh appearance 23-8
Applying the Car-Paint Appearance 23-11
Flatten Surfaces 23-16
Exercise: Flattening a shoe sole 23-20

Certification Practice for the CSWP Mechanical Design Exam **24-1**
Challenge I: Part Modeling & Modifications 24-2
Challenge II: Part Modifications & Configurations 24-18
Challenge III: Bottom Up Assembly & Mates 24-39

Glossary, Index, and SOLIDWORKS 2021 Quick-Guide
Quick Reference Guide to SOLIDWORKS 2021 Command Icons and Toolbars.