CSWE - Certified SolidWorks® Expert Preparation Materials

SolidWorks 2010 - 2013



Paul Tran, CSWE, CSWI

SDC PUBLICATIONS
Schroff Development Corporation

Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents

Copyrights Notices
Disclaimer
Trademarks

Introduction: Are you the next CSWE?

Chapter 1: **Surface Modifications** **1-1**





Chapter summary 1-1
Tools needed 1-2
Opening a part document 1-3
Working with Surfaces 1-3
- Deleting the faces 1-3
- Measuring the angle 1-4
- Rotating the handle 1-5
- Recreating the surfaces 1-6
- Hiding a solid body 1-8
- Trimming the surfaces 1-9
- Showing a surface body 1-10
- Knitting all surface bodies 1-10

Creating a section view 1-11
Measuring the mass 1-11
Exercise: Surface Modifications 1-13

Chapter 2: **Assembly Modifications** **2-1**



Chapter summary 2-1
Tools needed 2-2
Opening an assembly document 2-3
Editing the first component 2-3
- Adding Draft 2-4
- Viewing the draft results 2-5

Editing the second component 2-6
- Replacing a plane 2-6
- Repairing the sketch errors 2-7
- Correcting the end condition 2-8
- Exiting the edit component mode 2-9

Table of Contents



Measuring the center of mass 2-10
Exercise: Using manual drafts 2-11

Chapter 3: The Order of Fillets 3-1





Chapter summary 3-1
Tools needed 3-2
Opening a part document 3-3
Comparing the fillet results 3-3
Planning the order of fillets 3-4
Adding the face fillet 3-4
Creating the constant fillet 3-5
Adding another constant fillet 3-6
Measuring the mass 3-6
Exercise: Fillet Options 3-7

Chapter 4: Flat Spring Assembly 4-1





Chapter summary 4-1
Tools needed 4-2
Starting a new part template 4-3
Creating the helix - the sweep path 4-3
Creating the sweep profile 4-4
Adding the pierce relation 4-5
Creating the swept feature 4-5
Creating an axis 4-6
Opening an assembly document 4-7
Inserting the part into an assembly 4-7
Showing the axis 4-7
Adding mates 4-8
Checking the degrees of freedom 4-8
Adding coincident mates 4-9
Applying dimension changes 4-11
Viewing the results 4-12
Calculating the center of mass 4-12
Exercise: Spring Assembly 4-13

Chapter 5: Part Modifications 5-1

Chapter summary 5-1
Tools needed 5-2
Opening a part document 5-3

Table of Contents

Modifying the model 5-3
Converting the outline of a feature 5-3
Deleting the on-edge relations 5-4
Removing the raised feature 5-5
Creating a cut 5-5
Recreating the sweep path 5-6
Using projected curve 5-6
Creating the sweep profile 5-7
Adding the pierce relation 5-7
Creating a swept feature 5-8
Calculating the mass 5-9
Exercise: Part modifications 5-11

Chapter 6: Replacing External References 6-1

Chapter summary 6-1
Tools needed 6-2
Opening an assembly document 6-3
Examining the existing mates 6-3
Suppressing the inplace mate 6-4
Adding a concentric mate 6-4
Editing a component 6-5
Replacing the sketch plane 6-5
Viewing the external ref. symbols 6-6
Exiting the edit component mode 6-6
Adding new mates 6-7
Adding a concentric mate 6-7
Adding a distance mate 6-7
Measuring the center of mass 6-8
Exercise: Replacing External References 6-9

Chapter 7: Working with Multibody Parts 7-1

Chapter summary 7-1
Tools needed 7-2
Opening an assembly document 7-3
Switching to the part level 7-4
Editing a feature 7-4
Using Move / Copy / Constraint 7-5
Adding mates 7-6
Changing the display option 7-6
Using the combine command 7-7







Using combine add 7-7
Switching back to assembly 7-8
Rebuilding the assembly 7-9
Measuring the center of mass 7-9
Exercise: Combining Multibodies 7-11

Chapter 8: Creating a Curved Spring 8-1

Chapter summary 8-1
Tools needed 8-2
Starting a new part template 8-3
Creating the sweep path 8-3
Creating the sweep profile 8-4
Creating a swept feature 8-4
Setting the twist type 8-5
Entering the number of turns 8-5
Assigning the material 8-5
Calculating the final mass 8-6
Exercise: Circular Spring - Expanded 8-7

Chapter 9: Working with Sketch Pictures 9-1



Chapter summary 9-1
Tools needed 9-2
Creating a layout sketch 9-3
Inserting the picture 9-4
Locating the picture 9-4
Scaling the picture 9-5
Tracing the picture 9-5
Creating the offset entities 9-7
Closing the traced sketch 9-7
Adding the sketch fillets 9-8
Adding the revolved centerline 9-9
Revolving the sketch profile 9-10
Measuring the mass of the part 9-10
Exercise: Sketch picture - Eagle head 9-11

Chapter 10: Using Cut with Surface 10-1
Chapter summary 10-1
Tools needed 10-2
Opening an assembly document 10-3
Editing a component 10-3



Creating a surface offset 10-4
Creating a surface cut 10-5
Flipping the cut direction 10-5
Hiding a component 10-6
Hiding a surface 10-6
Adding fillets 10-6
Exiting the edit component mode 10-8
Calculating the mass 10-8
Exercise: Cut with Surface 10-9

Chapter 11: **Using Belt Chain** **11-1**



Chapter summary 11-1
Tools needed 11-2
Staring a new part template 11-3
Creating the main sketch 11-3
Making the blocks 11-4
Creating a belt chain 11-5
Entering the belt length 11-6
Adding the driving angular dimension 11-7
Adding a reference dimension 11-7
Applying dimension changes 11-8
Checking the new belt length 11-9
Changing the pulley's angle 11-9
Entering the new belt length 11-10
Exercise: Creating a belt chain **11-11**

Glossary

Index

SolidWorks Quick-Guides:

Quick Reference Guide to SolidWorks Command Icons and Toolbars.