SOLIDWORKS® 2016 and Engineering Graphics

An Integrated Approach



Randy H. Shih

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents

Preface i
Acknowledgments ii
Table of Contents iii
Certified SOLIDWORKS Associate Examination Reference Guide xiv
Tips about Taking the SOLIDWORKS Certified Associate Examination xx

Chapter 1
Introduction

Introduction 1-2
Drawing in CAD Systems 1-4
Development of Computer Geometric Modeling 1-4
Feature-Based Parametric Modeling 1-8
Getting Started with SOLIDWORKS 1-9
Starting SOLIDWORKS 1-9
Units Setup 1-11
SOLIDWORKS Screen Layout 1-13
Menu Bar 1-13
Menu Bar Pull-down Menus 1-14
Heads-up View Toolbar 1-14
Features Toolbar 1-14
Sketch Toolbar 1-14
Feature Manager-Design Tree/Property Manager 1-15
Configuration Manager/DimXpert Manager/Display Manager 1-15
Graphics Area 1-16
Reference Triad 1-16
Origin 1-16
Confirmation Corner 1-16
Graphics Cursor or Crosshairs 1-16
Message and Status Bar 1-16
Using the SOLIDWORKS Command Manager 1-17
Mouse Buttons 1-18
[Esc] - Canceling Commands 1-18
SOLIDWORKS Help System 1-19
Leaving SOLIDWORKS 1-19
Creating a CAD File Folder 1-20

Chapter 2
Parametric Modeling Fundamentals

Introduction 2-3
The Adjuster Design 2-4
Starting SOLIDWORKS 2-4
SOLIDWORKS Part Modeling Window Layout 2-5

Step 1: Determine/Setup the Base Feature 2-7
Sketching Plane – It is an XY CRT, but an XYZ world 2-7
Creating Rough Sketches 2-9
Step 2: Creating a Rough Sketch 2-10
Graphics Cursors 2-10
Geometric Relation Symbols 2-12
Step 3: Apply/Modify Relations and Dimensions 2-13
Viewing Functions – Zoom and Pan 2-15
Delete an Existing Geometry of the Sketch 2-16
Modifying the Dimensions of the Sketch 2-17
Step 4: Completing the Base Solid Feature 2-18
Isometric View 2-19
Rotation of the 3-D Model – Rotate View 2-19
Rotation and Panning – Arrow keys 2-21
Dynamic Viewing – Quick Keys 2-22
3D Rotation 2-24
Viewing Tools – Heads-up View Toolbar 2-24
View Orientation 2-25
Display Style 2-26
Orthographic vs. Perspective 2-26
Customizing the Heads-up View Toolbar 2-26
Step 5-1: Adding an Extruded Boss Feature 2-27
Step 5-2: Adding an Extruded Cut Feature 2-31
Step 5-3: Adding another Cut Feature 2-33
Save the Model 2-35
Questions 2-36
Exercises 2-37

Chapter 3
Constructive Solid Geometry Concepts

Introduction 3-3
Binary Tree 3-4
The Locator Design 3-5
Modeling Strategy – CSG Binary Tree 3-6
Starting SOLIDWORKS and Activating the Command Manager 3-7
GRID and *SNAP* Intervals Setup 3-9
Base Feature 3-10
Repositioning Dimensions 3-12
Completing the Base Solid Feature 3-13
Creating the Next Solid Feature 3-14
Creating an Extruded Cut Feature 3-17
Creating a Hole with the Hole Wizard 3-20
Creating a Rectangular Extruded Cut Feature 3-23
Using the View Selector 3-25
Questions 3-27

Exercises 3-28

Chapter 4
Geometric Constructions

Geometric Constructions 4-3
Geometric Constructions - Classical Methods 4-4
- Bisection of a Line or Arc 4-4
- Bisection of an Angle 4-5
- Transfer of an Angle 4-6
- Dividing a Given Line into a Number of Equal Parts 4-7
- Circle through Three Points 4-8
- A Line Tangent to a Circle 4-9
- Line Tangent to a circle from a Given Point 4-10
- Circle of a Given Radius Tangent to Two Given Lines 4-11
- Circle of a Given Radius Tangent to an Arc and a Line 4-12
- Circle of a Given Radius Tangent to Two Arcs 4-13

Starting SOLIDWORKS 4-14
Geometric Construction – CAD Method 4-16
- Bisection of a Line or Arc 4-16

Dimensions and Relations 4-18
Geometric Symbols available in parametric sketching 4-19
- Bisection of an Angle 4-20
- Dividing a Given Line into a Number of Equal Parts 4-22
- Circle through Three Points 4-29
- Line Tangent to a circle from a Given Point 4-30
- Circle of a Given Radius Tangent to Two Given Lines 4-31

Adding Geometric Relations and Fully Defined Geometry 4-34
Starting SOLIDWORKS 4-34
Over-Defining and Driven Dimensions 4-41
Deleting Existing Relations 4-42
Using the Fully Define Sketch Tool 4-43
Adding Additional Geometry 4-44
Adding New Equations 4-49
Questions 4-51
Exercises 4-52

Chapter 5
Feature Design Tree

Introduction 5-3
Starting SOLIDWORKS 5-4
Creating a User-Defined Part Template 5-5
The *Saddle Bracket* Design 5-9
Modeling Strategy 5-10
The SOLIDWORKS *Feature Manager Design Tree* 5-11

Creating the Base Feature 5-11
Adding the Second Solid Feature 5-14
Creating a 2D Sketch 5-15
Renaming the Part Features 5-17
Adjusting the Width of the Base Feature 5-18
Adding a Cut Feature 5-19
Creating a Rectangular Extruded Cut Feature 5-22
History-Based Part Modifications 5-23
A Design Change 5-24
Feature Manager Design Tree Views 5-26
Questions 5-28
Exercises 5-29

Chapter 6
Geometric Construction Tools

Introduction 6-3
The Gasket Design 6-3
Modeling Strategy 6-4
Starting SOLIDWORKS 6-5
Creating a 2D Sketch 6-6
Editing the Sketch by Dragging the Entities 6-8
Adding Additional Relations 6-10
Using the *Trim* and *Extend* Commands 6-11
Adding Dimensions with the Fully Define Sketch Tool 6-14
Fully Defined Geometry 6-16
Creating Fillets and Completing the Sketch 6-17
Profile Sketch 6-18
Redefining the Sketch and Profile using Contour Selection 6-19
Create an OFFSET Extruded Cut Feature 6-23
Questions 6-27
Exercises 6-28

Chapter 7
Orthographic Projections and Multiview Constructions

Introduction 7-3
Basic Principles of Projection 7-4
Orthographic Projection 7-4
Multiview Orthographic Projection 7-5
First-Angle Projection 7-6
Rotation of the Horizontal and Profile Planes 7-7
The 3D Adjuster Model and 1st angle projection 7-8
General Procedure: 1St Angle Orthographic Projection 7-9
Example 2: 1St Angle Orthographic Projection 7-10
Chapter 7 - 1St Angle Orthographic Sketching Exercise 1 7-11
Chapter 7 - 1St Angle Orthographic Sketching Exercise 2 7-13

Chapter 7 - 1St Angle Orthographic Sketching Exercise 3 7-15
Chapter 7 - 1St Angle Orthographic Sketching Exercise 4 7-17
Chapter 7 - 1St Angle Orthographic Sketching Exercise 5 7-19
Chapter 7 - 1St Angle Orthographic Sketching Exercise 6 7-21
Third-Angle Projection 7-23
Rotation of the Horizontal and Profile Planes 7-24
The 3D Adjuster Model and 3rd angle projection 7-25
The Glass Box and the Six Principal Views 7-26
General Procedure: 3rd Angle Orthographic Projection 7-28
Example 2: 3rd Angle Orthographic Projection 7-29
Example 3: 3rd Angle Orthographic Projection 7-30
Chapter 7 - 3rd Angle Orthographic Sketching Exercise 1 7-31
Chapter 7 - 3rd Angle Orthographic Sketching Exercise 2 7-33
Chapter 7 - 3rd Angle Orthographic Sketching Exercise 3 7-35
Chapter 7 - 3rd Angle Orthographic Sketching Exercise 4 7-37
Chapter 7 - 3rd Angle Orthographic Sketching Exercise 5 7-39
Chapter 7 - 3rd Angle Orthographic Sketching Exercise 6 7-41
Alphabet of Lines 7-43
Precedence of Lines 7-45
The U-Bracket Design 7-46
Starting SOLIDWORKS 7-46
Applying the BORN Technique 7-47
Creating the 2D Sketch of the Base Feature 7-48
Creating the First Extrude Feature 7-55
The Implied Parent/Child Relationships 7-55
Creating the Second Solid Feature 7-56
Creating the First Extruded Cut Feature 7-59
Creating the Second Extruded Cut Feature 7-60
Examining the Parent/Child Relationships 7-62
Modify a Parent Dimension 7-63
A Design Change 7-64
Feature Suppression 7-65
A Different Approach to the CENTER_DRILL Feature 7-66
Suppress the Rect_Cut Feature 7-67
Creating a Circular Extruded Cut Feature 7-68
A Flexible Design Approach 7-70
Drawings from Parts and Associative Functionality 7-71
Drawing Mode 7-72
Setting Document Properties 7-74
Setting Sheet Properties using the Pre-Defined Sheet Formats 7-75
Creating Three Standard Views 7-76
Repositioning Views 7-76
Adding a New Sheet 7-78
Adding a Base View 7-79
Adding an Isometric View using the View Palette 7-82
Adjusting the View Scale 7-83

Questions 7-85
Exercises 7-86

Chapter 8

Dimensioning and Notes

Introduction 8-3
Dimensioning Standards and Basic Terminology 8-4
Selection and Placement of Dimensions and Notes 8-5
Machined Holes 8-12
Baseline and Chain Dimensioning 8-15
Dimensioning and Tolerance Accumulation 8-16
(1) Tolerance Accumulation - Baseline Dimensioning 8-17
(2) Tolerance Accumulation - Chain Dimensioning 8-18
(3) Avoid Tolerance Accumulation Feature Functionality Manufacturing 8-19
Dimensioning Tools in SOLIDWORKS 8-20
The U-Bracket Design 8-20
Starting SOLIDWORKS 8-21
Displaying Feature Dimensions 8-22
Repositioning, Appearance, and Hiding of Feature Dimensions 8-23
Adding Additional Dimensions – Reference Dimensions 8-25
Tangent Edge Display 8-27
Adding Center Marks, Center Lines, and Sketch Objects 8-27
Edit Sheet vs. Edit Sheet Format 8-32
Modify the Title Block 8-32
Property Links 8-35
Associative Functionality – Modifying Feature Dimensions 8-39
Saving the Drawing File 8-42
Saving a Drawing Template 8-42
Questions 8-45
Exercises 8-46

Chapter 9

Tolerancing and Fits

Precision and Tolerance 9-2
Methods of Specifying Tolerances – English System 9-3
Nomenclature 9-4
Example 9.1 9-5
Fits between Mating parts 9-6
Selective Assembly 9-7
Basic Hole and Basic Shaft Systems 9-7
American National Standard Limits and Fits – Inches 9-8
Example 9.2 Basic Hole System 9-13
Example 9.3 Basic Hole System 9-14
Example 9.4 Basic Shaft System 9-15
Example 9.5 Basic Shaft System 9-16

Tolerancing – Metric System 9-17
Metric Tolerances and Fits Designation 9-18
Preferred ISO Metric Fits 9-19
Example 9.6 Metric Hole Basis System 9-20
Example 9.7 Shaft Basis System 9-21
Updating the U-Bracket Drawing 9-22
Determining the Tolerances Required 9-23
Questions 9-25
Exercises 9-26

Chapter 10

Pictorials and Sketching

Engineering Drawings, Pictorials and Sketching 10-2
Isometric Sketching 10-7
Chapter 10 - Isometric Sketching Exercise 1 10-9
Chapter 10 - Isometric Sketching Exercise 2 10-11
Chapter 10 - Isometric Sketching Exercise 3 10-13
Chapter 10 - Isometric Sketching Exercise 4 10-15
Chapter 10 - Isometric Sketching Exercise 5 10-17
Chapter 10 - Isometric Sketching Exercise 6 10-19
Chapter 10 - Isometric Sketching Exercise 7 10-21
Chapter 10 - Isometric Sketching Exercise 8 10-23
Chapter 10 - Isometric Sketching Exercise 9 10-25
Chapter 10 - Isometric Sketching Exercise 10 10-27
Oblique Sketching 10-29
Chapter 10 - Oblique Sketching Exercise 1 10-31
Chapter 10 - Oblique Sketching Exercise 2 10-33
Chapter 10 - Oblique Sketching Exercise 3 10-35
Chapter 10 - Oblique Sketching Exercise 4 10-37
Chapter 10 - Oblique Sketching Exercise 5 10-39
Chapter 10 - Oblique Sketching Exercise 6 10-41
Perspective Sketching 10-43
One-Point Perspective 10-44
Two-Point Perspective 10-45
Chapter 10 - Perspective Sketching Exercise 1 10-47
Chapter 10 - Perspective Sketching Exercise 2 10-49
Chapter 10 - Perspective Sketching Exercise 3 10-51
Chapter 10 - Perspective Sketching Exercise 4 10-53
Chapter 10 - Perspective Sketching Exercise 5 10-55
Chapter 10 - Perspective Sketching Exercise 6 10-57
Questions 10-59
Exercises 10-60

Chapter 11

Section Views & Symmetrical Features in Designs

Introduction 11-3
General Rules of Section Views 11-5
Section Drawing Types 11-6
- Full Section 11-6
- Half Section 11-6
- Offset Section 11-7
- Broken-Out Section 11-7
- Aligned Section 11-8
- Half Views 11-8
- Thin Sections 11-8
- Revolved Section 11-9
- Removed Section 11-9
- Conventional Breaks 11-10
- Ribs and Webs in Sections 11-10
- Parts Not Sectioned 11-10

Section Views in SOLIDWORKS 11-11
A Revolved Design: PULLEY 11-11
Modeling Strategy - A Revolved Design 11-12
Starting SOLIDWORKS 11-13
Creating the Base Feature 11-13
Creating the Revolved Feature 11-17
Mirroring Features 11-17
Creating an Extruded Cut Feature using Construction Geometry 11-19
Circular Pattern 11-24
Drawing Mode – Defining a New Border and Title Block 11-26
Creating a New Drawing Template 11-30
Creating Views 11-31
Retrieve Dimensions – Model Items Command 11-34
Save the Drawing File 11-35
Associative Functionality – A Design Change 11-36
Adding Centerlines to the Pattern Feature 11-38
Completing the Drawing 11-40
Questions 11-43
Exercises 11-44

Chapter 12

Auxiliary Views and Reference Geometry

Introduction 12-3
Normal View of an Inclined Surface 12-4
Construction Method I – Folding Line Method 12-6
Construction Method II – Reference Plane Method 12-8
Partial Views 12-10

Reference Geometry in SOLIDWORKS 12-11
Auxiliary Views in 2D Drawings 12-11
The *Rod-Guide* Design 12-11
Modeling Strategy 12-12
Starting SOLIDWORKS 12-13
Applying the BORN Technique 12-13
Creating the Base Feature 12-14
Creating an Angled Reference Plane 12-16
Creating an Extruded Feature on the Reference Plane 12-19
Using the Convert Entities Option 12-19
Completing the Solid Feature 12-25
Creating an Offset Reference Plane 12-26
Creating another Extruded Cut Feature using the Reference Plane 12-27
Starting a New 2D Drawing and Adding a Base View 12-29
Creating an Auxiliary View 12-30
Displaying Feature Dimensions 12-32
Adjusting the View Scale 12-34
Repositioning, Appearance, and Hiding of Feature Dimensions 12-34
Tangent Edge Display 12-37
Adding Center Marks and Center Lines 12-37
Controlling the View and Sheet Scales 12-40
Completing the Drawing Sheet 12-41
Editing the Isometric view 12-42
Adding a General Note 12-42
Questions 12-44
Exercises 12-45

Chapter 13

Threads and Fasteners

Introduction 13-2
Screw-Thread Terminology 13-3
Thread Forms 13-5
Thread Representations 13-6
- Detailed Representation 13-7
- Schematic Representation 13-8
- Simplified Representation 13-9

Thread Specification – English Units 13-10
Unified Thread Series 13-11
Thread Fits 13-12
Thread Specification – Metric 13-12
Thread Notes Examples 13-13
Specifying Fasteners 13-14
Commonly Used Fasteners 13-15
Drawing Standard Bolts 13-17
Bolt and Screw Clearances 13-17

Fasteners using SOLIDWORKS' Design Library 13-18
ANSI Inch - Machine Screw 13-18
ANSI Metric - Machine Screw 13-20
Questions 13-22

Chapter 14

Working Drawings

General Engineering Design Process 14-3
Working Drawings 14-4
Detail Drawings 14-4
Assembly Drawings 14-5
Bill of Materials (BOM) and Parts List 14-5
Drawing Sizes 14-6
Drawing Sheet Borders and Revisions Block 14-6
Title Blocks 14-7
Working Drawings with SOLIDWORKS 14-8
Assembly Modeling Methodology 14-8
The Shaft Support Assembly 14-9
Parts 14-9
Creating the Collar with the Chamfer Command 14-9
Creating the Bearing and Base-Plate 14-11
Creating the Cap-Screw 14-12
Starting SOLIDWORKS 14-13
Document Properties 14-13
Inserting the First Component 14-14
Inserting the Second Component 14-15
Degrees of Freedom 14-16
Assembly Mates 14-16
Apply the First Assembly Mate 14-18
Apply a Second Mate 14-19
Constrained Move 14-21
Apply a Third Mate 14-22
Inserting the Third Component 14-24
Applying Concentric and Coincident Mates 14-24
Assemble the Cap-Screws using SmartMates 14-26
Exploded View of the Assembly 14-30
Save the Assembly Model 14-32
Editing the Components 14-32
Setup a Drawing of the Assembly Model 14-34
Creating a Bill of Materials 14-35
Editing the Bill of Materials 14-37
Completing the Assembly Drawing 14-41
Exporting the Bill of Materials 14-43
Questions 14-44
Exercises 14-45

Chapter 15
CSWA Exam Preparation

Tips about Taking the Certified SOLIDWORKS Associate Examination 15-3
Introduction 15-4
The Part Problem 15-5
Strategy for Aligning the Part to the Default Axis System 15-6
Creating the Base Feature 15-6
Creating a New View Orientation 15-9
Create Reference Planes and a Reference Axis 15-10
Selecting the Material and Viewing the Mass Properties 15-16
The Assembly Problem 15-19
Creating the Parts 15-20
Creating the Assembly 15-21
Creating a Reference Coordinate System 15-27
View the Mass Properties 15-29
Questions 15-31
Exercises 15-32

Appendix

A. Running and Sliding Fits – American National Standard
B. Preferred Metric Fits –ISO standard
C. UNIFIED NATIONAL THREAD FORM
D. METRIC THREAD FORM
E. FASTENERS (INCH SERIES)
F. METRIC FASTENERS
G. BOLT AND SCREW CLEARANCE HOLES
H. REFERENCES

Index