Engineering & Computer Graphics Workbook

Using SOLIDWORKS® 2017



Ronald E. Barr
Thomas J. Krueger
Davor Juricic

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents

Page

1. Computer Graphics Lab 1: 2-D Computer Sketching I 1-1

Introduction to SOLIDWORKS; Screen Layout; Main Pull-Down Menu; Feature Manager Tree; View Orientation; View and Display Toolbars; Sketching Toolbars; Sketching Planes; Line Colors; Starting a New Part; Setting Grids and Units; Using Basic 2-D Primitives; Applying Basic Dimensions; Extruding and Revolving Simple Parts; Printing a Hardcopy.

Exercise 1.1: Carbon Fiber Gasket 1-8
Exercise 1.2: Cover Plate 1-14
Exercise 1.3: Wall Bracket 1-19
Exercise 1.4: Machine Handle 1-22
Supplementary Exercises 1-25

2. Computer Graphics Lab 2: 2-D Computer Sketching II 2-1

Review of All 2-D Sketch Entities; Advanced Sketching Tools; Sketch Editing Tools; Linear and Circular Repeats; Basic Dimensioning; Extruding and Revolving Simple Parts.

Exercise 2.1: Metal Grate 2-3
Exercise 2.2: Torque Sensor 2-8
Exercise 2.3: Scalloped Knob 2-11
Exercise 2.4: Linear Step Plate 2-14
Supplementary Exercises 2-19

3. Computer Graphics Lab 3: 3-D Solid Modeling of Parts I 3-1

Adding Sketch Relations; 3-D Features Toolbar; Advanced Extrusion and Revolution Operations; Insert Reference Geometry; Mirror 3-D Feature; Create Linear and Circular 3-D Patterns; Building 3-D Solid Parts.

Exercise 3.1 Clevis Mounting Bracket 3-3
Exercise 3.2 Manifold 3-8
Exercise 3.3: Hand Wheel 3-13
Exercise 3.4: Toe Clamp 3-17
Supplementary Exercises 3-21

Page

4. Computer Graphics Lab 4: 3-D Solid Modeling of Parts II 4-1

Creating Advanced 3-D Features: Draft, Shell, Dome, Loft, Sweep; Advanced Extrusion and Revolution Operations; Building 3-D Solid Parts.

Exercise 4.1: Drawer Tray 4-2
Exercise 4.2: Tap-Light Dome 4-6
Exercise 4.3: Threads and Fasteners 4-10
Exercise 4.4: Jack Stand 4-18
Supplementary Exercises 4-21

5. Computer Graphics Lab 5: Assembly Modeling and Mating 5-1

Building Multiple 3-D Parts; Color Shading of Parts in an Assembly; Starting a New Assembly File; Tiling the Screen Windows; Assembly Toolbar; Drag and Drop Parts into Assembly; Move and Rotate Component; Mate Parts with Different Mate Types; Print Assembly File.

Exercise 5.1: Terminal Support Assembly 5-4
Exercise 5.2: Pulley Assembly 5-15
Supplementary Exercises 5-26

6. Computer Graphics Lab 6: Analysis and Design Modification I 6-1

Measure Function; Mass Properties Function; Types of Mass Properties and Applicable Units; Print Mass Properties Report; Design Modification of a Solid Model; Setting Up a Design Table; Setting Parameters for the Design Table; Configuration Manager; Print Assembly File.

Exercise 6.1: Rocker Arm Mass Properties 6-4
Exercise 6.2: Socket Design Table 6-12
Supplementary Exercises 6-18

7. Computer Graphics Lab 7: Analysis and Design Modification II 7-1

Introduction to Finite Element Analysis Using COSMOS/Works; Definition of FEA Terms; Building a Solid Model for an FEA Study; Beginning an FEA Study; Applying Loads and Constraints; Creating a Mesh; Analyzing the Model for Stress Distribution; Printing the von Mises Stress Distribution; Design Modification of a Solid Model Based on Analysis Results.

Exercise 7.1: Finite Element Analysis of a Pillow Block 7-3
Exercise 7.2: Thermal Analysis of a Computer Chip 7-14

Page

8. Computer Graphics Lab 8: Kinematics Animation, Creating Views and Rapid Prototyping 8-1

Introduction to the SOLIDWORKS Animation Wizard; Loading an Assembly File; Exploding an Assembly; Creating the Animation; Animation Controller; Editing the Animation; Saving an .AVI File; Introduction to Physical Simulation, Introduction to Rapid Prototyping; Saving an .STL File; Sample Solid Models for Rapid Prototyping.

Exercise 8.1: Exploded Animation of the Terminal Support Assembly 8-5
Exercise 8.2: Exploded Animation of the Pulley Assembly 8-10
Exercise 8.3: Creating Views That Will Be Helpful When Illustrating Parts 8-15
Exercise 8.4: Rapid Prototyping of a Solid Model Part 8-19

9. Computer Graphics Lab 9: Section Views in 3-D and 2-D 9-1

Viewing 3-D Section Views of a Solid Model; Printing 3-D Section View; Inserting a Drawing Sheet; Setting Drawing and Hatch Pattern Options; Projecting Three Orthographic Views Onto a Drawing Sheet; Creating the Cutting Plane Line; Making a 2-D Section View; Completing a Section View Drawing; Print Section View Drawing.

Exercise 9.1: Rod Base Section View 9-3
Exercise 9.2: Tension Cable Bracket Section View 9-9
Exercise 9.3: Milling End Adapter Section View 9-15
Exercise 9-4: Plastic Revolving Ball Assembly Section View 9-21
Supplementary Exercises 9-27

Intro to Lab 10: Computer Graphics Intro to Lab 10: Setting Up Templates for Three View Drawings 10-1

10. Computer Graphics Lab 10: Generating and Dimensioning Three-View Drawings 10-3

Inserting a Drawing Sheet; Setting Drawing Sheet Options; Projecting Three Orthographic Views of a Solid Model Onto a Drawing Sheet; Adding Centerlines and Completing the Drawing Views; Setting the Dimensioning Variables; Dimensioning the Drawing; Adding Title Block and Annotations; Print a Drawing.

Exercise 10.1: Guide Block Drawing 10-7
Exercise 10.2: Pipe Joint Drawing 10-11
Exercise 10.3: Pedestal Base Drawing 10-17
Exercise 10.4: Tooling Pad Drawing 10-21
Supplementary Exercises 10-29

APPENDIX A – Example of a Titleblock with Dimensions