Certified SOLIDWORKS® Professional Advanced Preparation Material

Sheet Metal, Weldments, Surfacing, Mold Making and Drawing Tools

SOLIDWORKS® 2021



Paul Tran CSWE, CSWI

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents

CSWPA – Drawing Tools

Chapter 1: Advanced Drawing Tools 1-1

Challenge 1: Tank **1-3**
Open the part document: Tank 1-3
Transferring to a drawing 1-3
Changing the paper size 1-4
Adding the drawing view 1-5
Creating a section view 1-6
Measuring the surface area 1-7
Creating an aligned section view 1-7
Measuring the surface area 1-9



Challenge 2: Piston Assembly **1-10**
Open the assembly document: Piston Assembly 1-10
Creating a reference sketch 1-11
Modifying the view angle 1-12
Saving a new named-view 1-14
Making a drawing from assembly 1-15
Adding the first drawing view 1-16
Creating the projected drawing views 1-17
Adding reference lines 1-18
Converting an entity 1-19
Adding a reference dimension 1-19
Adding a top drawing view 1-20
Locking a view focus 1-21
Adding an angular dimension 1-23



Challenge 3: Radial Stretcher **1-24**
Open the assembly document: Radial Stretcher 1-24
Transferring to a drawing 1-24
Adding drawing views from the view palette 1-25
Breaking the view alignment 1-26
Adding balloons 1-27

Adding a bill of materials 1-28
Changing custom properties 1-29
Adding a new column 1-30
Optional 1-32

CSWPA – Mold Making

Chapter 2: Advanced Mold Making 2-1



Challenge 1: Interlock Surface 2-2
Open the document: Interlock Surface 2-3
Enabling the mold tools 2-3
Selecting the parting line 2-4
Creating the shut-off surfaces 2-5
Creating the parting surfaces 2-6
Making a new plane 2-7
Sketching the mold profile 2-8
Performing a tooling split 2-9
Separating the solid bodies 2-10
Assigning material 2-11
Calculating the mass 2-11



Challenge 2: Parting Lines Creation 2-13
Open the document: Parting Line Creation 2-14
Creating the parting line 2-14
Creating the shut-off surfaces 2-15
Creating the Parting surfaces 2-16
Sketching the mold block profile 2-17
Inserting a tooling split 2-18
Separating the block from the part 2-19
Assigning material 2-20
Calculating the mass 2-20



Challenge 3: Runners & Sprue 2-22
Open the document: Runners & Sprue 2-23
Creating the shut-off surfaces 2-24
Creating the parting surfaces 2-25
Sketching the shape of the mold profile 2-26
Inserting a tooling split 2-27
Finalizing the mold block sketch 2-28
Extruding the lower mold block 2-29



Converting a sketch 2-30
Extruding the upper mold block 2-31
Moving the cavity block 2-32
Measuring the distance 2-32
Copying the plastic part 2-33
Subtracting the solid bodies 2-33
Applying the shrink rate 2-34
Calculating the mass 2-34



Challenge 4: Shut-Off Surface Creation **2-36**
Open the document: Steering Wheel 2-37
Creating a split line 2-37
Creating the parting lines 2-39
Creating the shut-off surfaces 2-40
Measuring the surface area 2-41
Creating the parting surfaces 2-42
Inserting a tooling split 2-43
Adding chamfers 2-44
Creating an exploded view 2-45



Challenge 5: Undercut Analysis **2-46**
Open the document: Undercut Analysis 2-47
Performing an undercut analysis 2-47
Creating the parting lines 2-48
Creating the shut-off surfaces 2-49
Creating the parting surfaces 2-50
Inserting a tooling split 2-51
Adding the 1st slide core 2-52
Adding the 2nd slide core 2-53
Assigning material 2-54
Calculating the mass 2-54



Challenge 6: Virtual Part Creation **2-56**
Open the document: Virtual part Creation 2-57
Hiding components 2-57
Inserting a new part 2-58
Working in the part level 2-59
Inserting the 2nd part 2-60
Moving the solid bodies 2-61
Creating an intersect feature 2-62
Creating a combine-subtract feature 2-63
Working in the assembly level 2-64
Assigning material 2-65



Calculating the mass 2-65

CSWPA – Weldments

Chapter 3: Advanced Weldments 3-1









Challenge 1: Creating the Weldments profile 3-3
Starting a new part document 3-3
Enabling the Weldments tab 3-3
Sketching the first weldment profile 3-4
Creating the second weldment profile 3-5
Sketching the profile 3-5
Showing the weldment profiles folder 3-6
Creating a new weldment part 3-7
Adding structural members 3-8
Applying material 3-9
Calculating the mass 3-9
Changing the structural members 3-10
Calculating the mass 3-11

Challenge 2: Weldment Frame 3.sldprt 3-12
Open the document: Weldment Frame 3 3-12
Adding structural members 3-12
Creating the parallel group 3-14
Trimming the parallel group 3-15
Applying material 3-17
Calculating the mass 3-17
Creating the Upper Braces 3-18
Trimming the first Upper Braces 3-18
Updating the Cut list 3-20
Creating the Lower Braces 3-21
Trimming the Lower Braces 3-21
Adding End Caps 3-24
Calculating the final mass 3-25

Challenge 3: Weldment Frame 4.sldprt 3-26
Open the document: Weldment Frame 4 3-26
Creating a 3D sketch 3-26
Adding structural members 3-31
Creating the parallel group 3-32

Trimming the tubes 3-33



Challenge 4: Weldment Frame 5.sldprt **3-37**
Open the document: Weldment Frame 5 3-37
Assigning material 3-37
Modifying the properties 3-38
Transferring to a drawing 3-39
Adding a drawing view 3-39
Inserting the weldment cut list 3-40
Adding balloons 3-41

CSWPA – Sheet Metal

Chapter 4: Advanced Sheet Metal 4-1



Challenge 1: Converting to Sheet Metal **4-3**
Opening the document: Convert to SM 4-3
Enabling the sheet metal tab 4-3
Making a copy of the solid model 4-3
Converting to sheet metal 4-5
Calculating the mass 4-6
Measuring the flat pattern 4-7
Creating a Hem 4-8
Calculating the mass 4-10



Challenge 2: Sheet Metal Cut List **4-11**
Open the document: SM Cut List 4-11
Modifying the first bend radius 4-11
Measuring the flat length 4-12
Modifying the second bend radius 4-13
Measuring the flat length 4-13
Finding the Bounding Box Area 4-14



Challenge 3: Sheet Metal Part **4-15**
Open the document: SM Part 4-15
Creating the Edge Flanges 4-15
Closing the corners 4-16
Creating a cutout 4-17
Adding a Miter Flange 4-18



Mirroring the features 4-22
Calculating the mass 4-23
Changing the K-Factor value 4-24
Measuring the flat length 4-24
Adding hems 4-25
Adding a form feature 4-26
Creating a linear pattern 4-27
Calculating the mass 4-27

CSWPA – Surfacing

Chapter 5: Advanced Surfacing 5-1

Challenge 1: Surface patch 5-3
Open the document: Inlet-Outlet Patches 5-3
Enabling the surfaces tab 5-3
Patching the first opening 5-4
Measuring the surface area 5-5
Deleting and patching a hole 5-5
Knitting the surfaces 5-6
Creating a section view 5-6
Calculating the mass 5-7

Challenge 2: Surfaces & Sketch Picture 5-8
Open the document: Surfaces_ Sketch Picture 5-8
Examining the sketch pictures 5-8
Creating the 1st loft profile 5-9
Fully defining a sketch 5-9
Creating the 2nd loft profile 5-10
Converting the entities 5-10
Making the guide curve 5-11
Adjusting the spline 5-11
Creating a lofted surface 5-12
Measuring the surface area 5-13
Mirroring the surface bodies 5-14
Knitting the surfaces 5-15
Combining the solid bodies 5-15
Assigning material 5-16
Calculating the mass 5-16



Challenge 3: Ruled Surface **5-17**
Open the document: Ruled Surface 5-17
Creating a ruled surface 5-17
Using the taper to vector option 5-17
Trimming the surfaces 5-18
Measuring the surface area 5-19
Creating a section view 5-19



Challenge 4: Projected Curves **5-20**
Open the document: Project Curve 5-20
Creating a projected curve 5-20
Sketching the sweep profile 5-21
Creating a swept feature 5-22
Using path and guide curves 5-22
Trimming the surfaces 5-23
Knitting the surfaces 5-24
Adding fillets 5-24
Adding thickness 5-25
Calculating the mass 5-25

Challenge 5: Surface Split **5-26**
Open the document: Surface Split 5-26
Creating a split line 5-26
Using the projection type 5-26
Creating the 1st offset surface 5-27
Creating the 2nd offset surface 5-27
Making the 1st lofted cut feature 5-28
Making the 2nd lofted cut feature 5-28
Adding fillets 5-29
Shelling the model 5-30
Calculating the final mass 5-30

Challenge 6: Boundary Surface **5-31**
Open the document: Boundary Surface 5-31
Creating a lofted surface 5-31
Measuring the surface area 5-32
Mirroring a surface body 5-32
Mirroring a mirrored surface body 5-33
Creating a trimmed sketch 5-33
Fully defining the sketch 5-33
Trimming the surface bodies 5-34
Using standard trim 5-34

Measuring the total area 5-34

Glossary and Index

SOLIDWORKS 2021 Quick-Guide:

Quick Reference Guide to SOLIDWORKS 2021 Command Icons and Toolbars.