Parametric Modeling with SIEMENS® NX®

Spring 2022 Edition



Randy H. Shih

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

Table of Contents

Preface
Acknowledgments

Chapter 1
Introduction - Getting Started

Introduction 1-2
Development of Computer Geometric Modeling 1-2
Feature-Based Parametric Modeling 1-6
Getting Started with NX 1-7
The Siemens NX Main Window 1-8
Siemens NX Screen Layout 1-10
Quick Access Toolbar 1-11
Ribbon Bar 1-11
Zoom Toolbar 1-11
Additional Tools 1-11
Message and Status Bar 1-12
Part Navigator 1-12
Resource Bars 1-12
Mouse Buttons 1-13
[Esc] - Canceling commands 1-14
Online Help 1-14
Leaving Siemens NX 1-14
Creating a CAD Files Folder 1-15

Chapter 2
Parametric Modeling Fundamentals

Introduction 2-2
The Adjuster design 2-3
Step 1: Starting Siemens NX and Units setup 2-3
Siemens NX Application Screen Layout 2-5
Step 2: Determine/Set Up the First Solid Feature 2-6
Work Plane – It is an XY CRT, but an XYZ World 2-7
Creating Rough Sketches 2-9
Step 3: Creating a Rough 2D Sketch 2-10
Geometric Constraint Symbols 2-11
Step 4: Apply/Modify Constraints and Dimensions 2-12
View Functions 2-17
Dynamic Viewing Functions 2-17
Step 5: Completing the Base Solid Feature 2-18
Display Orientations 2-19
Dynamic Viewing – Icons, Mouse buttons and Quick keys 2-20

Display Modes 2-22
Step 6-1: Adding an Extruded Feature 2-23
Step 6-2: Adding a Cut Feature 2-27
Step 6-3: Adding another Cut Feature 2-30
Save the Model and Exit Siemens NX 2-34
Review Questions 2-35
Exercises 2-36

Chapter 3
Constructive Solid Geometry Concepts

Introduction 3-2
Binary Tree 3-3
The Locator Design 3-4
Modeling Strategy - CSG Binary Tree 3-5
Starting Siemens NX 3-6
Base Feature 3-7
Use the Rectangle Command 3-9
Completing the Base Solid Feature 3-10
Creating the Next Solid Feature 3-11
Creating a Cut Feature 3-14
Creating a Placed Feature 3-17
Creating a Rectangular Cut Feature 3-19
Review Questions 3-23
Exercises 3-24

Chapter 4
Model History Tree

The BORN Technique 4-2
Model History Tree 4-3
The Saddle Bracket Design 4-4
Starting Siemens NX 4-4
Modeling Strategy 4-5
Apply the BORN Technique 4-7
The NX Part Navigator 4-12
Create the Second Solid Feature 4-13
Use More Meaningful Feature Names 4-16
Adjust the Width of the Base Feature 4-17
Add a Placed Feature 4-19
Create a Rectangular Cut Feature 4-21
History-based Part Modifications 4-25
A Design Change 4-26
Assign and Calculate the Associated Physical Properties 4-28
Review Questions 4-33

Exercises 4-34

Chapter 5
Parametric Constraints Fundamentals

Constraints and Relations 5-2
Starting Siemens NX 5-3
Display Existing Constraints 5-6
Apply Geometric Constraints Implicitly 5-7
Apply a Geometric Constraint Explicitly 5-8
Add Dimensional Constraints 5-9
A Fully Constrained Sketch 5-11
A Fully Constrained Sketch – Alignment to Sketch Origin 5-12
A Fully Constrained Sketch – Add location dimensions 5-13
Delete Existing Dimensions and Constraints 5-14
2D Sketches with Multiple Loops 5-17
Parametric Relations 5-20
Dimensional Values and Dimensional Variables 5-21
Review Questions 5-26
Exercises 5-27

Chapter 6
Geometric Construction Tools

Introduction 6-2
The Gasket Design 6-2
Modeling Strategy 6-3
Starting NX 6-4
Create the Sketch of the Base Feature 6-5
Edit the Sketch by Dragging the Entities 6-7
Add Additional Constraints 6-9
First Construction Method – Trim/Extend 6-10
Create Fillets and Completing the Sketch 6-13
Complete the Extrusion Feature 6-14
Second Construction Method – Haystack Geometry 6-15
Use the NX Selection Intent Option 6-20
Create an Associative OFFSET Cut Feature 6-22
Review Questions 6-26
Exercises 6-27

Chapter 7
Parent/Child Relationships

Introduction 7-2
The U-Bracket Design 7-3

Create the Base Feature 7-4
Complete the Base Feature 7-6
The Implied Parent/Child Relationships 7-7
Create the Second Solid Feature 7-8
Fully Constrained 2D Sketch 7-10
Complete the Extrude Feature 7-11
Creating a Subtract Feature 7-12
Another Subtract Feature 7-13
Examine the Parent/Child Relationships 7-15
A Design Change 7-16
Feature Suppression 7-17
A Different Approach to the CENTER_DRILL Feature 7-19
Examine the Parent/Child Relationships 7-20
Suppress the Rect_Cut Feature 7-21
Create a Hole Feature 7-22
A Flexible Design Approach 7-23
Review Questions 7-24
Exercises 7-25

Chapter 8
Part Drawings and Associative Functionality

Drawings from Parts and Associative Functionality 8-2
Start NX 8-3
Drawing Mode - 2D Paper Space 8-3
NX Drafting Mode 8-4
Add a Base View 8-5
Drawing Display Option 8-7
Change the Size of the Drawing Sheet 8-7
Turn Off the Datum Coordinate System 8-9
Text Orientation Setup 8-10
Display Feature Dimensions 8-11
Adjust the Display of Tangency Edges 8-15
Edit the Display of Arrows on Diameter Dimensions 8-16
Hide Feature Dimensions 8-17
Unhide the Hidden Dimensions 8-18
Delete Feature Dimensions 8-19
Add Center Marks 8-20
Add Additional Dimensions – Reference Dimensions 8-21
Change the Dimension Appearance 8-22
Associative Functionality – Modifying Feature Dimensions 8-23
Review Questions 8-26
Exercises 8-27

Chapter 9
Datum Features and Auxiliary Views

Datum Features 9-2
Auxiliary Views in 2D Drawings 9-2
The Rod-Guide Design 9-2
Modeling Strategy 9-3
Start NX 9-4
Create the Base feature 9-4
Create an Angled Datum Plane 9-8
Create an Extruded Feature Using the Datum Plane 9-10
Apply Proper Constraints 9-11
Create an Offset Datum Plane 9-14
Create a Hole Feature Using the New Datum Plane 9-15
Create a Title Block Template 9-18
Use the Export File Command 9-22
Reopen the Rod Guide Design 9-23
Import the Title Block 9-24
Add a Base View 9-25
Create an Auxiliary View 9-26
Turn Off the Datum Planes and Reference Labels 9-28
Turn Off the Display Borders Option 9-29
Add another Base View 9-30
Loading the ASME Drafting Standard 9-31
Display Feature Dimensions 9-32
Delete and Add Dimensions 9-34
Review Questions 9-36
Exercises 9-37

Chapter 10
Introduction to 3D Printing

What is 3D Printing? 10-2
Development of 3D Printing Technologies 10-3
Primary types of 3D Printing processes 10-6
  Stereolithography 10-6
  Fused Deposition Modeling & Fused Filament Fabrication 10-7
  Laser Sintering / Laser Melting 10-8
Primary 3D Printing Materials for FDM and FFF 10-9
From 3D model to 3D printed Part 10-11
Start NX 10-12
Export the Design as an STL file 10-13
Using the 3D Printing software to create the 3D Print 10-14
Questions 10-21

Chapter 11
Symmetrical Features in Designs

Introduction	11-2
A Revolved Design: PULLEY	11-2
Modeling Strategy - A Revolved Design	11-3
Start NX	11-4
Create the Base Feature	11-4
Completing the Sketch and Creating the Feature	11-6
Mirroring Features	11-8
Join the Two Solid Features	11-10
Create a Pattern Leader	11-11
Circular Array	11-13
Create a New Drawing in the Drafting Mode	11-15
Import the Predefined Title Block	11-16
Create 2D Views	11-17
Add a Section View	11-18
Turn Off the Datum Features	11-20
Add Dimensions	11-21
Adjust the Display of the Views	11-23
Turn Off the Display Borders Option	11-26
Associative Functionality – A Design Change	11-27
Review Questions	11-30
Exercises	11-31

Chapter 12
Advanced 3D Construction Tools

Introduction	12-2
A Thin-Walled Design: Dryer Housing	12-2
Modeling Strategy	12-3
Start NX	12-4
Create the Base Feature	12-4
Create a Revolved Feature	12-7
Create the Dryer Handle	12-8
Create another Extruded Feature	12-10
Create 3D Rounds and Fillets	12-13
Create a Shell Feature	12-15
Create a Pattern Leader	12-16
Creating a Rectangular Array	12-19
Create a Swept Cut Feature	12-22
Define the Sweep Section	12-22
Create the Swept Feature	12-24
Review Questions	12-26
Exercises	12-27

Chapter 13
Basic Sheet Metal Designs

Sheet Metal Processes 13-2
Sheet Metal Modeling 13-4
K-Factor (Neutral Factor) 13-5
The Actuator Bracket Design 13-6
Start NX 13-7
Sheet Metal Preferences 13-8
Create the Base Feature of the Design 13-9
Create a Cut Feature with the Extrude Command 13-11
Create a Flange Feature 13-14
Confirm the Flange Location 13-16
Add another Extruded Feature 13-17
Create a Bend Feature 13-19
Create Mirrored Features 13-22
Create a 2D Sheet Metal Drawing 13-24
Import the Pre-Defined Title Block 13-25
Create 2D Views 13-26
Create the Associated Flat Pattern View 13-27
Confirm the Flattened Length 13-31
Set up Dimensions Preferences 13-33
Review Questions 13-35
Exercises 13-36

Chapter 14
Assembly Modeling - Putting It All Together

Introduction 14-2
The Shaft Support Assembly 14-2
Assembly Modeling Methodology 14-3
Additional Parts 14-4
(1) Collar 14-4
(2) Bearing 14-4
(3) Base-Plate 14-5
(4) Cap-Screw 14-5
Start NX 14-6
Loading and Placing the First Component 14-7
Place the Second Component 14-9
Degrees of Freedom 14-10
Assembly Constraints 14-12
Apply the First Assembly Constraint 14-15
Apply another Align Constraint 14-16
Constrained Move 14-17
Show Degrees of Freedom 14-19
Apply another Assembly Constraint 14-20

Placing the Third Component 14-22
Apply Assembly Constraints on Datum Planes 14-25
Assemble the First Cap-Screw 14-26
Placing the Second Cap-Screw Part 14-29
Exploded View of the Assembly 14-30
Edit the Components 14-34
Set up a Drawing of the Assembly Model 14-37
Importing the Title Block 14-37
Create a Parts List 14-39
Complete the Assembly Drawing 14-39
Summary of Modeling Considerations 14-41
Review Questions 14-42
Exercises 14-43

Chapter 15
Advanced Assembly Modeling and Animation

Introduction 15-2
NX Motion Simulation 15-2
Motion Bodies 15-3
Joint Connections 15-3
The Crank-Slider Assembly 15-6
Creating the Required Parts 15-6
(1) End Cap 15-6
(2) Connecting Rod 15-7
(3) Base Block 15-8
(4) Crank Shaft 15-9
(5) Piston 15-10
Create the Crank Slider Assembly Model 15-11
Loading and Placing the First Component 15-12
Assembling the Crank Shaft 15-14
Assembling the Connecting Rod 15-16
Complete the Assembly 15-17
Start the NX Motion Simulation Module 15-19
Defining a New Simulation 15-20
Define the Motion Bodies 15-21
Define the Joint Connections 15-23
Set up a Motion Driver for the Animation 15-30
Set up an Animation Analysis 15-31
View the Animation 15-32
Output the Animation as a Video file 15-33
Conclusion 15-34
Review Questions 15-35
Exercises 15-36

Appendix A

Index