# SOLIDWORKS® 2023 Advanced Techniques

## Mastering Parts, Surfaces, Sheet Metal, SimulationXpress, Top Down Assemblies, Core & Cavity Molds



Paul Tran CSWE, CSWI

SDC PUBLICATIONS
Better Textbooks. Lower Prices.
www.SDCpublications.com

Visit the following websites to learn more about this book:

# Table of Contents




**Introduction SOLIDWORKS 2023 User Interface** **21**
The 3 references planes 22
The toolbars 22
The system feedback symbols 24
The status bar 24
2D sketch examples 25
3D feature examples 26


## Advanced Modeling Topics




**Chapter 1 Introduction to 3D Sketch** **1-1**
Tools Needed 1-2
Creating a 3D Sketch 1-3
Completing the profile 1-4
Adding dimensions 1-5
Adding the sketch fillets 1-6
Creating the swept feature 1-7
Questions for review 1-8
Exercise: Sweep with 3D Sketch 1-9
Exercise: 3D Sketch & Planes 1-10
Exercise: 3D Sketch & Composite Curve 1-17

**Chapter 2 Plane Creation** **2-1**
**Advanced Topics** 2-1
Tools Needed 2-2
Revolving the base 2-3
Creating a tangent plane 2-4
Creating a flat surface 2-5
Extruding a cut 2-6
Creating an at-angle plane 2-7
Showing the sketches 2-8
Creating a coincident plane 2-9
Creating a parallel plane 2-10
Creating the recess feature 2-11
Creating an offset-distance plane 2-12
Creating the bore holes 2-12
Creating a perpendicular plane 2-13

Creating the side-grips 2-14
Creating a circular pattern of the grips 2-15
Creating a Mid-Plane 2-17
Adding fillets to all edges 2-19
Questions for Review 2-20
Exercise: Creating New Planes 2-22

**Chapter 3 Advanced Modeling 3-1**
**5/8" Spanner** 3-1
Tools needed 3-2
Opening the spanner sketch document 3-3
Creating the transition sketch 3-4
Creating a new work plane 3-6
Creating the closed-end sketch 3-7
Extruding the closed-end feature 3-7
Adding a 12-sided polygonal hole 3-8
Creating the recess profile 3-9
Mirroring the recessed feature 3-10
Adding fillets 3-11
Adding text 3-13
Extruding the text 3-14
Questions for Review 3-17
Exercise: Circular text wraps 3-19

**Chapter 4 Sweep with Composite Curves 4-1**
**Helical Extension Spring** 4-2
Tools needed 4-2
Converting to a helix 4-3
Creating a 2-degree plane 4-4
Sketching the large loop 4-5
Sketching the large hook 4-5
Creating a parallel plane 4-6
Creating a Composite Curve 4-8
Sweeping the profile along the path 4-11
Other spring examples 4-12
Questions for review 4-13
Exercise: Circular Spring – 180 deg. 4-14



**Using Variable Pitch 4-17**
Multi-Pitch Spring with Closed Ends 4-18
Tools Needed 4-18

Creating the base sketch 4-19
Creating a helix using variable pitch 4-19
Sweeping the profile along the path 4-21
Creating a trimmed sketch 4-22
Extruding a cut 4-22
Questions for Review 4-23
Exercise: Projected Curve & Composite Curve 4-30

**Chapter 5 Advanced Modeling with Sweep & Loft 5-1**
**Water Pump Housing** 5-2
Tools Needed 5-2
Understanding the draft options 5-3
Extruding the base with draft 5-4
Sketching the upper inlet port 5-5
Revolving the upper inlet port 5-5
Adding fillets 5-6
Creating offset-distance planes 5-7
Creating a loft feature 5-10
Creating the mounting bosses 5-11
Sketching the rear inlet port 5-12
Revolving the rear inlet port 5-12
Adding face Fillets 5-13
Mirroring the rear inlet port 5-15
Shelling the part 5-16
Adding a rib 5-17
Mirroring the rib 5-18
Adding fillets 5-19
Exercise: Loft without guide curves 5-21
Exercise: Loft with guide curves 5-23

**Chapter 6 Loft vs. Sweep 6-1**
**Water Meter Housing** 6-2
Tools Needed 6-2
Sketching the loft profile 6-3
Constructing loft profiles / features 6-5
Creating the inlet feature 6-6
Constructing the centerline parameter 6-10
Creating the outlet loft feature 6-11
Shelling the part 6-13
Extruding the left / right brackets 6-14
Constructing the upper ring 6-15



Adding fillets 6-17
Adding chamfers 6-18
Questions for Review 6-19
Exercise: Loft 6-20
Exercise: Loft vs. boundary 6-23
Exercise: Mirror using two planes 6-26
Exercise: Tangent vs. curvature 6-27

**Chapter 7 Loft with Guide Curves 7-1**



**Waved Washer** 7-2
Tools Needed 7-2
Creating the construction profile 7-3
Creating an offset distance plane 7-4
Positioning the derived sketch 7-5
Creating a curve through reference points 7-5
Sketching the loft sections 7-7
Creating the loft section using derived sketch 7-7
Creating a loft with guide curve 7-10
Hiding the construction sketches 7-11
Questions for review 7-12
Exercise: Using Curve Driven Pattern 7-13



**Advanced Sweep 7-19**
3D Sketch Sweep Path 7-20
Tools Needed 7-20
Creating the sweep path 7-21
Creating the sweep profile 7-22
Creating a sweep feature 7-23
Creating a circular Sketch pattern 7-25
Converting to construction geometry 7-26
Creating a derived sketch 7-27
Creating a 3D sketch 7-28
Creating the sweep feature 7-32
Exercise: Using Curve Through Reference Points 7-33



**Chapter 8 Using Surfaces 8-1**



**Advanced Modeling** 8-2
Tools Needed 8-2
Constructing a new work plane 8-3
Sketching the loft profiles 8-3
Creating a surface-loft 8-6

| | | |
|---|---|---|
| | Splitting the surface | 8-7 |
| | Deleting surfaces | 8-8 |
| | Thickening the surface | 8-9 |
| | Calculating the angle between the faces | 8-10 |
| | Adding a full round fillet | 8-12 |
| | Sketching the slot contours | 8-13 |
| | Extruding cut the contour | 8-15 |
| | Questions for Review | 8-17 |
| | **Lofted Surface** | **8-19** |
| | Creating new offset planes | 8-19 |
| | Sketch the first profile | 8-20 |
| | Selecting the loft profiles | 8-21 |
| | Lofting between the profiles | 8-22 |
| | Creating a revolved sketch | 8-23 |
| | Copying the revolved surface | 8-24 |
| | Trimming the base part | 8-25 |
| | Hiding the surfaces | 8-25 |
| | Patching the right side opening | 8-26 |
| | Creating a Surface-Knit | 8-29 |
| | Adding fillets | 8-30 |
| | Creating a solid from the surface model | 8-31 |
| | Removing the upper half | 8-32 |
| | Questions for Review | 8-36 |
| | Exercise: Loft & Delete Face | 8-37 |
| **Chapter 9** | **Offset Surface & Ruled Surface** | **9-1** |
| | Tools Needed | 9-2 |
| | Using offset & ruled surface options | 9-3 |
| | Creating the base loft | 9-4 |
| | Creating split lines | 9-5 |
| | Creating offset surfaces | 9-6 |
| | Creating a ruled surface | 9-7 |
| | Knitting the 2 surfaces | 9-8 |
| | Showing the solid body | 9-10 |
| | Creating the surface cut | 9-10 |
| | Exercise: Using Loft | 9-13 |
| | Exercise: Advanced Surfacing Techniques | 9-15 |
| | Exercise: Using Split | 9-25 |
| | Creating a split line | 9-25 |
| | Making an offset surface | 9-26 |
| | Adding a ruled surface | 9-26 |

Deleting a surface 9-27
Trimming surfaces 9-27
Knitting the surfaces 9-28
Adding fillets 9-29

**Chapter 10 Advanced Surfaces 10-1**
**Computer Mouse** 10-2
Tools Needed 10-2
Sketching the profiles 10-3
Extruding a surface 10-4
Trimming the surfaces 10-5
Mirroring the surfaces 10-6
Creating the lower surfaces 10-7
Creating a new plane 10-9
Making a 3-Point Arc 10-9
Creating a planar surface 10-12
Creating a knit surface 10-13

**Using Filled Surfaces 10-15**
Patch with Curvature Controls 10-16
Tools Needed 10-16
Enabling the surfaces toolbar 10-17
Creating a planar surface 10-18
Creating a surface fill with tangent control 10-18
Creating a surface fill with curvature control 10-20
Knitting all surfaces 10-21
Patch Types 10-22
Questions for Review 10-24

**Using Ruled Surface 10-25**
Creating a split line feature 10-25
Creating an offset surface 10-26
Adding a ruled surface 10-26
Knitting and cutting the surfaces 10-27
Shelling the model 10-29

**Chapter 11 Surfaces vs. Solid Modeling 11-1**
**Safety Helmet** 11-2
Tools Needed 11-2
Constructing the body of Helmet 11-3
Creating a new work plane 11-4
Sketching the sweep-profile 11-4

Creating the sweep path 11-5
Adding a planar surface 11-6
Knitting the three surface bodies into one 11-6
Creating a section view 11-7
Adding an extruded cut feature 11-7
Adding a revolve cut feature 11-9
Adding the side cut features 11-10
Creating the Cutout slot 11-11
Creating the sweep cut 11-13
Adding fillets 11-13
Exercise: Helmet_Surfaces 11-15
Exercise: Advanced Loft – Turbine Blades 11-25
Exercise: Advanced Sweep – Candle Holder 11-26
**Final Exam** **11-33**

**Chapter 12 SimulationXpress** **12-1**

**Using the Analysis Wizard** 12-2
Tools Needed 12-2
Starting SimulationXpress 12-3
Setting up the units 12-4
Adding a fixture 12-5
Applying a force 12-7
Selecting the material 12-8
Analyzing the model 12-9

Viewing the Results 12-10
Creating the report 12-12
Generating the eDrawings file 12-16
Questions for Review 12-19
Exercise 1: SimulationXpress: Force 12-20
Exercise 2: SimulationXpress: Pressure 12-21



SOLIDWORKS FlowXpress: Using the Flow Wizard 12-23


# Sheet Metal Topics


**Chapter 13 Sheet Metal Parts** **13-1**
**Post Cap** 13-2
Tools Needed 13-2
Starting with the Base Profile 13-3
Extruding the Base Flange 13-3
Creating an Edge Flange 13-4




Editing the Edge Flange Profile 13-5
Viewing the Flat Pattern 13-6
Changing the Fixed Face 13-6
Creating a Sketch Bend 13-7
Adding Holes 13-9
Switching to the Flat Pattern 13-12
Using Sheet Metal Costing 13-13
Inputting the information 13-14
Setting the Baseline 13-15
Questions for Review 13-17





**Vents** **13-18**
Tools Needed 13-19
Sketching the first profile 13-20
Extruding the Base-Flange 13-21
Creating the Miter-Flanges 13-22
Flattening the Part 13-24





Creating a new Forming Tool 13-25
Other Rectangle Options 13-26
Extruding the Base 13-27
Building the louver body 13-27
Creating the Positioning Sketch 13-31
Saving the Form Tool 13-33
Applying the Form Tool 13-34
Positioning the Form Tool 13-35





Adding a mounting hole 13-36
Creating a Linear Pattern 13-37
Creating an Axis 13-38
Creating a Circular Pattern 13-39
Questions for Review 13-40

**Chapter 14 Sheet Metal Forming Tools** **14-1**
**Button with Slots** 14-2
Tools Needed 14-2





Creating the Base Block 14-3
Revolving the Body 14-4
Sketching Slot Profiles 14-5
Creating the Split Lines 14-7
Adding more fillets 14-9
Inserting the forming tool feature 14-9
Saving the forming tool 14-10
Questions for Review 14-12



**Designing Sheet Metal Parts – Tool Holder** **14-13**
Tools Needed 14-14
Starting with the Base Sketch 14-15
Creating an Edge Flange 14-16
Adding Cut features 14-17
Extruding a cut 14-17
Using the Unfold Command 14-18
Using the Fold Command 14-20
Inserting a Sheet Metal Forming Tool 14-23
Locating the Bridge Lance 14-25
Creating the Linear Pattern of the Bridge Lance 14-26
Mirroring the Body 14-27
Adding Chamfers 14-30
Switching to the Flat Pattern 14-31
Questions for Review 14-32



**Chapter 15 Sheet Metal Conversions** **15-1**
**From IGES to SOLIDWORKS – Flat Pattern** 15-2
Tools Needed 15-2
Opening an IGES Document 15-3
Creating the Rips 15-4
Inserting the Sheet Metal Parameters 15-5
Adding Fillets 15-6
Switching to a Flat Pattern 15-7
Questions for Review 15-8

**Sheet Metal Gussets** **15-9**
Opening a sheet metal part document 15-9
Creating a gusset 15-9
Viewing the resulted gusset 15-11
Mirroring the gusset 15-12
Exercise: Hem & Vent Features 15-13



**Flat Pattern Stent** **15-16**
Tools Needed 15-17
Converting to Sheet Metal 15-19
Unfolding the Part 15-19
Adding the Sketch Pattern 15-20
Folding the Part 15-22
Creating a new Configuration 15-23
Adding Fillets 15-23
Switching to Flatten Mode 15-24
Questions for Review 15-25

Exercise: Screen Mesh - Sheet Metal Approach 15-26

**Chapter 16 Working with Sheet Metal STEP Files 16-1**



Tools Needed 16-2
Opening an Assembly Step File 16-3
Mating the components 16-4
Adding the Sheet Metal tool tab 16-7
Inserting Sheet Metal parameters 16-8
Viewing the Flat Pattern 16-9
Converting other components 16-9
Using the Hole Series 16-11
Using the Hole Wizard 16-13
Adding the Smart Fasteners 16-15
Creating an Exploded View 16-17

**Adding Parts to the Toolbox Library 16-18**

Starting the Toolbox Settings Utility 16-18
Activating Toolbox 16-21
Locating the new part 16-22
Viewing the new part 16-22
Adding a Part Number and Description 16-23
Sheet Metal-Enclosure Assembly 16-24

**Chapter 17 Advanced Weldments 17-1**

**Weldments Platform** 17-2



Tools Needed 17-2
Adding the weldments toolbar 17-3
Adding the structural members 17-4
Viewing the overlapped areas 17-8
Trimming the overlapped areas 17-9
Updating the cut list 17-12

**Using Weldments – Structural Members 17-14**



Enabling the Weldment Toolbar 17-14
Adding Structural Members 17-15
Setting the Corner Treatments 17-15
Adding Structural Members to Contiguous Groups 17-16
Adding Structural Members to the Parallel Groups 17-17
Trimming the Structural Members 17-19
Adding the foot pads 17-26
Adding the Gussets 17-27
Adding the Fillet Beads 17-29
Viewing the Weldment Cut List 17-31

Updating the Cut List 17-32
Creating a drawing 17-33

# Mold Tools Design Topics

**Chapter 18 Creating a Core and Cavity 18-1**
Linear Parting Lines 18-2
Tools Needed 18-2
Opening an existing Parasolid document 18-3
Creating the Parting Lines 18-4
Creating the Shut-Off Surfaces 18-5
Creating the Parting Surfaces 18-6
Sketching the profile of the mold blocks 18-7
Creating the Tooling Split 18-8
Saving the bodies as part files 18-10
Separating the 2 blocks 18-11
Exercise: Linear Parting Lines 18-13
Questions for Review 18-19



**Chapter 19 Non-Planar Parting Lines 19-1**
**Mold-Tooling Design** 19-2
Tools Needed 19-2
Enabling the Mold Tools toolbar 19-3
Creating the Parting Lines 19-4
Creating the Shut-Off Surfaces 19-5
Creating the Parting Surfaces 19-6
Creating a Ruled Surface 19-7
Creating the patches 19-9
Knitting the surfaces 19-13
Trimming the bottom of the ruled surface 19-15
Creating the Tooling Split sketch 19-16
Separating the solid bodies 19-18
Making the body transparent 19-19



**Creating Slides and Cores 19-21**
Tools Needed 19-22
Opening a part document 19-23
Analyzing the undercuts 19-23
Analysis parameters explained 19-24
Scaling the part 19-25
Creating the parting lines 19-26
Creating the parting surfaces 19-27

| | | |
|---|---|---|
| | Creating a new sketch | 19-28 |
| | Creating the tooling split | 19-29 |
| | Finalizing the block sizes | 19-29 |
| | Renaming the bodies and assigning materials | 19-32 |
| | Creating the front slide core | 19-32 |
| | Creating the back slide core | 19-34 |
| | Creating an exploded view | 19-35 |
| **Chapter 20** | **Top Down Assembly – Part 1** | **20-1** |
| | **Miniature Vise** | 20-2 |
| | Tools Needed | 20-2 |
| | Creating the Base part | 20-3 |
| | Adding the side flanges | 20-5 |
| | Creating an offset distance plane | 20-7 |
| | Creating the 3D Guide Curves | 20-9 |
| | Creating the fixed jaw clamp | 20-11 |
| | Creating a new component: The slide jaw | 20-14 |
| | Using the offset entities command | 20-15 |
| | Sketching the Guide Curve | 20-20 |
| | Creating the clamp block | 20-22 |
| | Extruding the clamp block | 20-23 |
| | Creating the Internal threads | 20-26 |
| | Creating a Section View | 20-29 |
| | Questions for Review | 20-32 |
| **Chapter 21** | **Top-Down Assembly – Part 2** | **21-1** |
| | **Water Control Valve** | 21-2 |
| | Tools Needed | 21-2 |
| | Starting a New Assembly Template | 21-3 |
| | Creating the 1st Component | 21-4 |
| | Adding the Inlet Flange | 21-5 |
| | Adding the Mounting Holes | 21-6 |
| | Adding Chamfers and Fillets | 21-8 |
| | Saving as Virtual Component | 21-10 |
| | Creating the 2nd Component | 21-10 |
| | Creating the Transition Body | 21-12 |
| | Adding another mounting Flange | 21-13 |
| | Adding an Offset-Distance plane | 21-14 |
| | Exiting the Edit Component Mode | 21-20 |
| | Applying dimension changes | 21-20 |
| | Viewing the External Reference Symbols | 21-22 |
| | Inserting other components | 21-23 |
| | Questions for Review | 21-25 |






**Chapter 22 External References & Repair Errors 22-1**
External Reference Symbols 22-2
Understanding & Removing External References 22-3
Removing External References 22-3
Understanding the External Symbols 22-4
Repairing the Sketches 22-5
Rebuilding the model 22-7
Questions for Review 22-8
Understanding and Repairing Part Errors 22-9
Repair Errors & External References 22-16

**Final Exam_1 of 2_Handle Mold 22-24**
**Final Exam_2 of 2_Mouse Mold 22-28**

**Chapter 23 Using Appearances 23-1**
Modeling diamond knurls 23-1
Applying the knurl appearance 23-5
Applying wire mesh appearance 23-8
Applying the Car-Paint Appearance 23-11
Flatten Surfaces 23-16
Exercise: Flattening a shoe sole 23-20

**Certification Practice for the CSWP Mechanical Design Exam 24-1**
Challenge I: Part Modeling & Modifications 24-2
Challenge II: Part Modifications & Configurations 24-18
Challenge III: Bottom Up Assembly & Mates 24-39

**Glossary, Index, and SOLIDWORKS 2023 Quick-Guide**
Quick Reference Guide to SOLIDWORKS 2023 Command Icons and Toolbars.