The Complete Guide to

Mold Making with SOLIDWORKS® 2026

Basic through Advanced Techniques



Paul Tran CSWE, CSWI

SDC PUBLICATIONS

Better Textbooks. Lower Prices.

www.SDCpublications.com

Visit the following websites to learn more about this book:

TABLE OF CONTENTS

Basic Through Advanced Mold Making Using SolidWorks

Chapter 1: Plastic part designs 1 1-1

Remote Control 1-1
Starting a new part document 1-1
Creating the parent sketch 1-1
Extruding the main body 1-2
Making the upper curved cut 1-2
Adding fillets 1-3
Shelling the part 1-4
Making the recess sketch 1-5
Creating the recess cut 1-6
Copying a sketch 1-7
Creating the mounting bosses 1-8
Adding the support ribs 1-9
Adding the mounting holes 1-10
Adding fillets to the rib 1-11
Assigning material 1-12
Changing the part color 1-13
Calculating the mass 1-14



Creating the core and cavity molds 1-15
Applying the scale factor 1-15
Creating the parting lines 1-15
Creating the shut-off surfaces 1-16
Creating the parting surfaces 1-17
Adding a reference plane 1-18
Inserting a tooling split 1-19
Separating the mold blocks 1-20
Hiding the references 1-21
Assigning material to the mold blocks 1-22
Exercise - Plastic part design 2 1-23

Chapter 2: Surface Repair 2-1

Surface Repair – Mouse **2-1**
Opening a parasolid document 2-1
Running Import Diagnostics 2-1
Examining the small surfaces 2-2
Deleting surfaces 2-3
Deleting hole 2-3
Patching the openings 2-4
Adding draft 2-5

Creating a split line feature 2-6
Creating a face fillet 2-7
Adding thickness 2-8
Creating a recess cut 2-9
Saving your work 2-10
Exercise: Repair surfaces 2-11

Chapter 3: Core and Cavity Creation 3-1



Core and Cavity – Plastic Tray **3-1**
Opening a part document 3-1
Applying the scale factor 3-1
Creating the parting lines 3-2
Creating the parting surfaces 3-3
Making the mold block sketch 3-4
Creating a tooling split feature 3-5
Hiding the references 3-6
Assigning materials 3-7
Changing the transparency 3-7
Separating the mold blocks 3-8
Saving your work 3-9



Exercise: Creating a core and cavity mold **3-11**
Opening a part document 3-11
Applying the scale 3-11
Creating the parting lines 3-12
Creating the shut-off surfaces 3-13
Creating the Parting surfaces 3-14
Adding a new plane 3-15
Sketching the profile of the mold block 3-15
Inserting a Tooling split feature 3-16

Separating the mold blocks 3-17
Saving your work 3-17
Exercise: Computer Mouse Housing Core and Cavity Molds 3-18

Chapter 4: Planar Parting Lines 4-1



Planar Parting Lines – Drone's Canopy 4-1
Opening a part document 4-1
Scaling the part 4-1
Creating the parting lines 4-2
Creating the parting surfaces 4-3
Making the mold block sketch 4-4
Adding the move/copy command 4-5
Separating the mold blocks 4-6
Hiding the references 4-7
Renaming the mold blocks 4-8
Assigning the materials 4-8
Switching to transparency 4-9
Saving your work 4-9



Exercise: Planar Parting Lines Drone Cover Housing 4-11
Opening a part document 4-11
Scaling the part 4-11
Creating the parting lines 4-12
Creating the parting surfaces 4-13
Adding a new plane 4-14
Making the mold block sketch 4-15
Inserting a tooling split 4-15
Changing materials 4-16
Saving your work 4-16
Exercise: Crank cover Core & Cavity molds 4-17

Chapter 5: Interlock Surface 5-1



Interlock Surface 1: Stabilizer 5-1
Opening a part document 5-1
Applying the scale factor 5-1
Creating the parting lines 5-2
Creating the parting surfaces 5-3
Making the mold block sketch 5-4
Hiding the references 5-5

Separating the mold blocks 5-6
Changing the transparency 5-7
Saving your work 5-8



Exercise: Interlock Surface 2 - Plastic Cap 5-9
Opening a part document 5-9
Applying the scale factor 5-9
Creating the parting lines 5-10
Adding the shut-off surfaces 5-11
Creating the parting surface 5-12
Adding a new plane 5-13
Making the mold block sketch 5-13
Creating a tooling split feature 5-14
Separating the mold blocks 5-15
Renaming the solid bodies 5-17
Assigning materials 5-17
Changing the transparency 5-18



Exercise: Interlock Surface 3 - Round Knob 5-19
Opening a part document 5-19
Applying the scale factor 5-19
Creating the parting lines 5-20
Creating the parting surfaces 5-21
Adding a new plane 5-22
Making the sketch of the mold block 5-22
Inserting a tooling split feature 5-23
Assigning materials 5-24
Saving your work 5-24

Chapter 6: Non-Planar Parting Lines 6-1

Non-Planar parting Lines – Fan Cover 6-1
Opening a part document 6-1
Applying the scale factor 6-1
Creating the parting lines 6-2
Creating the shut-off surfaces 6-3
Creating the parting surfaces 6-4
Adding a new plane 6-4
Sketching the mold block profile 6-5
Splitting the mold blocks 6-5
Hiding the references 6-6
Separating the mold blocks 6-7



Changing the transparency 6-8
Changing the materials 6-9
Saving your work 6-9

Exercise: Non-Planar Parting Lines 6-11
Meter Reader Upper Housing
Opening a part document 6-11
Applying the scale factor 6-11
Creating the parting lines 6-12
Creating the parting surfaces 6-13
Adding the ruled surfaces 6-14
Closing off the left end 6-15
Extending the lofted surface 6-15
Trimming the left end 6-16
Closing off the right end 6-17
Extending the lofted and ruled surfaces 6-18
Trimming the right end 6-19
Knitting all surfaces 6-20
Creating the shut-off surfaces 6-21
Adding a new plane 6-21
Inserting a tooling split feature 6-22
Separating the mold blocks 6-23
Changing materials 6-24
Saving your work 6-24



Chapter 7: Manual Parting Lines 7-1

Manual Parting Lines - Heat Shield 7-1
Open a part document 7-1
Applying the scale factor 7-1
Creating the parting lines 7-2
Creating the shut-off surfaces 7-3
Creating the parting surfaces 7-4
Deleting the surfaces 7-5
Creating the ruled surfaces 7-6
Trimming with a sketch 7-7
Making a 3D sketch 7-8
Creating the 1st corner patch 7-9
Patching other corners 7-10
Knitting the surfaces 7-11
Adding a reference plane 7-12
Creating a tooling split 7-13



Separating the mold blocks 7-14
Hiding the references 7-15
Changing the transparency 7-16
Exercise: Interlock Surface Alternatives 7-17

Chapter 8: Undercuts and Slide Cores 8-1



Stress Gauge Upper Housing 8-1
Opening a part document 8-1
Applying the scale factor 8-1
Creating the parting lines 8-2
Adding the shut-off surfaces 8-3
Creating the parting surfaces 8-4
Making the mold block sketch 8-5
Analyzing the undercuts 8-6
Sketching the slide core profile 8-7
Extruding the slide core block 8-8



Separating the mold blocks 8-9
Moving the slide core block 8-10
Hiding the references 8-11
Changing the transparency 8-12
Exercise: Creating the slide cores 8-13
Exercise: Multi-Cavity molds 8-17

Chapter 9: Alternative Methods 9-1



Using Combine Subtract – Rocker Arm 9-1
Opening a part document 9-1
Applying the scale factor 9-1
Making the mold block sketch 9-2
Extruding the mold block 9-2
Creating a combine subtract feature 9-3
Splitting a solid body 9-4
Rotating a solid body 9-5

Using Cut with Surface – Rocker Arm 9-6
Opening a part document 9-6
Isolating a surface body 9-6
Making the mold block sketch 9-7
Converting the planar sketch 9-8
Trimming the surfaces 9-9
Knitting the surfaces 9-10

Sketching the profile of the mold block 9-11
Cutting with a surface 9-12
Moving a solid body 9-13
Saving your work 9-13

Using Cavity in Assembly – Rocker Arm 9-14
Opening an assembly document 9-14
Inserting the engineered part 9-14
Editing a component 9-15
Inserting a cavity feature 9-15
Creating an exploded view 9-16
Saving your work 9-17
Exercise: Plastic handle 9-18



Chapter 10: Thickness Analysis 10-1

Thickness Analysis – Medication Upper Case 10-1
Open a part document 10-1
Setting the parameters 10-1
Analyzing the thickness 10-2
Creating a section view 10-3
Re-arranging the shell feature 10-4
Scaling the part 10-5
Creating the parting lines 10-5
Creating the parting surfaces 10-6
Adding a new plane 10-7
Making the mold block sketch 10-7
Extruding the mold blocks 10-8
Hiding the references 10-9
Separating the mold blocks 10-10
Changing the transparency 10-11
Saving your work 10-11



Chapter 11: Using SOLIDWORKS Plastics 11-1

Plastics Analysis– Basin 11-1
Open a part document 11-1
Enabling SOLIDWORKS Plastics 11-1
Creating a new study 11-2
Assigning material 11-3
Specifying the injection location 11-4
Creating a shell mesh 11-5



Running the flow analysis 11-6
Viewing the flow results 11-7
Viewing the report text file 11-9
Saving your work 11-10

Chapter 12: Using Plastics Flow Simulation 12-1

Plastics – Flow Simulation Analysis 12-1
Opening a part document 12-1
Enabling Plastics 12-1
Setting up the mesh 12-2
Viewing the PlasticsManager tree 12-2
Selecting a polymer 12-3
Adding an injection location 12-4
Creating a mesh 12-5
Running the flow analysis 12-6
Viewing the fill-time plot 12-7
Animating the results 12-8
Displaying the weld lines 12-9
Viewing the results 12-10

Model Library

Glossary and Index

SOLIDWORKS 2026 Quick-Guides:

Quick Reference Guide to SOLIDWORKS 2026 Command Icons and Toolbars.