


Parametric Modeling

With

I-DEAS 12[®]



Randy H. Shih
Oregon Institute of Technology

SDC
PUBLICATIONS

Schroff Development Corporation

www.schroff.com
www.schroff-europe.com

Table of Contents

Preface

Acknowledgments

Chapter 1

Introduction

Introduction	1-2
Development of Computer Geometric Modeling	1-2
Feature-Based Parametric Modeling	1-6
Getting Started with I-DEAS	1-7
I-DEAS Data Management Concepts	1-7
Model Files	1-8
Libraries	1-8
Catalogs	1-8
Starting I-DEAS	1-9
Project Name	1-9
Model File Name	1-10
Application Menu	1-10
Task Menu	1-10
I-DEAS Screen Layout	1-11
Mouse Buttons	1-12
Icon Panel	1-13
Top Menu Bars	1-13
Task and Application Specific Icon Panel	1-13
Display Icon Panel	1-14
Prompts	1-14
Quick Help	1-14
Icon Operation	1-15
Leaving I-DEAS	1-15

Chapter 2

Parametric Modeling Fundamentals

Introduction	2-2
The <i>L-Bracket</i> Design	2-2
Starting I-DEAS	2-3
Units Setup	2-4
Creating Rough Sketches	2-5
Step 1: Creating a rough sketch	2-6
Graphics Cursors	2-7
Dynamic Navigator	2-7

Dynamic Viewing Functions	2-10
Panning – [F1] and the Mouse	2-10
Zooming – [F2] and the mouse	2-10
Basic Editing – Using the Eraser	2-11
Creating a Single Line	2-12
Consideration of Design Intent	2-13
Step 2: Apply/Delete/Modify constraints and dimensions	2-14
Creating desired Dimensions	2-15
Modifying Dimensional Values	2-16
Pre-selection of Entities	2-18
Changing the Appearance of Dimensions	2-20
Repositioning Dimensions	2-21
Step 3: Completing the Base Solid Feature	2-22
Display Viewing Commands	2-23
Display Icon Panel	2-23
View icons	2-24
Shaded Solids	2-24
Hidden-line Removal	2-25
Wireframe Image	2-25
Redisplay & Refresh	2-25
Zoom-All	2-25
Zoom-In	2-25
Workplane – It is an XY CRT, but an XYZ World	2-26
Workplane Appearance	2-27
Step 4: Adding additional features	2-29
Sketch In Place	2-29
Step 4-1: Adding an extruded feature	2-30
Step 4-2: Adding a cut feature	2-34
Extrusion – Cut option	2-36
Saving the Part and Exit I-DEAS	2-37
Questions	2-38
Exercises	2-39

Chapter 3

Constructive Solid Geometry Concept

Introduction	3-2
Binary Tree	3-3
The Locator Design	3-4
Starting I-DEAS	3-5
The CSG Binary Tree of the Locator Design	3-6
Units Setup	3-7
Base Feature	3-7
Modifying the Size of the Rectangle	3-8
Completing the Base Solid Feature	3-9

Creating the next solid feature	3-10
Creating a Cut feature	3-13
The second CUT feature	3-16
The Third <i>CUT</i> Feature	3-18
Save the Part and Exit I-DEAS	3-20
Questions	3-21
Exercises	3-22

Chapter 4

Model History Tree and the BORN Technique

Introduction	4-2
The BORN technique	4-3
The Saddle Bracket Design	4-4
Modeling Strategy	4-5
Starting I-DEAS	4-6
Applying the BORN Technique using the Create Part option	4-7
Base Feature	4-8
Modifying Dimensional Values	4-9
Extrusion	4-10
Add Additional Features	4-12
Examining the History Tree	4-15
History Access Window	4-16
Rectangular Cut feature	4-18
Adding a Location Dimension	4-19
Modify Dimensions	4-20
Extrude – <i>Until Next</i> Option	4-20
Create the next Cut Feature	4-23
Examining the History Tree	4-26
History-based Part Modifications	4-27
A Design Change	4-29
Questions	4-34
Exercises	4-35

Chapter 5

Parametric Modeling Fundamentals

CONSTRAINTS and RELATIONS	5-2
Create Simple plate Designs	5-2
Starting I-DEAS	5-3
Automatic Application of Constraints – The Dynamic Navigator	5-3
Constrain and Dimension Options	5-6
Importance of Fully Constrained Geometry	5-8
Deleting Geometric Constraints	5-8

Adding Dimensional Constraints	5-9
Adding Geometric Constraints Manually	5-9
Over-constraining and Reference Dimensions	5-12
Adding Additional Geometry and Constraints	5-13
Opening a New Model File	5-16
Applying the BORN Technique	5-16
Creating the 2D sketch	5-17
Modifying Dimensional Values	5-20
Dimensional Values and Dimensional Variables	5-21
Additional Parametric Relations	5-23
Adjusting the control dimensions	5-25
Questions	5-26
Exercises	5-27

Chapter 6

Geometric Construction Tools

Introduction	6-2
The Gasket Design	6-2
Modeling Strategy	6-3
Starting I-DEAS	6-4
Applying the BORN Technique	6-4
Sketching with the Focus option	6-5
Using the <i>Trim/Extend</i> Command	6-8
Examining and Adding necessary Constraints	6-10
Modifying Dimensional Values	6-12
Making a Copy of the Sketch using the Move Command	6-13
First Construction Method – Trim/Extend	6-15
Creating 2-D Fillets	6-17
Second Construction Method – Haystack Geometry	6-18
Creating Additional 2-D Fillets on the Section	6-20
Extrusion	6-21
Create an Offset Feature	6-22
Completing the CUT feature	6-24
Questions	6-26
Exercises	6-27

Chapter 7

3-D Annotation and Associated Drawings

3D Annotation and 2D Drawings from 3D Parts	7-2
Changing the Color of the 3D Model	7-3
3D Annotation – Linear Dimension	7-4
Changing the Appearance of Dimensions	7-8

Adding Additional 3D Annotation	7-10
First Method - Model Views	7-13
Display Filter	7-15
Second Method - Multiple Viewports	7-16
The I-DEAS Master Drafting Application	7-19
Repositioning the Work View	7-22
Hiding View Borders and View Names	7-23
Hiding Dimensions and Projected Entities	7-24
Adding Centerlines	7-25
Adding Additional Reference Dimensions	7-27
Changing the Displayed Hidden Line Style	7-28
Associative Functionality - Modifying the Solid Model	7-29
Printing the 2D Drawing	7-32
Questions	7-33
Exercises	7-34

Chapter 8

Symmetrical Features in Designs

Introduction	8-2
A Symmetrical Design: PULLEY	8-2
Modeling Strategy - A Symmetrical Design	8-3
Starting Up I-DEAS	8-4
Applying the BORN Technique	8-5
Creating the Base Feature	8-6
Creating a Revolved Feature	8-8
Mirroring Features	8-9
Creating an Extruded Feature as a Pattern Leader	8-10
Circular Pattern	8-12
Creating a Template Title Block	8-14
Adding 2D Views	8-18
Add a Section View	8-21
Resizing the Views and Completing the Drawing	8-22
Questions	8-23
Exercises	8-24

Chapter 9

Feature interactions and Reference Geometry

Reference Geometry	9-2
The Guide Block Design	9-2
Modeling Strategy	9-3
Starting I-DEAS	9-4

Applying the BORN Technique	9-5
Base Feature	9-6
Create a Reference Plane	9-10
Creating a 2-D Sketch on the Reference Plane	9-11
Modifying Dimensions	9-12
Making the First Cut Feature	9-13
Second Cut – Without Creating a New Reference Plane	9-14
Completing the Second Cut	9-15
Third Cut – Using A New Reference Plane	9-16
Parametric Relations	9-19
Completing the Third Cut	9-20
Creating a Drill-Hole Using the REVOLVE Command	9-21
Parametric Relations	9-22
Completing the Revolved Cut	9-23
A Drill Through Hole	9-24
A Design Change	9-26
Questions	9-27
Exercises	9-28

Chapter 10

Three-Dimensional Construction Tools

Introduction	10-2
A Thin-walled Design: OIL PAN	10-2
Modeling Strategy	10-3
Starting Up I-DEAS	10-4
Applying the BORN Technique	10-5
The Base Feature	10-6
Create an OFFSET Feature	10-8
Extrude using the Draft Angle option	10-10
Extract Section	10-11
Put Away the solid object	10-12
Modify the Extracted Geometry	10-12
Retrieve the solid object from the BIN	10-14
Create the next Extrusion	10-15
Creating 3-D Rounds and Fillets	10-16
Creating 3-D Fillets - Edge Chain option	10-17
The Shell Feature	10-18
Changing the Color of the 3-D Model	10-19
Creating a Rectangular Pattern	10-20
Creating Another Rectangular Pattern	10-22
Questions	10-24
Exercises	10-25

Chapter 11

Part Modeling - Finishing Touches

Introduction	11-2
Summary of Modeling Considerations	11-2
The BRACKET Design	11-2
Modeling Strategy	11-3
Start Up I-DEAS	11-4
Applying the BORN Technique	11-5
The Base Feature	11-6
Creating the Second feature	11-9
Create a 2-D Sketch on the XY-plane	11-14
Create a Cylindrical Feature	11-17
Create a Hole through the Cylinder	11-19
Create Holes on the Base Feature	11-20
Adding 3-D Rounds and Fillets	11-22
Creating Chamfers	11-24
Questions	11-26
Exercises	11-27

Chapter 12

Assembly Modeling - Putting It All Together

Introduction	12-2
The <i>BRACKET</i> Assembly	12-2
Assembly Modeling Methodology	12-3
The Bottom Up approach	12-3
The Top Down approach	12-3
The Middle Out approach	12-3
Additional Parts	12-4
(1) Base Plate	12-4
Starting <i>I-DEAS</i>	12-4
Creating the Base-Plate part	12-5
(2) Bushing	12-7
(3) Cap Screw	12-7
Retrieve the Models from the BIN	12-8
The I-DEAS Master Assembly Application	12-9
Acquiring parts from the model file and establish an hierarchy	12-10
Placing the First Component in the Assembly model	12-11
Assembly Constraints	12-12
Degrees of Freedom and Constraints	12-14
Fully Constrained Component	12-17
Placing the Bushing	12-18
Changing the Orientation the Bushing Part	12-19
Locking the Bushing part	12-21

Adjusting the Orientation of the Cap-Screw	12-22
Assemble the Cap-Screw	12-23
Duplicating an instance	12-26
Exploded View of the Assembly	12-27
Conclusion	12-28
Questions	12-29
Exercise	12-30
1. Base Plate	12-31
2. Sliding Block	12-31
3. Lifting Block	12-32
4. Adjusting Screw	12-32

Index