
Parametric Modeling with UGS NX 6



Randy H. Shih Oregon Institute of Technology



Schroff Development Corporation www.schroff.com

Better Textbooks. Lower Prices.

Table of Contents

Preface Acknowledgments

Chapter 1 Introduction - Getting Started

Introduction	1-2
Development of Computer Geometric Modeling	1-2
Feature-Based Parametric Modeling	1-6
Getting Started with UGS NX 6	1-7
The UGS NX Main Window	1-8
UGS NX 6 Screen Layout	1-10
Pull-down Menus	1-11
Standard Toolbar	1-11
View Toolbar	1-11
Utility Toolbar	1-11
Additional Tools	1-11
Selection Toolbar	1-12
Message and Status Bar	1-12
Resource Bar	1-12
Mouse Buttons	1-13
[Esc] - Canceling commands	1-14
On-Line Help	1-14
Leaving UGS NX 6	1-14
Creating a CAD files folder	1-15

Chapter 2 Parametric Modeling Fundamentals

2-2
2-3
2-3
2-5
2-6
2-7
2-9
2-10
2-11
2-12
2-17
2-18
2-19

Dynamic Viewing – Icons, Mouse buttons and Quick keys	2-20
Display Modes	2-22
Step 6-1: Adding an extruded feature	2-23
Step 6-2: Adding a cut feature	2-28
Save the Model and Exit UGS NX	2-32
Questions	2-33
Exercises	2-34

Chapter 3 Constructive Solid Geometry Concepts

Introduction	3-2
Binary Tree	3-3
The Locator Design	3-4
Modeling Strategy - CSG Binary Tree	3-5
Starting UGS NX	3-6
Base Feature	3-7
Work plane GRID Display Setup	3-9
Completing the Base Solid Feature	3-11
Creating the next solid feature	3-12
Creating a CUT Feature	3-15
Creating a PLACED FEATURE	3-18
Creating a Rectangular Cut Feature	3-21
Questions	3-24
Exercises	3-25

Chapter 4 Model History Tree

Introduction	4-2
The Saddle Bracket Design	4-3
Starting UGS NX 6	4-3
Modeling Strategy	4-4
Creating the Base Feature	4-7
The UGS NX Part Navigator	4-9
Creating the Second Solid Feature	4-10
Using More Meaningful Feature Names	4-14
Adjusting the Width of the Base Feature	4-15
Adding a Placed Feature	4-17
Creating a Rectangular Cut Feature	4-19
History-based Part Modifications	4-23
A Design change	4-24
Assigning and Calculating the associated Physical Properties	4-26
Questions	4-29
Exercises	4-30

Chapter 5 Parametric Constraints Fundamentals

The BORN Technique	5-2
CONSTRAINTS and RELATIONS	5-2
Fully Constrained Geometry	5-3
Create a Simple Triangular Plate Design	5-3
Starting UGS NX 6	5-4
Displaying existing constraints	5-7
Applying Geometric Constraints implicitly	5-9
Applying Geometric Constraints Explicitly	5-10
Adding Dimensional Constraints	5-12
A Fully Constrained Sketch	5-14
Over-constraining 2D sketches	5-16
Deleting existing constraints and Dimensions	5-18
2D Sketches with Multiple Loops	5-21
Inferred Constraint Settings	5-23
Parametric relations	5-24
Dimensional Values and Dimensional Variables	5-25
Questions	5-27
Exercises	5-28

Chapter 6 Geometric Construction Tools

Introduction	6-2
The Gasket Design	6-2
Modeling Strategy	6-3
Starting UGS NX 6	6-4
Editing the Sketch by Dragging the Entities	6-7
Adding Additional Constraints	6-9
First Construction Method – Trim/Extend	6-10
Creating Fillets and Completing the Sketch	6-13
Completing the Extrusion Feature	6-14
Second Construction Method – Haystack Geometry	6-15
Using the UGS NX Selection Intent option	6-18
Create an Associative OFFSET Cut Feature	6-19
Questions	6-23
Exercises	6-24

Chapter 7 Parent/Child Relationships

Introduction	7-2
The U-Bracket Design	7-3
Creating the base feature	7-4
Completing the Base feature	7-7
The Implied Parent/Child Relationships	7-8
Creating the Second Solid Feature	7-9
Fully Constraining the Sketch	7-11
Completing the Extrude Feature	7-13
Creating A Subtract Feature	7-14
Another Subtract Feature	7-15
Examining the Parent/Child Relationships	7-16
A Design Change	7-17
Feature Suppression	7-18
A different approach to the CENTER DRILL feature	7-20
Examining the Parent/Child Relationships	7-22
Suppress the Rect Cut feature	7-23
Creating a Hole Feature	7-24
A Flexible Design Approach	7-26
Questions	7-27
Exercises	7-28

Chapter 8 Part Drawings and Associative Functionality

Starting UGS NX 68-3Drawing Mode - 2D Paper Space8-3UGS NX Drafting Mode8-4Adding a Base View8-5Drawing Display Option8-7Changing the Size of the Drawing Sheet8-7Turning Off the Datum Planes and WCS8-9Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25Exercises8-26	Drawings from Parts and Associative Functionality	8-2
UGS NX Drafting Mode8-4Adding a Base View8-5Drawing Display Option8-7Changing the Size of the Drawing Sheet8-7Turning Off the Datum Planes and WCS8-9Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Starting UGS NX 6	8-3
Adding a Base View8-5Drawing Display Option8-7Changing the Size of the Drawing Sheet8-7Turning Off the Datum Planes and WCS8-9Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Drawing Mode - 2D Paper Space	8-3
Drawing Display Option8-7Drawing Display Option8-7Changing the Size of the Drawing Sheet8-7Turning Off the Datum Planes and WCS8-9Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	UGS NX Drafting Mode	8-4
Changing the Size of the Drawing Sheet8-7Turning Off the Datum Planes and WCS8-9Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Adding a Base View	8-5
Turning Off the Datum Planes and WCS8-9Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Drawing Display Option	8-7
Displaying Feature Dimensions8-11Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Changing the Size of the Drawing Sheet	8-7
Adjusting the display of Tangency Edges8-14Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Turning Off the Datum Planes and WCS	8-9
Hiding Feature Dimensions8-15Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Displaying Feature Dimensions	8-11
Showing the Hidden Dimensions8-16Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Adjusting the display of Tangency Edges	8-14
Deleting Feature Dimensions8-17Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Hiding Feature Dimensions	8-15
Adding Center Marks and Center Lines8-18Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Showing the Hidden Dimensions	8-16
Adding Additional Dimensions – Reference Dimensions8-19Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Deleting Feature Dimensions	8-17
Changing the Dimension Appearance8-20Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Adding Center Marks and Center Lines	8-18
Associative Functionality – Modifying Feature Dimensions8-22Questions8-25	Adding Additional Dimensions – Reference Dimensions	8-19
Questions 8-25	Changing the Dimension Appearance	8-20
	Associative Functionality – Modifying Feature Dimensions	8-22
Exercises 8-26	Questions	8-25
	Exercises	8-26

Chapter 9 Datum Features and Auxiliary Views

Datum Features	9-2
Auxiliary Views in 2D Drawings	9-2
The Rod-Guide Design	9-2
Modeling Strategy	9-3
Starting UGS NX	9-4
Creating the Base feature	9-5
Creating Datum Axes and an Angled Datum Plane	9-8
Creating an Extruded Feature using the Datum Plane	9-10
Apply Proper Constraints	9-11
Creating an Offset Datum Plane	9-14
Creating another cut feature using the new datum plane	9-15
Creating a Title Block Template	9-17
Using the Export File command	9-21
Reopen the Rod Guide Design	9-22
Importing the Title Block	9-23
Adding a Base View	9-24
Creating an Auxiliary View	9-25
Turning Off the Datum Planes and DCS	9-26
Creating another Base View	9-28
Drawing Display Option	9-29
Displaying Feature Dimensions	9-30
Delete and Adding Dimensions	9-32
Questions	9-34
Exercises	9-35

Chapter 10 Symmetrical Features in Designs

0-2
0-2
0-3
0-4
0-6
0-8
0-10
0-11
0-13
0-15
0-16
0-17
0-18
0-20

Adding Dimensions	10-21
Adjusting the Display of the Views	10-23
Associative Functionality – A Design Change	10-25
Questions	10-29
Exercises	10-30

Chapter 11 Advanced 3D Construction Tools

Introduction	11-2
A Thin-Walled Design: Dryer Housing	11-2
Modeling Strategy	11-3
Starting UGS NX 6	11-4
Creating the 2-D Sketch for the Base Feature	11-5
Create a Revolved Feature	11-7
Creating the Handle section	11-8
Creating an Swept Feature	11-10
Joining the Two Solid Features	11-14
Hiding the 2D sketches	11-15
Create 3D Rounds and Fillets	11-16
Creating a Shell Feature	11-18
Create a Pattern Leader	11-19
Creating a Rectangular Array	11-23
Creating a Swept Cut Feature	11-25
Define the Sweep Section	11-24
Completing the Swept Feature	11-27
Questions	11-29
Exercises	11-30

Chapter 12 Assembly Modeling - Putting It All Together

Introduction	12-2
The Shaft Support Assembly	12-2
Assembly Modeling Methodology	12-3
Additional Parts	12-4
(1) Collar	12-4
(2) Bearing	12-4
(3) Base-Plate	12-5
(4) Cap-Screw	12-5
Starting UGS NX 6	12-6
Loading and Placing the First Component	12-7
Placing the Second Component	12-8
Degrees of Freedom and Assembly Constraints	12-9

Apply the First Assembly Constraint	12-13
Apply another Align Constraint	12-14
Constrained Move	12-16
Apply another Assembly Constraint	12-17
Placing the Third Component	12-19
Quick Editing of Applied Constraints	12-22
Assemble the First Cap-Screw	12-23
Placing the second Cap-Screw part	12-26
Exploded View of the Assembly	12-27
Switching the Exploded/Unexploded Views	12-29
Editing the Components	12-30
Setup a Drawing of the Assembly Model	12-33
Importing the Title Block	12-33
Creating a Parts List	12-35
Completing the Assembly Drawing	12-35
Conclusion	12-37
Summary of Modeling Considerations	12-37
Questions	12-38
Exercises	12-39

Index