
Introduction to Finite Element Analysis Using **SOLIDWORKS** Simulation 2015





Visit the following websites to learn more about this book:



amazon.com





Table of Contents

Preface Acknowledgments	i ii
Introduction	
Introduction Development of Finite Element Analysis FEA Modeling Considerations Types of Finite Elements Finite Element Analysis Procedure Matrix Definitions Getting Started with SolidWorks Starting SolidWorks Units Setup SolidWorks Screen Layout Menu Bar Toolbar Menu Bar Pull-down Menus Heads-up View Toolbar Features Toolbar Sketch Toolbar Feature Manager Design Tree Graphics Area Reference Triad Origin Confirmation Corner Graphics Cursor or Crosshairs Message and Status Bar Using the SolidWorks Command Manager Mouse Buttons [Esc] – Canceling Commands SolidWorks Help System Leaving SolidWorks Creating a CAD Files Folder	Intro-2 Intro-2 Intro-3 Intro-4 Intro-6 Intro-6 Intro-9 Intro-9 Intro-11 Intro-13 Intro-14 Intro-14 Intro-14 Intro-15 Intro-16 Intro-16 Intro-16 Intro-16 Intro-17 Intro-18 Intro-18 Intro-19 Intro-19 Intro-20
Chapter 1 The Direct Stiffness Method	
Introduction One-dimensional Truss Element Example 1.1 Example 1.2	1-2 1-3 1-5 1-7

Basic Solid Modeling using SolidWorks	1-10
The Adjuster Design	1-10
Starting SolidWorks	1-10
Step 1: Creating a Rough Sketch	1-12
Graphics Cursors	1-12
Geometric Relation Symbols	1-14
Step 2: Apply/Modify Relations and Dimensions	1-15
Viewing Functions – Zoom and Pan	1-17
Delete an Existing Geometry of the Sketch	1-18
Modifying the Dimensions of the Sketch	1-19
Step 3: Completing the Base Solid Feature	1-20
Isometric View	1-21
Rotation of the 3D Model – <i>Rotate View</i>	1-21
Rotation and Panning – Arrow Keys	1-23
Dynamic Viewing – Quick Keys	1-24
Viewing Tools – Heads-up View Toolbar	1-26
View Orientation	1-27
Display Style	1-28
Orthographic vs. Perspective	1-28
Customizing the Heads-up View Toolbar	1-28
Step 4-1: Adding an Extruded Boss Feature	1-29
Step 4-2: Adding an Extruded Cut Feature	1-33
Step 4-3: Adding another Cut Feature	1-35
Save the Model	1-37
Questions	1-38
Exercises	1-39
Chapter 2	
Truss Elements in Two-Dimensional Spaces	
Introduction	2-2
Truss Elements in Two-Dimensional Spaces	2-2
Coordinate Transformation	2-5
Example 2.1	2-9
Solution	2-10
Global Stiffness Matrix	2-10
Example 2.2	2-13
Solution	2-13
Questions	2-19
Exercises	2-20

Table of Contents

Chapter 3 2D Trusses in MS Excel and Truss Solver	
Direct Stiffness Matrix Method using <i>Excel</i> Example 3.1 Establish the Global K Matrix for each Member Assembly of the Overall Global Stiffness Matrix Solving the Global Displacements Calculating Reaction Forces Determining the Stresses in Elements The <i>Truss Solver</i> and the <i>Truss View</i> Programs The <i>Truss View</i> Program Questions Exercises	3-2 3-2 3-3 3-8 3-10 3-16 3-18 3-23 3-30 3-32 3-33
Chapter 4	
Truss Elements in SolidWorks Simulation One-dimensional Line Elements	4-2
Starting SolidWorks	4-4
Units Setup	4-5
Creating the CAD Model – Solid Modeling Approach	4-6
A CAD Model is NOT an FEA Model	4-15
The SolidWorks Simulation Module	4-16
Creating an FEA Model	4-17
Assign the Element Material Property	4-19
Applying Boundary Conditions - Constraints	4-20 4-23
Applying External Loads Create the FEA Mesh and Run the Solver	4-23 4-25
Viewing the Stress Results	4-25
Viewing the Displacement Results	4-28
Questions	4-29
Exercises	4-30
Chapter 5	
SolidWorks Simulation Two-Dimensional Truss Anal	ysis
Finite Element Analysis Procedure	5-2
Preliminary Analysis	5-3
Starting SolidWorks	5-4
Units Setup	5-5
Creating the CAD Model – Structural Member Approach	5-6
Creating Structural Members in <i>SolidWorks</i>	5-8
Weldment Profiles	5-9 5-12
Activate the SolidWorks Simulation Module	5-12
Setting Up Truss Elements	5-14

Setting Up Truss Elements

Assign the Element Material Property Applying Boundary Conditions - Constraints Applying External Loads Create the FEA Mesh and Run the Solver Viewing the Stress results Viewing the Internal Loads of All members Viewing the Reaction Forces at the supports Questions Exercises	5-15 5-16 5-21 5-23 5-24 5-26 5-27 5-28 5-29
Chapter 6 Three-Dimensional Truss Analysis	
Three-Dimensional Coordinate Transformation Matrix Stiffness Matrix Degrees of Freedom Problem Statement Preliminary Analysis Starting SolidWorks Units Setup Creating the CAD Model – Structural Member Approach Creating a Weldment Profile in SolidWorks Creating Structural Members using the New Profile Editing the Dimensions of the New Profile Activate the SolidWorks Simulation Module Setting Up the Truss Elements Assign the Element Material Property Applying Boundary Conditions - Constraints Applying the External Load Create the FEA Mesh and Run the Solver Using the Probe Option to View Individual Stress Viewing the Internal Loads of All Members Questions Exercises	6-2 6-3 6-3 6-5 6-5 6-7 6-8 6-9 6-12 6-16 6-18 6-19 6-21 6-22 6-23 6-24 6-26 6-27 6-28 6-29 6-30
Chapter 7 Basic Beam Analysis	
Introduction Modeling Considerations Problem Statement Preliminary Analysis Starting SolidWorks Units Setup	7-2 7-2 7-3 7-3 7-6 7-7

	Table of Contents
Creating the CAD Model – Structural Member Approach	7-8
Creating a Rectangular Weldment Profile	7-10
Creating Structural Members using the New Profile	7-14
Adjusting the Orientation of the Profile	7-15
Adding a Datum Point for the Concentrated Load	7-16
Activate the SolidWorks Simulation Module	7-18
Assign the Element Material Property	7-20
Applying Boundary Conditions - Constraints	7-21
Applying the Concentrated Point Load	7-24
Applying the Distributed Load	7-26
Create the FEA Mesh and Run the Solver	7-28
What Went Wrong?	7-29
Directions 1 and 2 in Shear and Moment Diagrams	7-32
Questions	7-34
Exercises	7-35
Chapter 8	
Beam Analysis Tools	
Introduction	8-2
Problem Statement	8-2
Preliminary Analysis	8-3
Stress Components	8-4
Starting SolidWorks	8-6
Creating the CAD Model – Structural Member Approach	8-7
Creating a Rectangular Weldment Profile	8-9
Creating Structural Members using the New Profile	8-13
Adjusting the Orientation of the Profile	8-14
Adding a Datum Point	8-15
Activate the SolidWorks Simulation Module	8-17
Assign the Element Material Property	8-19
Applying Boundary Conditions - Constraints	8-20
Applying the Distributed Load	8-23
Create the FEA Mesh and Run the Solver	8-25
Shear and Moment Diagrams	8-26
Using the Probe Option to Examine Stress at Point1	8-28
Questions	8-29
Exercises	8-30
Chapter 9	
Statically Indeterminate Structures	
Introduction	9-2
Problem Statement	9-3

vii

Preliminary Analysis Starting SolidWorks Creating the CAD Model Creating a Circular Weldment Profile Creating Structural Members using the New Profile Adding a Datum Point for the Concentrated Load Activate the SolidWorks Simulation Module Assign the Element Material Property Applying Boundary Conditions - Constraints Applying the Concentrated Point Load Create the FEA Mesh and Run the Solver Viewing the Internal Loads of All members Shear and Moment Diagrams Questions Exercises	9-3 9-6 9-7 9-9 9-13 9-14 9-16 9-18 9-19 9-22 9-24 9-25 9-26 9-28 9-29
Chapter 10 Two-Dimensional Surface Analysis	
Introduction	10-2
Problem Statement	10-3
Preliminary Analysis	10-3
Maximum Normal Stress	10-3
Maximum Displacement	10-4
Geometric Considerations of Finite Elements	10-5
Starting SolidWorks	10-6
Creating the CAD Model	10-7
Activate the <i>SolidWorks Simulation</i> Module	10-10
Defining a Surface Model	10-12
Assign the Element Material Property	10-13
Applying Boundary Conditions - Constraints	10-14
Applying the External Load	10-18
H-Element versus P-Element	10-20
Create the first FEA Mesh –Coarse Mesh	10-21
Run the Solver	10-23
Refinement of the FEA Mesh– Global Element Size 0.10	10-25
Refinement of the FEA Mesh– Global Element Size 0.05	10-27
Refinement of the FEA Mesh– Global Element Size 0.03	10-29
Refinement of the FEA Mesh– Global Element Size 0.02	10-30
Comparison of Results	10-31
Questions	10-32
Exercises	10-33

Chapter 11 Three-Dimensional Solid Elements

Introduction Problem Statement Preliminary Analysis Starting SolidWorks Creating a CAD Model in SolidWorks Define the Sweep Path Define the Sweep Section Create the Swept Feature Create a Cut Feature Activate the SolidWorks Simulation Module Assign the Element Material Property Applying Boundary Conditions - Constraints Applying the External Load to the system Create the first FEA Mesh —Coarse Mesh Run the Solver Refinement of the FEA Mesh — Global Element Size 0.10 Refinement of the FEA Mesh — Mesh Control Option Refinement of the FEA Mesh — Automatic Transition Comparison of Results Questions Exercises	11-2 11-3 11-4 11-7 11-8 11-8 11-10 11-12 11-13 11-15 11-17 11-18 11-19 11-20 11-22 11-24 11-26 11-29 11-31 11-32 11-33
Chapter 12 3D Thin Shell Analysis	
Introduction Problem Statement Preliminary Analysis Starting SolidWorks Creating a 3D Solid Model in SolidWorks Activate the SolidWorks Simulation Module Assign the Element Material Property Applying Boundary Conditions - Constraints Applying the Pressure to the System Create the first FEA Mesh —Coarse Mesh Run the Solver and View the Results Refinement of the FEA Mesh—Global Element Size 0.0125 Starting a New 3D Surface Model Starting a New FEA Study Completing the Definition of the Surface Model Assign the Element Material Property Applying Boundary Conditions - Constraints	12-2 12-4 12-4 12-6 12-7 12-9 12-11 12-12 12-14 12-15 12-16 12-17 12-18 12-21 12-22 12-23 12-24

Exercises

Applying the Pressure to the System Create the first FEA Mesh –Coarse Mesh Run the Solver and View the Results Refinement of the FEA Mesh– Global Element Size 0.010 Notes on FEA Linear Static Analyses Questions Exercises	12-28 12-29 12-30 12-31 12-32 12-33 12-34
Chapter 13 FEA Static Contact Analysis	
Introduction	13-2
Problem Statement	13-3
Preliminary Analysis	13-3
Parts	13-4
(1) Pliers-Jaw	13-4
(2) Pin	13-6
(3) Fork	13-6
Starting SolidWorks	13-8
Inserting the First Component	13-9
Inserting the Second Component	13-10
Assembly Mates	13-11
Inserting the third Component	13-14
Inserting the Upper Jaw Component	13-16
Identifying Coincident Surfaces in the Model	13-19
Activate the <i>SolidWorks Simulation</i> Module	13-20
Assign the Element Material Property	13-22
Applying Boundary Conditions – Constraints	13-23
Applying the External Load on the Handles	13-24
Global Contact Settings	13-25
Setup Specific Local Contact Sets	13-26
Setup Another Contact Set on the PIN part	13-28
Create the FEA Mesh	13-30
Run the Solver and View the Results	13-31
Use the Animate Option	13-33
Use the Section Clipping Option	13-34
Use the Iso Clipping Option	13-35
Setup a Contact Pressure Plot	13-36
Refinement of the FEA Mesh – Apply Mesh Control	13-39
Questions	13-41

13-42

Chapter 14 Dynamic Modal Analysis

Introduction	14-2
Problem Statement	14-3
Preliminary Analysis	14-3
The Cantilever Beam Modal Analysis Program	14-6
Starting SolidWorks	14-9
Creating the CAD Model	14-10
Activate the SolidWorks Simulation Module	14-12
Assign the Element Material Property	14-14
Applying Boundary Conditions—Constraints	14-15
Create the first FEA Mesh	14-16
Viewing the Results	14-18
Refinement of the FEA Mesh– Global Element Size 0.15	14-21
Adding an Additional Mass to the System	14-23
One-Dimensional Beam Frequency Analysis	14-27
Conclusions	14-28
Questions	14-29
Exercises	14-30

Index