
Principles and Practice

An Integrated Approach to Engineering Graphics and AutoCAD® 2018



Visit the following websites to learn more about this book:



amazon.com





Table of Contents

Preface	1
Acknowledgments	ii
Table of Contents	iii
AutoCAD Certified User Examination Reference Guide	xiii
Tips about Taking the AutoCAD Certified User Examination	XX
Chapter 1	
Introduction and AutoCAD Fundamentals	
Introduction	1-3
Drawing in CAD Systems	1-5
Development of Computer Geometric Modeling	1-5
Why use AutoCAD 2018?	1-8
Getting Started with AutoCAD 2018	1-10
AutoCAD 2018 Screen Layout	1-11
Application Menu	1-12
Quick Access Toolbar	1-12
AutoCAD Menu Bar	1-12
Layout Tabs	1-12
Drawing Area	1-13
Graphics Cursor or Crosshairs	1-13
Command Prompt Area	1-13
Cursor Coordinates	1-13
Status Toolbar	1-13
Ribbon Tabs and Panels	1-14
Draw and Modify Toolbar Panels	1-14
Layers Control Toolbar Panel	1-14
Viewport/View/Display Controls	1-14
Mouse Buttons	1-15
[Esc] - Canceling Commands	1-15
Online Help	1-16
Leaving AutoCAD 2018	1-17
Creating a CAD File Folder	1-17
Drawing in AutoCAD	1-18
Starting Up AutoCAD 2018	1-18
Drawing Units Setup	1-20
Drawing Area Setup	1-21
Drawing Lines with the Line Command	1-23
Visual Reference	1-25
Grid On	1-26
Snap Mode On	1-27
Using the Erase Command	1-28
Repeat the Last Command	1-29

The CAD Database and the User Coordinate System	1-30
Changing to the 2D UCS Icon Display	1-31
Cartesian and Polar Coordinate Systems	1-32
Absolute and Relative Coordinates	1-32
Defining Positions	1-33
GRID Style Setup	1-33
The GuidePlate	1-34
Creating Circles	1-38
Save the CAD Design	1-40
Close the Current Drawing	1-41
The Spacer Design	1-42
Start a New Drawing	1-42
Drawing Units Setup	1-43
Drawing Area Setup	1-44
Using the Line Command	1-46
Using the Erase Command	1-48
Using the Arc Command	1-48
Using the Circle Command	1-50
Saving the CAD Design	1-51
Exit AutoCAD 2018	1-51
Review Questions	1-52
Exercises	1-53
Chapter 2	
Geometric Constructions	
Geometric Constructions	2-3
Geometric Constructions - Classical Methods	2-3 2-4
Bisection of a Line or Arc	2-4 2-4
	2-4 2-5
Bisection of an Angle	2-3 2-6
Transfer of an Angle	2-6 2-7
Dividing a Given Line into a Number of Equal Parts	
Circle through Three Points	2-8
Line Tangent to a circle from a Given Point	2-9
Circle of a Given Radius Tangent to Two Given Lines	2-10
Circle of a Given Radius Tangent to an Arc and a Line	2-11
Circle of a Given Radius Tangent to Two Arcs	2-12
Starting Up AutoCAD 2018	2-13
Dynamic Input	2-13
Object Snap Toolbar	2-17
Geometric Construction - CAD Method	2-18
Bisection of a Line or Arc	2-18
Bisection of an Angle	2-21
Transfer of an Angle	2-23
Dividing a Given Line into a Number of Equal Parts	2-27
Circle through Three Points	2-29

Line Tangent to a Circle from a Given Point	2-30
Circle of a Given Radius Tangent to Two Given Lines	2-31
The RockerArm Design	2-34
Activate the Startup Option	2-34
Drawing Units Display Setup	2-36
GRID and SNAP Intervals Setup	2-36
Drawing Area Setup	2-37
Referencing the World Coordinate System	2-38
Creating Circles	2-39
Using the Line Command	2-40
Creating TTR Circles	2-42
Using the Trim Command	2-44
Using the Polygon Command	2-46
Creating a Concentric Circle	2-48
Using the QuickCalc Calculator to Measure Distance and Angle	2-49
Saving the CAD File	2-53
Exit AutoCAD	2-53
Review Questions	2-55
Exercises	2-56
Chapter 3 Object Properties and Organization	
Introduction	3-3
The Floor Plan Design	3-3
Starting Up AutoCAD 2018	3-4
Using the Setup Wizard	3-4
Drawing Units Setup	3-5
Reference Area Setup	3-5
Grid and Sanp Intervals Setup	3-6
Using the Zoom Extents Command in the Navigation Bar	3-7
The AutoCAD Multiline Command	3-7
Object Snap Toolbar	3-10
Drawing Multilines	3-11
Creating Interior Walls	3-14
Joining the Walls Using Multiline Edit	3-17
Using Layers and Object Properties	3-19
Using Zoom Realtime	3-22
Modeling the Bathroom	3-23
Controlling Layer Visibility	3-25
Adding a New Layer	3-25
Moving Objects to a Different Layer	3-26
Matching Layer Properties	3-27
Review Questions	3-29
Exercises	3-30

Chapter 4 Orthographic Projections and Multiview Constructions

Introduction	4-3
Basic Principles of Projection	4-4
Orthographic Projection	4-4
Multiview Orthographic Projection	4-5
First-Angle Projection	4-6
Rotation of the Horizontal and Profile Planes	4-7
Getting the 3D Adjuster Model through the Internet	4-8
Dynamic Rotation – 3D Orbit	4-9
General Procedure: 1 St Angle Orthographic Projection	4-10
1 St Angle Orthographic Sketching Exercises	4-11
Third-Angle Projection	4-13
Rotation of the Horizontal and Profile Planes	4-14
Examining the 3 rd Angle Projection	4-15
The Glass Box and the Six Principal Views	4-16
Examining the Glass Box Model	4-18
General Procedure: 3 rd Angle Orthographic Projection	4-19
Example 2: 3 rd Angle Orthographic Projection	4-20
3 rd Angle Orthographic Sketching Exercises	4-21
Alphabet of Lines	4-23
Precedence of Lines	4-25
The Locator Part	4-26
Starting Up AutoCAD 2018	4-26
Layers Setup	4-27
Drawing Construction Lines	4-28
Using the Offset Command	4-28
Set Layer Object as the Current Layer	4-30
Using the Running Object Snaps	4-30
Creating Object Lines	4-32
Turn OFF the Construction Lines Layer	4-33
Adding More Objects in the Front View	4-33
AutoCAD's AutoSnap TM and AutoTrack TM Features	4-34
Adding More Objects in the Top View	4-36
Drawing Using the Miter Line Method	4-40
More Layers Setup	4-42
Top View to Side View Projection	4-43
Completing the Front View	4-45
Object Information Using the List Command	4-47
Object Information Using the Properties Command	4-48
Review Questions	4-49
Exercises	4-50

Chapter 5 Pictorials and Sketching	
Engineering Drawings, Pictorials and Sketching Isometric Sketching Isometric Sketching Exercises Oblique Sketching Oblique Sketching Exercises Perspective Sketching One-point Perspective Two-point Perspective	5-2 5-7 5-9 5-19 5-20 5-26 5-27 5-28
Perspective Sketching Exercises Review Questions Exercises	5-29 5-35 5-36
Chapter 6 Dimensioning and Notes	
Introduction Dimensioning Standards and Basic Terminology	6-3 6-4
Selection and Placement of Dimensions and Notes Machined Holes Baseline and Chain Dimensioning	6-5 6-12 6-15
Dimensioning and Tolerance Accumulation (1) Tolerance Accumulation – Baseline Dimensioning	6-16 6-17
 (2) Tolerance Accumulation – Chain Dimensioning (3) Avoid Tolerance Accumulation – Dimensioning Features Dimensioning Tools in AutoCAD 	6-18 6-19 6-20
The P-Bracket Design Starting Up AutoCAD 2018	6-20 6-21 6-22
Layers Setup The P-Bracket Design LineWeight Display Control	6-23 6-23
Drawing Construction Lines Using the Offset Command	6-24 6-24
Set Layer Object_Lines as the Current Layer Creating Object Lines Creating Hilland Lines	6-26 6-26
Creating Hidden Lines Creating Center Lines Turn Off the Construction Lines	6-27 6-28 6-28
Using the Fillet Command Saving the Completed CAD Design	6-29 6-30
Accessing the Dimensioning Commands The Dimension Toolbar	6-31 6-32
Using Dimension Style Manager Dimensions Nomenclature and Basics	6-32 6-33
Using the Center Mark Command	6-36

Adding Linear Dimensions Adding an Angular Dimension Adding Radius and Diameter Dimensions Using the Multiline Text Command Adding Special Characters Saving the Design A Special Note on Layers Containing Dimensions Review Questions Exercises	6-37 6-38 6-39 6-40 6-41 6-42 6-42 6-43 6-44
Chapter 7 Tolerancing and Fits	
Precision and Tolerance	7-2
Methods of Specifying Tolerances – English System	7-3
Nomenclature	7-4
Example 7.1	7-5
Fits between Mating Parts	7-6
Selective Assembly	7-7
Basic Hole and Basic Shaft Systems	7-7
American National Standard Limits and Fits – Inches	7-8
Example 7.2 Basic Hole System	7-13
Example 7.3 Basic Hole System	7-14
Example 7.4 Basic Shaft System	7-15
Example 7.5 Basic Shaft System	7-16
Tolerancing – Metric System	7-17
Metric Tolerances and Fits Designation	7-18
Preferred ISO Metric Fits	7-19
Example 7.6 Metric Hole Basis System	7-20
Example 7.7 Shaft Basis System	7-21
Updating the Bracket Drawing	7-22
The Dimension Style Manager	7-22
Tolerances Settings in the Dimension Style Manager	7-23
Determining the Tolerances Required	7-24
Review Questions	7-28
Exercises	7-29
Chapter 8 Symmetrical Features in Designs	
Introduction	8-3
The GenevaCam Design	8-3
Starting Up AutoCAD 2018	8-4
Setting Up the Plot Style Mode	8-5
Starting a New File	8-7
Grid and Snap Intervals Setup	8-8

ix

Layers Setup	8-9
Adding Borders and Title Block in the Layout	8-10
Create a Template File	8-13
Exit AutoCAD 2018	8-14
Starting Up AutoCAD 2018	8-14
The Geneva Cam Drawing	8-15
Drawing Construction Lines	8-16
Creating Object Lines	8-17
Using the Offset Command	8-18
Using the Mirror Command	8-20
Using the Array Command	8-21
Creating a Viewport Inside the Title Block	8-24
Viewport Properties	8-25
Hide the Viewport Borders	8-26
Adjusting the Dimension Scale	8-26
Plot/Print the Drawing	8-28
Create a B size Layout of the design	8-30
Adjust the Dimension Scale for the B size Print	8-34
Review Questions	8-36
Exercises	8-37
Chapter 9	
Auxiliary Views	
Introduction	9-3
Normal View of an Inclined Surface	9-4
Construction Method I – Folding Line Method	9-6
Construction Method II – Reference Plane Method	9-8
Partial Views	9-10
Creating Auxiliary Views in AutoCAD	9-11
The V-Block Design	9-11
The V-Block Example	9-12
Starting Up AutoCAD 2018	9-12
Setting Up the Principal Views	9-13
Setting Up the Top View	9-16
Using the Offset Command	9-17
Creating Object Lines in the Front View	9-19
Setting the Polar Tracking Option	9-20
Setting Up an Auxiliary View	9-23
Aligning the Auxiliary View to the Front View	9-24
Creating the V-cut in the Auxiliary View	9-24
Creating the V-cut in the Front View and Top View	9-27
Setting the Polar Tracking Option	9-29
Completing the Top View	9-29
Edit the Plot Style Table	9-32
Using the Area Inquiry Tool to Measure Area and Perimeter	9-35

P	rinci	iples	and	Pra	ctice
•	11110	pres	ullu	1 14	-

1	
Start a new drawing for a Metric Template File	9-39
Layers Setup	9-40
Set up Metric Borders and Title Block by Copy & Paste	9-41
Review Questions	9-46
Exercises	9-47
Chapter 10 Section Views	
Introduction	10-3
General Rules of Section Views	10-5
Section Drawing Types	10-6
Full Section	10-6
Half Section	10-6
Offset Section	10-7
Broken-Out Section	10-7
Aligned Section	10-8
Half Views	10-8
Thin Sections	10-8
Revolved Section	10-9
Removed Section	10-9
Conventional Breaks Ribs and Webs in Sections	10-10
Parts Not Sectioned	10-10 10-10
Section Views in AutoCAD	10-11
The Bearing Design	10-11
Starting Up AutoCAD 2018	10-11
The Bearing Example	10-12
Setting up the Principal Views	10-13
Creating Object Lines in the Front View	10-15
Editing the Circles	10-17
Setting Up the Side View	10-18
Adding Hidden Lines in the Side View	10-20
Changing the Linetype Scale Property	10-22
Stretching and Moving Objects with Grips	10-23
Drawing a Cutting Plane Line	10-24
Converting the Side View into a Section View	10-27
Adding Section Lines	10-29
Review Questions	10-32
Exercises	10-33
Chapter 11 AutoCAD 2D Isometric Drawings	
Introduction	11-2
The Angle Support Design	11-2

	Table of Contents
Starting Up AutoCAD 2018	11-3
AutoCAD Isoplane and Isodraft Commands	11-4
Layers Setup	11-5
Create the Base Box of the Design	11-6
Create the Design inside the Base Box	11-10
Create the Isocircle on the top face	11-13
Using the Editing Tools in an Isometric drawing	11-16
The Tube Anchor Design – Modeling Strategy	11-16
Start a New Drawing and Layers Setup	11-17
Create a Base Box of the Design	11-18
Locate the Centers for the Isocircles	11-18
Create the Isocircles	11-21
Using the Object Snap tools to complete the drawing	11-23
Review Questions	11-34
Exercises	11-34
Exercises	11-33
Chapter 12 Threads and Fasteners	
Introduction	12-2
Screw-Thread Terminology	12-3
Thread Forms	12-5
Thread Representations	12-6
Detailed Representation	12-7
Schematic Representation	12-8
Simplified Representation	12-9
Thread Specification – English Units	12-10
Unified Thread Series	12-11
Thread Fits	12-12
Thread Specification – Metric	12-12
Thread Notes Examples	12-13
Specifying Fasteners	12-14
Commonly used Fasteners	12-15
Drawing Standard Bolts	12-17
Bolt and Screw Clearances	12-17
Review Questions	12-18
Exercises	12-19
	12 17
Chapter 13	
Working Drawings	
General Engineering Design Process	13-3
Working Drawings	13-4
Detail Drawings	13-4
Assembly Drawings	13-5
Bill of Materials (BOM) and Parts List	13-5
Diff of franctions (Doll) and I also hist	13 3

хi

Drawing Sheet Borders and Revisions Block Title Blocks 13-7 Working Drawings with AutoCAD 13-8 The Shaft Support Subassembly 13-9 Additional Parts 13-9 Cap-Screw 13-9 Collar Base-Plate 13-10 Starting Up AutoCAD and Loading Multiple Drawings 13-11 Using AutoCAD with the Internet 13-12 Rearrange the Displayed Windows 13-13 Defining a Block 13-14 Inserting a Block 13-16 Starting an Assembly Drawing 13-17 Copying and Pasting with the Windows Clipboard 13-18 Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing 13-31 Review Questions 13-37 Exercises	Drawing Sizes	13-6
Working Drawings with AutoCAD The Shaft Support Subassembly Additional Parts Cap-Screw Collar Base-Plate Starting Up AutoCAD and Loading Multiple Drawings Using AutoCAD with the Internet Rearrange the Displayed Windows Defining a Block Inserting a Block Starting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions 13-8 13-8 13-8 13-8 13-9 13-17 13-18 13-19 13-21 13-24 13-24 13-25 13-26 13-26 13-26 13-30 13-31 Review Questions	Drawing Sheet Borders and Revisions Block	13-6
The Shaft Support Subassembly Additional Parts Cap-Screw Collar Base-Plate Starting Up AutoCAD and Loading Multiple Drawings Using AutoCAD with the Internet Rearrange the Displayed Windows Defining a Block Isarting a Block Isarting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions 13-9 13-9 13-10 13-11 13-12 13-12 13-13 13-14 13-15 13-14 13-16 13-16 13-17 13-17 13-18 13-17 13-18 13-19 13-19 13-21	Title Blocks	13-7
Additional Parts Cap-Screw Collar Base-Plate Starting Up AutoCAD and Loading Multiple Drawings Using AutoCAD with the Internet 13-12 Rearrange the Displayed Windows 13-13 Defining a Block 13-14 Inserting a Block 13-16 Starting an Assembly Drawing 13-17 Copying and Pasting with the Windows Clipboard Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	Working Drawings with AutoCAD	13-8
Cap-Screw Collar Base-Plate Starting Up AutoCAD and Loading Multiple Drawings 13-10 Starting Up AutoCAD with the Internet 13-12 Rearrange the Displayed Windows 13-13 Defining a Block 13-14 Inserting a Block 13-16 Starting an Assembly Drawing 13-17 Copying and Pasting with the Windows Clipboard 13-18 Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	The Shaft Support Subassembly	13-9
Collar Base-Plate Starting Up AutoCAD and Loading Multiple Drawings 13-10 Using AutoCAD with the Internet 13-12 Rearrange the Displayed Windows 13-13 Defining a Block 13-14 Inserting a Block 13-16 Starting an Assembly Drawing 13-17 Copying and Pasting with the Windows Clipboard 13-18 Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	Additional Parts	13-9
Base-Plate 13-10 Starting Up AutoCAD and Loading Multiple Drawings 13-11 Using AutoCAD with the Internet 13-12 Rearrange the Displayed Windows 13-13 Defining a Block 13-14 Inserting a Block 13-16 Starting an Assembly Drawing 13-17 Copying and Pasting with the Windows Clipboard 13-18 Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout 13-29 Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing 13-31 Review Questions 13-37	Cap-Screw	13-9
Starting Up AutoCAD and Loading Multiple Drawings Using AutoCAD with the Internet Rearrange the Displayed Windows 13-13 Defining a Block Inserting a Block Isarting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions	Collar	13-10
Using AutoCAD with the Internet Rearrange the Displayed Windows Defining a Block Inserting a Block Starting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions 13-12 13-13 13-14 13-16 13-17 13-17 13-18 13-19 13-19 13-21 13-21 13-21 13-21 13-21 13-24 13-25 13-30 13-31 13-31	Base-Plate	13-10
Rearrange the Displayed Windows Defining a Block Inserting a Block Starting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions 13-13 13-14 13-16 13-16 13-17 13-17 13-18 13-19 Adding the Bearing to the Assembly 13-19 13-21 13-21 13-22 13-24 13-25 13-30 13-31 13-31	Starting Up AutoCAD and Loading Multiple Drawings	13-11
Defining a Block Inserting a Block Starting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Inserting Callouts with the Multileader Command Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions Inserting a 13-14 Inserting a 13-16 Inserting a 13-17 Inserting a 13-17 Inserting a 13-17 Inserting a 13-18 Inser	Using AutoCAD with the Internet	13-12
Inserting a Block Starting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	Rearrange the Displayed Windows	13-13
Starting an Assembly Drawing Copying and Pasting with the Windows Clipboard Converting the View into a Section View 13-19 Adding the Bearing to the Assembly 13-21 Adding the Cap-Screws to the Assembly 13-24 Creating Callouts with the Multileader Command 13-26 Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	Defining a Block	13-14
Copying and Pasting with the Windows Clipboard Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions 13-18 13-18 13-19 13-21 13-21 13-22 13-24 13-25 13-26 13-30 13-31 13-31	Inserting a Block	13-16
Converting the View into a Section View Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties Adding a Parts List to the Assembly Drawing Review Questions 13-19 13-21 13-22 13-24 13-26 13-29 13-30 13-31 13-37	Starting an Assembly Drawing	13-17
Adding the Bearing to the Assembly Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	Copying and Pasting with the Windows Clipboard	13-18
Adding the Cap-Screws to the Assembly Creating Callouts with the Multileader Command Creating a Viewport in the A-size Layout Viewport Properties 13-30 Adding a Parts List to the Assembly Drawing Review Questions 13-37	Converting the View into a Section View	13-19
Creating Callouts with the Multileader Command13-26Creating a Viewport in the A-size Layout13-29Viewport Properties13-30Adding a Parts List to the Assembly Drawing13-31Review Questions13-37	Adding the Bearing to the Assembly	13-21
Creating a Viewport in the A-size Layout13-29Viewport Properties13-30Adding a Parts List to the Assembly Drawing13-31Review Questions13-37	Adding the Cap-Screws to the Assembly	13-24
Viewport Properties13-30Adding a Parts List to the Assembly Drawing13-31Review Questions13-37	Creating Callouts with the Multileader Command	13-26
Adding a Parts List to the Assembly Drawing Review Questions 13-31 13-37	Creating a Viewport in the A-size Layout	13-29
Review Questions 13-37	Viewport Properties	13-30
	Adding a Parts List to the Assembly Drawing	13-31
Exercises 13-38	Review Questions	13-37
	Exercises	13-38

Appendix

- A. Running and Sliding Fits American National Standard
- B. Metric Limits and Fits
- C. Unified Nation Thread Form
- D. Metric Thread Form
- E. Fasteners (Inch Series)
- F. Metric Fasteners
- G. Bolt and Screw Clearance Holes
- H. References

Index