


Certified SOLIDWORKS® Professional Advanced Preparation Materials

Sheet Metal, Weldments, Surfacing,
Mold Tools and Drawing Tools

SOLIDWORKS® 2018



Paul Tran CSWE, CSWI

Visit the following websites to learn more about this book:



[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

Table of Contents

CSWPA – Drawing Tools

Chapter 1: Drawing Tools 1-1




Challenge 1: Tank.sldprt	1-3
Open the part document: Tank.sldprt	1-3
Transferring to a drawing	1-3
Changing the paper size	1-4
Adding the drawing view	1-5
Creating a section view	1-6
Measuring the surface area	1-7
Creating an aligned section view	1-7
Measuring the surface area	1-9



Challenge 2: Piston Assembly.sldasm	1-10
Open the assembly document: Piston Assembly.sldasm	1-10
Creating a reference sketch	1-11
Modifying the view angle	1-12
Saving a new named-view	1-14
Making a drawing from assembly	1-15
Adding the first drawing view	1-16
Creating the projected drawing views	1-17
Adding reference lines	1-18
Converting an entity	1-19
Adding a reference dimension	1-19
Adding a top drawing view	1-20
Locking a view focus	1-21
Adding an angular dimension	1-23

Challenge 3: Radial Stretcher.sldasm	1-24
Open the assembly document: Radial Stretcher.sldasm	1-24
Transferring to a drawing	1-24
Adding drawing views from the view palette	1-25



Breaking the view alignment	1-26
Adding balloons	1-27
Adding a bill of materials	1-28
Changing custom properties	1-29
Adding a new column	1-30
Optional	1-32

CSWPA – Mold Tools

Chapter 2: Mold Tools

2-1

Challenge 1: Cavity Creation.sldprt

2-3

Open the document: Cavity Creation.sldprt

2-3

Enabling the mold Tools

2-3

Creating the parting line

2-3

Creating the parting surfaces

2-4

Knitting the surfaces

2-5

Creating a new plane

2-6

Sketching the mold block

2-6

Creating the cavity block

2-7

Separating the block from the part


2-7

Hiding the reference surfaces

2-9

Measuring the cavity block

2-9



Challenge 2: Plastic Cap.sldprt

2-10

Open the document: Plastic Cap.sldprt

2-10

Creating the Parting line

2-10

Creating the Parting surfaces

2-11

Knitting the surfaces

2-12

Creating a new plane

2-13

Sketching the mold block

2-14

Extruding the Core block

2-14

Separating the block from the part

2-15

Hiding the reference surfaces

2-16

Assigning material

2-16

Calculating the mass

2-17



Challenge 3: Repair Surfaces.sldprt

2-18

Open the document: Repair Surfaces.sldprt

2-18

Creating a new plane

2-18

Converting the geometry

2-19



Extruding a surface	2-20
Creating a planar surface	2-21
Knitting the surfaces	2-22
Creating a section view	2-22
Applying material	2-23
Calculating the mass	2-23

Challenge 4: Surfaces Area.sldprt **2-24**



Open the document: Surfaces Area.sldprt	2-24
Creating the filled surfaces	2-24
Filling other slots	2-25
Filling the holes	2-25
Filling the ends with planar surfaces	2-26
Measuring the total surface area of the patches	2-27



Challenge 5: Wheel.sldprt **2-28**

Open the document: Wheel.sldprt	2-28
Analyzing the Draft angles	2-28
Changing the draft angle	2-30


CSWPA – Weldments

Chapter 3: Weldments **3-1**

Challenge 1: Creating the Weldments profile **3-3**




Starting a new part document	3-3
Enabling the Weldments tab	3-3
Sketching the first weldment profile	3-4
Creating the second weldment profile	3-5
Sketching the profile	3-5
Showing the weldment profiles folder	3-6
Creating a new weldment part	3-7
Adding structural members	3-8
Applying material	3-9
Calculating the mass	3-9
Changing the structural members	3-10
Calculating the mass	3-11




Challenge 2: Weldment Frame 3.sldprt **3-12**


Open the document: Weldment Frame 3.sldprt	3-12
--	------



Adding structural members	3-13
Creating the parallel group	3-14
Trimming the parallel group	3-15
Applying material	3-17
Calculating the mass	3-17
Creating the Upper Braces	3-18
Trimming the first Upper Braces	3-18
Updating the Cut list	3-20
Creating the Lower Braces	3-21
Trimming the Lower Braces	3-22
Adding End Caps	3-24
Calculating the final mass	3-25



Challenge 3: Weldment Frame 4.sldprt	3-26
Open the document: Weldment Frame 4.sldprt	3-26
Creating a 3D sketch	3-26
Adding structural members	3-31
Creating the parallel group	3-32
Trimming the tubes	3-33




Challenge 4: Weldment Frame 5.sldprt	3-37
Open the document: Weldment Frame 5.sldprt	3-37
Assigning material	3-37
Modifying the properties	3-38
Transferring to a drawing	3-39
Adding a drawing view	3-39
Inserting the weldment cut list	3-40
Adding balloons	3-41

CSWPA – Sheet Metal

Chapter 4: Sheet Metal

4-1





Challenge 1: Converting to Sheet Metal	4-3
Opening the document: Convert to SM.sldprt	4-3
Enabling the sheet metal tab	4-3
Making a copy of the solid model	4-3
Converting to sheet metal	4-5
Calculating the mass	4-6

Measuring the flat pattern	4-7
Creating a Hem	4-8
Calculating the mass	4-10

Challenge 2: Sheet Metal Cut List.sldprt	4-11
Open the document: SM Cut List.sldprt	4-11
Modifying the first bend radius	4-11
Measuring the flat length	4-12
Modifying the second bend radius	4-13
Measuring the flat length	4-13
Finding the Bounding Box Area	4-14



Challenge 3: Sheet Metal Part.sldprt	4-15
Open the document: SM Part.sldprt	4-15
Creating the Edge Flanges	4-15
Closing the corners	4-16
Creating a cutout	4-17
Adding a Miter Flange	4-18
Mirroring the features	4-22
Calculating the mass	4-23
Changing the K-Factor value	4-24
Measuring the flat length	4-24
Adding hems	4-25
Adding a form feature	4-26
Creating a linear pattern	4-27
Calculating the mass	4-27



CSWPA – Surfacing

Chapter 5: Surfacing 5-1



Challenge 1: Inlet-Outlet Patches.sldprt	5-3
Open the document: Inlet-Outlet Patches.sldprt	5-3
Enabling the surfaces tab	5-3
Patching the first opening	5-4
Measuring the surface area	5-5
Deleting the outlet port	5-5
Filling the openings	5-6
Measuring the surface area	5-7

Thickening the surface body	5-8
Creating a section view	5-8
Calculating the mass	5-9


Challenge 2: Mouse from Sketch Picture.sldprt 5-10

Open the document: Mouse from Sketch Picture.sldprt	5-10
Examining the sketch pictures	5-10
Tracing the profile	5-11
Extruding a surface	5-11
Trimming the surfaces	5-13
Creating the boundary profiles	5-15
Hiding and suppressing the references	5-17
Creating the boundary surfaces	5-18
Creating a filled surface	5-22
Creating a knit surface	5-23
Mirroring the surface bodies	5-23
Thickening the surface body	5-24
Assigning material	5-27
Calculating the mass	5-28



Challenge 3: Plastic Ball.sldprt 5-29

Open the document: Plastic Ball.sldprt	5-29
Hiding the solid body	5-29
Extending the surface	5-30
Trimming the surfaces	5-31
Making a copy of the solid body	5-32
Cutting the surface	5-33
Extending the offset surface	5-36
Measuring the surface area	5-39



Challenge 4: Tube Patches.sldprt 5-40

Open the document: Tube Patches.sldprt	5-40
Trimming the surface body	5-42
Measuring the surface area	5-44
Creating the lofted surfaces	5-45
Creating the filled surfaces	5-47
Measuring the total surface area	5-53



Challenge 5: Remote Body.sldprt 5-54

Open the document: Remote Body.sldprt	5-54
Tracing the sketch picture	5-54
Creating a 3D sketch	5-56
Creating a lofted surface	5-56



Measuring the surface area	5-57
Knitting the surfaces	5-58
Mirroring the surface body	5-59
Thickening the surface body	5-60
Creating a section view	5-60
Calculating the final mass	5-61

Glossary and Index by chapters

SOLIDWORKS 2018 Quick-Guides:

Quick Reference Guide to SOLIDWORKS 2018 Command Icons and Toolbars.

