


Certified SOLIDWORKS® Professional Advanced Preparation Material

Sheet Metal, Weldments, Surfacing,
Mold Tools and Drawing Tools

SOLIDWORKS® 2019



Paul Tran CSWE, CSWI

Visit the following websites to learn more about this book:



[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

Table of Contents

CSWPA – Drawing Tools

Chapter 1: Drawing Tools 1-1




Challenge 1: Tank	1-3
Open the part document: Tank	1-3
Transferring to a drawing	1-3
Changing the paper size	1-4
Adding the drawing view	1-5
Creating a section view	1-6
Measuring the surface area	1-7
Creating an aligned section view	1-7
Measuring the surface area	1-9



Challenge 2: Piston Assembly	1-10
Open the assembly document: Piston Assembly	1-10
Creating a reference sketch	1-11
Modifying the view angle	1-12
Saving a new named-view	1-14
Making a drawing from assembly	1-15
Adding the first drawing view	1-16
Creating the projected drawing views	1-17
Adding reference lines	1-18
Converting an entity	1-19
Adding a reference dimension	1-19
Adding a top drawing view	1-20
Locking a view focus	1-21
Adding an angular dimension	1-23


Challenge 3: Radial Stretcher	1-24
Open the assembly document: Radial Stretcher	1-24
Transferring to a drawing	1-24
Adding drawing views from the view palette	1-25




Breaking the view alignment	1-26
Adding balloons	1-27
Adding a bill of materials	1-28
Changing custom properties	1-29
Adding a new column	1-30
Optional	1-32

CSWPA – Mold Making


Chapter 2: Mold Making 2-1




Challenge 1: Interlock Surface	2-2
Open the document: Interlock Surface	2-3
Enabling the mold tools	2-3
Selecting the parting line	2-4
Creating the shut-off surfaces	2-5
Creating the parting surfaces	2-6
Making a new plane	2-7
Sketching the mold profile	2-8
Performing a tooling split	2-9
Separating the solid bodies	2-10
Assigning material	2-11
Calculating the mass	2-11





Challenge 2: Parting Lines Creation	2-13
Open the document: Parting Line Creation	2-14
Creating the parting line	2-14
Creating the shut-off surfaces	2-15
Creating the Parting surfaces	2-16
Sketching the mold block profile	2-17
Inserting a tooling split	2-18
Separating the block from the part	2-19
Assigning material	2-20
Calculating the mass	2-20





Challenge 3: Runners & Sprue	2-22
Open the document: Runners & Sprue	2-23
Creating the shut-off surfaces	2-24
Creating the parting surfaces	2-25
Sketching the shape of the mold profile	2-26
Inserting a tooling split	2-27





Finalizing the mold block sketch	2-28
Extruding the lower mold block	2-29
Converting a sketch	2-30
Extruding the upper mold block	2-31
Moving the cavity block	2-32
Measuring the distance	2-32
Copying the plastic part	2-33
Subtracting the solid bodies	2-33
Applying the shrink rate	2-34
Calculating the mass	2-34




Challenge 4: Shut-Off Surface Creation	2-36
Open the document: Steering Wheel	2-37
Creating a split line	2-37
Creating the parting lines	2-39
Creating the shut-off surfaces	2-40
Measuring the surface area	2-41
Creating the parting surfaces	2-42
Inserting a tooling split	2-43
Adding chamfers	2-44
Creating an exploded view	2-45



Challenge 5: Undercut Analysis	2-46
Open the document: Undercut Analysis	2-47
Performing an undercut analysis	2-47
Creating the parting lines	2-48
Creating the shut-off surfaces	2-49
Creating the parting surfaces	2-50
Inserting a tooling split	2-51
Adding the 1 st slide core	2-52
Adding the 2 nd slide core	2-53
Assigning material	2-54
Calculating the mass	2-54




Challenge 6: Virtual Part Creation	2-56
Open the document: Virtual part Creation	2-57
Hiding components	2-57
Inserting a new part	2-58
Working in the part level	2-59
Inserting the 2 nd part	2-60
Moving the solid bodies	2-61
Creating an intersect feature	2-62
Creating a combine-subtract feature	2-63




Working in the assembly level	2-64
Assigning material	2-65
Calculating the mass	2-65

CSWPA – Weldments


Chapter 3: Weldments 3-1




Challenge 1: Creating the Weldments profile	3-3
Starting a new part document	3-3
Enabling the Weldments tab	3-3
Sketching the first weldment profile	3-4
Creating the second weldment profile	3-5
Sketching the profile	3-5
Showing the weldment profiles folder	3-6
Creating a new weldment part	3-7
Adding structural members	3-8
Applying material	3-9
Calculating the mass	3-9
Changing the structural members	3-10
Calculating the mass	3-11



Challenge 2: Weldment Frame 3.sldprt	3-12
Open the document: Weldment Frame 3	3-12
Adding structural members	3-13
Creating the parallel group	3-14
Trimming the parallel group	3-15
Applying material	3-17
Calculating the mass	3-17
Creating the Upper Braces	3-18
Trimming the first Upper Braces	3-18
Updating the Cut list	3-20
Creating the Lower Braces	3-21
Trimming the Lower Braces	3-21
Adding End Caps	3-24
Calculating the final mass	3-25




Challenge 3: Weldment Frame 4.sldprt	3-26
Open the document: Weldment Frame 4	3-26
Creating a 3D sketch	3-26



Adding structural members	3-31
Creating the parallel group	3-32
Trimming the tubes	3-33

Challenge 4: Weldment Frame 5.sldprt 3-37

Open the document: Weldment Frame 5	3-37
Assigning material	3-37
Modifying the properties	3-38
Transferring to a drawing	3-39
Adding a drawing view	3-39
Inserting the weldment cut list	3-40
Adding balloons	3-41




CSWPA – Sheet Metal

Chapter 4: Sheet Metal 4-1

Challenge 1: Converting to Sheet Metal 4-3

Opening the document: Convert to SM	4-3
Enabling the sheet metal tab	4-3
Making a copy of the solid model	4-3
Converting to sheet metal	4-5
Calculating the mass	4-6
Measuring the flat pattern	4-7
Creating a Hem	4-8
Calculating the mass	4-10




Challenge 2: Sheet Metal Cut List 4-11


Open the document: SM Cut List	4-11
Modifying the first bend radius	4-11
Measuring the flat length	4-12
Modifying the second bend radius	4-13
Measuring the flat length	4-13
Finding the Bounding Box Area	4-14



Challenge 3: Sheet Metal Part 4-15

Open the document: SM Part	4-15
Creating the Edge Flanges	4-15
Closing the corners	4-16





Creating a cutout	4-17
Adding a Miter Flange	4-18
Mirroring the features	4-22
Calculating the mass	4-23
Changing the K-Factor value	4-24
Measuring the flat length	4-24
Adding hems	4-25
Adding a form feature	4-26
Creating a linear pattern	4-27
Calculating the mass	4-27

CSWPA – Surfacing

Chapter 5: Surfacing

5-1




Challenge 1: Inlet-Outlet Patches	5-3
Open the document: Inlet-Outlet Patches	5-3
Enabling the surfaces tab	5-3
Patching the first opening	5-4
Measuring the surface area	5-5
Deleting the outlet port	5-5
Filling the openings	5-6
Measuring the surface area	5-7
Thickening the surface body	5-8
Creating a section view	5-8
Calculating the mass	5-9



Challenge 2: Mouse from Sketch Picture	5-10
Open the document: Mouse from Sketch Picture	5-10
Examining the sketch pictures	5-10
Tracing the profile	5-11
Extruding a surface	5-11
Trimming the surfaces	5-13
Creating the boundary profiles	5-15
Hiding and suppressing the references	5-17
Creating the boundary surfaces	5-18
Creating a filled surface	5-22
Creating a knit surface	5-23
Mirroring the surface bodies	5-23

Thickening the surface body	5-24
Assigning material	5-27
Calculating the mass	5-28



Challenge 3: Plastic Ball	5-29
Open the document: Plastic Ball	5-29
Hiding the solid body	5-29
Extending the surface	5-30
Trimming the surfaces	5-31
Making a copy of the solid body	5-32
Cutting the surface	5-33
Extending the offset surface	5-36
Measuring the surface area	5-39



Challenge 4: Tube Patches	5-40
Open the document: Tube Patches	5-40
Trimming the surface body	5-42
Measuring the surface area	5-44
Creating the lofted surfaces	5-45
Creating the filled surfaces	5-47
Measuring the total surface area	5-53



Challenge 5: Remote Body	5-54
Open the document: Remote Body	5-54
Tracing the sketch picture	5-54
Creating a 3D sketch	5-56
Creating a lofted surface	5-56
Measuring the surface area	5-57
Knitting the surfaces	5-58
Mirroring the surface body	5-59
Thickening the surface body	5-60
Creating a section view	5-60
Calculating the final mass	5-61

Glossary and Index by chapters

SOLIDWORKS 2019 Quick-Guides:

Quick Reference Guide to SOLIDWORKS 2019 Command Icons and Toolbars.