


Kuang-Hua Chang, Ph.D.

MACHINING SIMULATION USING **SOLIDWORKS[®] CAM 2018**



Visit the following websites to learn more about this book:




Table of Contents

Preface i

Acknowledgments iv

About the Author v

About the Cover vi

Table of Contents vii

Lesson 1: Introduction to SOLIDWORKS CAM	1
1.1 Overview of the Lesson	1
1.2 Virtual Machining	2
1.3 SOLIDWORKS CAM Packages	4
1.4 User Interface	6
1.5 Opening Lesson 1 Model and Entering SOLIDWORKS CAM	9
1.6 Extracting Machinable Features	10
1.7 Technology Database	11
1.8 Tutorial Examples	11
Lesson 2: NC Part Programming	17
2.1 Overview of the Lesson	17
2.2 Basics of NC Machines	17
2.3 NC Words and NC Blocks	19
2.4 Alphabet Address Codes	20
2.5 Preparatory Functions or G Words	21
2.6 Machine Functions or M Codes	26
2.7 NC Part Programming	27
2.8 Tool Functions and Compensations	31
2.9 NC Program Review and Verification	34
2.10 Exercises	35
Lesson 3: SOLIDWORKS CAM NC Editor	37
3.1 Overview of the Lesson	37
3.2 Capabilities of SOLIDWORKS CAM NC Editor	37
3.3 User Interface	38
3.4 NC Program Examples	39
3.5 Example 1: Trajectory Milling	39
3.6 Example 2: Hole Drilling	43
3.7 Example 3: Profile Milling	46
3.8 Example 4: Turn Finish Operation	50
3.9 G-code Viewers and Editors	53
3.10 Exercises	59
Lesson 4: A Quick Run-Through	61
4.1 Overview of the Lesson	61
4.2 The Simple Plate Example	61
4.3 Using SOLIDWORKS CAM	62
4.4 The Post Process and G-Code	71
4.5 Reviewing Machining Time	75
4.6 Exercises	76

Lesson 5: Machining 2.5 Axis Features.....	79
5.1 Overview of the Lesson	79
5.2 The 2.5 Axis Features Example	80
5.3 Using SOLIDWORKS CAM.....	82
5.4 Creating a Face Milling Operation.....	86
5.5 Re-Ordering Machining Operations.....	88
5.6 Reviewing Machining Time.....	91
5.7 The Post Process and G-Code.....	91
5.8 Stepping Through the Toolpath	93
5.9 Exercises	93
Lesson 6: Machining a Freeform Surface and Limitations.....	95
6.1 Overview of the Lesson	95
6.2 The Freeform Surface Example	96
6.3 Using SOLIDWORKS CAM.....	98
6.4 Selecting Avoid Feature to Correct the Toolpath	102
6.5 Modifying the Area Clearance Toolpath.....	105
6.6 Reviewing the Machined Part Quality	107
6.7 Reviewing and Modifying the Z Level Operation	108
6.8 Exercises	110
Lesson 7: Multipart Machining.....	113
7.1 Overview of the Lesson	113
7.2 The Multipart Machining Example.....	113
7.3 Using SOLIDWORKS CAM.....	115
7.4 The Sequence of Part Machining.....	119
7.5 The G-code.....	120
7.6 Exercises	124
Lesson 8: Multiplane Machining	127
8.1 Overview of the Lesson	127
8.2 The Multiplane Machining Example	128
8.3 Using SOLIDWORKS CAM.....	131
8.4 The Sequence of Part Machining	137
8.5 Reviewing the G-code.....	138
8.6 Exercises	140
Lesson 9: Tolerance-Based Machining.....	145
9.1 Overview of the Lesson	145
9.2 The Machining Examples	146
9.3 Using <i>DimXpert for Parts</i> to Define Tolerances.....	150
9.4 Tolerance-Based Machining Settings	152
9.5 Carrying Out Tolerance-Based Machining.....	155
9.6 Exercises	160
Lesson 10: Turning a Stepped Bar.....	161
10.1 Overview of the Lesson	161
10.2 The Stepped Bar Example.....	162
10.3 Using SOLIDWORKS CAM.....	164
10.4 Reviewing the G-code of Turning Sequences.....	171
10.5 Exercises	173

Lesson 11: Turning a Stub Shaft.....	175
11.1 Overview of the Lesson	175
11.2 The Stub Shaft Example	176
11.3 Using SOLIDWORKS CAM.....	178
11.4 Cutting the Thread	184
11.5 Boring the Hole.....	191
11.6 Exercises	192
 Lesson 12: Machining a Robotic Forearm Member	195
12.1 Overview of the Lesson	195
12.2 The Forearm Members of the SoRo Robotic Arm	196
12.3 Manufacturing of the Rover Forearm Members	198
12.4 Five Machining Setups.....	198
12.5 Modifications of SOLIDWORKS CAM Operations	204
12.6 Post-Processing and G-Code Modification.....	205
12.7 Machined Part Clean-up.....	206
12.8 Lessons Learned.....	206
 Lesson 13: Turning a Scaled Baseball Bat	209
13.1 Overview of the Lesson	209
13.2 The Scaled Baseball Bat Solid Model	209
13.3 Turning the Scaled Baseball Bat.....	210
13.4 Machining Operations.....	210
13.5 Modifications of SOLIDWORKS CAM Operations	212
13.6 Post-Processing and G-Code Modification.....	215
13.7 Turning on a HAAS CNC Lathe.....	216
13.8 Lessons Learned.....	217
 Lesson 14: Third-Party CAM Modules	219
14.1 Overview of the Lesson	219
14.2 Freeform Surface Milling Example	220
14.3 Removing SOLIDWORKS CAM.....	220
14.4 CAMWorks.....	221
14.5 HSMWorks	229
14.6 Mastercam for SOLIDWORKS	240
14.7 Exercises	255
 Appendix A. Machinable Features.....	257
Appendix B: Machining Operations	265
Appendix C: Alphabetical Address Codes.....	267
Appendix D: Preparatory Functions	271
Appendix E: Machine Functions.....	273