


# Parametric Modeling

## with Autodesk® Inventor® 2020



Randy H. Shih

Visit the following websites to learn more about this book:



[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

# Table of Contents

|  |      |
|--|------|
| <b>Preface</b>   | i    |
| <b>Acknowledgments</b>                                       | ii   |
| <b>Table of Contents</b>                                     | iii  |
| <b>Autodesk Inventor Certified User Examination Overview</b> | xiii |
| <br>   |      |
| <b>Chapter 1</b>   |      |
| <b>Getting Started</b>                                       |      |
| <br>   |      |
| Introduction   | 1-3  |
| Development of Computer Geometric Modeling                   | 1-3  |
| Feature-Based Parametric Modeling                            | 1-7  |
| Getting Started with Autodesk Inventor                       | 1-8  |
| The Screen Layout and Getting Started Toolbar                | 1-9  |
| The New File Dialog Box and Units Setup                      | 1-10 |
| The Default Autodesk Inventor Screen Layout                  | 1-11 |
| File Menu  | 1-12 |
| Quick Access Toolbar   | 1-12 |
| Ribbon Tabs and Tool Panels                                  | 1-12 |
| Online Help Panel  | 1-12 |
| 3D Model Toolbar   | 1-13 |
| Graphics Window  | 1-13 |
| Message and Status Bar                                       | 1-13 |
| Mouse Buttons  | 1-14 |
| [Esc] - Canceling Commands                                   | 1-14 |
| Autodesk Inventor Help System                                | 1-15 |
| Data Management Using Inventor Project files                 | 1-16 |
| Setup of a New Inventor Project                              | 1-17 |
| The Content of the Inventor Project File                     | 1-20 |
| Leaving Autodesk Inventor                                    | 1-20 |
| <br>   |      |
| <b>Chapter 2</b>   |      |
| <b>Parametric Modeling Fundamentals</b>                      |      |
| <br>   |      |
| Introduction   | 2-3  |
| The Adjuster Design  | 2-4  |
| Starting Autodesk Inventor                                   | 2-4  |
| The Default Autodesk Inventor Screen Layout                  | 2-6  |
| Sketch Plane – It is an XY Monitor, but an XYZ World         | 2-7  |
| Creating Rough Sketches                                      | 2-9  |
| Step 1: Creating a Rough Sketch                              | 2-10 |
| Graphics Cursors   | 2-10 |
| Geometric Constraint Symbols                                 | 2-11 |
| Step 2: Apply/Modify Constraints and Dimensions              | 2-12 |
| Dynamic Viewing Functions – Zoom and Pan                     | 2-15 |

|   |      |
|---|------|
| Modifying the Dimensions of the Sketch        | 2-15 |
| Step 3: Completing the Base Solid Feature     | 2-16 |
| Isometric View                                | 2-17 |
| Dynamic Rotation of the 3D Block - Free Orbit | 2-18 |
| Dynamic Viewing - Quick Keys                  | 2-20 |
| Viewing Tools – Standard Toolbar              | 2-21 |
| Display Modes                                 | 2-25 |
| Orthographic vs. Perspective                  | 2-25 |
| Disable the Heads-Up Display Option           | 2-26 |
| Step 4-1: Adding an Extruded Feature          | 2-27 |
| Step 4-2: Adding a Cut Feature                | 2-31 |
| Step 4-3: Adding another Cut Feature          | 2-34 |
| Save the Model                                | 2-36 |
| Review Questions                              | 2-38 |
| Exercises                                     | 2-39 |

### **Chapter 3**

## **Constructive Solid Geometry Concepts**

|  |      |
|--|------|
| Introduction                           | 3-3  |
| Binary Tree                            | 3-4  |
| The Locator Design                     | 3-5  |
| Modeling Strategy - CSG Binary Tree    | 3-6  |
| Starting Autodesk Inventor             | 3-7  |
| Base Feature                           | 3-8  |
| GRID Display Setup                     | 3-9  |
| Model Dimensions Format                | 3-12 |
| Modifying the Dimensions of the Sketch | 3-12 |
| Repositioning Dimensions               | 3-13 |
| Using the Measure Tools                | 3-14 |
| Completing the Base Solid Feature      | 3-17 |
| Creating the Next Solid Feature        | 3-18 |
| Creating a Cut Feature                 | 3-22 |
| Creating a Placed Feature              | 3-25 |
| Creating a Rectangular Cut Feature     | 3-27 |
| Save the Model                         | 3-29 |
| Review Questions                       | 3-30 |
| Exercises                              | 3-31 |

### **Chapter 4**

## **Model History Tree**

|                               |     |
|-------------------------------|-----|
| Introduction                  | 4-3 |
| The Saddle Bracket Design     | 4-4 |
| Starting Autodesk Inventor    | 4-4 |
| Modeling Strategy             | 4-5 |
| The Autodesk Inventor Browser | 4-6 |

|  |      |
|--|------|
| Creating the Base Feature                                    | 4-6  |
| Adding the Second Solid Feature                              | 4-9  |
| Creating a 2D Sketch   | 4-10 |
| Renaming the Part Features                                   | 4-12 |
| Adjusting the Width of the Base Feature                      | 4-13 |
| Adding a Placed Feature                                      | 4-14 |
| Creating a Rectangular Cut Feature                           | 4-16 |
| History-Based Part Modifications                             | 4-17 |
| A Design Change  | 4-18 |
| Assigning and Calculating the Associated Physical Properties | 4-21 |
| Review Questions   | 4-23 |
| Exercises  | 4-24 |

## **Chapter 5**

### **Parametric Constraints Fundamentals**

|  |      |
|--|------|
| Constraints and Relations                        | 5-3  |
| Create a Simple Triangular Plate Design          | 5-3  |
| Fully Constrained Geometry                       | 5-4  |
| Starting Autodesk Inventor                       | 5-4  |
| Displaying Existing Constraints                  | 5-5  |
| Applying Geometric/Dimensional Constraints       | 5-7  |
| Over-Constraining and Driven Dimensions          | 5-11 |
| Deleting Existing Constraints                    | 5-12 |
| Using the Auto Dimension Command                 | 5-13 |
| Constraint and Sketch Settings                   | 5-18 |
| Parametric Relations                             | 5-19 |
| Dimensional Values and Dimensional Variables     | 5-21 |
| Parametric Equations                             | 5-22 |
| Viewing the Established Parameters and Relations | 5-24 |
| Saving the Model File                            | 5-25 |
| Using the Measure Tools                          | 5-26 |
| Review Questions                                 | 5-30 |
| Exercises  | 5-31 |

## **Chapter 6**

### **Geometric Construction Tools**

|   |      |
|---|------|
| Introduction                                      | 6-3  |
| The Gasket Design                                 | 6-3  |
| Modeling Strategy                                 | 6-4  |
| Starting Autodesk Inventor                        | 6-5  |
| Create a 2D Sketch                                | 6-6  |
| Edit the Sketch by Dragging the Sketched Entities | 6-8  |
| Add Additional Constraints                        | 6-10 |
| Use the Trim and Extend Commands                  | 6-11 |
| The Auto Dimension Command                        | 6-13 |

|  |      |
|--|------|
| Create Fillets and Completing the Sketch | 6-15 |
| Fully Constrained Geometry               | 6-16 |
| Profile Sketch                           | 6-18 |
| Redefine the Sketch and Profile          | 6-19 |
| Create an Offset Cut Feature             | 6-23 |
| Review Questions                         | 6-26 |
| Exercises                                | 6-27 |

## **Chapter 7**

### **Parent/Child Relationships and the BORN Technique**

|  |      |
|--|------|
| Introduction                                     | 7-3  |
| The BORN Technique                               | 7-3  |
| The U-Bracket Design                             | 7-4  |
| Sketch Plane Settings                            | 7-5  |
| Apply the BORN Technique                         | 7-6  |
| Create the 2D Sketch for the Base Feature        | 7-8  |
| Create the First Extrude Feature                 | 7-11 |
| The Implied Parent/Child Relationships           | 7-12 |
| Create the Second Solid Feature                  | 7-12 |
| Create a Cut Feature                             | 7-16 |
| The Second Cut Feature                           | 7-17 |
| Examine the Parent/Child Relationships           | 7-19 |
| Modify a Parent Dimension                        | 7-20 |
| A Design Change                                  | 7-21 |
| Feature Suppression                              | 7-22 |
| A Different Approach to the Center_Drill Feature | 7-23 |
| Suppress the Rect_Cut Feature                    | 7-25 |
| Create a Circular Cut Feature                    | 7-26 |
| A Flexible Design Approach                       | 7-28 |
| View and Edit Material Properties                | 7-29 |
| Review Questions                                 | 7-31 |
| Exercises  | 7-32 |

## **Chapter 8**

### **Part Drawings and 3D Model-Based Definition**

|   |      |
|---|------|
| Drawings from Parts and Associative Functionality | 8-3  |
| 3D Model-Based Definition                         | 8-4  |
| Starting Autodesk Inventor                        | 8-5  |
| Drawing Mode - 2D Paper Space                     | 8-5  |
| Drawing Sheet Format                              | 8-7  |
| Using the Pre-Defined Drawing Sheet Formats       | 8-9  |
| Delete, Activate, and Edit Drawing Sheets         | 8-11 |
| Add a Base View                                   | 8-12 |
| Create Projected Views                            | 8-13 |
| Adjust the View Scale                             | 8-14 |

|  |      |
|--|------|
| Repositioning Views                                      | 8-15 |
| Display Feature Dimensions                               | 8-16 |
| Repositioning and Hiding Feature Dimensions              | 8-18 |
| Add Additional Dimensions – Reference Dimensions         | 8-20 |
| Add Center Marks and Center Lines                        | 8-21 |
| Complete the Drawing Sheet                               | 8-24 |
| Associative Functionality – Modifying Feature Dimensions | 8-25 |
| 3D Model-Based Definition                                | 8-28 |
| Review Questions   | 8-36 |
| Exercises  | 8-37 |

## **Chapter 9**

### **Datum Features and Auxiliary Views**

|   |      |
|---|------|
| Work Features                                   | 9-3  |
| Auxiliary Views in 2D Drawings                  | 9-3  |
| The Rod-Guide Design                            | 9-3  |
| Modeling Strategy                               | 9-4  |
| Starting Autodesk Inventor                      | 9-5  |
| Apply the BORN Technique                        | 9-5  |
| Creating the Base Feature                       | 9-7  |
| Create an Angled Work Plane                     | 9-9  |
| Create a 2D Sketch on the Work Plane            | 9-10 |
| Use the Projected Geometry Option               | 9-10 |
| Complete the Solid Feature                      | 9-14 |
| Create an Offset Work Plane                     | 9-15 |
| Create another Cut Feature Using the Work Plane | 9-16 |
| Start a New 2D Drawing                          | 9-18 |
| Add a Base View                                 | 9-19 |
| Create an Auxiliary View                        | 9-20 |
| Display Feature Dimensions                      | 9-22 |
| Adjust the View Scale                           | 9-24 |
| Retrieving Dimensions in the Auxiliary View     | 9-25 |
| Add Center Marks and Center Lines               | 9-27 |
| Complete the Title Block with iProperties       | 9-30 |
| Edit the Isometric view                         | 9-32 |
| Review Questions                                | 9-33 |
| Exercises                                       | 9-34 |

## **Chapter 10**

### **Introduction to 3D Printing**

|   |       |
|---|-------|
| What is 3D Printing?                          | 10-2  |
| Development of 3D Printing Technologies       | 10-3  |
| Primary Types of 3D Printing Processes        | 10-6  |
| Primary 3D Printing Materials for FDM and FFF | 10-9  |
| From 3D Model to 3D Printed Part              | 10-11 |

|   |       |
|---|-------|
| Starting Autodesk Inventor                            | 10-12 |
| Export the Design as an STL File                      | 10-13 |
| Using the 3D Printing Software to Create the 3D Print | 10-16 |
| Questions   | 10-23 |

## **Chapter 11**

### **Symmetrical Features in Designs**

|  |       |
|--|-------|
| Introduction   | 11-3  |
| A Revolved Design: Pulley                            | 11-3  |
| Modeling Strategy - A Revolved Design                | 11-4  |
| Starting Autodesk Inventor                           | 11-5  |
| Set Up the Display of the Sketch Plane               | 11-5  |
| Creating the 2D Sketch for the Base Feature          | 11-6  |
| Create the Revolved Feature                          | 11-10 |
| Mirroring Features                                   | 11-11 |
| Create a Pattern Leader Using Construction Geometry  | 11-13 |
| Circular Pattern                                     | 11-18 |
| Examine the Design Parameters                        | 11-20 |
| Drawing Mode – Defining a New Border and Title Block | 11-20 |
| Create a Drawing Template                            | 11-24 |
| Create the Necessary Views                           | 11-25 |
| Retrieve Model Annotations – Features Option         | 11-28 |
| Associative Functionality – A Design Change          | 11-30 |
| Add Centerlines to the Pattern Feature               | 11-32 |
| Complete the Drawing                                 | 11-33 |
| Review Questions                                     | 11-36 |
| Exercises  | 11-37 |

## **Chapter 12**

### **Advanced 3D Construction Tools**

|   |       |
|---|-------|
| Introduction                              | 12-3  |
| A Thin-Walled Design: Dryer Housing       | 12-3  |
| Modeling Strategy                         | 12-4  |
| Starting Autodesk Inventor                | 12-5  |
| Set Up the Display of the Sketch Plane    | 12-5  |
| Create the 2D Sketch for the Base Feature | 12-6  |
| Create a Revolved Feature                 | 12-9  |
| Create Offset Work Planes                 | 12-10 |
| Start 2D Sketches on the Work Planes      | 12-11 |
| Create a Lofted Feature                   | 12-14 |
| Create an Extruded Feature                | 12-16 |
| Complete the Extruded Feature             | 12-18 |
| Create 3D Rounds and Fillets              | 12-19 |
| Create a Shell Feature                    | 12-20 |
| Create a Pattern Leader                   | 12-21 |



|                              |       |
|------------------------------|-------|
| Create a Rectangular Pattern | 12-24 |
| Create a Swept Feature       | 12-26 |
| Define a Sweep Path          | 12-26 |
| Define the Sweep Section     | 12-28 |
| Complete the Swept Feature   | 12-30 |
| Review Questions             | 12-32 |
| Exercises                    | 12-33 |

## **Chapter 13**

### **Sheet Metal Designs**

|  |       |
|--|-------|
| Sheet Metal Processes                      | 13-3  |
| Sheet Metal Modeling                       | 13-5  |
| K-Factor                                   | 13-6  |
| The Actuator Bracket Design                | 13-7  |
| Starting Autodesk Inventor                 | 13-8  |
| Sheet Metal Defaults                       | 13-9  |
| Create the Base Face Feature of the Design | 13-12 |
| Using the Flange Command                   | 13-15 |
| Mirroring Features                         | 13-19 |
| Create a Cut Feature                       | 13-20 |
| Create a Fold Feature                      | 13-22 |
| Create the Associated Flat Pattern         | 13-25 |
| Confirm the Flattened Length               | 13-26 |
| Create a 2D Sheet Metal Drawing            | 13-27 |
| Review Questions                           | 13-34 |
| Exercises                                  | 13-35 |

## **Chapter 14**

### **Assembly Modeling - Putting It All Together**

|                                     |       |
|-------------------------------------|-------|
| Introduction                        | 14-3  |
| Assembly Modeling Methodology       | 14-4  |
| The Shaft Support Assembly          | 14-5  |
| Additional Parts                    | 14-5  |
| (1) Collar                          | 14-5  |
| (2) Bearing                         | 14-6  |
| (3) Base-Plate                      | 14-6  |
| (4) Cap-Screw                       | 14-7  |
| Starting Autodesk Inventor          | 14-8  |
| Placing the First Component         | 14-9  |
| Placing the Second Component        | 14-10 |
| Degrees of Freedom and Constraints  | 14-11 |
| Assembly Constraints                | 14-12 |
| Apply the First Assembly Constraint | 14-15 |
| Apply a Second Mate Constraint      | 14-16 |
| Constrained Move                    | 14-17 |

|   |       |
|---|-------|
| Apply a Flush Constraint                                | 14-18 |
| Placing the Third Component                             | 14-20 |
| Applying an Insert Constraint                           | 14-21 |
| Assemble the Cap-Screws                                 | 14-22 |
| Exploded View of the Assembly                           | 14-23 |
| Editing the Components                                  | 14-25 |
| Adaptive Design Approach                                | 14-26 |
| Delete and Re-apply Assembly Constraints                | 14-30 |
| Set up a Drawing of the Assembly Model                  | 14-32 |
| Creating a Parts List                                   | 14-34 |
| Edit the Parts List                                     | 14-35 |
| Change the Material Type                                | 14-37 |
| Add the Balloon Callouts                                | 14-39 |
| Completing the Title Block Using the iProperties option | 14-39 |
| Bill of Materials                                       | 14-41 |
| (a) BOM from Parts List                                 | 14-41 |
| (b) BOM from Assembly Model                             | 14-42 |
| Review Questions  | 14-43 |
| Exercises   | 14-44 |

## **Chapter 15**

### **Content Center and Basic Motion Analysis**

|   |       |
|---|-------|
| Introduction  | 15-3  |
| The Crank-Slider Assembly                               | 15-4  |
| Create the Required Parts                               | 15-4  |
| Starting Autodesk Inventor                              | 15-6  |
| Placing the First Component                             | 15-7  |
| Placing the Second Component                            | 15-8  |
| Apply the Assembly Constraints                          | 15-9  |
| Apply a Second Mate Constraint                          | 15-10 |
| Constrained Move  | 15-11 |
| Place the Third Component                               | 15-11 |
| Assemble the CS-Rod Part                                | 15-14 |
| Make a Copy of the Pin                                  | 15-15 |
| Assemble the CS-Slider Part                             | 15-16 |
| Add an Angle Constraint to Fully Constrain the Assembly | 15-21 |
| Interference Analysis                                   | 15-23 |
| Basic Motion Analysis                                   | 15-24 |
| 3D Grip Editing the CS-Slider Part                      | 15-27 |
| Review Questions  | 15-31 |
| Exercises   | 15-32 |

## **Chapter 16**

### **2D Design Reuse, Collision and Contact**

|              |      |
|--------------|------|
| Introduction | 16-3 |
|--------------|------|

|  |       |
|--|-------|
| The Geneva CAM Assembly                  | 16-4  |
| Download the Geneva-Wheel DWG File       | 16-4  |
| Opening AutoCAD DWG File in Inventor     | 16-5  |
| Switch to the AutoCAD DWG Layout         | 16-6  |
| 2D Design Reuse                          | 16-8  |
| Complete the Imported Sketch             | 16-12 |
| Create the First Solid Feature           | 16-14 |
| Create a Mirrored Feature                | 16-15 |
| Circular Pattern                         | 16-16 |
| Complete the Geneva Wheel Design         | 16-17 |
| Additional Parts                         | 16-18 |
| Start a New Assembly                     | 16-20 |
| Placing the Second Component             | 16-21 |
| The Assembly Joint Command               | 16-22 |
| Create a Joint Connection                | 16-23 |
| Constrained Move                         | 16-24 |
| Placing a Copy of the Geneva-Driver Part | 16-24 |
| Create a Second Joint Connection         | 16-25 |
| Assemble the Geneva-Pin Part             | 16-26 |
| Repositioning the Pieces                 | 16-28 |
| Animation with Drive Tool                | 16-29 |
| Use the Inventor Contact Solver          | 16-31 |
| Constrained Move with Contact Solver     | 16-33 |
| Review Questions                         | 16-34 |
| Exercises                                | 16-35 |

## **Chapter 17**

### **Introduction to Stress Analysis**

|  |       |
|--|-------|
| Introduction                                     | 17-2  |
| Problem Statement                                | 17-4  |
| Preliminary Analysis                             | 17-4  |
| • Maximum Normal Stress                          | 17-4  |
| • Maximum Displacement                           | 17-5  |
| Finite Element Analysis Procedure                | 17-6  |
| Create the Autodesk Inventor Part                | 17-7  |
| Create the 2D Sketch for the Plate               | 17-7  |
| Assigning the Material Properties                | 17-10 |
| Switch to the Stress Analysis Module             | 17-11 |
| Apply Constraints and Loads                      | 17-14 |
| Create a Mesh and Run the Solver                 | 17-16 |
| Refinement of the FEA Mesh – Global Element Size | 17-18 |
| Refinement of the FEA Mesh – Local Element Size  | 17-20 |
| Comparison of Results                            | 17-23 |
| Create an HTML Report                            | 17-24 |
| Geometric Considerations of Finite Elements      | 17-25 |
| Conclusion                                       | 17-26 |

|                                    |       |
|------------------------------------|-------|
| Summary of Modeling Considerations | 17-26 |
| Review Questions                   | 17-27 |
| Exercises                          | 17-28 |

## **Appendix**

## **Index**