
# Parametric Modeling with SOLIDWORKS 2020

Covers materials found on the CSWA exam



## Visit the following websites to learn more about this book:









### **Table of Contents**

Preface Acknowledgments Table of Contents Certified SOLIDWORKS Associate (CSWA) Exam Overview	i ii iii xii
Chapter 1 Getting Started	
Introduction Development of Computer Geometric Modeling Feature-Based Parametric Modeling Getting Started with SOLIDWORKS Units Setup SOLIDWORKS Screen Layout Mouse Buttons [Esc] - Canceling Commands Online Help SOLIDWORKS Search Leaving SOLIDWORKS Creating a CAD Files Folder	1-2 1-2 1-6 1-7 1-10 1-12 1-18 1-18 1-19 1-20 1-20
Chapter 2 Parametric Modeling Fundamentals	
Introduction The Adjuster Design Starting SOLIDWORKS SOLIDWORKS Screen Layout Units Setup Creating Rough Sketches Step 1: Creating a Rough Sketch Graphics Cursors Geometric Relation Symbols Step 2: Apply/Modify Relations and Dimensions Changing the Dimension Standard Viewing Functions – Zoom and Pan Modifying the Dimensions of the Sketch Step 3: Completing the Base Solid Feature Isometric View Rotation of the 3-D Model – Rotate View Rotation and Panning – Arrow keys Viewing – Quick Keys Viewing Tools – Heads-up View Toolbar View Orientation Display Style	2-3 2-4 2-4 2-5 2-6 2-7 2-8 2-8 2-10 2-11 2-12 2-13 2-14 2-15 2-16 2-18 2-19 2-21 2-22 2-23

Orthographic vs. Perspective	2-23
Sketch Plane	2-24
Step 4-1: Adding an Extruded Boss Feature	2-26
Step 4-2: Adding an Extruded Cut Feature	2-29
Save the Part File	2-31
Questions	2-32
Exercises	2-33
Chapter 3	
Constructive Solid Geometry Concepts	
Introduction	3-3
Binary Tree	3-4
The Locator Design	3-5
Modeling Strategy – CSG Binary Tree	3-6
Starting SOLIDWORKS and Activating the CommandManager	3-7
GRID and SNAP Intervals Setup	3-9
Base Feature Modifying the Dimensions of the Sketch	3-9 2-12
Modifying the Dimensions of the Sketch	3-12 3-12
Repositioning Dimensions Completing the Base Solid Feature	3-12
Creating the Next Solid Feature	3-12
Creating an Extruded Cut Feature	3-17
Creating a Hole with the <i>Hole Wizard</i>	3-20
Creating a Rectangular Extruded Cut Feature	3-23
Using the View Selector	3-26
Questions	3-28
Exercises	3-29
Chapter 4	
Feature Design Tree	
Introduction	4-3
Starting SOLIDWORKS	4-4
Creating a User-Defined Part Template	4-5
The Saddle Bracket Design	4-9
Modeling Strategy	4-10
The SOLIDWORKS FeatureManager Design Tree	4-11
Creating the Base Feature	4-11
Adding the Second Solid Feature	4-14
Creating a 2D Sketch	4-15
Renaming the Part Features	4-17
Adjusting the Width of the Base Feature	4-18
Adding a Hole	4-19 4-22
Creating a Rectangular Extruded Cut Feature	4-22 4-23
History-Based Part Modifications  A Design change	4-23 4-24
A Design Change	4-24

Table of Contents	v

FeatureManager Design Tree Views	4-26
Selecting a Material and Viewing the Mass Properties	4-28
Questions	4-30
Exercises	4-31
Chapter 5	
Geometric Relations Fundamentals	
DIMENSIONS and RELATIONS	5-3
Create a Simple Triangular Plate Design	5-3
Fully Defined Geometry	5-4
Starting SOLIDWORKS and Activating the CommandManager	5-4
Displaying Existing Relations	5-6
Applying Geometric Relations/Dimensional Constraints	5-7
Over-Defining and Driven Dimensions	5-13
Deleting Existing Relations	5-14
Using the Fully Define Sketch Tool	5-15
Adding Additional Geometry	5-16
Relations Settings	5-19
Parametric Relations	5-20
Dimensional Values and Dimensional Variables	5-22
Parametric Equations	5-23
Viewing the Established Equations	5-23
Global Variables	5-26
Viewing/Editing Equations and Global Variables Using	
the Dimension Modify Dialog Box	5-30
View Options in the Equations, Global Variables, and	
Dimensions Dialog Box	5-31
Direct Input of Equations in PropertyManager Fields	5-33
Completing and Saving the Part File	5-34
Questions	5-35
Exercises	5-36
Chapter 6	
Geometric Construction Tools	
Introduction	6-3
The Gasket Design	6-3
Modeling Strategy	6-4
Starting SOLIDWORKS	6-5
Creating a 2D Sketch	6-6
Editing the Sketch by Dragging the Entities	6-8
Adding Additional Relations	6-10
Using the <i>Trim</i> and <i>Extend</i> Commands	6-11
Adding Dimensions with the Fully Define Sketch Tool	6-14
Fully Defined Geometry	6-16
Creating Fillets and Completing the Sketch	6-17

Profile Sketch	6-18
Redefining the Sketch and Profile using Contour Selection	6-19
Selecting Items by Box and Lasso	6-23
Create an OFFSET Extruded Cut Feature	6-25
Alternate Construction Method - Thin Feature Option	6-29
Questions	6-32
Exercises	6-33
Chapter 7	
Parent/Child Relationships and the BORN Technique	
Introduction	7-3
The BORN Technique	7-3
The U-Bracket Design	7-4
Starting SOLIDWORKS and Activating the CommandManager	7-4
Applying the BORN Technique	7-5
Creating the 2D Sketch for the Base Feature	7-7
Creating the First Extrude Feature	7-13
The Implied Parent/Child Relationships	7-13
Creating the Second Solid Feature	7-14
Creating the First Extruded Cut Feature	7-17
Creating the Second Extruded Cut Feature	7-18
Examining the Parent/Child Relationships	7-19
Modify a Parent Dimension	7-21
A Design Change	7-22
Feature Suppression	7-23
A Different Approach to the CENTER_DRILL Feature	7-24
Suppress the Rect_Cut Feature	7-25
Creating a Circular Extruded Cut Feature	7-26
A Flexible Design Approach	7-28
Save Part File	7-29
Questions	7-30
Exercises	7-31
Chapter 8	
Part Drawings and Associative Functionality	
Drawings from Parts and Associative Functionality	8-3
Starting SOLIDWORKS	8-4
Drawing Mode	8-4
Setting Document Properties	8-7
Setting Sheet Properties Using the Pre-Defined Sheet Formats	8-8
Creating Three Standard Views	8-8
Repositioning Views	8-9
Adding a New Sheet	8-10
Adding a Base View	8-11
Adding an Isometric View using the View Palette	8-13

Exercises

vii

9-36

Introduction to 3D Printing	
What is 3D Printing? Development of 3D Printing Technologies Primary Types of 3D Printing Processes Primary 3D Printing Materials for FDM and FFF From 3D Model to 3D Printed Part Starting SOLIDWORKS SOLIDWORKS Print3D Command Using the 3D Printing Software to Create the 3D Print Questions	10-2 10-3 10-6 10-9 10-11 10-12 10-13 10-18 10-26
Chapter 11 Symmetrical Features in Designs	
Introduction A Revolved Design: PULLEY Modeling Strategy – A Revolved Design Starting SOLIDWORKS Creating the 2D Sketch for the Base Feature Creating the Revolved Feature Mirroring Features Creating an Extruded Cut Feature using Construction Geometry Circular Pattern Drawing Mode – Defining a New Border and Title Block Creating a New Drawing Template Creating Views Retrieve Dimensions – Model Items Command Save the Drawing File Associative Functionality – A Design Change Adding Centerlines to the Pattern Feature Completing the Drawing Questions Exercises	11-3 11-3 11-4 11-5 11-5 11-9 11-10 11-11 11-16 11-18 11-21 11-22 11-25 11-26 11-27 11-29 11-30 11-33 11-34
Chapter 12 Advanced 3D Construction Tools	
Introduction A Thin-Walled Design: Dryer Housing Modeling Strategy Starting SOLIDWORKS Creating the 2D Sketch for the Base Feature Create a Revolved Boss Feature Creating Offset Reference Planes Creating 2D Sketches on the Reference Planes	12-3 12-3 12-4 12-5 12-5 12-8 12-9 12-10

	Table of Contents
Creating a Lofted Feature Creating an Extruded Boss Feature Completing the Extruded Boss Feature Creating 3D Rounds and Fillets Creating a Shell Feature Create a Rectangular Extruded Cut Feature Creating a Linear Pattern Creating a Swept Feature Using PhotoView 360, Scenes, and Appearances Questions Exercises	12-13 12-15 12-16 12-17 12-18 12-19 12-21 12-24 12-29 12-33 12-34
Chapter 13 Sheet Metal Designs	
Sheet Metal Processes Sheet Metal Modeling K-Factor The Actuator Bracket Design Starting SOLIDWORKS and Opening the Sheet Metal Toolbar Creating the Base Feature of the Design Creating an Edge Flange Adding a Tab Creating a Cut Feature Creating a Bend Flattening the Sheet Metal Part Confirm the Flattened Length Creating a Sheet Metal Drawing Sheet Metal Bend Notes Completing the Drawing Questions Exercises	13-3 13-5 13-6 13-7 13-8 13-9 13-14 13-18 13-20 13-22 13-24 13-25 13-26 13-30 13-31 13-34 13-35
Chapter 14 Assembly Modeling – Putting It All Together	
Introduction Assembly Modeling Methodology The Shaft Support Assembly Parts Creating the Collar Using the Chamfer Command Creating the Bearing and Base-Plate Creating the Cap-Screw Starting SOLIDWORKS	14-3 14-3 14-4 14-4 14-4 14-6 14-7 14-8

**Document Properties** 

Inserting the First Component

Inserting the Second Component

ix

14-8

14-9

14-10

Degrees of Freedom	14-11
Assembly Mates	14-11
Apply the First Assembly Mate	14-13
Apply a Second Mate	14-14
Constrained Move	14-15
Apply a Third Mate	14-16
Inserting the Third Component	14-19
Applying Concentric and Coincident Mates	14-19
Assemble the Cap-Screws using SmartMates	14-21
Exploded View of the Assembly	14-25
Save the Assembly Model	14-27
Editing the Components	14-27
Set up a Drawing of the Assembly Model	14-29
Creating a Bill of Materials	14-30
Editing the Bill of Materials	14-32
Completing the Assembly Drawing	14-35
Exporting the Bill of Materials	14-38
Questions	14-39
Exercises	14-40
Chapter 15 Design Library and Basic Motion Study	
Introduction	15-3
The Crank-Slider Assembly	15-4
Creating the Required Parts	15-4
Mate References	15-7
Starting SOLIDWORKS	15-9
Document Properties	15-9
Inserting the First Component	15-10
Inserting the Second Component	15-11
Apply Assembly Mates	15-12
Apply a Mate Using a Context Toolbar	15-13
Constrained Move	15-14
Placing the Third Component Using a Mate Reference	15-14
Assemble the CS-Rod Part	15-15
Inserting a Pin from the SOLIDWORKS Toolbox	15-16
Assemble the CS-Slider Part	15-18
Adding an Angle Mate	15-20
Collision Detection	15-21
Editing the CS-Slider Part in the Assembly	15-23
Basic Motion Analysis	15-24
Questions	15-26
Exercises	15-27

Table of Contents

Introduction	16-3
Γhe SimulationXpress Wizard Interface	16-4
Problem Statement	16-5
Preliminary Analysis	16-5
SOLIDWORKS SimulationXpress Study of the Flat Plate	16-7
Getting Started – Create the SOLIDWORKS Part	16-7
Create a SimulationXpress Study	16-9
Viewing SimulationXpress Results	16-12
Creating a Report and an eDrawings File	16-17
Accuracy of Results	16-18
Closing SimulationXpress and Saving Results	16-20
Questions	16-21
Exercises	16-22
Chapter 17 CSWA Exam Preparation	
Tips about Taking the Certified SOLIDWORKS Associate Examination	17-3
Introduction	17-3
Γhe Part Problem	17-5
The Part Problem Strategy for Aligning the Part to the Default Axis System	17-5 17-6
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature	17-5 17-6 17-6
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation	17-5 17-6
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part	17-5 17-6 17-6 17-8
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part Selecting the Material and Viewing the Mass Properties	17-5 17-6 17-6 17-8 17-10
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part Selecting the Material and Viewing the Mass Properties The Assembly Problem	17-5 17-6 17-6 17-8 17-10 17-16
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part Selecting the Material and Viewing the Mass Properties The Assembly Problem Creating the Parts	17-5 17-6 17-6 17-8 17-10 17-16
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part Selecting the Material and Viewing the Mass Properties The Assembly Problem Creating the Parts Creating the Assembly	17-5 17-6 17-6 17-8 17-10 17-16 17-19 17-20
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part Selecting the Material and Viewing the Mass Properties The Assembly Problem Creating the Parts Creating the Assembly Creating a Reference Coordinate System View the Mass Properties	17-5 17-6 17-6 17-8 17-10 17-16 17-19 17-20 17-21 17-27 17-29
The Part Problem Strategy for Aligning the Part to the Default Axis System Creating the Base Feature Creating a New View Orientation Completing the Part Selecting the Material and Viewing the Mass Properties The Assembly Problem Creating the Parts Creating the Parts Creating the Assembly Creating a Reference Coordinate System View the Mass Properties Questions Exercises	17-5 17-6 17-6 17-8 17-10 17-16 17-19 17-20 17-21 17-27

#### **Appendix**

#### Index