

Mastering Surface Modeling with **SOLIDWORKS® 2021**

Basic through Advanced Techniques



Lani Tran, CSWE

Visit the following websites to learn more about this book:



[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

TABLE OF CONTENTS

Chapter 1: Introduction to Surfaces	1-1
Solids vs. surfaces	1-1
Patching with continuity	1-2
Contact, tangent, and curvature continuous	1-2
When to use surfaces	1-3
When not to use surfaces	1-3
The spline handles	1-4
Check your surface model frequently	1-5
The best approach	1-6
Chapter 2: Surfacing Basics	2-1
Extruded surface	2-1
Creating a curve through reference points	2-2
Creating the planar surfaces	2-3
Knitting the surfaces	2-4
Saving your work	2-4
Revolved surface	2-5
Creating a section view	2-6
Adding fillets	2-6
Swept surface	2-8
Sketching the sweep path	2-8
Creating a swept surface	2-9
Lofted surface	2-10
Sketching the 3rd profile	2-10
Creating a lofted surface	2-11
Boundary surface	2-13
Sketching the 3D splines	2-13
Creating a boundary surface	2-16
Chapter 3: Using Boundary and Lofted Surface	3-1
Starting a new part document	3-1
Creating the 1st reference plane	3-3
Sketching the 1st boundary profile	3-3
Sketching the 2nd boundary profile	3-4
Comparing methods	3-5
Creating a boundary surface	3-6

Creating the 2nd reference plane	3-7
Constructing the 1st trim sketch	3-8
Trimming the bottom	3-9
Constructing a split sketch	3-10
Creating a split line feature	3-11
Deleting faces	3-12
Thickening the surface model	3-13
Adding fillets	3-14
RealView graphics	3-15
Ambient occlusion	3-16
Advanced Surfaces – Surface Trim & Loft	3-17
Creating a revolved surface	3-17
Trimming with a sketch	3-18
Making a surface offset	3-18
Trimming with another sketch	3-19
Creating a lofted surface	3-20
Knitting all surfaces	3-21
Chapter 4: Surface Creation	4-1
Creating the 1 st sketch	4-1
Creating the 2nd sketch	4-2
Trimming the surfaces	4-3
Mirroring a surface body	4-4
Making the loft profiles	4-5
Creating a lofted surface	4-6
Making the fill profiles	4-7
Creating two filled surfaces	4-8
Creating a planar surface	4-9
Knitting the surfaces	4-9
Adding fillets	4-10
Creating a split line feature	4-11
Creating a face fillet with hold line	4-12
Creating more fillets	4-13
Advanced Surfaces – Phone Case	4-14
Opening a part document	4-14
Creating a boundary surface	4-14
Creating the 1 st lofted surface	4-15
Creating the 2 nd lofted surface	4-16
Creating the 3 rd lofted surface	4-17
Hiding the sketches	4-18
Knitting the surface	4-19

Chapter 5: Using Filled, Knit & Boundary Surface	5-1
Opening a part document	5-1
Creating a boundary surface	5-2
Creating a revolved surface	5-3
Creating a filled surface	5-4
Knitting the surfaces	5-5
Creating a split line feature	5-6
Changing the face color	5-7
Shelling the model	5-8
Enabling RealView graphics	5-8
Advanced Surfaces – Using Deform	5-9
Creating a lofted surface	5-9
Creating a deform feature	5-10
Trimming to the final size	5-11
Patching the bottom surface	5-12
Knitting the surfaces	5-12
Adding fillets	5-13
Chapter 6: Using Trim, Thicken & Configurations	6-1
Opening a part document	6-1
Trimming the surfaces	6-1
Mirroring a surface body	6-2
Creating a lofted surface	6-3
Patching the ends	6-4
Creating the led holes	6-5
Making the power cord opening	6-6
Knitting the surfaces	6-7
Adding fillets	6-7
Adding thickness	6-8
Creating a recess cut	6-9
Making the cover plate	6-10
Creating a cut using offset from surface	6-13
Using Configurations	6-15
Adding a new configuration	6-15
Modifying dimensions	6-16
Adding other configurations	6-17
Toggling between the configurations	6-18
Chapter 7: Curved Driven Pattern & Flex Bending	7-1
Opening a part document	7-1
Creating a 3D sweep path	7-1
Creating a swept surface	7-2
Creating a curve driven pattern	7-3


Stent designs – Exercise 1	7-5
Creating a planar surface	7-5
Creating a rolled pattern	7-6
Thickening a surface model	7-7
Stent designs – Exercise 2	7-8
Creating a split sketch	7-9
Creating a split line feature	7-10
Deleting faces	7-10
Adding thickness	7-11
Creating an axis	7-12
Creating a circular pattern	7-13
Combining the solid bodies	7-14
Stent designs – Exercise 3	7-15
Creating the base sketch	7-15
Creating a planar surface	7-16
Trimming with a sketch	7-16
Thickening the surface	7-17
Creating a flex bending feature	7-18
Chapter 8: Surfaces & Solids– Hybrid Modeling	8-1
Opening a part document	8-1
Creating the extruded surfaces	8-1
Trimming the surfaces	8-4
Adding fillets	8-5
Thickening the surface model	8-7
Adding the inner support feature	8-8
Creating an extruded cut	8-9
Adding the support ribs	8-10
Adding the mounting bosses	8-11
Adding fillets	8-12
Saving the housing right-half	8-13
Mirroring the part	8-13
Creating an extruded cut feature	8-15
Saving the left half	8-16
Adding the alignment pins	8-17
Adding chamfers	8-18
Saving the right half	8-18
Inserting a part document	8-19
Creating an exploded view	8-20
Chapter 9: Mold Tools, Intersect & Core/Cavity	9-1
Starting a new part document	9-1
Sketch the base profile	9-1
Creating a revolve surface	9-2

Making the sweep path	9-2
Adding a new plane	9-3
Creating the 1st rib	9-4
Making the sweep profile	9-4
Patterning the rib	9-4
Trimming the overlaps	9-5
Adding thickness	9-6
Adding fillets	9-7
Making a mold	9-8
Assigning material	9-8
Scaling the model	9-8
Creating a parting line	9-9
Creating the shut off surfaces	9-10
Creating the parting surfaces	9-11
Creating a tooling split	9-12
Making an exploded view	9-13
Renaming the bodies	9-14
Using Intersect	9-15
Opening a part document	9-15
Inserting a part	9-15
Moving a solid body	9-16
Using the intersect options	9-17
Exercise: Core and Cavity Creation	9-19
Adding Drafts	9-19
Adding Fillets	9-20
Thickening the Surface Model	9-20
Scaling the Model	9-21
Creating the Parting Lines	9-21
Shutting off the Through Hole	9-22
Creating the Parting Surface	9-22
Making the Mold Block Sketch	9-23
Creating the Tooling Split	9-23
Moving the Mold Blocks	9-24
Chapter 10: Surface Repairs and Patches	10-1
Opening a part document	10-1
Creating the lofted surfaces	10-2
Patching the raised feature	10-3
Patching the corner of the keyway	10-5
Using the filled surface command	10-6
Using the lofted surface command	10-7
Using the boundary surface command	10-8
Creating the additional curves	10-9
Creating a loft with guide curves	10-10

Removing features	10-11
Deleting holes	10-12
Removing features	10-12
Knitting the surfaces	10-14
Assigning material	10-15
Calculating the mass	10-15
Lesson 11: Rendering with PhotoView 360	11-1
Opening an assembly document	11-1
Enabling the PhotoView 360 application	11-1
Changing the scene	11-2
Enabling the preview window	11-3
Setting the output image size	11-3
Creating the rendering	11-4
Increasing the image quality	11-5
Exercise: Rendering with PhotoView 360	11-8
Using Display States	11-12
Creating the 1st display state	11-12
Changing appearances	11-13
Adding other display states	11-14
Toggling between the display states	11-16
Making an assembly feature cut	11-17

Glossary

Index



Designed using SOLIDWORKS 2021, SPO