

# Mastering Surface Modeling with **SOLIDWORKS® 2023**

Basic through Advanced Techniques



Lani Tran, CSWE

Visit the following websites to learn more about this book:



[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

# TABLE OF CONTENTS

<b>Chapter 1: Introduction to Surfaces</b>	<b>1-1</b>
Solids vs. surfaces	1-1
Patching with continuity	1-2
Contact, tangent, and curvature continuous	1-2
When to use surfaces	1-3
When not to use surfaces	1-3
The spline handles	1-4
Check your surface model frequently	1-5
The best approach	1-6
<b>Chapter 2: Surfacing Basics</b>	<b>2-1</b>
Opening a part document	2-1
Extruding a surface	2-1
Creating a curve through reference points	2-2
Creating the planar surfaces	2-3
Knitting the surfaces	2-4
Saving your work	2-4
Revolved surface	2-5
Creating a section view	2-6
Adding fillets	2-6
Swept surface	2-8
Sketching the sweep path	2-8
Creating a swept surface	2-9
Lofted surface	2-10
Sketching the 3rd profile	2-10
Creating a lofted surface	2-11
Boundary surface	2-13
Sketching the 3D splines	2-13
Creating a boundary surface	2-16
Exercise: Extrude and Trim Surfaces	2-18
<b>Chapter 3: Using Boundary and Lofted Surface</b>	<b>3-1</b>
Starting a new part document	3-1
Creating the 1st reference plane	3-3
Sketching the 1st boundary profile	3-3

Sketching the 2nd boundary profile	3-4
Comparing methods	3-5
Creating a boundary surface	3-6
Creating the 2nd reference plane	3-7
Constructing the 1st trim sketch	3-8
Trimming the bottom	3-9
Constructing a split sketch	3-10
Creating a split line feature	3-11
Deleting faces	3-12
Thickening the surface model	3-13
Adding fillets	3-14
RealView graphics	3-15
Ambient occlusion	3-16
Using Surface Trim & Loft Lofted Surface	3-17
Creating a revolved surface	3-17
Trimming with a sketch	3-18
Making a surface offset	3-18
Trimming with another sketch	3-19
Creating a lofted surface	3-20
Knitting all surfaces	3-21
Exercise: Creating a Lofted Surface	3-23
<b>Chapter 4: Multibody Designs</b>	<b>4-1</b>
Opening a part document	4-1
Creating a revolved surface	4-1
Creating a trimmed sketch	4-2
Adding Thickness	4-4
Creating a split line feature	4-4
Making an offset surface	4-5
Creating a raised label area	4-5
Creating a 2 <sup>nd</sup> raised feature	4-6
Adding a new plane	4-6
Creating a boss feature	4-7
Adding fillets	4-8
Adding a pin hole	4-9
Mirroring features	4-10
Creating the handle sketch	4-10
Extruding the handle	4-11
Adding fillets	4-11
Adding a hole	4-12
Adding a fillet	4-13
Creating a pin	4-13

Mirroring the pin	4-14
Creating an exploded view	4-15
Exercise: Coffee Mug – Multibody Design	4-17
<b>Chapter 5: Surface Creation</b>	<b>5-1</b>
Creating the 1 <sup>st</sup> sketch	5-1
Creating the 2 <sup>nd</sup> sketch	5-2
Trimming the surfaces	5-3
Mirroring a surface body	5-4
Making the loft profiles	5-5
Creating a lofted surface	5-6
Making the fill profiles	5-7
Creating two filled surfaces	5-8
Creating a planar surface	5-9
Knitting the surfaces	5-9
Creating fillets	5-10
Creating a split line feature	5-11
Creating a face fillet with hold line	5-12
Creating more fillets	5-13
Boundary & Lofted Surface Exercise – Phone Case	5-14
Opening a part document	5-14
Creating a boundary surface	5-14
Creating the 1 <sup>st</sup> lofted surface	5-15
Creating the 2 <sup>nd</sup> lofted surface	5-16
Creating the 3 <sup>rd</sup> lofted surface	5-17
Hiding the sketches	5-18
Knitting the surface	5-19
Exercise: Trim & Mirror Surfaces	5-20
<b>Chapter 6: Using Filled, Knit &amp; Boundary Surface</b>	<b>6-1</b>
Opening a part document	6-1
Creating a boundary surface	6-2
Creating a revolved surface	6-3
Creating a filled surface	6-4
Knitting the surfaces	6-5
Creating a split line feature	6-6
Changing the face color	6-7
Shelling the model	6-8
Enabling RealView graphics	6-8
Using Deform Surface	6-9

Creating a lofted surface	6-9
Creating a deform feature	6-10
Trimming to the final size	6-11
Patching the bottom surface	6-12
Knitting the surfaces	6-12
Adding fillets	6-13
Exercise: Boundary Surface	6-15
Mid-Term Quiz: Toy Design	6-19
<b>Chapter 7: Using Trim, Thicken &amp; Configurations</b>	<b>7-1</b>
Opening a part document	7-1
Trimming the surfaces	7-1
Mirroring a surface body	7-2
Creating a lofted surface	7-3
Patching up the two ends	7-4
Creating the LED holes	7-5
Making the power cord opening	7-6
Knitting the surfaces	7-7
Adding fillets	7-7
Adding thickness	7-8
Creating a recess cut	7-9
Making a cut	7-10
Creating the cover plate	7-10
Using Configurations	7-15
Adding a new configuration	7-15
Modifying dimensions	7-16
Adding another configuration	7-17
Exercise: Trim, Knit & Patch Surfaces	7-18
<b>Chapter 8: Curved Driven Pattern &amp; Flex Bending</b>	<b>8-1</b>
Opening a part document	8-1
Creating a 3D sweep path	8-1
Creating a swept surface	8-2
Creating a curve driven pattern	8-3
Stent Designs – Exercise 1	8-5
Creating a planar surface	8-5
Creating a rolled pattern	8-6
Thickening a surface model	8-7
Stent Designs – Exercise 2	8-8

Creating a split sketch	8-9
Creating a split line feature	8-10
Deleting faces	8-10
Adding thickness	8-11
Creating an axis	8-12
Creating a circular pattern	8-13
Combining the solid bodies	8-14
Stent Designs – Exercise 3	8-15
Creating the base sketch	8-15
Creating a planar surface	8-16
Trimming with a sketch	8-16
Thickening the surface	8-17
Creating a flex bending feature	8-18
Exercise: Pattern & Flex Bending	8-19
Exercise: Using Surfaces	8-23
<b>Chapter 9: Surfaces &amp; Solids– Hybrid Modeling</b>	<b>9-1</b>
Opening a part document	9-1
Creating the extruded surfaces	9-1
Trimming the surfaces	9-4
Adding fillets	9-5
Thickening the surface model	9-7
Adding the inner support feature	9-8
Creating an extruded cut	9-9
Adding the support ribs	9-10
Adding the mounting bosses	9-11
Adding fillets	9-12
Saving the housing right-half	9-13
Mirroring the part	9-13
Creating an extruded cut feature	9-15
Saving the left half	9-16
Adding the alignment pins	9-17
Adding chamfers	9-18
Saving the right half	9-18
Inserting a part document	9-19
Creating an exploded view	9-20
Exercise: Hybrid Modeling	9-21
Exercise: Using the Wrap Tool	9-26
Exercise: Using Offset from Surface	9-28

<b>Chapter 10: Mold Tools, Intersect &amp; Core/Cavity</b>	<b>10-1</b>
Starting a new part document	10-1
Creating a revolved surface	10-2
Making the sketch of the sweep path	10-2
Creating a new plane	10-3
Creating a rib feature	10-4
Circular patterning the rib	10-4
Trimming the overlaps	10-5
Adding thickness	10-6
Adding fillets	10-7
Adding material	10-8
Scaling the model	10-8
Creating the parting lines	10-9
Creating the shut off surfaces	10-10
Creating the parting surfaces	10-11
Creating a tooling split	10-12
Creating an exploded view	10-13
Renaming and hiding the references	10-14
Using Intersect	10-15
Opening a part document	10-15
Inserting another part document	10-15
Moving the solid bodies	10-16
Using the intersect option	10-17
Exercise: Core and Cavity Creation	10-19
<b>Chapter 11: Surface Repairs and Patches</b>	<b>11-1</b>
Opening a part document	11-1
Creating the lofted surfaces	11-2
Patching the raised feature	11-3
Patching the corner of the keyway	11-5
Using the filled surface command	11-6
Using the lofted surface command	11-7
Using the boundary surface command	11-8
Creating the additional curves	11-9
Creating a loft with guide curves	11-10
Removing features	11-11
Deleting holes	11-12
Removing features	11-12
Knitting the surfaces	11-14
Assigning material	11-15
Calculating the mass	11-15



Exercise: Surface Repair & Patches	11-17
<b>Lesson 12: Rendering with PhotoView 360</b>	<b>12-1</b>
Opening an assembly document	12-1
Enabling PhotoView 360	12-1
Changing the scene	12-2
Enabling the preview window	12-3
Setting the output image size	12-3
Creating the rendering	12-4
Increasing the image quality	12-5
Quadrupling the image quality	12-6
Exercise: Rendering with PhotoView 360	12-8
Exercise 2: Bug-Bot Rendering	12-12
Using Display States	12-16
Creating the 1st display state	12-16
Changing the appearances	12-17
Adding other display states	12-18
Toggling between display states	12-20
Final Exam: Hybrid Modeling	12-22

Glossary

Index

