
# SOLIDWORKS 2025 and Engineering Graphics

An Integrated Approach













### **Table of Contents**

| Preface  | i    |
|--|------|
| Acknowledgments  | ii   |
| Table of Contents  | iii  |
| Certified SOLIDWORKS Associate Exam Overview                     | XV   |
| Tips about Taking the SOLIDWORKS Certified Associate Examination | xxi  |
| Chapter 1  |      |
| Introduction   |      |
| Introduction   | 1-2  |
| Drawing in CAD Systems   | 1-4  |
| Development of Computer Geometric Modeling                       | 1-4  |
| Feature-Based Parametric Modeling                                | 1-8  |
| Getting Started with SOLIDWORKS                                  | 1-9  |
| Starting SOLIDWORKS  | 1-9  |
| SOLIDWORKS Screen Layout   | 1-12 |
| Menu Bar   | 1-12 |
| Menu Bar Pull-down Menus   | 1-13 |
| Heads-up View Toolbar  | 1-13 |
| Features Toolbar   | 1-13 |
| Sketch Toolbar   | 1-13 |
| Feature Manager-Design Tree/Property Manager                     | 1-14 |
| Configuration Manager/DimXpert Manager/Display Manager           | 1-14 |
| Graphics Area  | 1-15 |
| Reference Triad  | 1-15 |
| Origin   | 1-15 |
| Confirmation Corner  | 1-15 |
| Graphics Cursor or Crosshairs                                    | 1-15 |
| Message and Status Bar   | 1-15 |
| Using the SOLIDWORKS Command Manager                             | 1-16 |
| Mouse Buttons  | 1-17 |
| [Esc] - Canceling Commands                                       | 1-17 |
| SOLIDWORKS Help System   | 1-18 |
| Leaving SOLIDWORKS   | 1-18 |
| Creating a CAD File Folder                                       | 1-19 |
| Chapter 2  |      |
| Parametric Modeling Fundamentals                                 |      |
| Introduction   | 2-3  |
| The Adjuster Design  | 2-4  |
| Starting SOLIDWORKS  | 2-4  |
| SOLIDWORKS Part Modeling Window Layout                           | 2-5  |
| Step 1: Determine/Set up the Base Solid Feature                  | 2-7  |
| Sketching Plane – It is an XY CRT, but an XYZ world              | 2-7  |
| 2  | - '  |

| Creating Rough Sketches                                | 2-9  |
|--|------|
| Step 2: Creating a Rough Sketch                        | 2-10 |
| Graphics Cursors                                       | 2-10 |
| Geometric Relation Symbols                             | 2-12 |
| Step 3: Apply/Modify Relations and Dimensions          | 2-13 |
| Viewing Functions – Zoom and Pan                       | 2-15 |
| Delete an Existing Geometry of the Sketch              | 2-16 |
| Modifying the Dimensions of the Sketch                 | 2-17 |
| Step 4: Completing the Base Solid Feature              | 2-18 |
| Isometric View   | 2-19 |
| Rotation of the 3D Model – Rotate View                 | 2-19 |
| Rotation and Panning – Arrow keys                      | 2-21 |
| Dynamic Viewing – Quick Keys                           | 2-22 |
| 3D Rotation  | 2-24 |
| Viewing Tools – Heads-up View Toolbar                  | 2-24 |
| View Orientation                                       | 2-25 |
| Display Style  | 2-26 |
| Orthographic vs. Perspective                           | 2-26 |
| Customizing the Heads-up View Toolbar                  | 2-26 |
| Step 5-1: Adding an Extruded Feature                   | 2-27 |
| Step 5-2: Adding a Cut Feature                         | 2-31 |
| Step 5-3: Adding another Cut Feature                   | 2-33 |
| Save the Model   | 2-35 |
| Questions  | 2-36 |
| Exercises  | 2-37 |
|  |      |
| Chantar 2  |      |
| Chapter 3 Constructive Solid Geometry Concepts         |      |
| ·  |      |
| Introduction   | 3-3  |
| Binary Tree  | 3-4  |
| The Locator Design                                     | 3-5  |
| Modeling Strategy – CSG Binary Tree                    | 3-6  |
| Starting SOLIDWORKS and Activating the Command Manager | 3-7  |
| GRID and SNAP Intervals Auto-Rotate Setup              | 3-9  |
| Base Feature   | 3-10 |
| Repositioning Dimensions                               | 3-12 |
| Completing the Base Solid Feature                      | 3-13 |
| Creating the Next Solid Feature                        | 3-14 |
| Creating an Extruded Cut Feature                       | 3-17 |
| Creating a Hole with the Hole Wizard                   | 3-20 |
| Creating a Rectangular Extruded Cut Feature            | 3-23 |
| Using the View Selector                                | 3-25 |
| Questions  | 3-27 |
| Exercises  | 3-28 |
|  |      |

| Chapter 4 |                      |
|-----------|----------------------|
| Geometric | <b>Constructions</b> |

| Geometric Constructions                                 | 4-3  |
|---|------|
| Geometric Constructions - Classical Methods             | 4-4  |
| Bisection of a Line or Arc                              | 4-4  |
| Bisection of an Angle                                   | 4-5  |
| Transfer of an Angle                                    | 4-6  |
| Dividing a Given Line into a Number of Equal Parts      | 4-7  |
| Circle through Three Points                             | 4-8  |
| • A Line Tangent to a Circle                            | 4-9  |
| Line Tangent to a circle from a Given Point             | 4-10 |
| • Circle of a Given Radius Tangent to Two Given Lines   | 4-11 |
| • Circle of a Given Radius Tangent to an Arc and a Line | 4-12 |
| • Circle of a Given Radius Tangent to Two Arcs          | 4-13 |
| Starting SOLIDWORKS                                     | 4-14 |
| Geometric Construction – CAD Method                     | 4-16 |
| Bisection of a Line or Arc                              | 4-16 |
| Dimensions and Relations                                | 4-18 |
| Geometric Symbols available in parametric sketching     | 4-19 |
| Bisection of an Angle                                   | 4-20 |
| Dividing a Given Line into a Number of Equal Parts      | 4-22 |
| Circle through Three Points                             | 4-29 |
| Line Tangent to a circle from a Given Point             | 4-30 |
| • Circle of a Given Radius Tangent to Two Given Lines   | 4-31 |
| Adding Geometric Relations and Fully Defined Geometry   | 4-34 |
| Starting SOLIDWORKS                                     | 4-34 |
| Over-Defining and Driven Dimensions                     | 4-41 |
| Deleting Existing Relations                             | 4-42 |
| Using the Fully Define Sketch Tool                      | 4-43 |
| Adding Additional Geometry                              | 4-44 |
| Adding New Equations                                    | 4-49 |
| Questions   | 4-51 |
| Exercises   | 4-52 |
| Chapter 5   |      |
| Feature Design Tree                                     |      |
| Introduction  | 5-3  |
| Starting SOLIDWORKS                                     | 5-4  |
| Creating a User-Defined Part Template                   | 5-5  |
| The Saddle Bracket Design                               | 5-9  |
| Modeling Strategy                                       | 5-10 |
| The SOLIDWORKS Feature Manager Design Tree              | 5-11 |
| Creating the Base Feature                               | 5-11 |
| Adding the Second Solid Feature                         | 5-14 |

| -15<br>-17<br>-18<br>-19<br>-22<br>-23<br>-24<br>-26<br>-28<br>-29                       |
|--|
|  |
| -3<br>-3<br>-4<br>-5<br>-6<br>-8<br>-10<br>-11<br>-14<br>-16<br>-17<br>-18<br>-23<br>-27 |
|  |
| -3<br>-4<br>-4<br>-5<br>-6<br>-7<br>-8<br>-9<br>-10<br>-11<br>-13<br>-15                 |
|  |

| Chapter 7 - 1 <sup>St</sup> Angle Orthographic Sketching Exercise 5 | 7-19 |
|---|------|
| Chapter 7 - 1 <sup>St</sup> Angle Orthographic Sketching Exercise 6 | 7-21 |
| Third-Angle Projection  | 7-23 |
| Rotation of the Horizontal and Profile Planes                       | 7-24 |
| The 3D Adjuster Model and 3 <sup>rd</sup> angle projection          | 7-25 |
| The Glass Box and the Six Principal Views                           | 7-25 |
| General Procedure: 3 <sup>rd</sup> Angle Orthographic Projection    | 7-28 |
| Example 2: 3 <sup>rd</sup> Angle Orthographic Projection            | 7-28 |
| Example 3: 3 <sup>rd</sup> Angle Orthographic Projection            | 7-29 |
| Chapter 7 - 3 <sup>rd</sup> Angle Orthographic Sketching Exercise 1 |      |
|   | 7-31 |
| Chapter 7 - 3 <sup>rd</sup> Angle Orthographic Sketching Exercise 2 | 7-33 |
| Chapter 7 - 3 <sup>rd</sup> Angle Orthographic Sketching Exercise 3 | 7-35 |
| Chapter 7 - 3 <sup>rd</sup> Angle Orthographic Sketching Exercise 4 | 7-37 |
| Chapter 7 - 3 <sup>rd</sup> Angle Orthographic Sketching Exercise 5 | 7-39 |
| Chapter 7 - 3 <sup>rd</sup> Angle Orthographic Sketching Exercise 6 | 7-41 |
| Alphabet of Lines   | 7-43 |
| Precedence of Lines   | 7-45 |
| The U-Bracket Design  | 7-46 |
| Starting SOLIDWORKS   | 7-46 |
| Applying the BORN Technique   | 7-47 |
| Creating the 2D Sketch of the Base Feature                          | 7-48 |
| Creating the First Extrude Feature                                  | 7-55 |
| The Implied Parent/Child Relationships                              | 7-55 |
| Creating the Second Solid Feature                                   | 7-56 |
| Creating an Extruded Cut Feature                                    | 7-59 |
| Creating another Extruded Cut Feature                               | 7-60 |
| Examining the Parent/Child Relationships                            | 7-62 |
| Modify a Parent Dimension   | 7-63 |
| A Design Change   | 7-64 |
| Feature Suppression   | 7-65 |
| A Different Approach to the CENTER DRILL Feature                    | 7-66 |
| Suppress the Rect Cut Feature                                       | 7-67 |
| Creating a Circular Extruded Cut Feature                            | 7-68 |
| A Flexible Design Approach  | 7-70 |
| Drawings from Parts and Associative Functionality                   | 7-71 |
| Drawing Mode  Drawing Mode  | 7-72 |
| Setting Document Properties   | 7-72 |
| Setting Sheet Properties using the Pre-Defined Sheet Formats        | 7-74 |
|   | 7-73 |
| Creating Three Standard Views                                       | 7-76 |
| Repositioning Views   |      |
| Adding a New Sheet  | 7-78 |
| Adding a Base View  | 7-79 |
| Adding an Isometric View using the View Palette                     | 7-82 |
| Adjusting the View Scale  | 7-83 |
| Questions   | 7-85 |
| Exercises   | 7-86 |

| Chapter 8 Dimensioning and Notes  |              |
|---|--------------|
| Introduction  | 8-3          |
| Dimensioning Standards and Basic Terminology  | 8-4          |
| Selection and Placement of Dimensions and Notes   | 8-5          |
| Machined Holes  | 8-12         |
| Baseline and Chain Dimensioning   | 8-15         |
| Dimensioning and Tolerance Accumulation   | 8-16         |
| (1) Tolerance Accumulation - Baseline Dimensioning  | 8-17         |
| (2) Tolerance Accumulation - Chain Dimensioning   | 8-18         |
| (3) Avoid Tolerance Accumulation - Dimensioning Features  | 8-19         |
| Dimensioning Tools in SOLIDWORKS  | 8-20         |
| The U-Bracket Design  | 8-20         |
| Start SOLIDWORKS  | 8-21         |
| Display Feature Dimensions  | 8-22         |
| Repositioning, Appearance, and Hiding of Feature Dimensions   | 8-23         |
| Adding Additional Dimensions – Reference Dimensions   | 8-25         |
| Tangent Edge Display  | 8-27         |
| Adding Center Marks, Center Lines, and Sketch Objects   | 8-27         |
| Edit Sheet vs. Edit Sheet Format  | 8-32         |
| Modify the Title Block  | 8-32<br>8-35 |
| Property Links Saying the current Title Block as a new Sheet Format   | 8-39         |
| Saving the current Title Block as a new Sheet Format Associative Functionality – Modifying Feature Dimensions | 8-40         |
| Saving the Drawing File   | 8-43         |
| Create a B size Drawing Template  | 8-43         |
| Questions   | 8-46         |
| Exercises   | 8-47         |
| Chapter 9   | 0 17         |
| Tolerancing and Fits  |              |
| Precision and Tolerance   | 9-2          |
| Methods of Specifying Tolerances – English System   | 9-3          |
| Nomenclature  | 9-4          |
| Example 9.1   | 9-5          |
| Fits between Mating parts   | 9-6          |
| Selective Assembly  | 9-7          |
| Basic Hole and Basic Shaft Systems  | 9-7          |
| American National Standard Limits and Fits – Inches   | 9-8          |
| Example 9.2 Basic Hole System   | 9-13         |
| Example 9.3 Basic Hole System   | 9-14         |
| Example 9.4 Basic Shaft System  | 9-15         |
| Example 9.5 Basic Shaft System  | 9-16         |
| Tolerancing – Metric System   | 9-17         |
| Metric Tolerances and Fits Designation  | 9-18         |

ix

## Section Views & Symmetrical Features in Designs

Introduction 11-3

| General Rules of Section Views                                   | 11-5           |
|--|----------------|
| Section Drawing Types  | 11-6           |
| • Full Section   | 11-6           |
| • Half Section   | 11-6           |
| Offset Section   | 11-7           |
| Broken-Out Section   | 11-7           |
| Aligned Section  | 11-8           |
| • Half Views   | 11-8           |
| • Thin Sections  | 11-8           |
| Revolved Section   | 11-9           |
| Removed Section  | 11-9           |
| Conventional Breaks  | 11-10          |
| • Ribs and Webs in Sections                                      | 11-10          |
| Parts Not Sectioned  | 11-10          |
| Section Views in SOLIDWORKS                                      | 11-11          |
| A Revolved Design: PULLEY  | 11-11          |
| Modeling Strategy - A Revolved Design                            | 11-12          |
| Starting SOLIDWORKS  | 11-13          |
| Creating the Base Feature  | 11-13          |
| Creating the Revolved Feature                                    | 11-17          |
| Mirroring Features   | 11-17          |
| Creating an Extruded Cut Feature with Construction Geometry      | 11-19          |
| Circular Pattern   | 11-24          |
| Drawing Mode – Defining a New Border and Title Block             | 11-26          |
| Create a New Drawing Template                                    | 11-30          |
| Creating Views   | 11-31          |
| Retrieve Dimensions – Model Items Command                        | 11-34          |
| Save the Drawing File  Associative Eventionality A Design Change | 11-35<br>11-36 |
| Associative Functionality – A Design Change                      | 11-38          |
| Adding Centerlines to the Pattern Feature                        | 11-36          |
| Completing the Drawing Additional Title Blocks                   | 11-40          |
| Questions  | 11-45          |
| Exercises  | 11-45          |
| LACIOISCS  | 11 10          |
| Chapter 12   |                |
| Auxiliary Views and Reference Geometry                           |                |
| Introduction   | 12-3           |
| Normal View of an Inclined Surface                               | 12-4           |
| Construction Method I – Folding Line Method                      | 12-6           |
| Construction Method II – Reference Plane Method                  | 12-8           |
| Partial Views  | 12-10          |
| Reference Geometry in SOLIDWORKS                                 | 12-11          |
| Auxiliary Views in 2D Drawings                                   | 12-11          |
| The Rod-Guide Design   | 12-11          |

| Modeling Strategy  | 12-12          |
|--|----------------|
| Starting SOLIDWORKS  | 12-12          |
| Applying the BORN Technique  | 12-13          |
| Creating the Base Feature  | 12-13          |
| Creating an Angled Reference Plane   | 12-14          |
| Creating an Angled Reference Flane Creating an Extruded Feature on the Reference Plane | 12-10          |
| Using the Convert Entities Option  | 12-19          |
| - · ·  | 12-19          |
| Completing the Solid Feature   | 12-23          |
| Creating an Offset Reference Plane   |                |
| Creating another Extruded Feature using the Reference Plane                            | 12-27          |
| Starting a New 2D Drawing and Adding a Base View                                       | 12-29          |
| Creating an Auxiliary View   | 12-30          |
| Displaying Feature Dimensions  | 12-32          |
| Adjusting the View Scale   | 12-34          |
| Repositioning, Appearance, and Hiding of Feature Dimensions                            | 12-34          |
| Tangent Edge Display   | 12-37          |
| Adding Center Marks and Center Lines   | 12-37          |
| Controlling the View and Sheet Scales  | 12-40          |
| Completing the Drawing Sheet   | 12-41          |
| Editing the Isometric view   | 12-42          |
| Adding a General Note  | 12-42          |
| Questions Exercises  | 12-44<br>12-45 |
| Exercises  | 12-43          |
| Chapter 13   |                |
| Introduction to 3D Printing  |                |
| What is 3D Printing  | 13-2           |
| Development of 3D Printing Technologies  | 13-3           |
| Primary types of 3D Printing processes   | 13-6           |
| Stereolithography  | 13-6           |
| Fused Deposition Modeling & Fused Filament Fabrication                                 | 13-7           |
| Laser Sintering / Laser Melting  | 13-8           |
| Primary 3D Printing Materials for FDM and FFF  | 13-9           |
| From 3D model to 3D printed Part   | 13-11          |
| Starting SOLIDWORKS  | 13-12          |
| SOLIDWORKS Print3D Command   | 13-13          |
| Using the 3D Printing software to create the 3D Print                                  | 13-18          |
| Questions  | 13-26          |
| Chapter 14   |                |
| Threads and Fasteners  |                |
| Introduction   | 14-2           |
| Screw-Thread Terminology   | 14-3           |
| Thread Forms   | 14-5           |

| Thread Representations                       | 14-6  |
|--|-------|
| Detailed Representation                      | 14-7  |
| Schematic Representation                     | 14-8  |
| Simplified Representation                    | 14-9  |
| Thread Specification – English Units         | 14-10 |
| Unified Thread Series                        | 14-11 |
| Thread Fits                                  | 14-12 |
| Thread Specification – Metric                | 14-12 |
| Thread Notes Examples                        | 14-13 |
| Specifying Fasteners                         | 14-14 |
| Commonly Used Fasteners                      | 14-15 |
| Drawing Standard Bolts                       | 14-17 |
| Bolt and Screw Clearances                    | 14-17 |
| Fasteners using SOLIDWORKS' Design Library   | 14-18 |
| ANSI Inch - Machine Screw                    | 14-18 |
| ANSI Metric - Machine Screw                  | 14-20 |
| Questions                                    | 14-22 |
|  |       |
| Chapter 15                                   |       |
| Assembly Modeling and Working Drawings       |       |
| General Engineering Design Process           | 15-3  |
| Working Drawings                             | 15-4  |
| Detail Drawings                              | 15-4  |
| Assembly Drawings                            | 15-5  |
| Bill of Materials (BOM) and Parts List       | 15-5  |
| Drawing Sizes                                | 15-6  |
| Drawing Sheet Borders and Revisions Block    | 15-6  |
| Title Blocks                                 | 15-7  |
| Working Drawings with SOLIDWORKS             | 15-8  |
| Assembly Modeling Methodology                | 15-8  |
| The Shaft Support Assembly                   | 15-9  |
| Parts  | 15-9  |
| Creating the Collar with the Chamfer Command | 15-9  |
| Creating the Bearing and Base-Plate          | 15-11 |
| Creating the Cap-Screw                       | 15-12 |
| Starting SOLIDWORKS                          | 15-13 |
| Document Properties                          | 15-13 |
| Insert the First Component                   | 15-14 |
| Insert the Second Component                  | 15-15 |
| Degrees of Freedom                           | 15-16 |
| Assembly Mates                               | 15-16 |
| Apply the First Assembly Mate                | 15-18 |
| Apply a Second Mate                          | 15-19 |
| Constrained Move                             | 15-21 |
| Apply a Third Mate                           | 15-22 |

| Inserting the Third Component   | 15-24          |
|---|----------------|
| Applying Concentric and Coincident Mates                                      | 15-24          |
| Assemble the Cap-Screws using SmartMates                                      | 15-26          |
| Exploded View of the Assembly   | 15-30          |
| Save the Assembly Model   | 15-32          |
| Editing the Components  | 15-32          |
| Set up a Drawing of the Assembly Model  | 15-34          |
| Creating a Bill of Materials  | 15-35          |
| Editing the Bill of Materials   | 15-37          |
| Completing the Assembly Drawing   | 15-41          |
| Exporting the Bill of Materials  Explanded Assembly Drawing                   | 15-43          |
| Exploded Assembly Drawing   | 15-44<br>15-45 |
| Questions<br>Exercises  | 15-45          |
| Exercises   | 13-40          |
| Chapter 16  |                |
| CSWA Exam Preparation   |                |
| •   | 16.2           |
| Tips about Taking the Certified SOLIDWORKS Associate Examination Introduction | 16-3<br>16-4   |
| The Part Problem  | 16-4           |
| Strategy for Aligning the Part to the Default Axis System                     | 16-6           |
| Creating the Base Feature   | 16-6           |
| Creating a New View Orientation   | 16-9           |
| Create Reference Planes and a Reference Axis                                  | 16-10          |
| Selecting the Material and Viewing the Mass Properties                        | 16-16          |
| The Assembly Problem  | 16-19          |
| Creating the Parts  | 16-20          |
| Creating the Assembly   | 16-21          |
| Creating a Reference Coordinate System  | 16-27          |
| View the Mass Properties  | 16-29          |
| Questions   | 16-31          |
| Exercises   | 16-32          |
| Appendix  |                |
| A. Running and Sliding Fits – American National Standard                      |                |
| B. Metric Limits and Fits   |                |
| C. UNIFIED NATIONAL THREAD FORM   |                |
| D. METRIC THREAD FORM   |                |
| E. FASTENERS (INCH SERIES)  |                |
| F. METRIC FASTENERS   |                |
| G. BOLT AND SCREW CLEARANCE HOLES   |                |
| H. REFERENCES   |                |

#### Index