


# Mastering Sheet Metal and Weldments with **SOLIDWORKS® 2026**

From Design to Manufacturing and Fabrication



Lani Tran, CSWE

Visit the following websites to learn more about this book:




[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)


[BARNES & NOBLE](https://www.barnesandnoble.com)

# TABLE OF CONTENTS

## Lesson 1: Introduction to Sheet Metal Parts 1-1




|                                   |      |
|-----------------------------------|------|
| Opening a part document           | 1-2  |
| Creating the base flange          | 1-2  |
| Making an edge flange             | 1-3  |
| Closing the corners               | 1-4  |
| Making a cut                      | 1-5  |
| Adding the angled flanges         | 1-6  |
| Making a manual relief cut        | 1-7  |
| Creating a sketched bend feature  | 1-8  |
| Adding the 3/8" holes             | 1-11 |
| Inserting a form tool             | 1-13 |
| Patterning the bridge lance       | 1-14 |
| Adding chamfers                   | 1-15 |
| Exercise: Basic Sheet Metal Parts | 1-16 |








## Lesson 2: Sheet Metal Flanges 2-1



|  |      |
|--|------|
| Opening a part document                | 2-1  |
| Creating a base flange                 | 2-1  |
| Making the 1st edge flange             | 2-2  |
| Adding the 2 <sup>nd</sup> edge flange | 2-3  |
| Making the 3rd edge flange             | 2-4  |
| Creating a jog feature                 | 2-5  |
| Adding another jog                     | 2-6  |
| Creating a miter flange                | 2-7  |
| Mirroring a solid body                 | 2-9  |
| Closing the corners                    | 2-10 |
| Adding holes                           | 2-11 |
| Adding chamfers                        | 2-12 |



|   |  |            |
|---|--|------------|
| <b>Lesson 3:</b>  | <b>Sheet Metal Sketched Bends</b>                  | <b>3-1</b> |
|    | Opening part document                              | 3-1        |
|   | Creating the 1st sketched bend                     | 3-1        |
|   | Making the 2nd sketched bend                       | 3-2        |
|   | Adding holes                                       | 3-3        |
|   | Adding chamfers                                    | 3-4        |
|    | Exercise: Using Sketched Bends                     | 3-6        |
|   | Creating the 1 <sup>st</sup> sketched bends        | 3-6        |
|   | Creating the 2 <sup>nd</sup> sketched bends        | 3-8        |
|   | Creating the 3 <sup>rd</sup> sketched bends        | 3-9        |
|   | Adding holes                                       | 3-10       |
| Viewing the flat pattern  | 3-11   |            |
| <b>Lesson 4:</b>  | <b>Sheet Metal Miter Flange &amp; Fill Pattern</b> | <b>4-1</b> |
|    | Opening a part document                            | 4-1        |
|   | Creating the miter flange feature                  | 4-1        |
|   | Adding the cuts                                    | 4-2        |
|   | Adding cuts  | 4-2        |
|  | Sheet Metal Fill Pattern                           | 4-4        |
|   | Opening a part document                            | 4-4        |
|   | Sketching the pattern boundary                     | 4-4        |
| Creating a fill-pattern   | 4-5  |            |
| <b>Lesson 5:</b>  | <b>Sheet Metal Fold &amp; Unfold</b>               | <b>5-1</b> |
|  | Opening a part document                            | 5-1        |
|   | Closing the corners                                | 5-1        |
|   | Unfolding the bends                                | 5-2        |
|   | Adding cuts across the bends                       | 5-3        |
|   | Folding the bends                                  | 5-4        |
|   | Breaking the corners                               | 5-5        |
| Flattening the part   | 5-6  |            |
|  | Exercise: Sheet Metal Fold & Unfold                | 5-8        |
|   | Unfolding the bends                                | 5-8        |
|   | Making the 1 <sup>st</sup> cut                     | 5-9        |
|   | Folding the bends                                  | 5-10       |

|                                |      |
|--------------------------------|------|
| Unfolding the bends            | 5-11 |
| Making the 2 <sup>nd</sup> cut | 5-12 |
| Folding the bends              | 5-13 |
| Viewing the flat pattern       | 5-14 |


**Lesson 6: Sheet Metal Curved Flange 6-1**



|                             |     |
|-----------------------------|-----|
| Opening a part document     | 6-1 |
| Creating a tab              | 6-1 |
| Breaking the corners        | 6-3 |
| Creating the curved flanges | 6-4 |
| Closing the corners         | 6-5 |
| Adding the cut features     | 6-6 |
| Removing the sharp corners  | 6-7 |



|                                |      |
|--------------------------------|------|
| Sheet metal jogs 1             | 6-8  |
| Making the 1 <sup>st</sup> jog | 6-8  |
| Making the 2 <sup>nd</sup> jog | 6-9  |
| Adding the cuts                | 6-11 |
| Adding fillets                 | 6-12 |




|                        |      |
|------------------------|------|
| Sheet metal jogs 2     | 6-13 |
| Creating a jog feature | 6-13 |
| Adding the cuts        | 6-15 |
| Mirroring a solid body | 6-16 |
| Adding fillets         | 6-17 |

**Lesson 7: Sheet Metal Tab/Slot & Multibody 7-1**



|                                 |     |
|---------------------------------|-----|
| Opening a part document         | 7-1 |
| Creating the tab & slot feature | 7-1 |
| Saving your work                | 7-3 |

|                                     |      |
|-------------------------------------|------|
| Sheet Metal multibody parts         | 7-4  |
| Creating the 1 <sup>st</sup> body   | 7-4  |
| Creating a curved flange            | 7-5  |
| Creating the 2 <sup>nd</sup> body   | 7-6  |
| Adding the tab & slot feature       | 7-7  |
| Adding the 5/16 <sup>th</sup> holes | 7-8  |
| Adding the lower gusset             | 7-9  |
| Adding the upper gusset             | 7-10 |




|                               |      |
|-------------------------------|------|
| Adding a slot to the 1st body | 7-11 |
| Toggling the flat display     | 7-12 |


**Lesson 8: Sheet Metal Lofted Bends 8-1**



|                                       |     |
|---------------------------------------|-----|
| Opening a part document               | 8-1 |
| Creating a lofted bend feature        | 8-1 |
| Viewing the flat pattern              | 8-2 |
| Creating a formed lofted bend feature | 8-3 |
| Viewing the flat pattern              | 8-4 |




|                                 |      |
|---------------------------------|------|
| Sheet metal swept flanges       | 8-6  |
| Opening a new part              | 8-6  |
| Creating a swept flange feature | 8-6  |
| Creating the rolled hem         | 8-7  |
| Adding the 1 <sup>st</sup> jog  | 8-8  |
| Adding the 2 <sup>nd</sup> jog  | 8-9  |
| 4 common types of hems          | 8-11 |




|                           |      |
|---------------------------|------|
| Creating a closed hem     | 8-11 |
| Creating an open hem      | 8-13 |
| Creating a teardrop hem   | 8-14 |
| Creating a rolled hem     | 8-15 |
| Toggling the flat display | 8-16 |

**Lesson 9: Sheet Metal Gussets & Vents 9-1**







|                                     |     |
|-------------------------------------|-----|
| Opening a part document             | 9-1 |
| Creating the 1 <sup>st</sup> gusset | 9-1 |
| Creating the 2 <sup>nd</sup> gusset | 9-3 |
| Adding fillets                      | 9-4 |




|                             |      |
|-----------------------------|------|
| Sheet Metal Vents           | 9-5  |
| Sketching the vent profile  | 9-5  |
| Creating the vent feature   | 9-7  |
| Adding the mounting holes   | 9-8  |
| Exercise: Sheet metal vents | 9-10 |




|                          |      |
|--------------------------|------|
| Creating the base flange | 9-10 |
| Adding a cut feature     | 9-11 |
| Adding fillets           | 9-12 |
| Adding the 3/8" holes    | 9-13 |
| Creating the vent sketch | 9-14 |

|   |                                 |             |
|---|---------------------------------|-------------|
|   | Adding the mounting holes       | 9-15        |
| <b>Lesson 10:</b>   | <b>Convert to Sheet Metal</b>   | <b>10-1</b> |
|    | Opening a part document         | 10-1        |
|   | Converting to sheet metal       | 10-1        |
|   | Flattening the part             | 10-3        |
|   | Toggling the flat display       | 10-4        |
|    | Convert to Sheet Metal 2        | 10-6        |
|   | Shelling the model              | 10-6        |
|   | Creating the rip edges          | 10-7        |
|   | Converting to sheet metal       | 10-8        |
|   | Flattening the sheet metal part | 10-9        |
|    | Sheet metal costing             | 10-10       |
|   | Launching the Costing program   | 10-11       |
|   | Filling out the costing info    | 10-12       |
|   | Changing the quantity           | 10-15       |
|   | Changing the material           | 10-16       |
| <b>Lesson 11:</b>   | <b>Sheet Metal Assemblies</b>   | <b>11-1</b> |
|  | Opening an assembly document    | 11-1        |
|   | Inserting a component           | 11-1        |
|   | Adding a Width mate             | 11-2        |
|   | Adding a coincident mate        | 11-3        |
|   | Adding another Coincident mate  | 11-4        |
|   | Enabling the Toolbox library    | 11-5        |
|   | Using the Hole Series           | 11-6        |
|   | Mirroring a screw               | 11-10       |
| <b>Lesson 12:</b>   | <b>Sheet Metal Drawings</b>     | <b>12-1</b> |
|  | Opening a drawing document      | 12-1        |
|   | Examining the drawing views     | 12-1        |
|   | Adding an auxiliary view        | 12-2        |
|   | Creating a crop-view            | 12-3        |
|   | Adding the model dimensions     | 12-4        |




|                                      |       |
|--------------------------------------|-------|
| Filling out the title block          | 12-7  |
| Adding the flat pattern drawing view | 12-9  |
| Adding centerlines                   | 12-10 |
| Adding the centerline symbol         | 12-11 |
| Adding dimensions                    | 12-12 |
| Adding other callouts                | 12-14 |
| Export to DXF                        | 12-16 |
| Testing the DXF file                 | 12-19 |

## **Lesson 13: SolidWorks Weldments 13-1**




|                                  |       |
|----------------------------------|-------|
| Weldments overview               | 13-1  |
| Weldment groups                  | 13-4  |
| Adding the structural members    | 13-5  |
| Adding other structural members  | 13-9  |
| Adding the square tubes          | 13-11 |
| Extending the structural members | 13-12 |
| Trimming the structural members  | 13-13 |
| Moving a structural member       | 13-14 |
| Deleting bodies                  | 13-16 |
| Removing the interferences       | 13-17 |

## **Lesson 14: Weldments Steel Frame 14-1**



|                               |       |
|-------------------------------|-------|
| Opening a part document       | 14-1  |
| Enabling the weldment tab     | 14-1  |
| Adding the structural members | 14-2  |
| Adding end caps               | 14-9  |
| Adding gussets                | 14-10 |
| Mirroring the gussets         | 14-11 |


## **Lesson 15: Weldments Platform 15-1**



|                                   |       |
|-----------------------------------|-------|
| Opening a part document           | 15-1  |
| Enabling the Weldment tab         | 15-1  |
| Adding pipe 2 sch 40 to the frame | 15-7  |
| Trimming the structural members   | 15-15 |
| Adding a new plane                | 15-17 |
| Creating the upper deck floor     | 15-18 |


|                                     |       |
|-------------------------------------|-------|
| Adding fillets                      | 15-19 |
| Optional: Creating an exploded view | 15-20 |

**Lesson 16: Weldments - Playground Slide 16-1**



|                                    |       |
|------------------------------------|-------|
| Opening a part document            | 16-1  |
| Adding the structural members      | 16-1  |
| Adding other groups                | 16-2  |
| Inspecting the weldments           | 16-11 |
| Rotating a group                   | 16-12 |
| Extending the structural members   | 16-13 |
| Modifying the corner treatments    | 16-14 |
| Extending other structural members | 16-15 |

**Lesson 17: Weldments – Locating Profiles 17-1**



|                               |       |
|-------------------------------|-------|
| Opening a part document       | 17-1  |
| Using interference detection  | 17-1  |
| Changing the profile’s angle  | 17-3  |
| Exercise: Weldments Fence     | 17-5  |
| Enabling the Weldment tab     | 17-5  |
| Adding the structural members | 17-5  |
| Inserting a solid model       | 17-8  |
| Patterning the Fence Finial   | 17-11 |

**Lesson 18: Weldments – Cut List 18-1**

| ITEM NO. | QTY. | DESCRIPTION | LENGTH           |
|----------|------|-------------|------------------|
| 1        | 8    | 15x4x0.1875 | 116              |
| 2        | 4    | 15x4x0.1875 | 76               |
| 3        | 13   | 15x4x0.1875 | 68               |
| 4        | 4    | 15x4x0.1875 | 56               |
| 5        | 4    | 15x4x0.1875 | 142              |
| 6        | 1    | 15x4x0.1875 | 140              |
| 7        | 4    | 15x4x0.1875 | 34               |
| 8        | 3    | 15x4x0.1875 | 44               |
| 9        | 6    | 15x4x0.1875 | 32               |
| 10       | 8    | End Cap     | 3.8125x3.8125x25 |
| 11       | 40   | Gussets     | 5.2x5.2x.5       |



|  |       |
|--|-------|
| Opening a part document                    | 18-1  |
| Updating the cut list                      | 18-1  |
| Viewing the structural member’s properties | 18-2  |
| Renaming the folders                       | 18-3  |
| Viewing the end cap’s properties           | 18-4  |
| Generating a drawing from part             | 18-5  |
| Inserting the weldment cut list            | 18-6  |
| Populating the weldment cut list           | 18-9  |
| Showing the exploded view                  | 18-10 |
| Adding balloons                            | 18-11 |


**Lesson 19: Certified SOLIDWORKS Professional Sheet Metal Exam Preparation Materials 19-1**

Challenge 1: Convert to Sheet Metal 19-1  
 Challenge 2: Modifying the sheet metal parameters 19-5  
 Challenge 3: Creating a sheet metal part 19-8  
 Challenge 4: Creating a sheet metal part 19-18  
 Challenge 5: Creating a sheet metal part 19-21

**Glossary**

**Reference Reading: Materials Science**

**Index**



**Model Library**

Measure your SolidWorks Skills. Take one or all of the exams below and become **SOLIDWORKS CERTIFIED**.  
 For more information, go to: [www.solidworks.com/certification](http://www.solidworks.com/certification)

