


DESIGN MODELING

with

SolidWorks 2007



180




Cast Iron
Scale: 1:3.33
All dimensions in millimeters
General tolerances ± 0.03

James E. Bolluyt
Iowa State University

PropSys 1642



\varnothing 3THRU ALL
 \varnothing 6 ∇ 3



Schroff Development Corporation
www.schroff.com




Table of Contents



Text Files ix

■	Chapter 1	Computers in Design	1
	1.0	Computer-Aided Design 1	
		Modeling and the Design Process 2	
		The Electronic Model Database 3	
	1.1	Model Representation Schemes 4	
		Wireframe Representation 4	
		Surface Representation 4	
		Surface Types 5	
		Solid Representation 5	
	1.2	Solid Model Creation Techniques 7	
		Constructive Solid Geometry 7	
		Boolean Operators 7	
		Sweeping 8	
	1.3	Parametric Solid Modeling 10	
		Chapter 1 Exercises 11	
■	Chapter 2	Working with a 3-D Model	15
	2.0	The <i>SolidWorks</i> User Interface 15	
		A Typical <i>SolidWorks</i> Screen Layout 15	
		Loading Model Files 15	
		Online Help 18	
	2.1	Entering Commands and Options 19	
		Command Format for this Text 20	
	2.2	View Manipulation in <i>SolidWorks</i> 21	
	2.3	Obtaining Multiple Simultaneous Views 26	
	2.4	Saving Work in <i>SolidWorks</i> 30	
		Backup and Recovery Files 30	
	2.5	Coordinate Spaces in Computer Modeling 31	
		Global Space Coordinates 31	
		Relative Coordinates 34	
		Local Coordinate Spaces 35	

2.6	Additional Model Inquiry	38
2.7	Obtaining Hardcopies	41
	Hardcopy of a Single View Screen Image	41
	Hardcopy of a Typical Multiview	42
	<i>Chapter 2 Exercises</i>	49
■	Chapter 3 Parametric Modeling Tools I	57
3.0	Introduction	57
3.1	Feature-based Modeling	57
3.2	Modeling in <i>SolidWorks</i> – A First Example	58
	Beginning the Base Feature	59
	Creating the 2-D Profile or Sketch	60
	Constraining the Sketch Geometry	62
	Completing the Base Feature	64
	Adding the First Detail Feature to the Base Feature	65
	Adding the Hole Features to Complete the Model	67
3.3	Advantages of Parametric Modeling	71
3.4	Parametric Modeling - A Second Example	74
3.5	Parametric Modeling - A Third Example	81
	Construction and Reference Features	81
	Creating the Base Feature	83
	<i>Chapter 3 Exercises</i>	92
■	Chapter 4 Documentation I	101
4.0	Introduction	101
4.1	Documentation Standards	102
4.2	Dimensioning Concepts	102
4.3	Documentation in <i>SW</i> – the Basics	103
	A Dimensioning Style in <i>SW</i>	104
	Obtaining the Necessary Views	105
	"Cleaning up" the Dimensions	106
	Adding Centerlines	109
	Adding Dimensions	109
	Adding Notes (Manufacturing Information)	110
	A Summary of the Basic Documentation Process	111
4.4	The Model-Documentation Connection	106

4.5	Starting Model Files (Templates)	114
	Formal Output - A Format	114
	Creating a Custom Drawing Template	114

Chapter 4 Exercises 125

■ **Chapter 5 Parametric Modeling Tools II** 129

5.0	Introduction	129
5.1	Sketching Tools and Surface Models	129
	Sketch Geometry and Symmetry	129
	Surface Models	133
	Thin-walled Solids	133
5.2	Reference Planes and Sweeps	134
	Auxiliary Reference Planes and Sweeps	138
5.3	Inserted Features	143
5.4	Copying Features	145
	Rectangular Patterns of Features	147
	Creating the Rectangular Pattern	148
	Suppressing Features	149
	Circular Patterns of Features	150
	Parametric Relations	153
	Patterns of Sketched Features	158
	Mirror Copies of Features	162

Chapter 5 Exercises 164

■ **Chapter 6 Creating an Assembly** 171

6.0	Introduction	171
6.1	Creating an Assembly Model in SW	171
	The Base Feature for an Assembly	172
	Constraining Components in an Assembly	175
	The Nature of the Assembly Model	184
6.2	Exploded Assemblies	185
6.3	Assembly Documentation	187

Chapter 6 Exercises 190

■ **Chapter 7 Parametric Modeling Tools III** 197

7.0	Introduction	197
-----	--------------	-----

7.1	Splines and Thin Solids	197	
	Spline and Thin Solid Example 1	198	
	Spline and Thin Solid Example 2	199	
	Spline and Thin Solid Example 3	200	
7.2	Lofts	203	
	Loft Example 1	203	
	Loft Example 2	204	
	Loft Example 3	206	
7.3	Other Special Curves	208	
	Helix Example	208	
	Spiral Example	208	
7.4	Multibody Parts	208	
	<i>Chapter 7 Exercises</i>	211	
■	Chapter 8 Documentation II		215
8.0	Introduction	215	
8.1	Section Views	215	
	Full Section	216	
	Half Section	219	
	Offset Section	221	
	Detail View	222	
8.2	Dimensional Tolerances	227	
	<i>Chapter 8 Exercises</i>	229	
	<i>Index</i>	231	
