
Introduction to Finite Element Analysis

Using Pro/MECHANICA Wildfire 5.0®



Randy H. Shih
Oregon Institute of Technology



Schroff Development Corporation www.schroff.com

Better Textbooks. Lower Prices.

Table of Contents

Preface Acknowledgments

Introduction

Introduction	Intro-2
Development of Finite Element Analysis	Intro-2
FEA Modeling Considerations	Intro-3
Гуреs of Finite Elements	Intro-4
Finite Element Analysis Procedure	Intro-6
Matrix Definitions	Intro-6
Getting Started with <i>Pro/ENGINEER</i>	Intro-9
Starting <i>Pro/ENGINEER</i>	Intro-9
Pro/ENGINEER Screen Layout	Intro-10
• Pull-down menus	Intro-11
Standard toolbar	Intro-11
• Single Line Help	Intro-11
Dashboard	Intro-11
 Graphics display 	Intro-11
Datum toolbar	Intro-12
Navigator	Intro-12
• Web Browser	Intro-12
Basic Functions of Mouse Buttons	Intro-13
Model Tree window and Feature Toolbars	Intro-14
On-Line Help	Intro-15
Leaving Pro/ENGINEER	Intro-16
Creating a CAD files folder	Intro-16

Chapter 1 The Direct Stiffness Method

Introduction	1-2
One-dimensional Truss Element	1-3
Basic Solid Modeling using <i>Pro/ENGINEER</i>	1-10
The Adjuster design	1-10
Starting <i>Pro/ENGINEER</i>	1-10
Step 1: Units and Basic Datum Geometry Setups	1-12
Units Setup and <i>Pro/ENGINEER</i> Menu Structure	1-12
Adding the First Part Features — Datum Planes	1-14
Step 2: Determine/Setup the Base Solid Feature	1-15
Defining the Sketching Plane	1-16

Defining the Orientation of the Sketching Plane Step 3: Creating 2D rough sketches Shape Before Size – Creating Rough Sketches The <i>Pro/ENGINEER</i> SKETCHER and INTENT MANAGER Graphics Cursors Geometric Constraint Symbols Dynamic Viewing Functions	1-17 1-19 1-19 1-20 1-21 1-22 1-23
Step 4: Apply/modify constraints and dimensions Modifying the dimensions of the sketch Repositioning Dimensions Step 5: Completing the Base Solid Feature The Third Dynamic Viewing Function Display Modes: Wireframe, Shaded, Hidden Edge, No Hidden Step 6: Adding additional features Creating a CUT Feature Creating the 2D Section of the CUT Feature Save the Part and Exit Questions Exercises	1-24 1-27 1-29 1-30 1-31 1-32 1-33 1-38 1-39 1-42 1-43
Chapter 2 Truss Elements in Two-Dimensional Spaces	
Introduction Truss Elements in Two-Dimensional Spaces Coordinate Transformation EXAMPLE 2.1 Solution Global Stiffness Matrix EXAMPLE 2.2 Solution Questions Exercises	2-2 2-2 2-5 2-9 2-10 2-13 2-13 2-19 2-20
Chapter 3 2D Trusses in MS Excel and the Truss Solver	
Direct Stiffness Matrix method using Excel EXAMPLE 3.1 Establish the Global K matrix for each member Assembly of the Overall Global Stiffness Matrix Solving the Global Displacements Calculating Reaction Forces Determining the Stresses in Elements The Truss Solver and the Truss View programs	3-2 3-2 3-3 3-8 3-10 3-16 3-18 3-23

	Table of Contents
The Truss View program Questions Exercises	3-30 3-32 3-33
Chapter 4 Pro/MECHANICA Two-Dimensional Truss Analy	/sis
Finite Element Analysis Procedure Preliminary Analysis Starting Pro/ENGINEER Units and Basic Datum Geometry Setups The Integrated mode of Pro/MECHANICA Creating Datum Points as FEA Nodes Select and Examine the Element Material Property Setting Up an Element Cross Section Setting Up an Element Releases Creating Elements Beam Action Coordinate System (BACS) Applying Boundary Conditions - Constraints and Loads Applying External Loads Running the Solver Viewing the results Dynamic Query Questions Exercises	4-2 4-3 4-4 4-5 4-8 4-10 4-14 4-15 4-16 4-17 4-18 4-21 4-23 4-25 4-27 4-28 4-30 4-31
Chapter 5 Three-Dimensional Truss Analysis	
Three-Dimensional Coordinate Transformation Matrix Stiffness Matrix Degrees of Freedom Problem Statement Preliminary Analysis Starting Pro/ENGINEER Creating a New Template Saving the New Template The Integrated mode of Pro/MECHANICA Creating 3D Datum Points Select and Examine the Element Material Property Setting Up an Element Cross Section Setting Up Beam Element Releases Creating Elements Applying Boundary Conditions - Constraints and Loads Applying External Loads	5-2 5-3 5-3 5-5 5-5 5-7 5-8 5-10 5-11 5-12 5-14 5-15 5-16 5-17 5-20 5-21

Running the Solver Viewing the results Questions	5-22 5-25 5-28
Exercises	5-29
Chapter 6 Basic Beam Analysis	
Introduction Modeling Considerations Problem Statement Preliminary Analysis Starting Pro/ENGINEER New Template Setup Setup the Isometric View Saving as a New Template The Integrated mode of Pro/MECHANICA Creating Datum Points Creating a Datum Curve for the Distributed Load Select and Examine the Element Material Property Setting Up an Element Cross Section Creating Elements Applying Boundary Conditions - Constraints and Loads Applying External Loads Running the Solver Viewing the results What Went Wrong? Running the Solver Viewing the results > Bending Stress > Shear Diagram > Moment Diagram Refine the FE Model Questions Exercises	6-2 6-3 6-3 6-6 6-7 6-8 6-11 6-12 6-12 6-15 6-17 6-19 6-20 6-21 6-23 6-26 6-28 6-30 6-33 6-34 6-36 6-37 6-39 6-40 6-49 6-50
Chapter 7 Beam Analysis Tools	
Introduction Problem Statement Preliminary Analysis Stress Components Starting <i>Pro/ENGINEER</i>	7-2 7-2 7-3 7-4 7-6

vii

Chapter 9 Two Dimensional Solid Elements

Introduction	9-2
Problem Statement	9-3
Preliminary Analysis	9-3
Maximum Normal Stress	9-3
Maximum Displacement	9-4
Geometric Considerations of Finite Elements	9-5
Starting <i>Pro/ENGINEER</i>	9-6
Creating a CAD Model in <i>Pro/ENGINEER</i>	9-7
Select and Examine the Element Material Property	9-11
The Integrated mode of <i>Pro/MECHANICA</i>	9-12
Applying Boundary Conditions - Constraints	9-14
Applying External Loads	9-16
FEA Surface Idealization	9-17
H-Element versus P-Element	9-18
Create the 2D Mesh	9-19
Running the Solver	9-20
Viewing the results	9-22
Maximum Principal Stress	9-22
> X Displacement	9-23
Refinement of the P-mesh	9-24
Running the Solver	9-27
Viewing the results	9-29
Maximum Principal Stress	9-29
> X Displacement	9-30
Questions	9-31
Exercises	9-32
Ob 1 40	
Chapter 10 Three-Dimensional Solid Elements	
Introduction	10-2
Problem Statement	10-3
Preliminary Analysis	10-4
Starting <i>Pro/ENGINEER</i>	10-7
Creating a CAD Model in <i>Pro/ENGINEER</i>	10-8
> Define the Sweep Trajectory	10-8
> Define the Sweep Section	10-12
Select and Examine the Element Material Property	10-15
The Integrated mode of <i>Pro/MECHANICA</i>	10-16
Applying Boundary Conditions - Constraints	10-17
Applying External Loads	10-18

	Table of Contents
Create the 2D Mesh Running the Solver Viewing the results Von Mises Stress Viewing with the Cutting/Capping option Notes on FEA Linear Static Analyses Questions Exercises	10-19 10-20 10-23 10-23 10-24 10-27 10-28 10-29
Chapter 11 Axisymmetric and Thin Shell Elements	
Introduction Problem Statement Preliminary Analysis Starting Pro/ENGINEER Creating a CAD Model in Pro/ENGINEER Select and Examine the Element Material Property The Integrated mode of Pro/MECHANICA Applying Boundary Conditions - Constraints Applying the pressure Create the 2D Mesh Running the Solver Viewing the Von Mises Stress Perform a 3D Shell Analysis Applying Boundary Conditions - Constraints Applying the pressure Create the 3D Shell Mesh Running the Solver Viewing the Von Mises Stress Perform a 3D Solid Analysis Create the 3D Solid Analysis Create the 3D Solid Mesh Running the Solver Viewing the Von Mises Stress Viewing Multiple Analyses Results Questions Exercises	11-2 11-4 11-4 11-6 11-7 11-9 11-10 11-12 11-14 11-15 11-16 11-19 11-20 11-23 11-25 11-26 11-27 11-29 11-30 11-32 11-34 11-36 11-37 11-38 11-39
Chapter 12 Dynamic Modal Analysis	
Introduction Problem Statement Preliminary Analysis	12-2 12-3 12-3

ix

The Cantilever Beam Modal Analysis program	12-6
Starting <i>Pro/ENGINEER</i>	12-9
Creating a CAD Model in <i>Pro/ENGINEER</i>	12-10
Select and Examine the Element Material Property	12-12
The Integrated mode of <i>Pro/MECHANICA</i>	12-13
Applying Boundary Conditions - Constraints	12-14
Create the 3D Mesh	12-15
Running the Solver	12-16
Viewing the Von Mises Stress	12-19
Adding an additional mass to the system	12-22
Conclusions	12-26
Questions	12-27
Exercises	12-28

Index