


# Learning SOLIDWORKS® 2015

## Modeling, Assembly and Analysis



Randy H. Shih

Visit the following websites to learn more about this book:



[amazon.com](https://www.amazon.com)

[Google books](https://books.google.com)

[BARNES & NOBLE](https://www.barnesandnoble.com)

# Table of Contents

|  |      |
|--|------|
| <b>Preface</b>                                 | i    |
| <b>Acknowledgments</b>                         | ii   |
| <b>Table of Contents</b>                       | iii  |
| <br>   |      |
| <b>Chapter 1</b>                               |      |
| <b>Introduction – Getting Started</b>          |      |
| Introduction                                   | 1-2  |
| Development of Computer Geometric Modeling     | 1-2  |
| Feature-Based Parametric Modeling              | 1-6  |
| Getting Started with SolidWorks                | 1-7  |
| Starting SolidWorks                            | 1-7  |
| Units Setup                                    | 1-9  |
| SolidWorks Screen Layout                       | 1-11 |
| Menu Bar                                       | 1-11 |
| Menu Bar Pull-down Menus                       | 1-12 |
| Heads-up View Toolbar                          | 1-12 |
| Features Toolbar                               | 1-12 |
| Sketch Toolbar                                 | 1-12 |
| Property Managers                              | 1-13 |
| Graphics Area                                  | 1-14 |
| Reference Triad                                | 1-14 |
| Origin   | 1-14 |
| Confirmation Corner                            | 1-14 |
| Graphics Cursor or Crosshairs                  | 1-14 |
| Message and Status Bar                         | 1-14 |
| Using the SolidWorks Command Manager           | 1-15 |
| Mouse Buttons                                  | 1-16 |
| [Esc] - Canceling Commands                     | 1-16 |
| SolidWorks Help System                         | 1-17 |
| Leaving SolidWorks                             | 1-17 |
| Creating a CAD files folder                    | 1-18 |
| <br>   |      |
| <b>Chapter 2</b>                               |      |
| <b>Parametric Modeling Fundamentals</b>        |      |
| Introduction                                   | 2-2  |
| The Tiger Head Design                          | 2-3  |
| Starting SolidWorks                            | 2-3  |
| SolidWorks Screen Layout                       | 2-4  |
| Step 1: Determine/Setup the Base Solid Feature | 2-6  |

|   |      |
|---|------|
| Sketching Plane – It is an XY CRT, but an XYZ World | 2-6  |
| Creating Rough Sketches                             | 2-8  |
| Step 2: Create a Rough Sketch                       | 2-9  |
| Graphics Cursors                                    | 2-9  |
| Geometric Relation Symbols                          | 2-10 |
| Step 3: Apply/Modify Constraints and Dimensions     | 2-11 |
| Viewing Functions – <i>Zoom</i> and <i>Pan</i>      | 2-16 |
| Delete an Existing Geometry of the Sketch           | 2-17 |
| Use the 3-Point Arc Command                         | 2-17 |
| Step 4: Complete the Base Solid Feature             | 2-19 |
| Isometric View                                      | 2-20 |
| Rotation of the 3D Model – Rotate View              | 2-20 |
| Rotation and Panning – Arrow Keys                   | 2-22 |
| Dynamic Viewing - Quick Keys                        | 2-23 |
| Viewing Tools – Heads-up View Toolbar               | 2-25 |
| View Orientation                                    | 2-26 |
| Display Style                                       | 2-27 |
| Orthographic vs. Perspective                        | 2-27 |
| Customizing the Heads-up View Toolbar               | 2-27 |
| Step 5-1: Add an Extruded Feature                   | 2-28 |
| Step 5-2: Add a Cut Feature                         | 2-32 |
| Step 6: Add Additional Features                     | 2-34 |
| Add a Decal   | 2-36 |
| Save the Model                                      | 2-39 |
| Review Questions                                    | 2-40 |
| Exercises   | 2-41 |

### **Chapter 3**

## **CSG Concepts and Model History Tree**

|   |      |
|---|------|
| Introduction                              | 3-2  |
| Binary Tree                               | 3-3  |
| Model History Tree                        | 3-4  |
| The A6-Knee Part                          | 3-5  |
| Starting SolidWorks                       | 3-5  |
| Modeling Strategy                         | 3-6  |
| The <i>SolidWorks Feature Manager</i>     | 3-7  |
| Base Feature                              | 3-7  |
| Units Setup                               | 3-8  |
| Create the Base Feature                   | 3-9  |
| Adding the Second Solid Feature           | 3-13 |
| Renaming the Part Features                | 3-15 |
| Adjust the Dimensions of the Base Feature | 3-15 |
| History-Based Part Modifications          | 3-18 |
| Add a Placed Feature                      | 3-19 |
| Create an Offset Extruded Feature         | 3-22 |

---

|   |      |
|---|------|
| Add another Hole Feature                                | 3-25 |
| Assign and Calculate the Associated Physical Properties | 3-27 |
| Review Questions  | 3-30 |
| Exercises   | 3-31 |

## **Chapter 4**

### **Parametric Constraints Fundamentals**

|   |      |
|---|------|
| DIMENSIONS and RELATIONS                          | 4-2  |
| Create a Simple Triangular Plate Design           | 4-2  |
| Fully Defined Geometry                            | 4-3  |
| Starting SolidWorks                               | 4-3  |
| Create a User-Defined Part Template               | 4-4  |
| Start a New Model using the New Template          | 4-6  |
| Display/Hide Applied Geometric Relations          | 4-7  |
| Apply Geometric Relations/Dimensional Constraints | 4-8  |
| Geometric Editing with Drag and Drop              | 4-12 |
| Create Fully Constrained Sketches                 | 4-14 |
| Over-Defining and Driven Dimensions               | 4-15 |
| Delete the Fix Constraint                         | 4-17 |
| Use the Fully Define Sketch Tool                  | 4-18 |
| Add Additional Geometry                           | 4-20 |
| Relations Settings                                | 4-24 |
| Model the B3-Leg Part                             | 4-25 |
| Create the 2D Sketch for the Base Feature         | 4-26 |
| Parametric Relations                              | 4-27 |
| Use the Equations Command                         | 4-29 |
| Complete the Base Feature                         | 4-30 |
| Sketches vs. Profiles                             | 4-32 |
| Redefine the Profile with Contour Selection       | 4-35 |
| Create an Extrusion with the Taper Angle Option   | 4-36 |
| A Profile Containing Multiple Closed Regions      | 4-39 |
| The Convert Entities Option                       | 4-41 |
| Add a Feature using Existing Geometry             | 4-41 |
| Save the Model File                               | 4-43 |
| Use the Measure Tools                             | 4-43 |
| Create a Metric Part Template                     | 4-46 |
| The <i>Boot</i> Part                              | 4-48 |
| Review Questions                                  | 4-51 |
| Exercises   | 4-52 |

## **Chapter 5**

### **Pictorials and Sketching**

|   |      |
|---|------|
| Engineering Drawings, Pictorials and Sketching  | 5-2  |
| Isometric Sketching                             | 5-7  |
| Isometric Sketching Exercises                   | 5-9  |
| Oblique Sketching                               | 5-10 |
| Oblique Sketching Exercises                     | 5-11 |
| Perspective Sketching                           | 5-12 |
| SolidWorks Orthographic vs. Perspective Display | 5-13 |
| One-point Perspective                           | 5-14 |
| Two-point Perspective                           | 5-15 |
| Perspective Sketching Exercises                 | 5-16 |
| Review Questions                                | 5-17 |
| Exercises                                       | 5-18 |

## **Chapter 6**

### **Symmetrical Features and Part Drawings**

|   |      |
|---|------|
| Drawings from Parts and Associative Functionality     | 6-2  |
| The <i>A12- Rear Axle Support</i> Design              | 6-3  |
| Starting SolidWorks                                   | 6-3  |
| Modeling Strategy                                     | 6-4  |
| Create the Base Feature                               | 6-5  |
| Create a Symmetrical Cut Feature                      | 6-8  |
| Create a Revolved Feature                             | 6-10 |
| Create another Extruded Feature                       | 6-15 |
| Create a Cut Feature                                  | 6-18 |
| Create a Mirrored Feature                             | 6-20 |
| Drawing Mode – 2D Paper Space                         | 6-21 |
| The Drawing Sheet Properties                          | 6-22 |
| Add a Base View                                       | 6-24 |
| Add Centerlines                                       | 6-26 |
| Display Feature Dimensions                            | 6-29 |
| Add Additional Dimensions – Reference Dimensions      | 6-31 |
| Complete the Drawing Sheet                            | 6-32 |
| Associative Functionality – Modify Feature Dimensions | 6-34 |
| Review Questions                                      | 6-37 |
| Exercises   | 6-38 |

## Chapter 7

### Datum Features in Designs

|   |      |
|---|------|
| Reference Features                                | 7-2  |
| The <i>B2-Chassis</i> Part                        | 7-2  |
| Modeling Strategy                                 | 7-3  |
| Starting SolidWorks                               | 7-4  |
| Create the Base Feature                           | 7-5  |
| Create the Second Extruded Feature                | 7-8  |
| Create a Tapered Extruded Feature                 | 7-10 |
| Create an Offset Reference Plane                  | 7-11 |
| Create a Revolved Feature                         | 7-12 |
| Create an Angled Reference Plane                  | 7-15 |
| Create another Offset Reference Plane             | 7-16 |
| Create an Extruded Feature with Reference Plane 3 | 7-18 |
| Change the Appearance of the Solid Model          | 7-22 |
| The <i>Crank Right</i> Part                       | 7-24 |
| The <i>A10-Crank Left</i> Part                    | 7-28 |
| The <i>Motor</i> Part                             | 7-30 |
| The <i>A1-Axle End Cap</i> Part                   | 7-33 |
| The <i>Hex Shaft Collar</i> Part                  | 7-34 |
| The <i>A8-Rod Pin</i> Part                        | 7-38 |
| Review Questions                                  | 7-39 |
| Exercises   | 7-40 |

## Chapter 8

### Gears and SolidWorks Design Library

|  |      |
|--|------|
| Introduction to Gears                    | 8-2  |
| Spur Gear Nomenclatures                  | 8-4  |
| Basic Involute Tooth Profile             | 8-6  |
| Gear Ratio                               | 8-7  |
| The SolidWorks Gear Toolbox              | 8-9  |
| Starting SolidWorks                      | 8-10 |
| Open the SolidWorks Design Library       | 8-10 |
| The SolidWorks Spur Gear Toolbox         | 8-12 |
| Create a 42 Teeth Spur Gear              | 8-13 |
| Modify the Generated 42T Gear            | 8-14 |
| Create a Mirrored Feature                | 8-18 |
| Import the Profile of the Pinion Gear    | 8-19 |
| Complete the <i>G2-Spur Gear</i> Part    | 8-25 |
| Create the <i>G3-Spur Gear</i> Part      | 8-27 |
| Create the <i>G0-Pinion</i> Part         | 8-31 |
| Start a New Part File                    | 8-33 |
| Export/Import the Generated Gear Profile | 8-36 |
| Create a Circular Pattern                | 8-39 |

|                  |      |
|------------------|------|
| Review Questions | 8-46 |
| Exercises        | 8-47 |

## **Chapter 9**

### **Advanced 3D Construction Tools**

|   |      |
|---|------|
| Introduction                              | 9-2  |
| A Thin-Walled Design: <i>Battery Case</i> | 9-2  |
| Modeling Strategy                         | 9-3  |
| Starting SolidWorks                       | 9-4  |
| Create the Base Feature                   | 9-5  |
| Create a Cut Feature                      | 9-7  |
| Create a Shell Feature                    | 9-11 |
| Create a Cut Feature                      | 9-12 |
| Create another Extruded Feature           | 9-14 |
| Create another Cut Feature                | 9-16 |
| Mirror the Last Feature                   | 9-18 |
| Create another Cut Feature                | 9-19 |
| Complete the Model                        | 9-20 |
| A Thin-Wire Design: <i>Linkage Rod</i>    | 9-22 |
| The Sweep Operation                       | 9-22 |
| Start a New Model                         | 9-22 |
| Complete the Swept Feature                | 9-27 |
| Create a Mirrored Feature                 | 9-28 |
| The <i>Gear Box Right</i> Part            | 9-29 |
| The <i>Gear Box Left</i> Part             | 9-34 |
| Review Questions                          | 9-38 |
| Exercises                                 | 9-39 |

## **Chapter 10**

### **Planar Linkage Analysis using GeoGebra**

|   |       |
|---|-------|
| Introduction to Four-Bar Linkages           | 10-2  |
| Introduction to GeoGebra                    | 10-5  |
| Hide the Display of Objects                 | 10-14 |
| Add a Slider Control                        | 10-16 |
| Use the Animate Option                      | 10-19 |
| Tracking the Path of a Point on the Coupler | 10-20 |
| Exercises                                   | 10-25 |



## Chapter 11

### Design Makes the Difference

|   |       |
|---|-------|
| Engineering Analysis – How does this work?                  | 11-2  |
| Identify the Six-bar Linkage of the <i>Mechanical Tiger</i> | 11-4  |
| Starting GeoGebra   | 11-6  |
| Add a Slider Control  | 11-14 |
| Create the Second Four-bar Mechanism                        | 11-16 |
| Use the Animate Option                                      | 11-20 |
| Tracking the Paths of the Feet                              | 11-21 |
| Adjusting the Crank Length                                  | 11-23 |
| The Jansen Mechanism  | 11-24 |
| The Klann Mechanism   | 11-25 |
| Exercises   | 11-27 |

## Chapter 12

### Assembly Modeling and Basic Motion Analysis

|  |       |
|--|-------|
| Introduction   | 12-2  |
| Assembly Modeling Methodology                        | 12-3  |
| The <i>Mechanical Tiger</i> Assembly                 | 12-4  |
| Additional Parts                                     | 12-4  |
| Creating the Leg Subassembly                         | 12-6  |
| Starting SolidWorks                                  | 12-6  |
| Document Properties                                  | 12-7  |
| Place the First Component                            | 12-8  |
| Place the Second Component                           | 12-9  |
| Degrees of Freedom and Assembly Relations            | 12-10 |
| Assembly Mates                                       | 12-11 |
| Apply the First Assembly Mate                        | 12-12 |
| Apply a Second Assembly Mate                         | 12-14 |
| Constrained Move                                     | 12-15 |
| Place the Third Component                            | 12-16 |
| Apply a Coincident Mate                              | 12-17 |
| Apply another Aligned Mate                           | 12-19 |
| Edit Parts in the Assembly Mode                      | 12-21 |
| Assemble the <i>Boot</i> Part                        | 12-25 |
| Use the Design Library and Assemble Two Screws       | 12-27 |
| Start the <i>Main Assembly</i>                       | 12-29 |
| Assemble the <i>Gear Box Right</i> Part              | 12-32 |
| Assemble the <i>Motor</i> and the <i>Pinion Gear</i> | 12-35 |
| Assemble the <i>G1 Gear</i>                          | 12-38 |
| <i>SolidWorks</i> Basic Motion Study                 | 12-41 |
| Assemble the <i>G2 Gear</i>                          | 12-43 |
| Assemble the <i>G3 Gear</i>                          | 12-46 |

|  |       |
|--|-------|
| Assemble the Hex Shafts                        | 12-48 |
| Assemble the <i>Crank</i> Parts                | 12-51 |
| Assemble the <i>Rear Shaft</i> and <i>Legs</i> | 12-55 |
| Assemble the Linkage-Rods                      | 12-57 |
| Complete the Assembly Model                    | 12-62 |
| Record an Animation Movie                      | 12-63 |
| Conclusion                                     | 12-64 |
| Review Questions                               | 12-65 |
| Exercises                                      | 12-66 |

## **Index**