



# Engineering & Computer Graphics Workbook

Using SOLIDWORKS® 2016



Ronald E. Barr  
Thomas J. Krueger  
Davor Juricic

Visit the following websites to learn more about this book:



# Table of Contents

	<u>Page</u>
<b>1. Computer Graphics Lab 1: 2-D Computer Sketching I.....</b>	1-1
Introduction to SOLIDWORKS; Screen Layout; Main Pull-Down Menu; Feature Manager Tree; View Orientation; View and Display Toolbars; Sketching Toolbars; Sketching Planes; Line Colors; Starting a New Part; Setting Grids and Units; Using Basic 2-D Primitives; Applying Basic Dimensions; Extruding and Revolving Simple Parts; Printing a Hardcopy.	
Exercise 1.1: Metal Gasket.....	1-8
Exercise 1.2: Cover Plate.....	1-14
Exercise 1.3: Wall Bracket.....	1-19
Exercise 1.4: Machine Handle.....	1-22
Supplementary Exercises.....	1-25
<b>2. Computer Graphics Lab 2: 2-D Computer Sketching II.....</b>	2-1
Review of All 2-D Sketch Entities; Advanced Sketching Tools; Sketch Editing Tools; Linear and Circular Repeats; Basic Dimensioning; Extruding and Revolving Simple Parts.	
Exercise 2.1: Metal Grate.....	2-3
Exercise 2.2: Torque Sensor.....	2-8
Exercise 2.3: Scalloped Knob.....	2-11
Exercise 2.4: Linear Step Plate.....	2-14
Supplementary Exercises.....	2-19
<b>3. Computer Graphics Lab 3: 3-D Solid Modeling of Parts I.....</b>	3-1
Adding Sketch Relations; 3-D Features Toolbar; Advanced Extrusion and Revolution Operations; Insert Reference Geometry; Mirror 3-D Feature; Create Linear and Circular 3-D Patterns; Building 3-D Solid Parts.	
Exercise 3.1 Clevis Mounting Bracket.....	3-3
Exercise 3.2 Manifold.....	3-8
Exercise 3.3: Hand Wheel.....	3-13
Exercise 3.4: Toe Clamp.....	3-17
Supplementary Exercises.....	3-21

<b>4. Computer Graphics Lab 4: 3-D Solid Modeling of Parts II.....</b>	<b>4-1</b>
Creating Advanced 3-D Features: Draft, Shell, Dome, Loft, Sweep; Advanced Extrusion and Revolution Operations; Building 3-D Solid Parts.	
Exercise 4.1: Drawer Tray.....	4-2
Exercise 4.2: Tap-Light Dome.....	4-7
Exercise 4.3: Threads and Fasteners.....	4-11
Exercise 4.4: Jack Stand.....	4-18
Supplementary Exercises.....	4-21
<b>5. Computer Graphics Lab 5: Assembly Modeling and Mating.....</b>	<b>5-1</b>
Building Multiple 3-D Parts; Color Shading of Parts in an Assembly; Starting a New Assembly File; Tiling the Screen Windows; Assembly Toolbar; Drag and Drop Parts into Assembly; Move and Rotate Component; Mate Parts with Different Mate Types; Print Assembly File.	
Exercise 5.1: Terminal Support Assembly.....	5-4
Exercise 5.2: Pulley Assembly.....	5-15
Supplementary Exercises.....	5-25
<b>6. Computer Graphics Lab 6: Analysis and Design Modification I.....</b>	<b>6-1</b>
Measure Function; Mass Properties Function; Types of Mass Properties and Applicable Units; Print Mass Properties Report; Design Modification of a Solid Model; Setting Up a Design Table; Setting Parameters for the Design Table; Configuration Manager; Print Assembly File.	
Exercise 6.1: Rocker Arm Mass Properties.....	6-4
Exercise 6.2: Socket Plug Design Table.....	6-12
Supplementary Exercises.....	6-18
<b>7. Computer Graphics Lab 7: Analysis and Design Modification II.....</b>	<b>7-1</b>
Introduction to Finite Element Analysis Using COSMOS/Works; Definition of FEA Terms; Building a Solid Model for an FEA Study; Beginning an FEA Study; Applying Loads and Constraints; Creating a Mesh; Analyzing the Model for Stress Distribution; Printing the von Mises Stress Distribution; Design Modification of a Solid Model Based on Analysis Results.	
Exercise 7.1: Finite Element Analysis of a Pillow Block.....	7-3
Exercise 7.2: Thermal Analysis of a Computer Chip.....	7-14

	<u>Page</u>
<b>8. Computer Graphics Lab 8: Kinematics Animation, Creating Views and Rapid Prototyping.....</b>	8-1
Introduction to the SOLIDWORKS Animation Wizard; Loading an Assembly File; Exploding an Assembly; Creating the Animation; Animation Controller; Editing the Animation; Saving an .AVI File; Introduction to Physical Simulation, Introduction to Rapid Prototyping; Saving an .STL File; Sample Solid Models for Rapid Prototyping.	
Exercise 8.1: Exploded Animation of the Terminal Support Assembly.....	8-5
Exercise 8.2: Exploded Animation of the Pulley Assembly.....	8-10
Exercise 8.3: Creating Views That Will Be Helpful When Illustrating Parts .....	8-15
Exercise 8.4: Rapid Prototyping of a Solid Model Part.....	8-19
<b>9. Computer Graphics Lab 9: Section Views in 3-D and 2-D.....</b>	9-1
Viewing 3-D Section Views of a Solid Model; Printing 3-D Section View; Inserting a Drawing Sheet; Setting Drawing and Hatch Pattern Options; Projecting Three Orthographic Views Onto a Drawing Sheet; Creating the Cutting Plane Line; Making a 2-D Section View; Completing a Section View Drawing; Print Section View Drawing.	
Exercise 9.1: Rod Base Section View.....	9-3
Exercise 9.2: Tension Cable Bracket Section View.....	9-9
Exercise 9.3: Milling End Adapter Section View.....	9-15
Exercise 9.4: Plastic Revolving Ball Assembly Section View.....	9-21
Supplementary Exercises.....	9-27
<b>Intro to Lab 10: Computer Graphics Intro to Lab 10: Setting Up Templates for Three View Drawings.....</b>	10-1
<b>10. Computer Graphics Lab 10: Generating and Dimensioning Three-View Drawings.....</b>	10-3
Inserting a Drawing Sheet; Setting Drawing Sheet Options; Projecting Three Orthographic Views of a Solid Model Onto a Drawing Sheet; Adding Centerlines and Completing the Drawing Views; Setting the Dimensioning Variables; Dimensioning the Drawing; Adding Title Block and Annotations; Print a Drawing.	
Exercise 10.1: Guide Block Drawing.....	10-7
Exercise 10.2: Pipe Joint Drawing.....	10-11
Exercise 10.3: Pedestal Base Drawing.....	10-17
Exercise 10.4: Tooling Pad Drawing.....	10-21
Supplementary Exercises.....	10-29

## APPENDIX A – Example of a Titleblock with Dimensions