


Parametric Modeling with SOLIDWORKS® 2016

Covers material found on the CSWA exam



Randy H. Shih
Paul J. Schilling

Visit the following websites to learn more about this book:



amazon.com

Google books

BARNES&NOBLE

Table of Contents

Preface	i
Acknowledgments	ii
Table of Contents	iii
Certified SOLIDWORKS Associate (CSWA) Exam Overview	xii

Chapter 1

Getting Started

Introduction	1-2
Development of Computer Geometric Modeling	1-2
Feature-Based Parametric Modeling	1-6
Getting Started with SOLIDWORKS	1-7
Units Setup	1-9
SOLIDWORKS Screen Layout	1-11
Mouse Buttons	1-17
[Esc] - Canceling Commands	1-17
On-Line Help	1-18
Leaving SOLIDWORKS	1-18
Creating a CAD Files Folder	1-19

Chapter 2

Parametric Modeling Fundamentals

Introduction	2-3
The Adjuster Design	2-4
Starting SOLIDWORKS	2-4
SOLIDWORKS Screen Layout	2-5
Units Setup	2-6
Creating Rough Sketches	2-7
Step 1: Creating a Rough Sketch	2-8
Graphics Cursors	2-8
Geometric Relation Symbols	2-10
Step 2: Apply/Modify Relations and Dimensions	2-11
Changing the Dimension Standard	2-12
Viewing Functions – Zoom and Pan	2-13
Modifying the Dimensions of the Sketch	2-14
Step 3: Completing the Base Solid Feature	2-15
Isometric View	2-16
Rotation of the 3-D Model – Rotate View	2-16
Rotation and Panning – Arrow keys	2-18
Viewing – Quick Keys	2-19
Viewing Tools – Heads-up View Toolbar	2-21
View Orientation	2-22
Display Style	2-23
Orthographic vs. Perspective	2-23

Sketch Plane	2-24
Step 4-1: Adding an Extruded Boss Feature	2-26
Step 4-2: Adding an Extruded Cut Feature	2-29
Save the Part File	2-31
Questions	2-32
Exercises	2-33

Chapter 3

Constructive Solid Geometry Concepts

Introduction	3-3
Binary Tree	3-4
The Locator Design	3-5
Modeling Strategy – CSG Binary Tree	3-6
Starting SOLIDWORKS and Activating the CommandManager	3-7
<i>GRID</i> and <i>SNAP</i> Intervals Setup	3-9
Base Feature	3-9
Modifying the Dimensions of the Sketch	3-12
Repositioning Dimensions	3-12
Completing the Base Solid Feature	3-12
Creating the Next Solid Feature	3-14
Creating an Extruded Cut Feature	3-17
Creating a Hole with the Hole Wizard	3-20
Creating a Rectangular Extruded Cut Feature	3-23
Using the View Selector	3-26
Questions	3-28
Exercises	3-29

Chapter 4

Feature Design Tree

Introduction	4-3
Starting SOLIDWORKS	4-4
Creating a User-Defined Part Template	4-5
The <i>Saddle Bracket</i> Design	4-9
Modeling Strategy	4-10
The SOLIDWORKS <i>FeatureManager Design Tree</i> Creating the Base Feature	4-11
Adding the Second Solid Feature	4-14
Creating a 2D sketch	4-15
Renaming the Part Features	4-17
Adjusting the Width of the Base Feature	4-18
Adding a Hole	4-19
Creating a Rectangular Extruded Cut Feature	4-22
History-Based Part Modifications	4-23
A Design change	4-24
FeatureManager Design Tree Views	4-26

Selecting a Material and Viewing the Mass Properties	4-28
Questions	4-30
Exercises	4-31

Chapter 5

Geometric Relations Fundamentals

DIMENSIONS and RELATIONS	5-3
Create a Simple Triangular Plate Design	5-3
Fully Defined Geometry	5-4
Starting SOLIDWORKS	5-4
Displaying Existing Relations	5-5
Applying Geometric Relations/Dimensional Constraints	5-6
Over-Defining and Driven Dimensions	5-12
Deleting Existing Relations	5-13
Using the Fully Define Sketch Tool	5-14
Adding Additional Geometry	5-15
Relations Settings	5-18
Parametric Relations	5-19
Dimensional Values and Dimensional Variables	5-21
Parametric Equations	5-22
Viewing the Established Equations	5-22
Global Variables	5-25
Viewing/Editing Equations and Global Variables Using the Dimension <i>Modify</i> Dialog Box	5-29
View Options in the <i>Equations, Global Variables, and</i> <i>Dimensions</i> Dialog Box	5-30
Direct Input of Equations in PropertyManager Fields	5-32
Completing and Saving the Part File	5-33
Questions	5-34
Exercises	5-35

Chapter 6

Geometric Construction Tools

Introduction	6-3
The Gasket Design	6-3
Modeling Strategy	6-4
Starting SOLIDWORKS	6-5
Creating a 2D Sketch	6-6
Editing the Sketch by Dragging the Entities	6-8
Adding Additional Relations	6-10
Using the <i>Trim</i> and <i>Extend</i> Commands	6-11
Adding Dimensions with the Fully Define Sketch Tool	6-14
Fully Defined Geometry	6-16
Creating Fillets and Completing the Sketch	6-17
Profile Sketch	6-18

Redefining the Sketch and Profile using Contour Selection	6-19
Selecting Items by Box and Lasso	6-23
Create an OFFSET Extruded Cut Feature	6-25
Alternate Construction Method - Thin Feature Option	6-29
Questions	6-32
Exercises	6-33

Chapter 7

Parent/Child Relationships and the BORN Technique

Introduction	7-3
The BORN Technique	7-3
The U-Bracket Design	7-4
Starting SOLIDWORKS	7-4
Applying the BORN Technique	7-5
Creating the 2-D Sketch for the Base Feature	7-6
Creating the First Extrude Feature	7-13
The Implied Parent/Child Relationships	7-13
Creating the Second Solid Feature	7-14
Creating the First Extruded Cut Feature	7-17
Creating the Second Extruded Cut Feature	7-18
Examining the Parent/Child Relationships	7-19
Modify a Parent Dimension	7-21
A Design Change	7-22
Feature Suppression	7-23
A Different Approach to the CENTER_DRILL Feature	7-24
Suppress the Rect_Cut Feature	7-25
Creating a Circular Extruded Cut Feature	7-26
A Flexible Design Approach	7-28
Save Part File	7-29
Questions	7-30
Exercises	7-31

Chapter 8

Part Drawings and Associative Functionality

Drawings from Parts and Associative Functionality	8-3
Starting SOLIDWORKS	8-4
Drawing Mode	8-4
Setting Document Properties	8-7
Setting Sheet Properties Using the Pre-Defined Sheet Formats	8-8
Open the Drawing Toolbar	8-8
Creating Three Standard Views	8-9
Repositioning Views	8-9
Adding a New Sheet	8-10
Adding a Base View	8-11
Adding an Isometric View using the View Palette	8-13

Adjusting the View Scale	8-14
Displaying Feature Dimensions	8-15
Repositioning, Appearance, and Hiding of Feature Dimensions	8-16
Adding Additional Dimensions – Reference Dimensions	8-18
Tangent Edge Display	8-20
Adding Center Marks, Center Lines, and Sketch Objects	8-20
Edit Sheet vs. Edit Sheet Format	8-24
Completing the Drawing Sheet	8-24
Property Links	8-26
Associative Functionality – Modifying Feature Dimensions	8-31
Saving the Drawing File	8-34
Saving a Drawing Template	8-34
Questions	8-37
Exercises	8-38

Chapter 9

Reference Geometry and Auxiliary Views

Reference Geometry	9-3
Auxiliary Views in 2D Drawings	9-3
The <i>Rod-Guide</i> Design	9-3
Modeling Strategy	9-4
Starting SOLIDWORKS	9-5
Applying the BORN Technique	9-5
Creating the Base Feature	9-6
Creating an Angled Reference Plane	9-8
Creating a 2D sketch on the Reference Plane	9-11
Using the Convert Entities Option	9-11
Completing the Solid Feature	9-16
Creating an Offset Reference Plane	9-17
Creating another Extruded Cut Feature Using the Reference Plane	9-18
Starting a New 2D Drawing and Adding a Base View	9-20
Creating an Auxiliary View	9-21
Displaying Feature Dimensions	9-23
Adjusting the View Scale	9-25
Repositioning, Appearance, and Hiding of Feature Dimensions	9-25
Tangent Edge Display	9-28
Adding Center Marks and Center Lines	9-28
Controlling the View and Sheet Scales	9-31
Completing the Drawing Sheet	9-32
Editing the Isometric View	9-33
Questions	9-35
Exercises	9-36

Chapter 10

Symmetrical Features in Designs

Introduction	10-3
A Revolved Design: PULLEY	10-3
Modeling Strategy - A Revolved Design	10-4
Starting SOLIDWORKS	10-5
Creating the 2-D Sketch for the Base Feature	10-5
Creating the Revolved Feature	10-9
Mirroring Features	10-10
Creating an Extruded Cut Feature using Construction Geometry	10-11
Circular Pattern	10-16
Drawing Mode – Defining a New Border and Title Block	10-18
Creating a New Drawing Template	10-21
Creating Views	10-22
Retrieve Dimensions – Model Items Command	10-25
Save the Drawing File	10-26
Associative Functionality – A Design Change	10-27
Adding Centerlines to the Pattern Feature	10-29
Completing the Drawing	10-30
Questions	10-33
Exercises	10-34

Chapter 11

Advanced 3D Construction Tools

Introduction	11-3
A Thin-Walled Design: <i>Dryer Housing</i>	11-3
Modeling Strategy	11-4
Starting SOLIDWORKS	11-5
Creating the 2-D Sketch for the Base Feature	11-5
Create a Revolved Boss Feature	11-8
Creating Offset Reference Planes	11-9
Creating 2D Sketches on the Reference Planes	11-10
Creating a Lofted Feature	11-13
Creating an Extruded Boss Feature	11-15
Completing the Extruded Boss Feature	11-16
Create 3D Rounds and Fillets	11-17
Creating a Shell Feature	11-18
Create a Rectangular Extruded Cut Feature	11-19
Creating a Linear Pattern	11-21
Creating a Swept Feature	11-24
Using PhotoView 360, Scenes, and Appearances	11-29
Questions	11-33
Exercises	11-34

Chapter 12

Sheet Metal Designs

Sheet Metal Processes	12-3
Sheet Metal Modeling	12-5
K-Factor	12-6
The Actuator Bracket Design	12-7
Starting SOLIDWORKS and Opening the <i>Sheet Metal</i>	12-8
Toolbar Creating the Base Feature of the Design	12-9
Creating an Edge Flange	12-14
Adding a Tab	12-18
Creating a Cut Feature	12-20
Creating a Bend	12-22
Flattening the Sheet Metal Part	12-24
Confirm the Flattened Length	12-25
Creating a Sheet Metal Drawing	12-26
Sheet Metal Bend Notes	12-30
Completing the Drawing	12-31
Questions	12-34
Exercises	12-35

Chapter 13

Assembly Modeling – Putting It All Together

Introduction	13-3
Assembly Modeling Methodology	13-3
The Shaft Support Assembly	13-4
Parts	13-4
Creating the Collar Using the Chamfer Command	13-4
Creating the Bearing and Base-Plate	13-6
Creating the Cap-Screw	13-7
Starting SOLIDWORKS	13-8
Document Properties	13-8
Inserting the First Component	13-9
Inserting the Second Component	13-10
Degrees of Freedom	13-11
Assembly Mates	13-11
Apply the First Assembly Mate	13-13
Apply a Second Mate	13-14
Constrained Move	13-15
Apply a Third Mate	13-16
Inserting the Third Component	13-19
Applying Concentric and Coincident Mates	13-19
Assemble the Cap-Screws using SmartMates	13-21
Exploded View of the Assembly	13-25
Save the Assembly Model	13-27
Editing the Components	13-27

Setup a Drawing of the Assembly Model	13-29
Creating a Bill of Materials	13-30
Editing the Bill of Materials	13-32
Completing the Assembly Drawing	13-34
Exporting the Bill of Materials	13-37
Questions	13-38
Exercises	13-39

Chapter 14

Design Library and Basic Motion Study

Introduction	14-3
The Crank-Slider Assembly	14-4
Creating the Required Parts	14-4
Mate References	14-7
Starting SOLIDWORKS	14-9
Document Properties	14-9
Inserting the First Component	14-10
Inserting the Second Component	14-11
Apply Assembly Mates	14-12
Apply a Mate Using a Context Toolbar	14-13
Constrained Move	14-14
Placing the Third Component Using a Mate Reference	14-14
Assemble the CS-Rod Part	14-15
Inserting a Pin from the SOLIDWORKS Toolbox	14-16
Assemble the CS-Slider Part	14-18
Adding an Angle-Mate	14-20
Collision Detection	14-21
Editing the CS-Slider Part in the Assembly	14-23
Basic Motion Analysis	14-24
Questions	14-26
Exercises	14-27

Chapter 15

Design Analysis with SimulationXpress

Introduction	15-3
The SimulationXpress Wizard Interface	15-4
Problem Statement	15-5
Preliminary Analysis	15-5
SOLIDWORKS SimulationXpress Study of the Flat Plate	15-7
Getting Started – Create the SOLIDWORKS Part	15-7
Create a SimulationXpress Study	15-9
Viewing SimulationXpress Results	15-12
Creating a Report and an eDrawings File	15-17
Accuracy of Results	15-18
Closing SimulationXpress and Saving Results	15-20

Questions	15-21
Exercises	15-22

Chapter 16

CSWA Exam Preparation

Tips about Taking the Certified SOLIDWORKS Associate Examination	16-3
Introduction	16-4
The Part Problem	16-5
Strategy for Aligning the Part to the Default Axis System	16-6
Creating the Base Feature	16-6
Creating a New View Orientation	16-8
Completing the Part	16-10
Selecting the Material and Viewing the Mass Properties	16-16
The Assembly Problem	16-19
Creating the Parts	16-20
Creating the Assembly	16-21
Creating a Reference Coordinate System	16-27
View the Mass Properties	16-29
Questions	16-32
Exercises	16-33

Appendix

Index