


INCLUDES
Video presentations and a
digital copy of Technical Drawing

ENGINEERING GRAPHICS

TOOLS FOR THE MIND

A COMPREHENSIVE SET OF ENGINEERING GRAPHICS TOOLS



BRYAN GRAHAM



Better Textbooks. Lower Prices.
www.SDCpublications.com



ACCESS CODE
UNIQUE CODE INSIDE

Visit the following websites to learn more about this book:




ENGINEERING GRAPHICS:

Tools for the Mind


Bryan Graham

Table of Contents




1. Lettering

Guidelines for Lettering




2. Sketching

Lines
Circles
Arcs
Isometric Sketching




3. Orthographic Projection

Planes and Surfaces
Curved Surfaces




4. Isometric Drawings

Inclined Surface
Oblique Surface
Curved Surfaces




5. Oblique Drawings

Cavalier Oblique
Cabinet Oblique
Curved Surfaces




6. Auxiliary Views

Inclined Surface



7. Sections

Full Sections
Half Sections
Offset Sections
Revolved/Removed Sections
Broken-Out Sections
Aligned Sections



8. Dimensioning

Basic Rules
Size
- Arc Dimension
Placement
- Holes and Cylindrical Features
- Machined Holes
Locate
- Finished Surfaces
- Holes or Cylinders on an arc or circle
Overall Dimensions
- Rounded End Objects

Exclusive Bonus Content

Technical Graphics

Meyers • Croft • Miller • Demel • Enders

Ohio State University

Table of Contents

CHAPTER 1 Getting Started

1.1	Introduction	1-1
1.2	What You Will Learn From This Text	1-3
1.2.1	Lettering	1-3
1.2.2	Sketching Techniques	1-3
1.2.3	Shape Description	1-3
	Orthographic Projection	1-3
	Pictorial Drawings	1-4
	Perspective Drawings	1-4
1.2.4	Sections and Conventions	1-4
1.2.5	Size Description	1-4
1.2.6	Fastening and Joining	1-5
1.2.7	Drawing Notes	1-5
1.2.8	Production Drawings	1-5
1.2.9	Descriptive Geometry	1-5
1.2.10	Presentation Graphics	1-7
1.2.11	Computer Systems	1-9
	Computer-aided Manufacturing	1-10
	Computer-integrated Manufacturing	1-11
	Flexible Manufacturing Systems	1-11
1.3	Tools You Will Need	1-12
1.3.1	Tools for Sketching	1-12
1.3.2	Tools for Instrument Drawing	1-13
1.3.3	Drawing by Computer	1-15
	Central Processing Unit	1-15
	Input Devices	1-15
	Output Devices	1-16
	Data Storage Devices	1-16
	Software	1-16
1.4	Using Your Drawing Tools	1-17
1.4.1	Sketching	1-17
1.4.2	Alphabet of Lines	1-17
1.4.3	Instrument Drawing	1-17
	Straight Lines	1-17
	Drawing Straight Lines with Your CAD System	1-19
	Circles and Arcs	1-20
	Drawing Circles and Arcs With Your CAD System	1-20
	Measuring	1-21
	Measuring With Your CAD System	1-22

1.5 Lettering	1-22
1.5.1 Lettering Guidelines	1-23
1.5.2 Lettering Styles	1-23
1.5.3 Character Uniformity	1-24
1.5.4 Spacing	1-24
1.6 Summary	1-25

CHAPTER 2 Technical Sketching

2.1 Introduction	2-1
2.2 Sketching Horizontal Lines	2-2
2.3 Sketching Vertical Lines	2-2
2.4 Sketching Angular Lines	2-2
2.5 Sketching Curved Lines	2-2
2.6 Drawing Media	2-3
2.7 Grids for Sketching	2-3
2.8 Line Weights	2-4
2.9 Sketching Instruments	2-4
2.10 Enlarging and Reducing Using a Grid	2-4
2.11 Enlarging and Reducing Using a Rectangular Diagonal	2-5
2.12 Enlarging and Reducing by Changing the Focal Distance from the Object to the Plane	2-5
2.13 Sketching Small Objects with a Hand for Proportion	2-6
2.14 Sketching Solids	2-6
2.15 Four Steps to Sketching an Object	2-6
2.16 Basic Shading of Solids	2-8
2.17 Orthographic Projection Sketch	2-8
2.18 Isometric Pictorial Sketch	2-9
2.19 Oblique Pictorial Sketch	2-9
2.20 Where Do Ideas Come From That Require Sketching?	2-10
2.21 Sample Engineering Applications	2-11
2.22 Sample Problem: Table Saw Fixture	2-12
2.23 Summary	2-13

CHAPTER 3 Orthographic Projection

3.1 Introduction	3-1
3.1.1 Communicating in Three Dimensions	3-1
3.2 Theory of Orthographic Projection	3-2
3.2.1 First-Angle and Third-Angle Projection	3-3
3.3 Principal Views and Planes	3-4
3.3.1 Front View and the Frontal Plane	3-5
3.3.2 Top View and the Horizontal Plane	3-5

3.3.3	Side View and the Profile Plane	3-5
3.3.4	Other Principal Views and Planes	3-5
3.3.5	Relation of the Principal Views	3-6
3.4	Principal Dimensions	3-7
3.5	Nonlinear Features	3-7
3.5.1	Center Lines	3-8
3.6	Visibility	3-8
3.6.1	Describing Hidden Features	3-8
3.7	The Alphabet of Lines	3-9
3.7.1	Visible Lines	3-9
3.7.2	Dashed Lines for Hidden Features	3-9
3.7.3	Junctions of Lines	3-10
3.7.4	Center Lines	3-10
3.7.5	Construction Lines	3-10
3.7.6	Precedence of Lines	3-11
3.8	Using Subscripts	3-11
3.9	What a Line Represents	3-12
3.9.1	A Line as the Edge View of a Surface	3-12
3.9.2	A Line as an Intersection	3-12
3.9.3	A Line as a Limiting Element	3-12
3.9.4	What Can a Line Represent?	3-12
3.10	What a Point Represents	3-13
3.10.1	A Point as the Intersection of Lines	3-13
3.10.2	What Can a Point Represent?	3-13
3.11	Reading the Surfaces of Objects	3-14
3.11.1	Surfaces That Are True Size and Shape	3-14
3.11.2	Surfaces That Are Inclined	3-14
3.11.3	Surfaces That Are Oblique	3-15
3.11.4	Reading by Sketching	3-15
3.11.5	Curved and Tangent Surfaces	3-16
3.11.6	Conventional Practices	3-16
3.11.7	Fillets, Rounds, and Runouts	3-17
3.12	Keys to Reading Three-Dimensional Objects	3-18
3.12.1	Identify and Locate Points on the Object	3-18
3.12.2	Identify and Locate Lines on the Object	3-19
3.12.3	Identify and Locate Surfaces on the Object	3-19
3.12.4	Curved Surfaces and Limiting Elements	3-20
3.12.5	Reading an Object by Sketching It	3-20
3.12.6	Reading by Modeling the Object	3-20
3.13	Creating a Multiview Orthographic Drawing	3-21
3.13.1	Choice of Views	3-22
3.13.2	Planning a Drawing	3-22
3.13.3	Developing the Drawing	3-23
3.13.4	Checking Your Work	3-24
3.14	Creating a Drawing on the Computer	3-24
3.14.1	Selecting a Grid	3-24
3.14.2	Selecting the Layers	3-25
3.14.3	Selecting Pen Widths and Colors for a Printer	3-25
3.14.4	Developing the Drawing on the Computer	3-25
	Construction Lines	3-25
	Visible Lines	3-26

	Finishing the Drawing	3-26
	Alternate Methods for Layering	3-26
3.14.5	Modeling With CAD	3-28
3.15	Auxiliary Views	3-29
3.15.1	Preparing an Auxiliary View Drawing	3-30
3.15.2	Other Auxiliary Views	3-32
3.16	Sample Problem: Table Saw Fixture	3-32
3.17	Summary	3-33

CHAPTER 4 Pictorial Drawings

4.1	Introduction	4-1
4.2	Axonometric Drawings	4-1
4.2.1	Types of Axonometric Drawings	4-1
4.2.2	The Isometric Axes	4-2
4.2.3	Normal Surfaces in Isometric	4-2
4.2.4	Inclined Surfaces in Isometric	4-3
4.2.5	Oblique Surfaces in Isometric	4-4
4.2.6	Circles and Arcs Using an Isometric Template	4-4
4.2.7	Sketching and Drawing Circles and Arcs	4-6
4.2.8	Sketching or Drawing Ellipses on Non-isometric Surfaces	4-8
4.2.9	Sketching an Irregular Ellipse or Curve	4-9
4.2.10	Exploded Views	4-9
4.2.11	Isometric Assembly Sketches and Drawings	4-10
4.2.12	Isometric Projections	4-10
4.3	Oblique Drawings	4-12
4.3.1	Oblique Views	4-12
4.3.2	Cabinet and Cavalier Oblique Drawings	4-13
4.4	Perspective Drawings	4-14
4.4.1	Perspective Overview	4-14
4.4.2	One-Point Perspective	4-14
4.4.3	Two-Point Perspective	4-16
4.4.4	Layout of the Object and Picture Plane	4-17
4.4.5	The Measuring Line	4-18
4.4.6	The Horizon	4-19
4.4.7	The Station Point	4-20
4.4.8	Vanishing Points	4-20
4.4.9	Projectors	4-20
4.4.10	Visual Rays	4-21
4.4.11	Presentation Variables	4-22
4.4.12	Angular Surfaces	4-22
4.4.13	Curved Surfaces	4-23
4.4.14	Three-Point Perspective	4-25
4.5	Computer Applications	4-25
4.6	Sample Problem: Table Saw Fixture	4-25
4.7	Summary	4-25

CHAPTER 5 Sections and Conventions

5.1	Introduction	5-1
5.2	Cutting Plane	5-1

5.3	Section Lines	5-3
5.4	Full Section	5-5
5.5	Half Sections	5-6
5.6	Offset Sections	5-7
5.7	Revolved Sections	5-7
5.8	Removed Sections	5-7
5.9	Broken-out Sections	5-8
5.10	Sectioned Assemblies	5-8
5.11	Sectioned Isometric Drawings	5-8
5.12	Conventional Breaks	5-9
5.13	Conventional Revolutions	5-9
5.13.1	Conventional Hole Revolutions	5-10
5.13.2	Conventional Rib Revolutions	5-10
5.13.3	Conventional Spoke Revolutions	5-11
5.13.4	Conventional Lug Revolutions	5-12
5.13.5	Hole, Rib, Spoke, and Lug Combination	5-12
5.13.6	Alternate Crosshatching	5-13
5.14	Sample Problem: Table Saw Fixture	5-13
5.15	Summary	5-13

CHAPTER 6 Dimensions and Tolerances

6.1	Introduction	6-1
6.1.1	Dimensioning Standards	6-1
6.1.2	Dimensioning Practices	6-2
6.2	Scaling and Dimensions	6-2
6.2.1	Types of Scales	6-3
6.2.2	Specifying Scales on a Drawing	6-5
6.3	Dimensioning Basic Shapes	6-5
6.3.1	Assumptions	6-5
Perpendicularity	6-5	
Symmetry	6-5	
6.3.2	Simple Shapes	6-5
Rectangular Prisms	6-5	
Cylinders	6-5	
Cone and Frustum	6-6	
6.3.3	Simple Curved Shapes	6-6
6.3.4	Circular Center Lines	6-7
6.4	Placement of Dimensions	6-8
6.4.1	Characteristic View	6-8
6.4.2	Dimensions Should Be Grouped	6-8
6.4.3	Preferred Locations	6-8
6.5	Dimensioning Systems	6-8
6.5.1	Alignment of Dimension Numbers	6-8
6.5.2	Units of Measurement	6-9
6.6	Standard Practices	6-9
6.6.1	Lines for Dimensioning	6-9

6.6.2	Arrowheads	6-9
6.6.3	Lettering and Notes	6-10
6.6.4	Readability	6-10
6.7	Planning and Layout	6-11
6.8	Functional Relationships	6-11
6.8.1	Tolerance Accumulation	6-11
6.8.2	Dimensioning to Finished Surfaces	6-12
6.8.3	Dimensions for Locating Features on an Object	6-13
6.8.4	Procedure for Functional Dimensioning	6-14
6.9	Dimensioning on the Computer	6-14
6.9.1	A Layer for Dimensions	6-14
6.9.2	Scaling a CAD Drawing	6-14
6.9.3	Automatic Dimensioning	6-15
6.10	Other Standard Dimensioning Systems	6-15
6.10.1	Datum Lines and Surfaces	6-16
6.10.2	Tabular Dimensioning	6-16
6.10.3	Other Design Disciplines	6-17
6.11	Dimensioning for Interchangeable Parts	6-18
6.11.1	Types of Fits	6-18
Clearance Fits	6-19	
Checking Fit Calculations	6-19	
Interference Fits	6-20	
Transition Fits	6-20	
6.11.2	Standard Fits	6-20
6.11.3	Cylindrical Fits	6-21
Basic Hole System	6-21	
Basic Shaft System	6-22	
6.12	Advanced Dimensioning Topics	6-23
6.12.1	Metric Dimensioning With International Standards	6-23
6.12.2	Surface Control	6-23
6.12.3	Geometric Tolerancing	6-23
6.13	Principles of Good Dimensioning	6-23
6.14	Checking a Dimensioned Drawing	6-28
6.15	Sample Problem: Table Saw Fixture	6-28
6.16	Summary	6-29

CHAPTER 7 Dimensioning for Production

7.1	Introduction	7-1
7.2	Manufacturing Processes	7-2
7.2.1	Material Reformation	7-2
7.2.2	Material Removal	7-3
7.2.3	Material Addition	7-5
7.2.4	Assembly Processes	7-6
7.3	Standard Tables for Fits	7-7
7.3.1	Preferred Limits and Fits in Inches	7-7
7.3.2	Preferred Metric Limits and Fits	7-9
7.4	Surface Control	7-11
7.5	Geometric Tolerancing	7-14

7.5.1	Definitions and Symbols	7-15
7.5.2	Datum Referencing	7-16
7.5.3	Tolerances of Location	7-17
7.5.4	Tolerances of Form	7-19
7.6	Sample Problem: Table Saw Fixture	7-22
7.7	Summary	7-22

CHAPTER 8 Fastening, Joining, and Standard Parts

8.1	Introduction	8-1
8.2	Screw-Thread Terms	8-2
8.3	Other Properties of Threads	8-3
8.3.1	Right-hand and Left-hand Threads	8-3
8.3.2	Screw-Thread Forms	8-3
8.3.3	Multiple Threads	8-4
8.3.4	Thread Series	8-5
8.3.5	Specifying a Thread	8-6
8.4	Threaded Fasteners	8-7
8.4.1	Screws	8-7
8.4.2	Bolts, Nuts, Studs, and Washers	8-9
8.4.3	Materials for Fasteners	8-11
8.5	Representing Threads and Fasteners on Drawings	8-11
8.5.1	Detailed Thread Symbols	8-12
8.5.2	Schematic Thread Symbols	8-13
8.5.3	Simplified Thread Symbols	8-14
8.5.4	Drawing Screw Heads and Nuts	8-14
8.5.5	Specifying Fasteners	8-15
8.6	Other Mechanical Fasteners	8-15
8.6.1	Rivets	8-16
8.6.2	Pins	8-16
8.6.3	Keys	8-17
8.6.4	Retaining Rings	8-18
8.7	Other Machine Elements	8-18
8.8	Thermal Processes	8-20
8.8.1	Welding Processes	8-20
8.8.2	Specifying Welds on Drawings	8-22
8.8.3	Soldering and Brazing	8-23
8.9	Adhesives	8-24
8.9.1	Principal Types of Adhesives	8-24
8.10	The Future of Fastening and Joining	8-25
8.11	Sample Problem: Table Saw Fixture	8-26
8.12	Summary	8-26

CHAPTER 9 Production Drawings

9.1	Introduction	9-1
9.2	Applications of Production Drawings	9-12
9.3	Types of Production Drawings	9-12

9.3.1	Orthographic Detail Drawings	9-12
9.3.2	Sectioned Assembly Drawings	9-13
9.3.3	Pictorial Drawings and Diagrams	9-14
9.3.4	Drawings for Other Disciplines	9-16
9.4	Callouts	9-19
9.5	Identification of Measuring Units	9-19
9.6	Paper Sizes for Drawings	9-20
9.7	Title Blocks	9-21
9.8	Revisions	9-24
9.9	Parts List	9-24
9.10	General Notes	9-25
9.11	Applications of the CAD Database	9-26
9.12	Flow of Information	9-29
9.13	Accompanying Written Specifications	9-30
9.14	Sample Problem: Table Saw Fixture	9-30
9.15	Summary	9-31

CHAPTER 10 Three-Dimensional Geometry Concepts

10.1	Introduction	10-1
10.2	Applications of Descriptive Geometry	10-8
10.2.1	Problem-solving Skills	10-9
10.2.2	Developing Visualization Skills	10-10
10.3	Operations	10-10
10.3.1	The Direct Method	10-10
10.3.2	The Glass Box: Fold Line Method	10-13
10.4	Line Relationships	10-15
10.4.1	Principal Lines	10-15
10.4.2	Inclined Lines	10-15
10.4.3	Oblique Lines	10-15
10.4.4	Parallel Lines	10-18
10.4.5	Perpendicular Lines	10-19
10.4.6	Angular Relationships	10-20
10.4.7	Applications	10-21
10.5	Plane and Line Relationships	10-22
10.5.1	Principal Planes	10-22
10.5.2	Inclined Planes	10-22
10.5.3	Oblique Planes	10-27
10.5.4	Lines Parallel to Planes	10-29
10.5.5	Lines Perpendicular to Planes	10-30
10.5.6	Angles between Lines and Planes	10-30
10.5.7	Lines Intersecting Planes	10-33
10.5.8	Planes Parallel to Planes	10-34
10.5.9	Dihedral Angles	10-34
10.5.10	Planar Intersections	10-35
10.5.11	Plane-Solid Intersections	10-36
10.5.12	Solid-Solid Intersections	10-39

10.6	Curved Surfaces	10-40
10.6.1	Line-Cylinder Intersections	10-43
10.6.2	Line-Cone Intersections	10-44
10.6.3	Line-Sphere Intersections	10-45
10.6.4	Plane-Cylinder Intersections	10-45
10.6.5	Plane-Cone Intersections	10-46
10.6.6	Cylinder-Cylinder Intersections	10-47
10.6.7	Cylinder-Right Circular Cone Intersection	10-48
10.7	Sample Problem: Table Saw Fixture	10-49
10.8	Summary	10-50

CHAPTER 11 3-D Geometry Applications

11.1	Introduction	11-1
11.2	Pattern Developments	11-1
11.2.1	Principles and Examples	11-1
11.2.2	Right Solids	11-2
11.2.3	Cylinders	11-6
11.2.4	Cones	11-10
11.2.5	Pyramids and Tetrahedrons	11-11
11.2.6	Transition Pieces	11-12
11.2.7	Models From Intersecting Solids	11-13
11.2.8	Applications	11-16
11.3	Maps and Contour Plots	11-16
11.3.1	Map Introduction	11-17
11.3.2	Concept of Representing Elevation	11-22
11.3.3	Sections or Profiles and Applications	11-22
11.4	Vector Graphics	11-23
11.4.1	Vector Addition and Subtraction	11-24
11.4.2	Applications	11-25
	Statics: Two-Dimensional, Single-Joint Problem	11-25
	Statics: Two-Dimensional Truss Analysis	11-27
	Statics: Three-Dimensional Analysis	11-27
11.5	Shades and Shadows	11-28
11.5.1	Shade, Shadows, and the Standard Light Ray	11-28
11.5.2	Orthographic Views	11-29
11.5.3	Shades and Shadows in Isometric Pictorials	11-37
11.5.4	Shades and Shadows in Perspective Pictorials	11-40
11.6	Sample Problem: Table Saw Fixture	11-42
11.7	Summary	11-42

CHAPTER 12 Graphical Presentation of Data

12.1	Introduction	12-1
12.2	Charts and Graphs	12-1
12.2.1	Classes of Charts and Graphs	12-1
12.2.2	Typical Uses of Charts and Graphs	12-2
12.2.3	Types of Graphs and Their Uses	12-4
	Line Graphs	12-4
	Multiple-Line Graphs	12-5
	Multiple-Scale Graphs	12-5

Pie Charts	12-6
Polar Charts	12-7
Bar Charts	12-8
Surface Charts	12-9
Three-Coordinate Charts	12-9
Tri-linear Charts	12-10
12.2.4 Plotting a Graph	12-11
Selecting the Type of Graph	12-11
Selecting a Size for a Graph	12-11
Selecting and Calibrating a Scale	12-12
12.2.5 Adding Titles and Labels	12-14
Chart/Graph Title	12-14
Labeling the Axes	12-15
12.2.6 Modeling Empirical Data (Data Scatter)	12-16
Best-Fit Methods	12-16
Types of Data	12-17
12.2.7 Computer-based Chart and Graph Programs	12-17
12.3 Merging Text and Graphics by Computer	12-20
12.4 Sample Problem: Table Saw Fixture	12-23
12.5 Summary	12-23

CHAPTER 13 Design Process

13.1 Introduction	13-1
13.1.1 Product Design and Systems Design	13-2
13.2 Scientific Method	13-4
13.2.1 Determine a Need	13-5
13.2.2 Establish Known Information	13-6
13.2.3 Stimulate Design Concepts	13-6
13.2.4 Investigate Design Concepts With Analytical Tools	13-7
13.2.5 Gather and Review Investigation Data	13-8
13.2.6 Now Test the Design	13-8
13.2.7 Propose to Accept, Modify, or Reject the Design	13-9
13.2.8 Render the Final Decision and Prepare Working Drawings	13-10
13.2.9 Optimize Design by Iteration	13-10
13.3 Lateral Thinking	13-11
13.4 Presentation	13-12
13.4.1 What Is Being Presented?	13-12
13.4.2 Why Is the Presentation Being Made?	13-12
13.4.3 Who Is the Audience?	13-13
13.4.4 When Will the Presentation Be Made?	13-13
13.4.5 Where Will the Presentation Be Made?	13-13
13.4.6 How Will the Information Be Presented?	13-14
13.4.7 How Much Will the Presentation Cost?	13-14
13.4.8 Notes on Content of Presentations	13-14
13.5 Protection of Designs	13-15
13.6 A Design Problem	13-16
13.6.1 Determine a Need	13-16
13.6.2 Establish Known Information	13-16
13.6.3 Stimulate Design Concepts	13-18
13.6.4 Investigate Design Concepts With Analytical Tools	13-20
13.6.5 Gather and Review Investigation Data	13-22

13.6.6	Now Test the Design	13-22
13.6.7	Propose to Accept, Modify, or Reject the Design	13-23
13.6.8	Render the Final Decision	13-24
13.6.9	Optimize Design by Iteration	13-25
13.7	Summary	13-26

APPENDIX Tables

Table A.1	Preferred Limits and Fits (Inches)	A-3
Table A.2	Preferred Limits and Fits (Metric)	A-10
Table A.3	American National Standard Unified Inch Screw Threads	A-14
Table A.4	Standard Coarse Pitch Metric Threads	A-15
Table A.5	Standard Fine Pitch Metric Threads	A-15
Table A.6	Dimensions of Hex Bolts	A-16
Table A.7	Dimensions of Square Bolts	A-17
Table A.8	Dimensions of Hex Nuts and Hex Jam Nuts	A-18
Table A.9	Dimensions of Square Nuts	A-19
Table A.10	Dimensions of Hex Cap Screws	A-20
Table A.11	Dimensions of Slotted Flat Countersunk Head Cap Screws	A-21
Table A.12	Dimensions of Slotted Round Head Cap Screws	A-22
Table A.13	Dimensions of Slotted Fillister Head Cap Screws	A-23
Table A.14	Dimensions of Hex Head Machine Screws	A-24
Table A.15	Dimensions of Slotted Flat Countersunk Head Machine Screws	A-25
Table A.16	Dimensions of Slotted Fillister Head Machine Screws	A-26
Table A.17	Dimensions of Square and Hex Machine Screw Nuts	A-27
Table A.18	Dimensions of Slotted Headless Set Screws	A-28
Table A.19	Dimensions of Square Head Set Screws	A-29
Table A.20	Shoulder Screws	A-30
Table A.21	Dimensions of Preferred Sizes of Type A Plain Washers	A-31
Table A.22	Dimensions of Woodruff Keys	A-32
Table A.23	Tap Drill Sizes – Inches	A-33
Table A.24	Tap Drill Sizes – Metric	A-33
Table A.25	Standard Welding Symbols	A-34
Table A.26	Fraction – Decimal Conversion Table	A-36