
Learning SOLIDWORKS 2018

Modeling, Assembly and Analysis



Visit the following websites to learn more about this book:



amazon.com





Table of Contents

Preface Acknowledgments Table of Contents	1 ii iii
Chapter 1 Introduction – Getting Started	
Introduction Development of Computer Geometric Modeling Feature-Based Parametric Modeling Getting Started with SOLIDWORKS Starting SOLIDWORKS SOLIDWORKS Screen Layout Menu Bar Menu Bar Pull-down Menus Heads-up View Toolbar Features Toolbar Sketch Toolbar Property Managers Graphics Area Reference Triad Origin Confirmation Corner Graphics Cursor or Crosshairs Message and Status Bar Using the SOLIDWORKS Command Manager Mouse Buttons [Esc] - Canceling Commands SOLIDWORKS Help System Leaving SOLIDWORKS Creating a CAD files folder	1-2 1-2 1-6 1-7 1-7 1-7 1-10 1-10 1-11 1-11 1-11 1-
Chapter 2 Parametric Modeling Fundamentals	
Introduction The Tiger Head Design Starting SOLIDWORKS SOLIDWORKS Screen Layout Units Setup	2-2 2-3 2-3 2-4 2-5

Step 1: Determine/Set up the Base Solid Feature	2-6
Sketching Plane – It is an XY CRT, but an XYZ World	2-6
Creating Rough Sketches	2-8
Step 2: Creating a Rough Sketch	2-9
Graphics Cursors	2-9
Geometric Relation Symbols	2-10
Step 3: Apply/Modify Constraints and Dimensions	2-11
Viewing Functions – Zoom and Pan	2-16
Delete an Existing Geometry of the Sketch	2-17
Use the 3-Point Arc Command	2-17
Step 4: Complete the Base Solid Feature	2-19
Isometric View	2-20
Rotation of the 3D Model – Rotate View	2-20
Rotation and Panning –Arrow Keys	2-22
Dynamic Viewing - Quick Keys	2-23
Viewing Tools – Heads-up View Toolbar	2-25
View Orientation	2-26
Display Style	2-20 2-27
Orthographic vs. Perspective	2-27
Customizing the Heads-up View Toolbar	2-27
	2-28
Step 5-1: Add an Extruded Feature	
Step 5-2: Add a Cut Feature	2-32
Step 6: Add Additional Features	2-34
Add a Decal	2-36
Save the Model	2-39
Review Questions	2-40
Exercises	2-41
Chapter 3	
CSG Concepts and Model History Tree	
Introduction	3-2
Binary Tree	3-3
Model History Tree	3-4
The A6-Knee Part	3-5
Starting SOLIDWORKS	3-5
Modeling Strategy	3-6
The SOLIDWORKS Feature Manager	3-7
Base Feature	3-7
Units Setup	3-8
Create the Base Feature	3-9
Adding the Second Solid Feature	3-13
Renaming the Part Features	3-15
Adjust the Dimensions of the Base Feature	3-15
History-Based Part Modifications	3-18
Add a Placed Feature	3-19

	Table of Contents
Create an Offset Extruded Feature	3-22
Add another Hole Feature	3-25
Assign and Calculate the Associated Physical Properties	3-27
Review Questions	3-30
Exercises	3-31
Chapter 4	
Parametric Constraints Fundamentals	
DIMENSIONS and RELATIONS	4-2
Create a Simple Triangular Plate Design	4-2
Fully Defined Geometry	4-3
Starting SOLIDWORKS	4-3
Create a User-Defined Part Template	4-4
Start a New Model using the New Template	4-6
Display/Hide Applied Geometric Relations	4-7
Apply Geometric/Dimensional Constraints	4-8
Geometric Editing with Drag and Drop	4-12
Create Fully Constrained Sketches	4-14
Over-Defining and Driven Dimensions	4-15
Delete the Fix Constraint	4-17
Use the Fully Define Sketch Tool	4-18
Add Additional Geometry	4-20
Relations Settings	4-24
Model the B3-Leg Part	4-25
Create the 2D Sketch for the Base Feature	4-26
Parametric Relations	4-27
Use the Equations Command	4-29
Complete the Base Feature	4-30
Sketches vs. Profiles	4-32
Redefine the Profile with Contour Selection	4-35
Create an Extrusion with the Taper Angle Option	4-36
A Profile Containing Multiple Closed Regions	4-39
The Convert Entities Option	4-41
Add a Feature using Existing Geometry	4-41
Save the Model File	4-43
Use the Measure Tools	4-43
Create a Metric Part Template	4-46
The Boot Part	4-48
Review Questions	4-51

Exercises

4-52

Chapter 5		
Pictorials	and	Sketching

Modeling Strategy

Create a Cut Feature

Add a Base View

Review Questions

Exercises

Add Centerlines

Create the Base Feature

Create a Revolved Feature

Create a Mirrored Feature

Create a Symmetrical Cut Feature

Create another Extruded Feature

Drawing Mode – 2D Paper Space

Add Additional Dimensions – Reference Dimensions

Associative Functionality – Modify Feature Dimensions

The Drawing Sheet Properties

Display Feature Dimensions

Complete the Drawing Sheet

Pictorials and Sketching	
Engineering Drawings, Pictorials and Sketching	5-2
Isometric Sketching	5-7
Isometric Sketching Exercises	5-9
Oblique Sketching	5-19
Oblique Sketching Exercises	5-20
Perspective Sketching	5-26
SOLIDWORKS Orthographic vs. Perspective Display	5-27
One-point Perspective	5-28
Two-point Perspective	5-29
Perspective Sketching Exercises	5-30
Review Questions	5-36
Exercises	5-37
Chapter 6 Symmetrical Features and Part Drawings	
	(2
Drawings from Parts and Associative Functionality	6-2
The A12- Rear Axle Support Design	6-3
Starting SOLIDWORKS	6-3

6-4

6-5

6-8

6-10

6-15

6-18 6-20

6-21

6-22

6-24

6-26

6-29

6-31

6-32

6-34

6-37

6-38

Chapter	7		
Datum	Features	in	Designs

Datum Features in Designs	
Reference Features	7-2
The B2-Chassis Part	7-2
Modeling Strategy	7-3
Starting SOLIDWORKS	7-4
Create the Base Feature	7-5
Create the Second Extruded Feature	7-8
Create a Tapered Extruded Feature	7-10
Create an Offset Reference Plane	7-11
Create a Revolved Feature	7-12
Create an Angled Reference Plane	7-15
Create another Offset Reference Plane	7-16
Create an Extruded Feature with Reference Plane 3	7-18
Change the Appearance of the Solid Model	7-22
The Crank-Right Part	7-24
The A10-Crank Left Part	7-28
The <i>Motor</i> Part	7-30
The A1-Axle End Cap Part	7-33
The Hex Shaft Collar Part	7-34
The A8-Rod Pin Part	7-38
Review Questions	7-39
Exercises	7-40
Chapter 8	
Gears and SOLIDWORKS Design Library	
	0.2
Introduction to Gears	8-2
Spur Gear Nomenclatures	8-4
Basic Involute Tooth Profile	8-6
Gear Ratio	8-7
SOLIDWORKS Gear Toolbox	8-9
Starting SOLIDWORKS	8-10
Open the SOLIDWORKS Design Library	8-10
SOLIDWORKS Spur Gear Toolbox	8-12
Create a 42 Teeth Spur Gear	8-13
Modify the Generated 42T Gears	8-14 8-18
Create a Mirrored Feature	8-19
Import the Profile of the Pinion Gear	
Complete the G2-Spur Gear Part	8-25 8-27
Create the <i>G3-Spur Gear</i> Part Create the <i>G0-Pinion</i> Part	8-27 8-31
Start a New Part File	8-33
Export/Import the Generated Gear Profile	8-36
Create a Circular Pattern	8-39
Create a Circular i attern	0 - 39

	Learning	SOLID	WORKS
--	----------	--------------	-------

viii

Review Questions Exercises	8-46 8-47
Chapter 9 Advanced 3D Construction Tools	
Introduction A Thin-Walled Design: Battery Case Modeling Strategy Starting SOLIDWORKS Create the Base Feature Create a Cut Feature Create a Shell Feature Create a Cut Feature Create another Extruded Feature Create another Cut Feature Mirror the Last Feature Create another Cut Feature Create another Cut Feature Complete the Model A Thin-Wire Design: Linkage Rod The Sweep Operation Start a New Model Complete the Swept Feature Create a Mirrored Feature The Gear Box Right Part The Gear Box Left Part Review Questions Exercises	9-2 9-2 9-3 9-4 9-5 9-7 9-11 9-12 9-14 9-16 9-18 9-19 9-20 9-22 9-22 9-22 9-22 9-23 9-29 9-34 9-38 9-39
Chapter 10 Planar Linkage Analysis using GeoGebra	
Introduction to Four-Bar Linkages Introduction to GeoGebra Hide the Display of Objects Add a Slider Control Use the Animate Option Tracking the Path of a Point on the Coupler Exercises	10-2 10-5 10-14 10-16 10-19 10-20 10-25

Chapter	11			
Design	Makes	the	Differ	ence

Engineering Analysis – How does this work?	11-2
Identify the Six-bar Linkage of the Mechanical Tiger	11-4
Starting GeoGebra	11-6
Add a Slider Control	11-14
Create the Second Four-bar Mechanism	11-16
Use the Animate Option	11-20
Tracking the Paths of the Feet	11-21
Adjusting the Crank Length	11-23
The Jansen Mechanism	11-24
The Klann Mechanism	11-25
Exercises	11-27

Chapter 12 Assembly Modeling and Basic Motion Analysis

Introduction	12-2
Assembly Modeling Methodology	12-3
The Mechanical Tiger Assembly	12-4
Additional Parts	12-4
Creating the Leg Subassembly	12-6
Starting SOLIDWORKS	12-6
Document Properties	12-7
Place the First Component	12-8
Place the Second Component	12-9
Degrees of Freedom and Assembly Relations	12-10
Assembly Mates	12-11
Apply the First Assembly Mate	12-12
Apply a Second Assembly Mate	12-14
Constrained Move	12-15
Place the Third Component	12-16
Apply a Coincident Mate	12-17
Apply another Aligned Mate	12-19
Edit Parts in the Assembly Mode	12-21
Assemble the <i>Boot</i> Part	12-25
Use the Design Library and Assemble Two Screws	12-27
Start the <i>Main Assembly</i>	12-29
Assemble the <i>Gear Box Right</i> Part	12-32
Assemble the <i>Motor</i> and the <i>Pinion Gear</i>	12-35
Assemble the <i>G1 Gear</i>	12-38
SOLIDWORKS Basic Motion Study	12-41
Assemble the <i>G2 Gear</i>	12-43
Assemble the <i>G3 Gear</i>	12-46

Assemble the Hex Shafts	12-48
Assemble the <i>Crank</i> Parts	12-51
Assemble the <i>Rear Shaft</i> and <i>Legs</i>	12-55
Assemble the Linkage-Rods	12-57
Complete the Assembly Model	12-62
Record an Animation Movie	12-63
Conclusion	12-64
Summary of Modeling Considerations	12-64
Review Questions	12-65
Exercises	12-66
Chapter 13	
Introduction to 3D Printing	
What is 3D Printing	13-2
Development of 3D Printing Technologies	13-3
Primary types of 3D Printing processes	13-6
Stereolithography	13-6
Fused Deposition Modeling & Fused Filament Fabrication	13-7
Laser Sintering / Laser Melting	13-8
Primary 3D Printing Materials for FDM and FFF	13-9
From 3D model to 3D printed Part	13-11
Starting SOLIDWORKS	13-12
Export the Design as an STL file	13-13
Using the 3D Printing software to create the 3D Print	13-18
Questions	13-26

Index