Autodesk Inventor 2024 and Engineering Graphics

An Integrated Approach













Table of Contents

Preface	1
Acknowledgments	ii
Table of Contents	iii
Autodesk Inventor Certified User Examination Overview	XV
Tips for Taking the Autodesk Inventor Certified User Examination	XX
Chantar 1	
Chapter 1 Introduction	
Introduction	1-3
Drawing in CAD Systems	1-5
Development of Computer Aided Design	1-5
Feature-Based Parametric Modeling	1-9
Getting Started with Autodesk Inventor	1-10
The Screen Layout and Getting Started Toolbar	1-11
The New File Dialog Box and Units Setup	1-12
The Default Autodesk Inventor Screen Layout	1-13
File Menu	1-14
Quick Access Toolbar	1-14
Ribbon Tabs and Tool Panels	1-14
Online Help Panel	1-14
3D Model Toolbar	1-15
Graphics Window	1-15
Message and Status Bar	1-15
Mouse Buttons	1-16
[Esc] - Canceling Commands	1-16
Autodesk Inventor Help System	1-17
Data Management Using Inventor Project Files	1-18
Setup of a New Inventor Project	1-19
The Content of the Inventor Project File	1-22
Leaving Autodesk Inventor	1-22
Leaving Autodesk inventor	1-22
Chapter 2	
Parametric Modeling Fundamentals	
Introduction	2-3
The Adjuster Design	2-4
Starting Autodesk Inventor	2-4
The Default Autodesk Inventor Screen Layout	2-6
Sketch Plane – It is an XY Monitor, but an XYZ World	2-7
Creating A Rough Sketch	2-9
Step 1: Creating a Rough Sketch	2-10
2. The street of	2 10

Graphics Cursors	2-10
Geometric Constraint Symbols	2-11
Step 2: Apply/Modify Constraints and Dimensions	2-12
Dynamic Viewing Functions – Zoom and Pan	2-15
Modifying the Dimensions of the Sketch	2-15
Step 3: Completing the Base Solid Feature	2-16
Isometric View	2-17
Dynamic Rotation of the 3D Block – Free Orbit	2-18
Dynamic Viewing – Quick Keys	2-20
Viewing Tools – Standard Toolbar	2-21
Full Navigation Wheel	2-23
Display Modes	2-25
Orthographic vs. Perspective	2-25
Disable the Heads-up Display Option	2-26
Step 4-1: Adding an Extruded Feature	2-27
Step 4-2: Adding a Cut Feature	2-31
Step 4-3: Adding another Cut Feature	2-34
Save the Model	2-36
Review Questions	2-38
Exercises	2-39
Chapter 3 Constructive Solid Geometry Concepts	
Constructive Solid Geometry Concepts	3-3
Constructive Solid Geometry Concepts Introduction	3-3 3-4
Constructive Solid Geometry Concepts Introduction Binary Tree	3-4
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design	3-4 3-5
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree	3-4 3-5 3-6
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design	3-4 3-5 3-6 3-7
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature	3-4 3-5 3-6 3-7 3-8
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup	3-4 3-5 3-6 3-7 3-8 3-9
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format	3-4 3-5 3-6 3-7 3-8 3-9 3-12
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch	3-4 3-5 3-6 3-7 3-8 3-9
Constructive Solid Geometry Concepts Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-12 3-13
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-13 3-14
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools Completing the Base Solid Feature	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-12 3-13
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools Completing the Base Solid Feature Creating the Next Solid Feature	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-13 3-14 3-17
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools Completing the Base Solid Feature	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-12 3-13 3-14 3-17 3-18
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools Completing the Base Solid Feature Creating a Cut Feature	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-13 3-14 3-17 3-18 3-22
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools Completing the Base Solid Feature Creating a Cut Feature Creating a Placed Feature	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-13 3-14 3-17 3-18 3-22 3-25
Introduction Binary Tree The Locator Design Modeling Strategy – CSG Binary Tree Starting Autodesk Inventor Base Feature GRID Display Setup Model Dimensions Format Modifying the Dimensions of the Sketch Repositioning Dimensions Using the Measure Tools Completing the Base Solid Feature Creating a Cut Feature Creating a Placed Feature Creating a Rectangular Cut Feature	3-4 3-5 3-6 3-7 3-8 3-9 3-12 3-13 3-14 3-17 3-18 3-22 3-25 3-27

Chapter 4	
Geometric	Constructions

Geometric Constructions	4-3
Geometric Constructions - Classical Methods	4-4
Bisection of a Line or Arc	4-4
Bisection of an Angle	4-5
Transfer of an Angle	4-6
Dividing a Given Line into a Number of Equal Parts	4-7
Circle through Three Points	4-8
A Line Tangent to a Circle	4-9
Line Tangent to a Circle from a Given Point	4-10
Circle of a Given Radius Tangent to Two Given Lines	4-11
Circle of a Given Radius Tangent to an Arc and a Line	4-12
Circle of a Given Radius Tangent to Two Arcs	4-13
Starting Autodesk Inventor	4-14
Geometric Construction - CAD Method	4-15
Bisection of a Line or Arc	4-15
Dimensions and Relations	4-17
Applying Geometric/Dimensional Constraints	4-18
Bisection of an Angle	4-19
Dividing a Given Line into a Number of Equal Parts	4-21
Arc through Three Points	4-28
Line Tangent to a Circle from a Given Point	4-29
Circle of a Given Radius Tangent to Two Given Lines	4-30
Adding Geometric Relations and Fully Defined Geometry	4-33
Starting a New Drawing	4-33
Displaying Existing Constraints	4-34
Over-Constraining and Driven Dimensions	4-39
Deleting Existing Constraints	4-40
Using the Auto Dimension Command	4-41
Constraint and Sketch Settings	4-46
Parametric Relations	4-47
Dimensional Values and Dimensional Variables	4-49
Parametric Equations	4-50
Viewing the Established Parameters and Relations	4-52
Saving the Model File	4-53
Using the Measure Tools	4-54
Review Questions	4-58
Exercises	4-59
Chapter 5 Model History Tree	
Introduction	5-3
The Saddle Bracket Design	5-4
Starting Autodesk Inventor	5-4

Modeling Strategy The Autodesk Inventor Browser Creating the Base Feature Adding the Second Solid Feature Creating a 2D Sketch Renaming the Part Features Adjusting the Width of the Base Feature Adding a Placed Feature Creating a Rectangular Cut Feature History-Based Part Modifications A Design Change	5-5 5-6 5-6 5-9 5-10 5-12 5-13 5-14 5-16 5-17
Assigning and Calculating the Associated Physical Properties Review Questions Exercises Chapter 6 Geometric Construction Tools	5-21 5-23 5-24
Introduction The Gasket Design Modeling Strategy Starting Autodesk Inventor Create a 2D Sketch Edit the Sketch by Dragging the Sketched Entities Add Additional Constraints Use the Trim and Extend Commands The Auto Dimension Command Create Fillets and Completing the Sketch Fully Constrained Geometry Profile Sketch Redefine the Sketch and Profile Create an Offset Cut Feature Review Questions Exercises	6-3 6-4 6-5 6-6 6-8 6-10 6-13 6-15 6-16 6-18 6-23 6-26 6-27
Chapter 7 Orthographic Projection and Multiview Constructions	
Introduction Basic Principles of Projection Orthographic Projection Multiview Orthographic Projection First-Angle Projection Rotation of the Horizontal and Profile Planes The 3D Adjuster Model and 1st Angle Projection General Procedure: 1st Angle Orthographic Projection	7-3 7-4 7-4 7-5 7-6 7-7 7-8 7-9

Example 1: 1st Angle Orthographic Projection	7-10
Orthographic Sketching Exercises	7-11
Third-Angle Projection	7-17
Rotation of the Horizontal and Profile Planes	7-18
The 3D Adjuster Model and 3rd Angle Projection	7-19
The Glass Box and the Six Principal Views	7-20
General Procedure: 3rd Angle Orthographic Projection	7-22
Example 2: 3rd Angle Orthographic Projection	7-23
Example 3: 3rd Angle Orthographic Projection	7-34
3rd Angle Orthographic Sketching Exercises	7-25
Alphabet of Lines	7-31
Precedence of Lines	7-33
The U-Bracket Design	7-34
The BORN Technique	7-35
Starting Autodesk Inventor	7-35
Sketch Plane Settings	7-36
Apply the BORN Technique	7-37
Create the 2D Sketch for the Base Feature	7-39
Create the First Extrude Feature	7-42
The Implied Parent/Child Relationships	7-43
Create the Second Solid Feature	7-43
Create a Cut Feature	7-47
The Second Cut Feature	7-48
Examine the Parent/Child Relationships	7-50
Modify a Parent Dimension	7-51
A Design Change	7-52
Feature Suppression	7-53
A Different Approach to the Center_Drill Feature	7-54
Suppress the Rect_Cut Feature	7-56
Create a Circular Cut Feature	7-57
A Flexible Design Approach	7-59
View and Edit Material Properties	7-60
Drawings from Parts and Associative Functionality	7-62
Drawing Mode	7-63
Drawing Sheet Format	7-64
Using the Pre-defined Drawing Sheet Formats	7-66
Activate, Delete, and Edit Drawing Sheets	7-67
Add a Base View	7-68
Create Projected Views	7-69
Adjust the View Scale	7-70
Repositioning Views	7-71
Review Questions	7-73
Exercises	7-74

Chapter 8 Dimensioning and Notes	
Introduction	8-3
Dimensioning Standards and Basic Terminology	8-4
Selection and Placement of Dimensions and Notes	8-5
Metric Dimensioning versus English Dimensioning	8-12
Machined Holes	8-13
Baseline and Chain Dimensioning	8-16
Dimensioning and Tolerance Accumulation	8-17
(1) Tolerance Accumulation - Baseline Dimensioning	8-18
(2) Tolerance Accumulation - Chain Dimensioning	8-19
(3) Avoid Tolerance Accumulation - Dimensioning Features	8-20
Dimensioning Tools in Autodesk Inventor	8-21
The U-Bracket Design	8-21
Starting Autodesk Inventor	8-22
Display Feature Dimensions	8-23
Repositioning and Hiding Feature Dimensions	8-25
Add Additional Dimensions – Reference Dimensions	8-27
Add Center Marks and Center Lines	8-28
Complete the Drawing Sheet	8-31 8-32
Associative Functionality – Modifying Feature Dimensions 3D Model Based Definition	8-32 8-35
Review Questions	8-43
Exercises	8-44
Chapter 9 Tolerancing and Fits	
Precision and Tolerance	9-2
Methods of Specifying Tolerances – English System	9-3
Nomenclature	9-4
Example 9.1	9-5
Fits between Mating Parts	9-6
Selective Assembly	9-7
Basic Hole and Basic Shaft Systems	9-7
American National Standard Limits and Fits – Inches	9-8
Example 9.2 Basic Hole System	9-13
Example 9.3 Basic Hole System	9-14
Example 9.4 Basic Shaft System	9-15
Example 9.5 Basic Shaft System	9-16
Tolerancing – Metric System	9-17
Metric Tolerances and Fits Designation	9-18
Preferred ISO Metric Fits	9-19
Example 9.6 Metric Hole Basis System	9-20
Example 9.7 Shaft Basis System	9-21

9-22

Updating the U-Bracket Drawing

	Table of Contents
Determining the Telegrape Demains 1	0.22
Determining the Tolerances Required	9-23 9-25
Review Questions Exercises	9-25 9-26
Exercises	9-20
Chapter 10 Pictorials and Sketching	
Engineering Drawings, Pictorials and Sketching	10-2
Isometric Sketching	10-7
Chapter 10 - Isometric Sketching Exercises	10-9
Oblique Sketching	10-19
Chapter 10 - Oblique Sketching Exercises	10-20
Perspective Sketching	10-26
One-Point Perspective	10-27
Two-Point Perspective	10-28
Chapter 10 - Perspective Sketching Exercises	10-29
Review Questions	10-35
Exercises	10-36
Chapter 11 Auxiliary Views and Reference Geometry	
Introduction	11-3
Normal View of an Inclined Surface	11-4
Construction Method I – Folding Line Method	11-6
Construction Method II – Reference Plane Method	11-8
Partial Views	11-10
Work Features	11-11
Auxiliary Views in 2D Drawings	11-11
The Rod-Guide Design	11-11
Modeling Strategy	11-12
Starting Autodesk Inventor	11-13
Apply the BORN Technique	11-13
Creating the Base Feature	11-15
Create an Angled Work Plane	11-17
Create a 2D Sketch on the Work Plane	11-18
Use the Projected Geometry Option	11-18
Complete the Solid Feature	11-22
Create an Offset Work Plane	11-23
Create another Cut Feature Using the Work Plane	11-24
Start a New 2D Drawing	11-26
Add a Base View	11-27
Create an Auxiliary View	11-28
Display Feature Dimensions	11-30
Adjust the View Scale Retrieving Dimensions in the Auxiliary View	11-32 11-33
Redieving Difficusions in the Auxiliary view	11-33

ix

Add Center Marks and Center Lines	11-35
Complete the Title Block with iProperties	11-38
Edit the Isometric view	11-40
Review Questions	11-41
Exercises	11-42
Chapter 12 Section Views & Symmetrical Features in Designs	
Introduction	12-3
General Rules of Section Views	12-5
Section Drawing Types	12-6
Full Section	12-6
Half Section	12-6
Offset Section	12-7
Broken-Out Section	12-7
Aligned Section	12-8
Half Views	12-8
Thin Sections	12-8
Revolved Section	12-9
Removed Section	12-9
Conventional Breaks	12-10
Ribs and Webs in Sections	12-10
Parts Not Sectioned	12-10
Section Views in Autodesk Inventor	12-11
A Revolved Design: Pulley	12-11
Modeling Strategy - A Revolved Design	12-12
Starting Autodesk Inventor	12-13
Set Up the Display of the Sketch Plane	12-13
Creating the 2D Sketch for the Base Feature	12-14
Create the Revolved Feature	12-18
Mirroring Features	12-19
Create a Pattern Leader Using Construction Geometry	12-21
Circular Pattern	12-26
Examine the Design Parameters	12-28
Drawing Mode – Defining a New Border and Title Block	12-28
Create a Drawing Template	12-32
Create the Necessary Views	12-33
Retrieve Model Annotations – Features Option	12-36
Associative Functionality – A Design Change	12-38
Add Centerlines to the Pattern Feature	12-40
Complete the Drawing	12-41
Additional Title Blocks	12-44
Review Questions	12-46
Exercises	12-47

Chapter 13 Threads and Fasteners	
Introduction	13-3
Screw-Thread Terminology	13-4
Thread Forms	13-6
Thread Representations	13-7
Detailed Representation	13-8
Schematic Representation	13-9
Simplified Representation	13-10
Thread Specification – English Units	13-11
Unified Thread Series Thread Fits	13-12
	13-13 13-13
Thread Specification – Metric Thread Notes Examples	13-13
Specifying Fasteners	13-14
Commonly Used Fasteners	13-16
Drawing Standard Bolts	13-18
Bolt and Screw Clearances	13-18
Fasteners Using Autodesk Inventor's Content Center	13-19
Starting Autodesk Inventor	13-19
Review Questions	13-25
Chapter 14 Assembly Modeling and Working Drawings	
General Engineering Design Process	14-3
Working Drawings	14-4
Detail Drawings	14-4
Assembly Drawings	14-5
Bill of Materials (BOM) and Parts List	14-5
Drawing Sizes	14-6
Drawing Sheet Borders and Revisions Block	14-6
Title Blocks	14-7
Working Drawings with Autodesk Inventor	14-8
Assembly Modeling Methodology	14-9
The Shaft Support Assembly	14-10
Additional Parts	14-10
Starting Autodesk Inventor	14-13
Placing the First Component	14-14
Placing the Second Component	14-15
Degrees of Freedom and Constraints	14-16
Assembly Constraints	14-17
Apply the First Assembly Constraint	14-20
Apply a Second Mate Constraint	14-21
Constrained Move	14-22 14-23
Apply a Flush Constraint	14-23

Placing the Third Component	14-25
Applying an Insert Constraint	14-26
Assemble the Cap-Screws	14-27
Exploded View of the Assembly	14-28
Editing the Components	14-30
Adaptive Design Approach	14-31
Delete and Re-apply Assembly Constraints	14-35
Setup a Drawing of the Assembly Model	14-37
Creating a Parts List	14-39
Edit the Parts List	14-40
Change the Material Type	14-42
Add the Balloon Callouts	14-44
Completing the Title Block Using the iProperties Option	14-44
Bill of Materials	14-46
Review Questions	14-48
Exercises	14-49
Chapter 15	
Introduction to Stress Analysis	
Introduction	15-2
Problem Statement	15-4
Preliminary Analysis	15-4
Maximum Normal Stress Analysis	15-4
Maximum Displacement	15-5
Finite Element Analysis Procedure	15-6
Create the Autodesk Inventor Part	15-7
Create the 2D Sketch for the Plate	15-7
Assigning the Material Properties	15-10
Switch to the Stress Analysis Module	15-11
Apply Constraints and Loads	15-14
Create a Mesh and Run the Solver	15-16
Refinement of the FEA Mesh – Global Element Size	15 10
	15-18
Refinement of the FEA Mesh – Local Element Size	15-18 15-20
Refinement of the FEA Mesh – Local Element Size Comparison of Results	15-20
Comparison of Results	15-20 15-23
Comparison of Results Create an HTML Report	15-20 15-23 15-24
Comparison of Results Create an HTML Report Geometric Considerations of Finite Elements	15-20 15-23 15-24 15-25
Comparison of Results Create an HTML Report Geometric Considerations of Finite Elements Conclusion	15-20 15-23 15-24 15-25 15-26
Comparison of Results Create an HTML Report Geometric Considerations of Finite Elements	15-20 15-23 15-24 15-25

Appendix

- A. Running and Sliding Fits American National Standard
- B. METRIC LIMITS AND FITS
- C. UNIFIED NATIONAL THREAD FORM
- D. METRIC THREAD FORM
- E. FASTENERS (INCH SERIES)
- F. METRIC FASTENERS
- G. FASTENERS
- H. REFERENCES

Index