Principles and Practice

An Integrated Approach to Engineering Graphics and AutoCAD® 2026














Table of Contents

Preface	1
Acknowledgments	ii
Table of Contents	iii
AutoCAD Certified User Examination Reference Guide	xiii
Tips on Taking the AutoCAD Certified User Examination	XX
Chapter 1	
Introduction and AutoCAD Fundamentals	
Introduction	1-3
Drawing in CAD Systems	1-5
Development of Computer Geometric Modeling	1-5
Why use AutoCAD 2026?	1-8
Getting Started with AutoCAD 2026	1-10
AutoCAD 2026 Screen Layout	1-11
Application Menu	1-12
Quick Access Toolbar	1-12
AutoCAD Menu Bar	1-12
Layout Tabs	1-12
Drawing Area	1-13
Graphics Cursor or Crosshairs	1-13
Command Prompt Area	1-13
Cursor Coordinates	1-13
Status Toolbar	1-13
Ribbon Tabs and Panels	1-14
Draw and Modify Toolbar Panels	1-14
Layers Control Toolbar Panel	1-14
Viewport/View/Display Controls	1-14
Mouse Buttons	1-15
[Esc] - Canceling Commands	1-15
Online Help	1-16
Leaving AutoCAD 2026	1-17
Creating a CAD File Folder	1-17
Drawing in AutoCAD	1-18
Starting Up AutoCAD 2026	1-18
Drawing Units Setup	1-20
Drawing Area Setup	1-21
Drawing Lines with the Line Command	1-23
Visual Reference	1-25
Grid On	1-26
Snap Mode On	1-27
Using the Erase Command	1-28
Repeat the Last Command	1-29

The CAD Detahase and the Hear Coordinate System	1.20
The CAD Database and the User Coordinate System	1-30 1-31
Changing to the 2D UCS Icon Display Cartesian and Polar Coordinate Systems	1-31
Absolute and Relative Coordinates	1-32
	1-33
Defining Positions CRID Style Setup	1-33
GRID Style Setup The Guide Plate	
	1-34
Creating Circles	1-38
Saving the CAD Design	1-40
Close the Current Drawing	1-41
The Spacer Design	1-42
Start a New Drawing	1-42
Drawing Units Setup	1-43
Drawing Area Setup	1-44
Use the Line Command	1-46
Use the Erase Command	1-48
Using the Arc Command	1-48
Using the Circle Command	1-50
Saving the CAD Design	1-51
Exit AutoCAD 2026	1-51
Review Questions	1-52
Exercises	1-53
Chapter 2 Geometric Constructions	
	2.2
Geometric Constructions	2-3
Geometric Constructions - Classical Methods	2-4
Bisection of a Line or Arc	2-4
Bisection of an Angle	2-5
Transfer of an Angle	2-6
Dividing a Given Line into a Number of Equal Parts	2-7
Circle through Three Points	2-8
Line Tangent to a circle from a Given Point	2-9
Circle of a Given Radius Tangent to Two Given Lines	2-10
Circle of a Given Radius Tangent to an Arc and a Line	2-11
Circle of a Given Radius Tangent to Two Arcs	2-12
Starting Up AutoCAD 2026	2-13
Dynamic Input	2-13
Object Snap Toolbar	2-17
Geometric Construction - CAD Method	2-18
Bisection of a Line or Arc	2-18
Bisection of an Angle	2-21
Transfer of an Angle	2-23
Dividing a Given Line into a Number of Equal Parts	2-26
Circle through Three Points	2-28

Exercises 3-30

Chapter 4				
Orthographic	Projection	and	Multiview	Constructions

Introduction	4-3
Basic Principles of Projection	4-4
Orthographic Projection	4-4
Multiview Orthographic Projection	4-5
First-Angle Projection	4-6
Rotation of the Horizontal and Profile Planes	4-7
Getting the 3D Adjuster Model through the Internet	4-8
Dynamic Rotation – 3D Orbit	4-9
General Procedure: 1 St Angle Orthographic Projection	4-10
1 St Angle Orthographic Sketching Exercises	4-11
Third-Angle Projection	4-13
Rotation of the Horizontal and Profile Planes	4-14
Examining the 3 rd Angle Projection	4-15
The Glass Box and the Six Principal Views	4-16
Examining the Glass Box Model	4-18
General Procedure: 3 rd Angle Orthographic Projection	4-19
Example 2: 3 rd Angle Orthographic Projection	4-20
3 rd Angle Orthographic Sketching Exercises	4-21
Alphabet of Lines	4-23
Precedence of Lines	4-25
The Locator Part	4-26
Starting Up AutoCAD 2026	4-26
Layers Setup	4-27
Drawing Construction Lines	4-28
Using the Offset Command	4-28
Set Layer Object as the Current Layer	4-30
Using the Running Object Snaps	4-30
Creating Object Lines	4-32
Turn Off the Construction Lines Layer	4-33
Adding More Objects in the Front View	4-33
AutoCAD's AutoSnap TM and AutoTrack TM Features	4-34
Adding More Objects in the Top View	4-36
Drawing Using the Miter Line Method	4-40
More Layers Setup	4-42
Top View to Side View Projection	4-43
Completing the Front View	4-45
Object Information Using the List Command	4-47
Object Information Using the Properties Command	4-48
Review Questions	4-49
Exercises	4-50

Chapter 5 Pictorials and Sketching	
Engineering Drawings, Pictorials and Sketching Isometric Sketching Isometric Sketching Exercises	5-2 5-7 5-9
Oblique Sketching	5-19
Oblique Sketching Exercises	5-20
Perspective Sketching	5-26
One-point Perspective	5-27
Two-point Perspective Perspective Sketching Exercises	5-28 5-29
Review Questions	5-35
Exercises	5-36
Chapter 6 AutoCAD 2D Isometric Drawings	
Introduction	6-2
The Angle Support Design	6-3
Starting Up AutoCAD 2026	6-4
AutoCAD Isoplane and Isodraft Commands	6-5
Layers Setup	6-6
Create the Base Box of the Design	6-7
Create the Design inside the Base Box	6-11
Create the Isocircle on the top face	6-14
Using the Editing Tools in an Isometric drawing The Tyles Angles Posics Modeling Strategy	6-17
The Tube Anchor Design – Modeling Strategy Start a New Drawing and Layers Setup	6-17 6-18
Create a Base Box of the Design	6-19
Locate the Centers for the Isocircles	6-22
Create the Isocircles	6-24
Using the Parametric tools to complete the drawing	6-31
Review Questions	6-36
Exercises	6-37
Chapter 7 Dimensioning and Notes	
Introduction	7-3
Dimensioning Standards and Basic Terminology	7-4
Selection and Placement of Dimensions and Notes	7-5
Metric Dimensioning versus English Dimensioning	7-12
Machined Holes	7-13
Baseline and Chain Dimensioning	7-16
Dimensioning and Tolerance Accumulation	7-17

	7-18
` '	7-19
E .	7-20
Dimensioning Tools in AutoCAD	7-21
The P-Bracket Design	7-21
Starting Up AutoCAD 2026	7-22
Layers Setup	7-23
The P-Bracket Design	7-24
LineWeight Display Control	7-24
Drawing Construction Lines	7-25
Using the Offset Command	7-25
Set Layer Object Lines as the Current Layer	7-27
Creating Object Lines	7-27
Creating Hidden Lines	7-28
Creating Center Lines	7-29
	7-29
Using the Fillet Command	7-30
Saving the Completed CAD Design	7-31
	7-32
ε	7-33
	7-33
	7-34
Using the Center Mark Command	7-37
Adding Linear Dimensions	7-38
	7-39
Adding Radius and Diameter Dimensions	7-41
	7-42
Adding Special Characters	7-43
Saving the Design	7-43 7-44
	7- 44 7-44
Review Questions	7-45 7-46
Exercises	/-40
Chapter 8	
Tolerancing and Fits	
•	0.2
Precision and Tolerance	8-2
Methods of Specifying Tolerances – English System	8-3
Nomenclature	8-4
Example 8.1	8-5
Fits between Mating Parts	8-6
Selective Assembly	8-7
Basic Hole and Basic Shaft Systems	8-7
American National Standard Limits and Fits – Inches	8-8
Example 8.2 Basic Hole System	8-13
Example 8.3 Basic Hole System	8-14

Exercises

ix

9-39

Chapter 10	
Auxiliary	Views

Introduction	10-3
Normal View of an Inclined Surface	10-4
Construction Method I – Folding Line Method	10-6
Construction Method II – Reference Plane Method	10-8
Partial Views	10-10
Creating Auxiliary Views in AutoCAD	10-11
The V-Block Design	10-11
Starting Up AutoCAD 2026	10-12
Setting Up the Principal Views	10-13
Setting Up the Top View	10-16
Using the Offset Command	10-17
Creating Object Lines in the Front View	10-19
Setting the Polar Tracking Option	10-20
Setting Up an Auxiliary View	10-23
Aligning the Auxiliary View to the Front View	10-24
Creating the V-cut in the Auxiliary View	10-24
Creating the V-cut in the Front View and Top View	10-27
Setting the Polar Tracking Option	10-27
Completing the Top View	10-29
Edit the Plot Style Table – Black and White Prints	10-29
· · · · · · · · · · · · · · · · · · ·	10-32
Start a new drawing for a Metric Template File	10-35
Layers Setup Set yn Metric Borders and Title Block by Cony & Posts	
Set up Metric Borders and Title Block by Copy & Paste	10-37
Review Questions Exercises	10-42
Exercises	10-43
Chapter 11	
Section Views	
Introduction	11-3
General Rules of Section Views	11-5
Section Drawing Types	11-6
Full Section	11-6
Half Section	11-6
Offset Section	11-7
Broken-Out Section	11-7
Aligned Section	11-8
Half Views	11-8
Thin Sections	11-8
Revolved Section	11-9
Removed Section	11-9
Conventional Breaks	11-10
Ribs and Webs in Sections	11-10
Parts Not Sectioned	11-10

Section Views in AutoCAD The Bearing Design Starting Up AutoCAD 2026 The Bearing Design Setting up the Principal Views Creating Object Lines in the Front View Editing the Circles Setting Up the Side View Adding Hidden Lines in the Side View Changing the Linetype Scale Property Stretching and Moving Objects with Grips Drawing a Cutting Plane Line Converting the Side View into a Section View Adding Section Lines Review Questions Exercises Chapter 12	11-11 11-12 11-13 11-13 11-15 11-17 11-18 11-20 11-22 11-23 11-24 11-27 11-29 11-32 11-33
Threads and Fasteners	
Introduction Screw-Thread Terminology Thread Forms Thread Representations Detailed Representation Schematic Representation Simplified Representation Thread Specification – English Units Unified Thread Series Thread Fits Thread Specification – Metric Thread Notes Examples Specifying Fasteners Commonly used Fasteners Drawing Standard Bolts Bolt and Screw Clearances Review Questions Exercises	12-2 12-3 12-5 12-6 12-7 12-8 12-9 12-10 12-11 12-12 12-12 12-13 12-14 12-15 12-17 12-17 12-17
Chapter 13 Working Drawings	
General Engineering Design Process Working Drawings Detail Drawings Assembly Drawings	13-3 13-4 13-4 13-5

Bill of Materials (BOM) and Parts List	13-5
Drawing Sizes	13-6
Drawing Sheet Borders and Revisions Block	13-6
Title Blocks	13-7
Working Drawings with AutoCAD	13-8
The Shaft Support Subassembly	13-9
Additional Parts	13-9
Cap-Screw	13-9
Collar	13-10
Base-Plate	13-10
Starting Up AutoCAD and Loading Multiple Drawings	13-11
Using AutoCAD with the Internet	13-12
Rearrange the Displayed Windows	13-13
Defining a Block	13-14
Insert and Rotate a Block	13-16
Starting the Assembly Drawing	13-17
Copying and Pasting with the Windows Clipboard	13-18
Converting the View into a Section View	13-19
Adding the Bearing to the Assembly	13-21
Adding the Cap-Screws to the Assembly	13-24
Creating Callouts with the Multileader Command	13-26
Creating a Viewport in the A-size Layout	13-29
Viewport Properties	13-30
Adding a Parts List to the Assembly Drawing	13-31
Review Questions	13-37
Exercises	13-38

Appendix

- A. Running and Sliding Fits American National Standard
- B. Metric Limits and Fits
- C. Unified National Thread Form
- D. Metric Thread Form
- E. Fasteners (Inch Series)
- F. Metric Fasteners
- G. Bolt and Screw Clearance Holes
- H. References

Index